

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Calvert Cliffs, Unit 1DOCKET NUMBER (2)
050003171 OF 02TITLE (4)
Reactor Trip on Low Steam Generator Water Level, Low Power and Feed System in Manual

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
08	06	85	85	009	010	08	29	85			050003171

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																																		
1	<table border="1"><thead><tr><th>20.402(b)</th><th>20.405(a)</th><th>90.73(a)(2)(iv)</th><th>73.71(b)</th></tr></thead><tbody><tr><td>20.405(a)(1)(i)</td><td>90.73(a)(1)</td><td>90.73(a)(2)(v)</td><td>73.71(a)</td></tr><tr><td>20.405(a)(1)(ii)</td><td>90.73(a)(2)</td><td>90.73(a)(2)(vi)</td><td>OTHER (Specify in Abstract below and in Text, NRC Form 305A)</td></tr><tr><td>20.405(a)(1)(iii)</td><td>90.73(a)(3)(i)</td><td>90.73(a)(2)(vii)(A)</td><td></td></tr><tr><td>20.405(a)(1)(iv)</td><td>90.73(a)(3)(ii)</td><td>90.73(a)(2)(vii)(B)</td><td></td></tr><tr><td>20.405(a)(1)(v)</td><td>90.73(a)(3)(iii)</td><td>90.73(a)(2)(viii)</td><td></td></tr></tbody></table>											20.402(b)	20.405(a)	90.73(a)(2)(iv)	73.71(b)	20.405(a)(1)(i)	90.73(a)(1)	90.73(a)(2)(v)	73.71(a)	20.405(a)(1)(ii)	90.73(a)(2)	90.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 305A)	20.405(a)(1)(iii)	90.73(a)(3)(i)	90.73(a)(2)(vii)(A)		20.405(a)(1)(iv)	90.73(a)(3)(ii)	90.73(a)(2)(vii)(B)		20.405(a)(1)(v)	90.73(a)(3)(iii)	90.73(a)(2)(viii)	
20.402(b)	20.405(a)	90.73(a)(2)(iv)	73.71(b)																																
20.405(a)(1)(i)	90.73(a)(1)	90.73(a)(2)(v)	73.71(a)																																
20.405(a)(1)(ii)	90.73(a)(2)	90.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 305A)																																
20.405(a)(1)(iii)	90.73(a)(3)(i)	90.73(a)(2)(vii)(A)																																	
20.405(a)(1)(iv)	90.73(a)(3)(ii)	90.73(a)(2)(vii)(B)																																	
20.405(a)(1)(v)	90.73(a)(3)(iii)	90.73(a)(2)(viii)																																	

LICENSEE CONTACT FOR THIS LER (12)
NAME
Charles Walker, Procedural Development CoordinatorTELEPHONE NUMBER
AREA CODE
301 260-4706

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
YES (If yes, complete EXPECTED SUBMISSION DATE)	NO				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 2146 on August 6, 1985 Calvert Cliffs Unit One Reactor tripped on low steam generator water level. Power level was 19% and load was being increased. An operator was controlling feedwater control valves (FCVs) and the operating steam generator feed pump (SGFP #11) in manual. Load on the main generator was increased and the operator opened the FCVs to increase feed rate, but feed pump speed was not sufficient to provide adequate feed flow. Feed pump speed was then increased, but not fast enough to prevent a Reactor (RX) Trip on low steam generator water level.

8509040041 850829
PDR ADOCK 05000317
S PDRIE 22
111

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Calvert Cliffs, Unit 1	0 5 0 0 0 3 1 7 8 5	— 0	0 9	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 305A's) (17)

At 2146 on August 6, 1985 Calvert Cliffs Unit One was in MODE 1 at 19% power, following a refueling outage and turbine control valve testing had just been completed. Feedwater controls (EHS-JB) were in manual and an operator was at the feed station. As load was increased on the main generator (EHS-TB) Unit One Reactor (EHS-AC) tripped on low steam generator water level. The low steam generator water level was a result of the operating steam generator feed pump (EHS SJ-P) speed not being increased fast enough by the operator, to compensate for the increased feed demand.

As the Reactor Operator (RO) increased main generator load, the operator at the feedwater controls opened the feedwater control valves (EHS SJ-FCV) to increase feed rate. The operator saw that steam generator levels were not recovering and then realized that steam generator feed pump speed was not sufficient to increase feed flow. The operator then increased steam generator feed pump speed in an attempt to match feed flow with steam flow. The response by the operator was insufficient to provide adequate feed flow and as a result the reactor tripped on low steam generator water level.

Following the trip the plant was placed in hot standby in accordance with plant emergency operating procedures without further incident.

During reactor startup and until 15% to 20% power feedwater controls are in manual and control is a demanding task. During this startup it was more demanding due to the strong positive moderator temperature co-efficient and the performance of turbine control valve testing.

To minimize recurrence of this type of event:

1. Operating with a positive temperature co-efficient while having feedwater controls in manual is a very infrequent evolution. This evolution will be performed frequently on the plant simulator to improve operator response in this mode of operation.
2. This event will be reviewed with all licensed operators.

A review of reportable events at Calvert Cliffs revealed no similar events.

The contact for this event is C. A. Walker, Jr., 301-260-4706.

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475

BALTIMORE, MARYLAND 21203

NUCLEAR POWER DEPARTMENT
CALVERT CLIFFS NUCLEAR POWER PLANT
LUSBY, MARYLAND 20657

August 29, 1985

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Docket No. 50-317
License No. DPR 53

Dear Sirs:

The attached LER 85-09 is being sent to you as required by
10 CFR 50.73.

Should you have any questions regarding this report, we would be
pleased to discuss them with you.

Very truly yours,

L B Russell

L. B. Russell
Plant Superintendent

Pa
LBR:CAW:pah

cc: Dr. Thomas E. Murley
Director, Office of Management Information
and Program Control
Messrs: A. E. Lundvall, Jr.
J. A. Tiernan

IF22
11