

Georgia Power Company  
40 Inverness Center Parkway  
Post Office Box 1295  
Birmingham, Alabama 35201  
Telephone 205 992-7122



C. K. McCoy  
Vice President, Nuclear  
Vogtle Project

November 14, 1996

LCV-0908

Docket No. 50-425


U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555

Ladies and Gentlemen:

VOGTLE ELECTRIC GENERATING PLANT  
LICENSEE EVENT REPORT 2-96-8  
TURBINE/REACTOR TRIP WHILE RESTORING  
MAIN FEED PUMP TURBINE TO SERVICE

In accordance with the requirements of 10 CFR 50.73, Georgia Power Company (GPC) hereby submits the enclosed report associated with an event that occurred on October 23, 1996.

Sincerely,

  
C. K. McCoy

CKM/TEW/afs

Enclosure: LER 2-96-8

cc: Georgia Power Company  
Mr. J. B. Beasley, Jr.  
Mr. M. Sheibani  
NORMS

U. S. Nuclear Regulatory Commission  
Mr. S. D. Ebnetter, Regional Administrator  
Mr. L. L. Wheeler, Licensing Project Manager, NRR  
Mr. C. R. Ogle, Senior Resident Inspector, Vogtle

IF22'1

9611260087 961114  
PDR ADOCK 05000425  
S PDR

**LICENSEE EVENT REPORT (LER)**

PAGE 131

## TURBINE/RX TRIP WHILE RESTORING MAIN FEED PUMP TURBINE TO SERVICE

7	0	6	8	2	6	-	3	2	0	9
---	---	---	---	---	---	---	---	---	---	---

EXPECTED  
SUBMISSION  
DATE (15)

NRC Form 366 (4-95)

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Vogtle Electric Generating Plant - Unit 2	05000425	96	008	00	2	OF	3

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

## A. REQUIREMENT FOR REPORT

This report is required per 10 CFR 50.73 (a)(2)(iv) because an unplanned reactor protection system actuation occurred.

## B. UNIT STATUS AT TIME OF EVENT

At the time of this event, Unit 2 was operating in Mode 1 (power operation) at 64 percent of rated thermal power. Main feed pump turbine B (MFPTB) was being restored to service. Other than that described herein, there was no other inoperable equipment that contributed to the occurrence of this event.

## C. DESCRIPTION OF EVENT

On October 23, 1996, personnel were restoring MFPTB to service following repairs. At 1707 EDT, an automatic turbine/reactor trip signal was received in the control room. The main feedwater system isolated and the auxiliary feedwater (AFW) system actuated, as designed. Operators responded by stabilizing steam generator water levels and transitioning the unit to normal operation in Mode 3 (hot standby).

## D. CAUSE OF EVENT

The cause of this event was an inadequate procedure. Procedure 13615-2, "Condensate and Feedwater Systems," did not clearly address the proper sequence for opening steam line valves to a MFPT when restoring the turbine to service while at power. On October 23, 1996, the steam supply above seat drain valves were opened prior to opening the exhaust line valve. Although the exhaust line valve was leaking by to the condenser, main steam line pressure in the MFPTB was great enough to rupture a 15 psig rupture disk. When operators subsequently closed the steam supply above seat drain valves, outside air was inducted through the ruptured disk and past the leaking exhaust line valve, resulting in a low condenser vacuum condition that led to the turbine/reactor trip.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Vogtle Electric Generating Plant - Unit 2	05000425	96	008	00	3	OF	3

TEXT (If more space is required, use additional copies of NRC Form 366A)(17)

## E. ANALYSIS OF EVENT

The main feedwater system isolated and the AFW system actuated, as designed. Control room operators properly responded to stabilize SG water levels. No problems arose following the trip that prevented operators from transitioning the plant to stable operation in Mode 3. Based on these considerations, there was no adverse effect on plant safety or on the health and safety of the public as a result of this event.

## F. CORRECTIVE ACTIONS

- 1) The rupture disk was replaced, and MFPTB was returned to service.
- 2) Procedure 13615-2 was revised to add specific guidance for the sequence of opening steam line valves. Procedure 13615-1 will be revised by November 30, 1996.
- 3) The leaking exhaust valve will be repaired during the next appropriate unit outage.

## G. ADDITIONAL INFORMATION

- 1) Failed Components:  
None
- 2) Previous Similar Events:  
None
- 3) Energy Industry Identification System Code:  
Main Feedwater System - SJ  
Auxiliary Feedwater System - BA