

## LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)  
DIABLO CANYON, UNIT 1DOCKET NUMBER (2)  
05000275PAGE (3)  
1 OF 1TITLE (4)  
CONTAINMENT VENTILATION ISOLATION

EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)
08	05	85	85	027	00	09	04	85		050000

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)																														
1	<table border="1"><tr><td>20.402(b)</td><td>20.405(c)</td><td>X</td><td>50.73(a)(2)(iv)</td><td>73.71(b)</td></tr><tr><td>20.405(a)(1)(i)</td><td>50.36(c)(1)</td><td></td><td>50.73(a)(2)(v)</td><td>73.71(c)</td></tr><tr><td>20.405(a)(1)(ii)</td><td>50.36(c)(2)</td><td></td><td>50.73(a)(2)(vii)</td><td>OTHER (Specify in Abstract below and in Text, NRC Form 366A)</td></tr><tr><td>20.405(a)(1)(iii)</td><td>50.73(a)(2)(i)</td><td></td><td>50.73(a)(2)(viii)(A)</td><td></td></tr><tr><td>20.405(a)(1)(iv)</td><td>50.73(a)(2)(ii)</td><td></td><td>50.73(a)(2)(viii)(B)</td><td></td></tr><tr><td>20.405(a)(1)(v)</td><td>50.73(a)(2)(iii)</td><td></td><td>50.73(a)(2)(ix)</td><td></td></tr></table>	20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)	20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)		20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)		20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)	
20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)																											
20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)																											
20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)																											
20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)																												
20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)																												
20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(ix)																												

LISCENSEE CONTACT FOR THIS LER (12)  
NAME  
DAVID P. SISK, REGULATORY COMPLIANCE ENGINEERTELEPHONE NUMBER  
AREA CODE  
805595-7351

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	

SUPPLEMENTAL REPORT EXPECTED (14)  
YES (If yes, complete EXPECTED SUBMISSION DATE) ☒ NOEXPECTED SUBMISSION DATE (15)  
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At 0815 PDT, August 5, 1985, while the unit was in Mode 1 (power operation), an automatic isolation of the Containment Ventilation System (CVS)(JM), an Engineered Safety Feature (ESF), occurred. Three containment air isolation valves (ISV) closed as designed. The required 4-hour Significant Event Report was made at 0950 PDT.

The containment ventilation isolation (CVI) occurred while replacing a signal cable connector on radiation monitor (IL)(MON) RM-12. The cable connector was being replaced in accordance with corrective action as identified in Unit 1 LER 85-025 regarding a previous inadvertent CVI.

This event was caused by a combination of an incomplete shopwork follower and personnel error. The shopwork follower, specifically generated for this work, did not contain all the steps necessary to return the monitor to operation. The plant technician, not having all the steps in the follower, erroneously removed power from the monitor by pulling its fuse. The loss of power to the monitor triggered the CVI. The fuse was immediately replaced and RM-12 was returned to service.

To prevent recurrence, signs are now installed on RM-11 and RM-12 stating that deenergization of these instruments may cause an ESF actuation. In addition, appropriate personnel have received additional training which emphasizes the requirement to notify a foreman when the procedure or work follower cannot be followed.

8509110071 850904  
PDR ADGCK 05000275  
S PDRIE22  
11

# PACIFIC GAS AND ELECTRIC COMPANY

PG&E

77 BEALE STREET • SAN FRANCISCO, CALIFORNIA 94106 • (415) 781-4211 • TWX 910-372-6587

JAMES D. SHIFFER  
VICE PRESIDENT  
NUCLEAR POWER GENERATION

September 4, 1985

PGandE Letter No.: DCL-85-292

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Re: Docket No. 50-275, OL-DPR-80  
Diablo Canyon Unit 1  
Licensee Event Report 85-027-00  
Containment Ventilation Isolation


Gentlemen:

Pursuant to 10 CFR 50.73(A)(2)(iv), PGandE is submitting the enclosed Licensee Event Report concerning the inadvertent actuation of an Engineered Safety Feature (ESF), Containment Ventilation Isolation.

This event has in no way affected the public's health and safety.

Kindly acknowledge receipt of this material on the enclosed copy of this letter and return it in the enclosed addressed envelope.

Sincerely,



Enclosure

cc: J. B. Martin

IE22  
1/1