

# AVERAGE DAILY UNIT POWER LEVEL

Completed by J. P. Ronafalvy

Docket No. 50-272  
 Unit Name Salem # 1  
 Date September 10, 1985  
 Telephone 609-935-6000  
 Extension 4455

Month August 1985

Day Average Daily Power Level  
 (MWe-NET)

1	<u>1068</u>
2	<u>1069</u>
3	<u>1065</u>
4	<u>1044</u>
5	<u>1075</u>
6	<u>1077</u>
7	<u>1070</u>
8	<u>1084</u>
9	<u>1085</u>
10	<u>1064</u>
11	<u>1060</u>
12	<u>1084</u>
13	<u>1074</u>
14	<u>1075</u>
15	<u>1078</u>
16	<u>1073</u>

Day Average Daily Power Level  
 (MWe-NET)

17	<u>1068</u>
18	<u>1073</u>
19	<u>1073</u>
20	<u>1090</u>
21	<u>1071</u>
22	<u>1079</u>
23	<u>1079</u>
24	<u>1075</u>
25	<u>1080</u>
26	<u>1080</u>
27	<u>1075</u>
28	<u>1118</u>
29	<u>1046</u>
30	<u>1108</u>
31	<u>1019</u>

P. 8.1-7 R1

8509170360 850831  
 PDR ADOCK 05000272  
 R PDR

1524  
 111

# OPERATING DATA REPORT

Docket No. 50-272  
 Date September 10, 1985  
 Telephone 935-6000  
 Extension 4455

Completed by J. P. Ronafalvy

## Operating Status

	<u>Salem No. 1</u>	<u>Notes</u>
1. Unit Name	<u>August 1985</u>	
2. Reporting Period		
3. Licensed Thermal Power (MWt)	<u>3338</u>	
4. Nameplate Rating (Gross MWe)	<u>1170</u>	
5. Design Electrical Rating (Net MWe)	<u>1090</u>	
6. Maximum Dependable Capacity (Gross MWe)	<u>1124</u>	
7. Maximum Dependable Capacity (Net MWe)	<u>1079</u>	
8. If Changes Occur in Capacity Ratings (items 3 through 7) since Last Report, Give Reason	<u>N/A</u>	

9. Power Level to Which Restricted, if any (Net MWe) N/A

10. Reasons for Restrictions, if any N/A

	<u>This Month</u>	<u>Year to Date</u>	<u>Cumulative</u>
11. Hours in Reporting Period	<u>744</u>	<u>5831</u>	<u>71640</u>
12. No. of Hrs. Reactor was Critical	<u>744</u>	<u>5813.6</u>	<u>41637.1</u>
13. Reactor Reserve Shutdown Hrs.	<u>0</u>	<u>0</u>	<u>3088.4</u>
14. Hours Generator On-Line	<u>744</u>	<u>5810.7</u>	<u>39969.3</u>
15. Unit Reserve Shutdown Hours	<u>0</u>	<u>0</u>	<u>0</u>
16. Gross Thermal Energy Generated (MWH)	<u>2490518</u>	<u>19345903</u>	<u>122113900</u>
17. Gross Elec. Energy Generated (MWH)	<u>831840</u>	<u>6572710</u>	<u>40488760</u>
18. Net Elec. Energy Generated (MWH)	<u>798663</u>	<u>6316931</u>	<u>38414913</u>
19. Unit Service Factor	<u>100</u>	<u>99.7</u>	<u>55.8</u>
20. Unit Availability Factor	<u>100</u>	<u>99.7</u>	<u>55.8</u>
21. Unit Capacity Factor (using MDC Net)	<u>99.5</u>	<u>100.4</u>	<u>49.7</u>
22. Unit Capacity Factor (using DER Net)	<u>98.5</u>	<u>99.4</u>	<u>49.2</u>
23. Unit Forced Outage Rate	<u>0</u>	<u>.3</u>	<u>29.8</u>

24. Shutdowns scheduled over next 6 months (type, date and duration of each)  
N/A

25. If shutdown at end of Report Period, Estimated Date of Startup:  
N/A

26. Units in Test Status (Prior to Commercial Operation):

	<u>Forecast</u>	<u>Achieved</u>
Initial Criticality	<u>9/30/76</u>	<u>12/11/76</u>
Initial Electricity	<u>11/1/76</u>	<u>12/25/76</u>
Commercial Operation	<u>12/20/76</u>	<u>6/30/77</u>

UNIT SHUTDOWN AND POWER REDUCTIONS  
REPORT MONTH August 1985

Docket No. 50-272  
Unit Name Salem No.1  
Date September 10, 1985  
Telephone 609-935-6000  
Extension 4455

Completed by J.P. Ronafalvy

No.	Date	Type 1	Duration Hours	Reason 2	Method of Shutting Down Reactor	License Event Report	System Code 4	Component Code 5	Cause and Corrective Action to Prevent Recurrence
-----	------	-----------	-------------------	-------------	------------------------------------------	----------------------------	------------------	---------------------	---------------------------------------------------------

\* There were no outages for the month of August resulting in a load reduction of greater than 20%.

1  
F: Forced  
S: Scheduled

2 Reason  
A-Equipment Failure-explain  
B-Maintenance or Test  
C-Refueling  
D-Regulatory Restriction  
E-Operator Training & Licensing Exam  
F-Administrative  
G-Operational Error-explain  
H-Other-explain

3 Method  
1-Manual  
2-Manual Scram.  
3-Automatic Scram.  
4-Continuation of  
Previous Outage  
5-Load Reduction  
9-Other

4 Exhibit G  
Instructions  
for Prepara-  
tion of Data  
Entry Sheets  
for Licensee  
Event Report  
(LER) File  
(NUREG 0161)

5 Exhibit 1  
Salem as  
Source

MAJOR PLANT MODIFICATIONS  
REPORT MONTH August 1985

DOCKET NO.: 50-272  
UNIT NAME: Salem 1  
DATE: September 10, 1985  
COMPLETED BY: J. Ronafalvy  
TELEPHONE: 609/339-4455

*DCR NO.	PRINCIPLE SYSTEM	SUBJECT
1EC-0675	Fuel Handling Cranes	Revise limit switch protection arrangement as necessary to comply with intent of No. 2 Unit Outstanding Item No. 047043.
1EC-1591	NPDES Thermal Monitoring System	Relocate circ. water inlet and outlet temperature monitors from their present location at the condenser inlet and outlet waterboxes to the circ. water intake structure for measuring inlet ambient river water temperature and to the six outlet pipes for measuring combined plant discharge temperature.
1EC-2025	Fire Protection-Doors	Addition of three fire rated doors. Two doors are located in the Aux Building and Mechanical/Electrical Penetration Areas, third door is located in the Service Water Intake Structure. In addition, door #379 is to be removed. All three doors rated for 3 hours (Class A).
1EC-2050A	Communication	New raceways for upgrading telephone and data transmission from Service Building. Conduit must be provided to house 300-pair cable of telephone twister copper cable.
1EC-2069	Radiation Monitoring	Install field modification kits for waterproofing the R13 radiation monitors.

\* Design Change Request

MAJOR PLANT MODIFICATIONS  
REPORT MONTH AUGUST 1985

DOCKET NO.: 50-272  
UNIT NAME: Salem 1  
DATE: September 10, 1985  
COMPLETED BY: J. Ronafalvy  
TELEPHONE: 609/339-4455

---

\*DCR NO.                      SAFETY EVALUATION    10 CFR 50.59

---

- 1EC-0675    The installation of the new upper limit switch and other hardware in the Fuel Handling Crane will not affect the safe shutdown of the reactor nor will it create any new fire hazard. No changes to the FSAR or the Tech. Specs. are involved. Implementation of this DCP will comply with NUREG-0612 requirements for upgrading the cranes at operating nuclear power plants. No unreviewed safety or environmental questions are involved.
- 1EC-1591    This DCP involves moving the location of the circulating water system temperature monitors and as such does not involve a change to the FSAR or the Tech. Specs. No unreviewed safety or environmental questions are involved.
- 1EC-2025    The new fire doors are not safety related. Their presence will not impact the operation of existing safety related equipment nor will they reduce the margin of safety related equipment as outlined in the Tech. Specs. Since the fire doors are relatively passive and "inert", a failure of the doors will not result in any damage or influence the operation of safety related equipment. The new fire doors will reduce the risk of fire damage to safety related equipment. No unreviewed safety or environmental questions are involved.
- 1EC-2050A    This DCP involves the installation of telephone conduit between the Administration Building and the Service Building. No work is being performed in safety related areas of the plant. This DCP does not impinge or interfere with any safety related system. This package does not affect the basis for the Tech. Specs. or the FSAR from an electrical standpoint. No unreviewed safety or environmental questions are involved.
- 1EC-2069    This design change enhances the operation of the five R-13 radiation monitors which are not safety related. This modification will not alter, affect or compromise the safety related components and systems in the plant. No unreviewed safety or environmental questions are involved.

\*DCR - Design Change Request

PSE&G SALEM GENERATING STATION  
SAFETY RELATED WORK ORDER LOG

SALEM UNIT 1

---

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

---

8508180021

SIC

1

DORIC 577/P250 T2609A

FAILURE DESCRIPTION: 13 AUX. FEED PUMP TURBINE INBOARD BEARING TEMP.  
INDICATION IS FAILED.

CORRECTIVE ACTION: REMOVED FIELD LEADS FROM DORIC AND P-250. PLACED  
JUMPERS ON APPROPRIATE POINTS P-250 READ 8.0.7  
AND DORIC READ 82 DEGREES F. RECONNECTED  
FIELD LEADS.

---

8508060572

SIC

1

13 S/G FWR FLO CH 2

FAILURE DESCRIPTION: COMPARATOR TRIPPING OUT OF SPEC., REWORK AS  
NECESSARY, THEN COMPLETE CHANNEL FUNCTIONAL.

CORRECTIVE ACTION: COMP. 1FC531 #1B OUTPUT OUT OF SPEC FOUND CAPS  
LEAKING C2 & C3 REG/MED ALSO REGISTOR. INSTALLED  
DCR 1EC0575 R39.

---

8508060050

SIC

1

1 SW 308

FAILURE DESCRIPTION: THE MOORE CONTROLLER FOR THIS VALVE CAUSES THE VALVE  
TO GO OPEN WHEN PUT IN THE SEAL POSITION.

CORRECTIVE ACTION: REMOVED POSITIONER AND DISCONNECTED AIR SUPPLY AND  
PROCESS IMPACT LINE TO 1SW308. 8/7/85 REINSTALLED  
POSITIONER. 8/7/85 VERIFIED CONTROLLER OPERATION.

---



## SALEM UNIT 1

---

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

---

8508030177

SMD

1

14AF920

FAILURE DESCRIPTION: THE 14AF920 (CHECK) VALVE IS LEAKING THRU, ALLOWING FLOW BACK FROM 14 S/G TO THE AFST.

CORRECTIVE ACTION: REMOVED BONNET, CLEANED INTERNALS, REPLACED BONNET

---

8508010036

SIC

1

RX COOL FLO LOOP 12 CH1

FAILURE DESCRIPTION: COMPARATOR IS TRIPPING OUT OF SPEC.

CORRECTIVE ACTION: REPLACED COMPARATOR SINAO-997 WITH SINAO-962. PERFORMED "AS LEFT" OF PAGE 9, STEPS 8.8.1.1. AND ILLUMINATED. I&C SAYS THE PROBLEM IS IN THE CONSOLE, NO COMPARATOR IS TRIPPED TO GENERATE THE ALARM.

---

8507301797

SMD

1

11GB4

FAILURE DESCRIPTION: LEAKING AT VALVE BODY.

CORRECTIVE ACTION: TEMPORARILY REPAIRED VALVE BY FURMANITE. NEW WORK ORDER TO BE WRITTEN FOR PERMANENT REPAIR.

---

8507260357

SOD

1

2" RECIRC HEADER

FAILURE DESCRIPTION: CRUD BUILDUP IN S.F. PIT DEMINERALIZER RECIRC. HEADER WHICH IS CAUSING A HIGH RAD AREA AND IS GETTING LARGER. WOULD LIKE 2" HEADER FLUSHED BY UTILIZING SF29 AND SF37 VIA REFUEL. WTR. PURIF PUMP. RECIRC LINE IN QUESTION HAS SF60 AND 61 FLOW GAGE TAPS.

CORRECTIVE ACTION: READINGS BEFORE STARTED 1.2R/HR SLUICED RESINS AND FLUSHED READINGS AFTER .2MR/HR RESTORED LINEUP TO NORMAL.

---

## SALEM UNIT 1

---

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

---

8505130472

SMD

1

13CC197

FAILURE DESCRIPTION: THE VALVE HANDWHEEL IS BROKEN.

CORRECTIVE ACTION: REPLACED STRIPPED OUT HANDWHEEL.

0099178737

SMD

1

16 SERVICE WATER PUMP

FAILURE DESCRIPTION: THE PUMP PACKING RING IS BLOWN.

CORRECTIVE ACTION: TIGHTENED TUBE TENSION AND REPLACED SEAL RING UNDER LOCK NUT.

0099178079

SIC

1

11WHUT LEVEL INDICATION

FAILURE DESCRIPTION: LEVEL INDICATION FOR 11 WHUT IS NOT WORKING PROPERLY. TANK OVERFLOWED WITH LEVEL INDICATING 82%. NO HIGH LEVEL ALARM WAS RECEIVED.

CORRECTIVE ACTION: CAL. RECEIVER GAUGE AND ALARM HI/LO LIS 1008 CAL. XMTR 1LT 1008 AND SIMULATED INPUT TO TRANSMITTER AND VERIFIED CORRECTED READINGS AND ALARM POINTS ON RECEIVER GAUGE ON PNL 104 AND PNL 107 - ALSO BLEWDOWN INSTRUMENT LINE FROM TRANSMITTER TO #11 WHUT

0099178095

SIC

1

DORIC POINT 205

FAILURE DESCRIPTION: THE DORIC POINT IS FAILED.

CORRECTIVE ACTION: FOUND BROKEN LEAD TO TERMINAL 205 ON DORIC SATELLITE IN UNIT 1 RACK AREA. REPAIRED LEAD AND RECONNECTED TO TERMINAL BOARD. POINT NOW READING ON DORIC SCANNER.



## SALEM UNIT 1

---

WO NO	DEPT	UNIT	EQUIPMENT IDENTIFICATION
-------	------	------	--------------------------

---

0099176637

SMD

1

11AF8

FAILURE DESCRIPTION: THIS VALVE LEAKS THRU CAUSING THE AFWST TO OVERFLOW.

CORRECTIVE ACTION: OPEN AND INSPECTED VALVE, CLEANED VALVE INTERNALS - REASSEMBLED W/NEW GASKETS.

---

0099165533

SIC

1

LOOP 12 CH I RX COOL FLOW

FAILURE DESCRIPTION: CH I RX. COOL. FLOW IS INDICATING THREE % HIGHER THAN OTHER CHANNELS.

CORRECTIVE ACTION: REPLACED TRANSMITTER, BENCH CALIBRATED NEW TRANSMITTER AND PERFORMED TIME RESPONSE TEST PROCEDURE 1PD-2.8.006.

---

0099165392

SIC

1

PLANT VENT RMS MONITOR

FAILURE DESCRIPTION: PLEASE REPAIR "+" L.E.D. ON REMOTE DISPLAY MODULE. PRESENTLY NOT VISIBLE.

CORRECTIVE ACTION: REPLACED L.E.D. I.C. FOR "+" INDICATION ON REMOTE DISPLAY 8/12/85.

---

0099165121

SIC

1

POWER RANGE CHAN.

FAILURE DESCRIPTION: NEGATIVE RATE TRIP INOPERABLE. FOUND DURING CHANNEL FUNCT.

CORRECTIVE ACTION: FOUND NEG. RATE BISTABLE CARD BAD AND AN UN-LANDED SHIELD WIRE. LANDED WIRE AND REPLACED BISTABLE CARD. FINISHED FUNCTIONAL SAT.

SALEM GENERATING STATION  
MONTHLY OPERATING SUMMARY - UNIT NO. 1  
AUGUST 1985

SALEM NO. 1

The Unit operated at full power for the entire period.

## REFUELING INFORMATION

COMPLETED BY: J. RonafalvyDOCKET NO.: 50-272UNIT NAME: Salem 1DATE: September 10, 1985TELEPHONE: 609/935-6000EXTENSION: 4455Month August 1985

1. Refueling information has changed from last month:

YES \_\_\_\_\_ NO X

2. Scheduled date for next refueling:
- February 22, 1986

3. Scheduled date for restart following refueling:
- May 4, 1986

4. A) Will Technical Specification changes or other license amendments be required?

YES \_\_\_\_\_ NO \_\_\_\_\_

NOT DETERMINED TO DATE \_\_\_\_\_

- B) Has the reload fuel design been reviewed by the Station Operating Review Committee?

YES \_\_\_\_\_ NO XIf no, when is it scheduled? January 1986

5. Scheduled date(s) for submitting proposed licensing action:

January 1986 if required

6. Important licensing considerations associated with refueling:

NONE

7. Number of Fuel Assemblies:

A) Incore

193

B) In Spent Fuel Storage

296

8. Present licensed spent fuel storage capacity:

1170

Future spent fuel storage capacity:

1170

9. Date of last refueling that can be discharged to spent fuel pool assuming the present licensed capacity:

September 2001

8-1-7.R4



Public Service Electric and Gas Company P.O. Box E Hancocks Bridge, New Jersey 08038

Salem Generating Station

September 10, 1985

Director, Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Dear Sir:

MONTHLY OPERATING REPORT  
SALEM NO. 1  
DOCKET NO. 50-272

In compliance with Section 6.9, Reporting Requirements for the Salem Technical Specifications, 10 copies of the following monthly operating reports for the month of August 1985 are being sent to you.

Average Daily Unit Power Level  
Operating Data Report  
Unit Shutdowns and Power Reductions  
Major Plant Modification  
Safety Related Work Orders  
Operating Summary  
Refueling Information

Sincerely yours,

J. M. Zupko, Jr.  
General Manager - Salem Operations

JR:sbh

cc: Dr. Thomas E. Murley  
Regional Administrator USNRC  
Region I  
631 Park Avenue  
King of Prussia, PA 19406

Director, Office of Management  
Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Enclosures  
8-1-7.R4