


## ACCIDENT SEQUENCE PRECURSOR PROGRAM EVENT ANALYSIS

LER No: 287/91-007, 269/91-009  
 Event Description: Reactor trip due to LOFW plus degraded EFW  
 Date of Event: July 3, 1991  
 Plant: Oconee 3

### Summary

A loss of condensate flow caused a loss of main feedwater (LOFW) and a reactor scram. All three emergency feedwater (EFW) pumps started as required. The EFW flow control valve for one steam generator (SG) did not automatically respond, and manual control was taken 4 min into the event. Operator errors while restarting the main feedwater (MFW) pumps further degraded the EFW system. Two main steam relief valves (MSRVs) did not reseal until pressure was reduced to 90% of their actuation setpoints.

The conditional probability of core damage associated with this event is  $1.8 \times 10^{-5}$ . The relative significance of the event compared to other postulated events at Oconee 3 is shown below.



### Event Description

On July 3, 1991, at 1118 hours, while operating at 100% full power, Oconee 3 scrammed as a result of an LOFW. The LOFW was initiated when particles from a degraded seal clogged an instrument air flow path in the master valve controller for the condensate demineralizer system. This caused five parallel valves to fail closed, blocking all condensate flow. Demineralizer bypass valves did not open to compensate because an operator had failed to return them to automatic control. The loss of condensate flow

resulted in the trip of condensate booster pumps due to low suction pressure, which then caused a trip of the main feedwater pumps, followed by the reactor scram.

All three EFW pumps started on a low main feedwater pump turbine control oil pressure signal. At 1119 hours, operators shut down the turbine-driven EFW pump, after confirming that both motor-driven EFW pumps were operating. As SG level dropped toward the post trip setpoint, it was observed that FDW-315, EFW throttle valve to SG A, was not controlling properly in automatic, so manual control was initiated at 1122 hours. SG level reached a minimum of 21 in. prior to operators taking action to compensate for the failed valve. The valve failed to control in automatic because a normally energized solenoid valve failed to move to its deenergized position. This solenoid valve model had caused earlier problems at Oconee, and a decision was made after this event to replace this and similar valves.

Two MSRVs did not reseal until main steam pressure was reduced to approximately 88% to 90% of their actuation setpoints, which is slightly lower than desired. Also, the low-flow alarm for cooling water flow to EFW pump B did not clear as expected. An operator was dispatched to check local instrumentation and verified that cooling flow to the pump was acceptable.

After the unit was stabilized at hot shutdown, the operators initiated actions to restart the MFW pumps so that they could be used for SG makeup. This required starting a condensate booster pump in the recirculation mode, which fills the upper storage tank (UST) with water from the hotwell. Water in the UST is then used to makeup to the hotwell as its inventory is used by the MFW pumps. Refilling the UST with water from the hotwell increased its temperature to 170°F. This exceeded a 130°F procedural limit for maximum EFW pump source water temperature. At the time of the event, the operators believed that the 130°F limit only applied while at power, and that a 190°F limit applied while shut down. A subsequent review of the Reactor Trip Recovery Procedure indicated that the 130°F limit also applied for up to 5 h after a trip. With the UST temperature greater than 130°F within the 5-h post-trip period, decay heat removal required two of three EFW pumps instead of one of three.

When the operators added water to the UST from the hotwell, they overfilled the tank, which resulted in water flowing into the normally dry reference leg of the UST level instrumentation and generating a false low-level signal. For ~30 min during post-trip recovery, UST level instrumentation indicated that the tank level was less than minimum requirements. During this event the condensate storage tank, which receives overflow from the UST, itself overflowed onto the turbine building floor, and operators were able to confirm that the UST was full. The UST serves as the primary source of water for the EFW pumps. If the UST is determined to be unavailable, procedures require the operators to break condenser vacuum and provide EFW from the hotwell, which can

consume substantial personnel resources and time.

Analysis of post-trip data indicated that one of the two EFW pump actuation signals following loss of the MFW pumps, low pump discharge pressure, was not generated during the LOFW. (The EFW pumps actuated on a low MFW pump turbine control oil pressure signal.) Continued operation of the D heater drain pumps maintained MFW pump discharge piping pressure above the low discharge pressure setpoint. This was subsequently determined to be a potential problem on all three Oconee units for all trips in which the heater drain pumps continue to operate.

### **ASP Modeling Assumptions and Approach**

The event has been modeled as a potentially recoverable LOFW with one EFW flow control valve unavailable. Because of the high UST temperature, two of three EFW pumps were assumed to be required for success. A revised EFW failure probability given these conditions was calculated as follows:

$$p(\text{EFW}) \approx [p(\text{MTR PMP 3A}) \times p(\text{MTR PMP 3B} \mid \text{MTR PMP 3A fails}) + p(\text{MTR PMP 3A}) \times p(\text{TURB PMP}) + p(\text{MTR PMP 3B}) \times p(\text{TURB PMP}) + p(\text{common cause})] \times p(\text{NON REC}) + p(\text{second EFW flow control valve fails}) \times p(\text{fail to manually control flow from control room})$$


$$p(\text{EFW}) \approx [0.01 \times 0.1 + 0.01 \times 0.05 + 0.01 \times 0.05 + 0.00028] \times 0.26 + 0.1 \times 0.04$$

$$p(\text{EFW}) \approx 4.6 \times 10^{-3}$$

### **Analysis Results**

The conditional probability of subsequent core damage estimated for this event is  $1.8 \times 10^{-5}$ . The dominant core damage sequence, highlighted on the following event tree, involves a failure to recover from the LOFW, a subsequent failure of EFW, and failure of feed and bleed.

# B-160



(1) OK for Class D

Dominant core damage sequence for LER 287/91-007

# B-161

## CONDITIONAL CORE DAMAGE PROBABILITY CALCULATIONS

Event Identifier: 287/91-007  
 Event Description: Reactor trip due to LOFW plus degraded EFW  
 Event Date: 07/03/91  
 Plant: Oconee 3

### INITIATING EVENT

#### NON-RECOVERABLE INITIATING EVENT PROBABILITIES

TRANS 1.0E+00

#### SEQUENCE CONDITIONAL PROBABILITY SUMS

End State/Initiator	Probability
CD	
TRANS	1.8E-05
Total	1.8E-05
ATWS	
TRANS	3.4E-05
Total	3.4E-05

#### SEQUENCE CONDITIONAL PROBABILITIES (PROBABILITY ORDER)

Sequence	End State	Prob	N Rec**
17 trans -rt AFW MFW hpi(f/b)	CD	1.6E-05	2.9E-01
16 trans -rt AFW MFW -hpi(f/b) hpr/-hpi	CD	1.8E-06	3.4E-01
18 trans rt	ATWS	3.4E-05	1.2E-01

\*\* non-recovery credit for edited case

#### SEQUENCE CONDITIONAL PROBABILITIES (SEQUENCE ORDER)

Sequence	End State	Prob	N Rec**
16 trans -rt AFW MFW -hpi(f/b) hpr/-hpi	CD	1.8E-06	3.4E-01
17 trans -rt AFW MFW hpi(f/b)	CD	1.6E-05	2.9E-01
18 trans rt	ATWS	3.4E-05	1.2E-01

\*\* non-recovery credit for edited case

SEQUENCE MODEL: c:\asp\1989\pwrdsel.cmp  
 BRANCH MODEL: c:\asp\1989\oconee3.s11  
 PROBABILITY FILE: c:\asp\1989\pwr\_bs11.pro

No Recovery Limit

#### BRANCH FREQUENCIES/PROBABILITIES

Branch	System	Non-Recov	Opr Fail
trans	1.5E-04	1.0E+00	

Event Identifier: 287/91-007

# B-162

loop	1.6E-05	2.4E-01	
loca	2.4E-06	4.3E-01	
rt	2.8E-04	1.2E-01	
rt/loop	0.0E+00	1.0E+00	
emerg.power	2.9E-03	8.0E-01	
AFW	3.8E-04 > 4.6E-03 **	2.6E-01 > 1.0E+00	
Branch Model: 1.OF.3+ser			
Train 1 Cond Prob:	2.0E-02		
Train 2 Cond Prob:	1.0E-01		
Train 3 Cond Prob:	5.0E-02		
Serial Component Prob:	2.8E-04		
afw/emerg.power	5.0E-02	3.4E-01	
MFW	2.0E-01 > 1.0E+00	3.4E-01	
Branch Model: 1.OF.1			
Train 1 Cond Prob:	2.0E-01 > Failed		
porv.or.srv.chall	8.0E-02	1.0E+00	
porv.or.srv.reseat	1.0E-02	1.1E-02	
porv.or.srv.reseat/emerg.power	1.0E-02	1.0E+00	
seal.loca	0.0E+00	1.0E+00	
ep.rec(sl)	0.0E+00	1.0E+00	
ep.rec	4.5E-01	1.0E+00	
hpi	3.0E-04	8.4E-01	
hpi(f/b)	3.0E-04	8.4E-01	1.0E-02
hpr/-hpi	1.5E-04	1.0E+00	1.0E-03
* branch model file			
** forced			

Minarick  
06-08-1992  
15:21:25

Event Identifier: 287/91-007