

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Virgil C. Summer Nuclear Station

DOCKET NUMBER (2)

050003951 OF 03

PAGE (3)

TITLE (4)

Feedwater Regulating Valves

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)
0	5	8	4	027	000	0	6	8			050003951
OPERATING MODE (9)			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)								
POWER LEVEL (10)			73.7101								
960			73.7102								
			X OTHER (Specify in Abstract below and in Text, NRC Form 200A)								
			VOLUNTARY REPORT								

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
A. R. Koon, Asso. Mgr., Reg. Compliance	803 345-5209

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFAC TURE	REPORTABLE TO NRC
X	SV	PCVE	130	N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (15) (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30)	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X				

ABSTRACT (16) (17) (18) (19) (20) (21) (22) (23) (24) (25) (26) (27) (28) (29) (30)

This Voluntary Report is being submitted with respect to maintenance activities associated with the Feedwater Regulating Valves (FRV's) which resulted in a management decision to initiate a controlled shutdown on May 5, 1984.

Based on a concern of the Independent Safety Engineering Group (ISEG) upon completion of their review of the Reactor Trip document package associated with LER 84-025 (titled "Reactor Trip," dated May 25, 1984) with respect to the failure of FRV's A&B to close, the stroke closure times of the FRV's were adjusted prior to restart on May 4, 1984.

While in the process of escalating power during startup, problems were experienced with the FRV's controlling properly. In an effort to stabilize the valves, adjustments were made to the Volume Boosters which affected the valve stroke time resulting in a decision to shut down.

In order to prevent recurrence, a design modification was implemented to segregate the Volume Boosters from the "Trip Close" portion of the Control Air System on the valves. Upon completion of this modification, the FRV's were tested and verified to be operating within acceptable time limits, and the Plant was returned to power operation.

8509130443 840605
PDR ADOCK 05000395
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 2180-0104

EXPIRES 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (3)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
		0 5 0 0 0 3 9 5	8 4	0 2 7	0 0	0 2 OF 0 3

TEXT IF more space is required, use additional NRC Form 2554 (1/77)

This Voluntary Report is being submitted with respect to maintenance activities associated with the Feedwater Regulating Valves (FRV's) which resulted in a management decision to initiate a controlled shutdown on May 5, 1984.

The Licensee submitted LER 84-025 on May 25, 1984, as a result of a Reactor Trip on April 25, 1984. It was identified in the report that following the Reactor Trip, FRV's A&B did not automatically close upon the Reactor Trip coincident with Low Tavg. Maintenance Work Requests (MWR's) were initiated, repairs were made, and operation of the valves' closure upon receipt of an automatic closure signal were verified.

The Reactor Trip document package was reviewed by the Independent Safety Engineering Group (ISEG) which identified the failure of the FRV as a concern because information in sections 6.2 and 15.4.2 of the Final Safety Analysis Report (FSAR) indicates that these valves could affect the analysis for containment overpressure protection during a postulated rupture of a secondary piping inside containment. ISEG's report was reviewed by the Plant Safety Review Committee (PSRC), and the decision was made to verify valve closure stroke time.

MWR's were initiated, and the stroke closure time for the three (3) FRV's was adjusted for a closing time of 3.5 seconds minimum and 5 seconds maximum as timed from the Main Control Board. Adjustments were made, and the valves were tested to demonstrate their operability prior to the plant restart on May 4, 1984.

While in the process of escalating power during plant startup subsequent to the May 4 restart, problems were experienced with the FRV's controlling properly. In an effort to stabilize the operation of these valves, the Volume Boosters, which are part of the Control Air System for these valves, were adjusted. Because of the design of the Control Air System, adjustment to the Volume Boosters also affected the valve stroke time. Because of the adjustment to the Volume Booster on May 5, 1984, with the Plant in Mode 1, a management decision was made to shut down (mode 2) for the purpose of stroke testing the FRV's.

Upon completion of the stroke time testing on the FRV's, it was identified that the Engineering Safety Feature (ESF) Response Time for the "B" FRV (10.21 sec.) exceeded the 10 second acceptance criteria for Feedwater Isolation as required by Technical Specification Table 3.3-5. The ESF Response Time for the remaining two (2) FRV's were within their acceptance criteria.

There were no adverse consequences as a result of this event because the Feedwater Isolation Valves were operable and therefore capable of performing Feedwater Isolation upon demand. Also, an evaluation of the Safety Analysis for a Main Steam Line Break inside Containment verifies that there would be no significant adverse effects of the FRV's closing within the time frames experienced by the "B" FRV, considering the worst case single failures which includes the associated Feedwater Isolation Valve not closing.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES 5/31/85

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (3)

PAGE (3)

Virgil C. Summer Nuclear Station

0 8 0 0 0 3 9 5 8 4 - 0 2 7 - 0 0 0 3 OF 0 3

TEXT IF more space is required, use additional NRC Form 350A (17)

In order to prevent recurrence, a design modification was implemented to segregate the Volume Boosters from the "Trip Close" portion of the Control Air System on the valves. Upon completion of this modification, the PRV's were tested and verified to be operating within acceptable time limits, and the Plant was returned to power operation.

In addition to the design modification which was implemented as described above, Nuclear Engineering is conducting an evaluation of the Feedwater Isolation function with respect to equipment required versus Accident Analysis. This additional evaluation will be completed by July 31, 1984. In the interim, the PRV's will be programmatically controlled as equipment required for the Feedwater Isolation function.

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 784

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

June 5, 1984

JDH

RHR

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

7/6
TB 840618
0001144 E12
LER
LER # 395-84027
EVENT DATE 840505
INPO RCVD DATE 840613-JAH
NSAC RCVD DATE


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
LER 84-027

Dear Sir:

Please find attached Licensee Event Report #84-027 (Voluntary Report) for the Virgil C. Summer Nuclear Station.

Should there be any questions, please call us at your convenience.

Very truly yours,


O. W. Dixon, Jr.

RJB:OWD/dwf
Attachment

cc: V. C. Summer
T. C. Nichols, Jr./O. W. Dixon, Jr.
E. H. Crews, Jr.
E. C. Roberts
W. A. Williams, Jr.
D. A. Nauman
J. P. O'Reilly
Group Managers
O. S. Bradham
C. A. Price
D. A. Lavigne

J. F. Heilman
C. L. Ligon (NSRC)
K. E. Nodland
R. A. Stough
G. Percival
C. W. Hehl
J. B. Knotts, Jr.
INPO Records Center
ANI Library
NPCF
File

1E22
111
84 RETROFIT