

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
McGuire Nuclear Station - Unit 2DOCKET NUMBER (2)
0 5 0 0 0 3 7 0PAGE (3)
1 OF 0 4

TITLE (4)

Reactor Trip on Loss of Generator Exciter Voltage Regulator

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)						
1	0	2	6	8	5	8	5	0	2	7	0	5	0	0	0		

OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10)	0 9 1 1	20.402(b)		20.405(c)		X	50.73(a)(2)(iv)		73.71(b)		
		20.405(a)(1)(i)		50.36(e)(1)			50.73(a)(2)(v)		73.71(c)		
		20.405(a)(1)(ii)		50.36(e)(2)			50.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)		
		20.405(a)(1)(iii)		50.73(a)(2)(i)			50.73(a)(2)(vii)(A)				
		20.405(a)(1)(iv)		50.73(a)(2)(ii)			50.73(a)(2)(vii)(B)				
		20.405(a)(1)(v)		50.73(a)(2)(iii)			50.73(a)(2)(ix)				

LICENSEE CONTACT FOR THIS LER (12)
NAME
Jerry Day, LicensingTELEPHONE NUMBER
AREA CODE
7 0 4 3 7 3 1 7 0 3 3

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)
☐ YES (If yes, complete EXPECTED SUBMISSION DATE)
☒ NOEXPECTED SUBMISSION DATE (15)
MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On October 26, 1985, at 0240, the Unit 2 reactor tripped from 91% power due to a turbine trip. The turbine trip was initiated when an improperly aligned fuse in the generator voltage regulator sensing circuitry caused the voltage blocking relay to energize and swap control from "automatic" to "manual". Because of the deadband in the regulator automatic compensation circuits and the higher voltages applied from the recently installed permanent magnet generator, a significant step change in output voltage was seen by the protective relaying. The loss of field relay sensed this voltage step as a loss of excitation condition and operated to isolate and shutdown the generator.

The fuse was improperly installed due to a lack of training; therefore this incident is attributed to a management deficiency.

All systems responded properly to the trip with few exceptions. The fuse was reinstalled correctly and training on fuse installation will be developed.

FE22
1/1

TEXT (If more space is required, use additional NRC Form 364's) (17)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/88

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

McGuire Nuclear Station - Unit 2

YEAR

SEQUENTIAL
NUMBERREVISION
NUMBER

0 5 0 0 0 3 7 0 8 5 - 0 2 7 - 0 0 0 3 OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

These and other fuses in the station are removed as required to isolate electrical circuits for personnel safety. The fuses are removed and replaced and appropriately "tagged" for safety. There are no specific procedures for removing fuses since the task is of a simple nature. These particular fuses are approximately 18 inches long. The metal contacts on the ends of the fuses have a shoulder which is an alignment device. This shoulder was in contact with the holder clamp and did not allow maximum contact of the holder and fuse.

The fuses had been removed in August 1985 to facilitate work on the main generator current transformers.

Conclusion

The mispositioned fuse caused the generator to swap to manual operation at a time when the base adjuster potentiometer was not closely matched to the automatic signal.

Under certain conditions the swap from automatic to manual would produce a large change in the exciter field current. This large drop in exciter current caused a drop in generator output voltage great enough to be sensed by the protective relaying. The loss of field relay actuated during this event to isolate and shut down the generator.

The momentary dip in the generator output voltage caused a voltage dip on the station transformers and load centers. The voltage on all three phases of the A train 4160 Bus (2ETA) dropped below the undervoltage trip setpoint which initiated a blackout signal and started the diesel generator 2A. The voltage dip was of short duration and the 2ETA load sequencer did not actuate. Only one phase on the 2ETB bus momentarily dropped low enough to pick up an undervoltage relay. This did not initiate a diesel generator 2B start.

During the subsequent unit startup, the generator tripped two times due to a loose X phase regulating potential transformer drawer. This drawer was not properly secured following the inspection of the potential transformer fuses. The result of the improperly secured drawer was the actuation of the neutral ground detection relay. A reactor trip did not occur at this low power level.

This is the first incident of this nature at McGuire. Due to the unique combination of the misaligned fuse and PMG voltage variance, this is determined to be an isolated event.

CORRECTIVE ACTIONS:

Immediate: Appropriate measures were taken to stabilize the unit following the turbine trip/reactor trip.

Subsequent: The potential transformer fuse was discovered installed incorrectly and was correctly replaced.

The voltage balance blocking relay function has been temporarily disabled to eliminate the automatic swapper from automatic to manual operation.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
McGuire Nuclear Station - Unit 2	0 5 0 0 0 3 7 0 8 5	-	0 2 7	-	0 0	0 4	OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The unit main power oscillograph has been temporarily connected to monitor the regulator voltages. The voltage balance blocking relay was connected to initiate the oscillograph.

Planned: Training for the installation of these fuses will be developed and incorporated into the Employee Training and Qualification Program (ETQS) and also included in the Nuclear Equipment Operator Requalification Program.

The exciter is to be returned to Westinghouse for inspection and replacement of the PMG with a unit designed for this application.

SAFETY ANALYSIS:

The turbine trip/reactor trip in this incident was initiated by the main generator protective relaying circuits. The voltage balance blocking relay function has been temporarily defeated but the sensing circuit will still energize the relay and initiate the unit oscillograph. This defeated relay function reduces the units' ability to prevent a turbine trip due to a blown fuse in the sensing circuits.

TRANSIENT ASSESSMENT:

Primary system parameters responded properly following the trip will Tave converging to the no-load target of 557 degress -F, and pressure dropping to a minimum of 2034 psig before recovering to the post-trip reference value of 2235 psig. No Emergency Core Cooling Systems were actuated. Steam generator (S/G) levels responded properly, dropping to a minimum of 27% (Narrow Range) in S/G "C" before recovering to the target of 38%. The maximum steam pressure was 1102 psig in S/G "B"; no S/G PORV's opened (this is proper). The only anomaly was the feedwater pump recirculation valves responded slowly following the feedwater isolation. This led to a trip of the three condensate booster pumps then the main feedwater pumps. Auxiliary feedwater initiated on the feedwater pump trips to supply the steam generators, as designed.

The health and safety of the public were not affected by this incident.

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

November 25, 1985


Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-370
LER 370/85-27

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report 370/85-27 concerning a reactor trip due to the loss of generator exciter voltage regulator. This event was considered to be of no significance with respect to the health and safety of the public.

Very truly yours,



Hal B. Tucker

JBD/jgm

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30323

INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

M&M Nuclear Consultants
1221 Avenue of the Americas
New York, NY 10020

Mr. W.T. Orders
NRC Resident Inspector
McGuire Nuclear Station

American Nuclear Insurers
c/o Dottie Sherman, ANI Library
The Exchange, Suite 245
270 Farmington Avenue
Farmington, CT 06032

IE22
11