

LICENSEE EVENT REPORT (LER)

Facility Name (1) Byron, Unit 1 Docket Number (2) 0 | 5 | 0 | 0 | 0 | 4 | 5 | 4 Page (3) 1 | of | 0 | 2

Title (4) REACTOR TRIP ON LOW STEAM GENERATOR LEVEL DUE TO INADVERTENT FEED PUMP TRIP

Event Date (5)			LER Number (6)			Report Date (7)			Other Facilities Involved (8)				
Month	Day	Year	Year	Sequential Number	Revision Number	Month	Day	Year	Facility Names	Docket Number(s)			
0	6	2	4	8	5	8	5	---	0 6 1	---	0 1 1 1 2 6 8 5	None	0 5 0 0 0 1 1

OPERATING MODE (9) 1 THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10CFR (Check one or more of the following) (11)

POWER LEVEL (10) 0 9 7	20.402(b)	20.405(c)	X	50.73(a)(2)(iv)	73.71(b)
	20.405(a)(1)(i)	50.36(c)(1)		50.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	50.36(c)(2)		50.73(a)(2)(vii)	Other (Specify in Abstract below and in Text)
	20.405(a)(1)(iii)	50.73(a)(2)(i)		50.73(a)(2)(viii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)		50.73(a)(2)(viii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)		50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

Name Richard M. Williams, System Test Engineer, Ext. 2385 TELEPHONE NUMBER AREA CODE 8 | 1 | 5 2 | 3 | 4 | - | 5 | 4 | 4 | 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A									

SUPPLEMENTAL REPORT EXPECTED (14)

Expected Submission Date (15) Month | Day | Year

Yes (If yes, complete EXPECTED SUBMISSION DATE) X | NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

While operating in Mode 1 at a reactor power of 97%, a reactor trip occurred due to 1A Steam Generator LO-2 level. The low Steam Generator level was caused by the trip of the 1C Feedwater Pump, after an Equipment Attendant inadvertently activated the local overspeed trip bar. Following the 1C Feedwater Pump trip, the main turbine/generator load was run back and the 1A Motor Driven Feedwater Pump was started. However, the recovery attempt was not successful. This was an isolated incident. The trip lever handles were removed to prevent recurrence. An inspection was initiated to identify other equipment with similar problems. No equipment was specifically identified.

8512060036 851126
PDR ADOCK 05000454 PDR
S

IE20
//

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)					Page (3)		
		Year	///	Sequential Number	///	Revision Number			
Byron, Unit 1	0 5 0 0 0 4 5 4	8 5	-	0 6 1	-	0 1	0 2	OF	0 2

TEXT

On June 24th at 0127 CST, Unit 1 was operating in Mode 1 at 97% power. The 1B and 1C Turbine Driven Feedwater Pumps [SJ] were supplying Steam Generator feedwater demand. The 1A Motor Driven Feedwater Pump was shut down, but available.

The Unit 1 Turbine Building Equipment Attendant was instructing two new trainees at the 1C Turbine Driven Feedwater Pump. The trainees were logging the necessary readings while the Equipment Attendant explained to them what they were recording. As the Equipment Attendant illustrated the last reading, he turned, snagging his 2-way radio microphone cord on the local turbine overspeed trip bar causing the 1C Turbine Driven Feedwater Pump to trip.

Noting the trip of the 1C Feedwater Pump, the Control Room operator immediately started the 1A Motor Driven Feedwater Pump and decreased the Main Turbine/Generator load. Even though turbine and reactor power levels were reduced, a reactor trip occurred due to 1A Steam Generator LO-2 level. Both Auxiliary Feedwater Pumps [BA] automatically started to insure minimum Steam Generator levels were maintained. No Safety Injection occurred and the plant was stable in Hot Standby 40 minutes into the event.

This event has never happened before at Byron Station. The event posed no threat to public safety. The licensed personnel on shift and the Reactor Protection Systems reacted appropriately to bring this event to a safe conclusion. Immediate action taken was to remove the trip lever handles. An inspection was initiated to identify other equipment with similar problems. A review of all equipment for possible modification to prevent inadvertent operation was completed by the Technical Staff. No equipment was specifically identified for modification.



Commonwealth Edison
Byron Nuclear Station
4450 North German Church Road
Byron, Illinois 61010

November 26, 1985

LTR: BYRON 85-1514


U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 10555

Dear Sir:

The enclosed Licensee Event Report from Byron Generating Station is being transmitted to you as a Supplemental Report to LER 85-061-00.

This report number is 85-061-01, Docket No. 50-454.

Very truly yours,



R. E. Querio
Station Manager
Byron Nuclear Power Station

REQ/CB/gt

Enclosure: Licensee Event Report No. 85-061-01

cc: J.G. Keppler, NRC Region III Administrator
J. Hinds, NRC Resident Inspector
INPO Record Center
CECo Distribution List

#3/039

LE22
11