

ORIGINAL

ACRS-T-1488^{HA}

UNITED STATES NUCLEAR REGULATORY COMMISSION

IN THE MATTER OF:

DOCKET NO:

ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

SUBCOMMITTEE ON REACTOR OPERATIONS

LOCATION: WASHINGTON, D. C.

PAGES: 1 - 162

DATE: WEDNESDAY, FEBRUARY 12, 1986

ACRS OFFICE COPY
Do Not Remove from ACRS Office

8602200104 860212
PDR ACRS
T-1488 PDR

ACE-FEDERAL REPORTERS, INC.

Official Reporters
444 North Capitol Street
Washington, D.C. 20001
(202) 347-3700

NATIONWIDE COVERAGE

TR04
a/1

1 UNITED STATES OF AMERICA
2 NUCLEAR REGULATORY COMMISSION
3 ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
4 SUBCOMMITTEE ON REACTOR OPERATIONS

5 Nuclear Regulatory Commission
6 Room 1046
7 1717 H Street, N.W.
8 Washington, D. C.

9 Wednesday, February 12, 1986

10 The meeting of the ACRS subcommittee convened at
11 1:30 p.m., Mr. Jesse C. Ebersole, chairman, presiding.

12 ACRS MEMBERS PRESENT:

13 MR. JESSE C. EBERSOLE
14 DR. WILLIAM KERR
15 MR. CARLYLE MICHELSON
16 DR. DADE W. MOELLER
17 MR. GLENN A. REED
18 MR. DAVID A. WARD

19 DR. IVAN CATTON, Consultant

20 MR. HERMAN ALDERMAN, ACRS Staff Member
21
22
23
24
25

PUBLIC NOTICE BY THE
UNITED STATES NUCLEAR REGULATORY COMMISSIONERS'
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

WEDNESDAY, FEBRUARY 12, 1986

The contents of this stenographic transcript of the proceedings of the United States Nuclear Regulatory Commission's Advisory Committee on Reactor Safeguards (ACRS), as reported herein, is an uncorrected record of the discussions recorded at the meeting held on the above date.

No member of the ACRS Staff and no participant at this meeting accepts any responsibility for errors or inaccuracies of statement or data contained in this transcript.

P R O C E E D I N G S

MR. EBERSOLE: The meeting will come to order.

This is a meeting of the ACRS Subcommittee on Reactor Operations. I am Jesse Ebersole, Chairman of the Subcommittee on Reactor Operations. The other members are Bill Kerr, Carlyle Michelson, Dave Moeller, Mr. Glen Reed, and we have Mr. Ivan Catton as a consultant.

The Subcommittee will discuss recent operating events. We will be briefed on the 50-54(f) Improvement Program on Fermi and Technical Specification Improvement Program.

The rules for participation have been announced as part of the notice of the meeting published in the Federal Register on January 21, 1986. It is requested that each speaker first identify himself or herself and speak with sufficient clarity and volume so that he or she can be readily heard.

We have received no written comments or requests for time to make oral statements from members of the public.

I will now ask if any Subcommittee members or consultants have any comments or solicitations to make before we get into the meat of this meeting.

MR. MOELLER: I have one comment. Just to ask, Carlyle Michelson had brought to my attention this draft report or report that the AEOD is preparing on the loss of

1 the ventilation system in the control room at the McGuire
2 plant, I believe it was. We could take it up as a joint
3 effort.

4 MR. EBERSOLE: Perhaps next time.

5 MR. MOELLER: It will depend on when they finish
6 their report.

7 MR. MICHELSON: I wasn't going to get into it
8 until the end of the meeting, but there is this question of,
9 IE does a fine job of bringing to us these current events
10 as they come up but we don't hear briefings on AEOD reports
11 which deal with combinations often of current events and
12 final analysis in the longer-range sense. Which
13 subcommittee is going to listen to the results of those
14 kind of studies as opposed to current events?

15 They are also operating history, just from a
16 different viewpoint. We don't normally bring those up here
17 because this is the operating events.

18 MR. EBERSOLE: I suggested that we take this up
19 as a part of our presentation to the full committee.

20 MR. MICHELSON: That was the question, should
21 this subcommittee do it?

22 MR. EBERSOLE: Let's introduce that as a copy
23 tomorrow.

24 Well, we have just gotten through a full morning
25 which I think ellipses most operation events of recent

1 times. But I see an interesting number here. Let me ask
2 Mr. Dennis Allison to get us going right away.

3 MR. ALLISON: I am Dennis Allison. I am the
4 acting branch chief for the events analysis branch in IE.
5 Next to me is Ron Hernan, principal spokesman for NRR.
6 Before we start the first event, I would like to say, I
7 understand that the team that has been looking at the
8 earthquake at Perry will arrive a little later, about 3:30.
9 So there toward the end of the presentation, we won't be
10 able to move them up until they get here. I think that is
11 all we had to start off with. The first presentation is on
12 McGuire, startup with the degraded HPSI system. It is not
13 an air system but a HPSI system.

14 MR. GIITTER: My name is Joe Giitter. I am in
15 the events analysis branch of the Office of Inspection and
16 Enforcement. At the last Subcommittee meeting, you heard
17 about a single failure of a nonsafety-related system, that
18 resulted in a loss of instrument air and a challenge to the
19 safety systems at both McGuire units. This afternoon, I am
20 going to discuss a set of undesirable conditions that
21 existed the following day when unit 1 attempted to start up.

22 The problem was failure to repair volume control
23 tank isolation valve motor operators prior to startup which
24 would have prevented VCT isolation on a safety injection
25 signal. The safety significance of this is that HPSI may

1 not have functioned as required on a real demand.

2 As you recall, at 0640 on November 2, a rupture
3 in a flexible pipe at the discharge of an instrument air
4 compressor resulted in a loss of instrument air to both
5 units 1 and 2, a trip of both units 1 and 2 and a safety
6 injection in unit 1. Ordinarily on a safety injection, you
7 would have isolation -- first you would have opening of
8 these two valves here and then isolation of the volume
9 control tank as suction is swapped from the VCT to the
10 refueling storage tank. These valves will go closed as
11 required.

12 However, it was later discovered that the valve
13 motor operators had burned out. The licensee has two
14 theories that they are looking at as to why these motor
15 operators may have burned out. One is that there was a
16 hammering problem.

17 In a hammering problem, as a valve closes, the
18 torque builds up which causes a torque switch to open.
19 When the torque switch opens, power is removed from the
20 valve motor which relaxes torque. When the torque is
21 relaxed, that torque switch is allowed to reset. If a
22 close demand signal is still present, once that torque
23 switch resets, the valve will start to close again even
24 though it is closed. It will try to close against a seat.
25 Torque will build up, the torque switch will open, and the

1 motor operator will stop -- will stop trying to close the
2 valve, torque will relax, the same thing will happen over
3 and over again and the valve will be hammered closed. This
4 can eventually result in overheating of the valve motor.

5 Another theory is that on the McGuire system,
6 there is a miniflow line from the centrifugal charging
7 pumps that is not isolated on a safety injection signal.
8 So what happened during this event is that the VCT actually
9 went solid and the safety relief lifted on the VCT,
10 pressure setpoint about 75 pounds. This increases the
11 static head that these -- that this valve here sees. It
12 was believed that there may have been some leakage past
13 this valve here and when the operators, seeing that the VCT
14 was full, tried to open remote this valve, remote manually,
15 that they encountered high differential pressures and that
16 caused the motor operator to burn out here and subsequently
17 high differential pressure caused this motor operator to
18 burn out because this motor operator here wouldn't see the
19 DP that this one would.

20 It doesn't seem to be fully explained yet. The
21 licensee is still investigating. But those are two of the
22 theories right now.

23 MR. EBERSOLE: This event is still open as to
24 why these valves failed?

25 MR. GIITTER: That is correct. The licensee is

1 still --

2 MR. EBERSOLE: It would have been unlikely that
3 the torque switch would have been, the lockout or the
4 return -- when the torque switch closes or opens to stop
5 the motor, doesn't that result in an interlock which it
6 cannot subsequently attempt to close again until it opens
7 again?

8 MR. GIITTER: There are various types of
9 antihammering devices on different types of valves. My
10 understanding is that this particular type of valve had an
11 old mechanical latch system that prevented that torque
12 switch from resetting if the limit switch had sensed that
13 valve being closed. Why that wouldn't have worked, I don't
14 know.

15 MR. EBERSOLE: Was it both --

16 MR. GIITTER: Both of these.

17 MR. EBERSOLE: So we have an even validation of
18 the single failure theory.

19 MR. GIITTER: It seems that a single failure did
20 cause the failure of both of these motor operators.

21 MR. EBERSOLE: Well, it is nice to add another
22 one to the list. Like Salem. Carry on.

23 MR. GIITTER: Prior to startup, the operators
24 manually opened the valves, but did not repair the motor
25 operators. So this put them in a situation that if they

1 were to have a safety injection signal, these valves would
2 not have automatically closed. And you would then be in a
3 situation where you were taking suction from the VCT and
4 RWST. Unit startup was commenced at about 6:00 on the 3rd
5 and the unit was in mode 2 for about six hours. The
6 startup was pending repair of the severed instrument line
7 on the secondary side of the steam generator. Because they
8 couldn't get that repaired, they decided to go into cold
9 shutdown.

10 MR. EBERSOLE: So what would have happened if
11 you had taken common suction on the VCT as well as the RWST.
12 Would you get nitrogen?

13 MR. GIITTER: I will get to that.

14 There are two concerns. One concern, I think
15 this is a lesser one, that is because of the difference in
16 volume -- this is the volume of the VCT is on the order of
17 several thousand gallons whereas the volume of the RWST is
18 on the order of several hundred thousand gallons. But
19 there is a concern, if you were to draw some suction from
20 the VCT, that the boron injected into the vessel would be
21 lower than that assumed in the safety analysis. That is a
22 concern more from reactivity perspective than anything else.

23 I think the more major concern is could the VCT,
24 the hydrogen and the nitrogen, if this VCT level was low
25 enough, could this hydrogen and nitrogen get entrained into

1 the charging pump suction path and ultimately result in gas
2 binding of the charging pumps. I think that was a question
3 you had.

4 MR. EBERSOLE: That is what happened at Palo
5 Verde.

6 MR. GIITTER: Yes. We asked the licensee about
7 this. And first -- well, I will get to that.

8 The NRC op center was notified at 1218 on
9 January 14, 1986. This event happened on November 3rd.
10 The only way we found out about this event is that the
11 resident inspector, investigating the previous loss of
12 instrument air event, went back through the shift
13 supervisor's log and saw that they had started up with
14 these valve motor operators being inoperable. That is the
15 only way we found out about it.

16 The day after the resident found that out, the
17 licensee called this in to the op center and notified us.
18 Apparently what happened is the licensee looked at their
19 tech specs and because they did not consider these valves
20 to be in an ECCS flow path, didn't think there was any
21 problem from a tech spec of starting up. And I believe
22 they were planning to repair these valves once in the
23 process of starting up or once they had actually gone to
24 power.

25 MR. EBERSOLE: Why didn't they consider them in

1 the ECCS set? One basis would be if they are closed, they
2 are not in the ECCS set. If they are open, they are.

3 MR. GIITTER: Right.

4 MR. EBERSOLE: Do they discriminate like that?
5 That is the mode or the position of the valve in order to
6 determine whether this is within or without the ECCS set?

7 MR. GIITTER: I can't tell you what the
8 licensee's logic was. I don't think that we agree with it.

9 MR. EBERSOLE: Certainly if they are open, then
10 the ECCS function is degraded?

11 MR. GIITTER: That is right.

12 MR. EBERSOLE: So they are in fact in the ECCS
13 set if they are shut, are they not?

14 MR. GIITTER: I would have to agree with that.

15 MR. EBERSOLE: I am asking in the general
16 context, do the licensees do that discriminatory
17 classification to determine whether a valve in a given
18 position is or is not in the ECCS set?

19 MR. GIITTER: They have some means of making
20 that determination, but I don't know what the logic is.

21 MR. EBERSOLE: It sounds a little vague to me.

22 MR. GIITTER: That was the official response we
23 got.

24 MR. EBERSOLE: We got these things on every
25 plant. Are they all in the ECCS set?

1 MR. GIITTER: I am sorry.

2 MR. ALLISON: I don't think we know the answer
3 to that today. We will have to --

4 MR. EBERSOLE: I am talking about the generic
5 aspect. Carry on.

6 MR. GIITTER: Okay. They did repair the valve
7 motor operator when they went into cold shutdown. They
8 reviewed the design and determined that this -- at first,
9 when it was believed that the hammering problem may have
10 been a contributor, they looked at other valves and
11 determined that hammering wasn't a problem in any other
12 valve motor operators in the plant.

13 They performed a test -- let me pull this up a
14 little bit -- when they were in operation, they performed a
15 test. They started the charging pumps and they left these
16 valves open and they sent an operator down there to see how
17 long it would take him to go down and close these valves
18 manually. The first time they conducted tests, it required
19 19.4 minutes for the operator from the time he left the
20 control room or did whatever he had to do to actually
21 closing the valves, it took 19.4 minutes. The licensee
22 concluded at that point in time that the VCT level was down
23 at around 20 percent. And according to their analysis,
24 original analysis, at about the 20 percent level, initially
25 you have a higher pressure here and the suction is

1 originally going to be taken from the VCT because you have
2 30 pounds cover gas pressure. But once the VCT level drops
3 to 20 percent, the pressure decays because the gas volume
4 is increasing. And at that point, the primary source of
5 suction is the RWST. So they concluded that at 19.4
6 minutes that it would take the operator to get down there,
7 that the VCT level would be at about 20 percent.

8 Under those conditions, they were assuming the
9 VCT initial level was at 100 percent, which it was for this
10 particular event because of the failure to -- the design in
11 not isolating the miniflow lines.

12 They subsequently did two other tests. Both of
13 those tests, they sent two different operators down. In
14 one case it took them 15 minutes. The other case took them
15 18 minutes. They concluded that there would be no gas
16 binding of the charging pumps sooner than that 18.5 minutes.

17 Now, there is one question that comes to mind is,
18 in a real safety injection instance, is it likely, is it
19 realistic that an operator could get down there in that
20 amount of time, if they really did have a small break LOCA,
21 for example. Is it realistic that they could get down
22 there in that amount of time and that they would close
23 those isolation valves.

24 There is an enforcement conference scheduled for
25 February 28. I believe that these issues will be brought

1 up at that point in time.

2 MR. EBERSOLE: The fact that it is two valves
3 there suggests that they needed redundancy and in fact it
4 is almost evident that they had to be considered as safety
5 grade elements of the design, just because there are two of
6 them. Were they in the tech specs, to be periodically
7 examined and tested. The safety grade list?

8 MR. GIITTER: I believe they are.

9 MR. EBERSOLE: You told me that the operator
10 didn't even know what classification these valves were in.

11 MR. GIITTER: They looked at tech specs and they
12 didn't see any problems. This is my understanding, from
13 what the licensee told me, they didn't see any tech specs
14 that addressed having these valves --

15 MR. EBERSOLE: -- function as designed. And
16 they were not able to discern from the tech specs or the
17 physical needs that they were critical to the safety
18 function.

19 MR. GIITTER: They made the determination that
20 they could have these valves inoperable, prior to startup.

21 MR. EBERSOLE: They did.

22 MR. GIITTER: They started up with those valves
23 inoperable. It may have been an oversight on their part.

24 MR. EBERSOLE: What are you going to do about
25 that, as far as I am concerned, a gross misinterpretation

1 of the reliability of the HPC?

2 MR. KERR: This was inoperable but closed? They
3 assumed that they were inoperable but closed?

4 MR. MICHELSON: Open.

5 MR. GIITTER: In order to start up, you need to
6 open these valves up.

7 MR. MICHELSON: You need to normally operate off
8 the volume control tank.

9 MR. GIITTER: You need to open these valves up.
10 They manually opened the valves so that if the valves
11 received a safety injection signal, because the motor
12 operators were inoperable, they would have been incapable
13 of isolating the VCT on a safety injection and you would
14 get suction from the VCT and the RWST.

15 MR. REED: Whether or not there is a loophole in
16 the tech specs in saying these have to be operable, I
17 think there is a question of good judgment here that comes
18 into play. I really think the licensee is ignoring the
19 safety-related aspects of this system and those valves in
20 particular. I would certainly, if I was the staff, pursue
21 how this decision got made.

22 MR. GIITTER: We are currently pursuing that
23 right now. As I mentioned, there is an enforcement meeting
24 on the 28th of this month to discuss this.

25 MR. EBERSOLE: I hope you will take that pursuit

1 into regions more distant from just this one. If they are
2 that lax in interpreting the critical needs of the safety
3 system, you may find it all over the place. This might not
4 be an isolated case. This sounds like a gross
5 misinterpretation of a critical functional need.

6 MR. ALLISON: I don't believe this is a typical
7 kind of thing.

8 MR. REED: I have a little concern here, as I
9 have watched resident inspectors function, I am surprised
10 the resident inspector didn't catch this the very next
11 morning and have his citation book going.

12 MR. EBERSOLE: That what I was about to say.

13 MR. REED: Normally they review the logs the
14 very first thing in the morning, looking at all the
15 incidents through the preceding day and over the nightfall.
16 This thing just stands out.

17 MR. GIITTER: The resident was the one that did
18 notice it.

19 MR. REED: But it took him how many days?

20 MR. GIITTER: I guess he was investigating the
21 loss of instrument air. I really don't know what the
22 situation was there. But it is possible that he could have
23 been tied up with the loss of instrument air at both units.

24 MR. EBERSOLE: They knew that they were
25 inoperable?

1 MR. GIITTER: That is my understanding.

2 MR. MOELLER: Is it part of the resident
3 inspector's duty to go each morning and look at the log? I
4 mean, is there a system of fines for a resident inspector?

5 MR. ALLISON: Looking at the logs every morning
6 is part of their job.

7 MR. MOELLER: Does anyone ask, you know, how he
8 missed it or she missed it?

9 MR. ALLISON: We will ask that and find out.

10 MR. EBERSOLE: Are the operators commonly asked
11 about the nature of need of these valves in an operational
12 examination?

13 MR. GIITTER: I can't answer that question. I
14 can find out for you.

15 MR. EBERSOLE: Why don't we do that as a generic
16 problem. We would like to know whether the operators know
17 whether or not the system -- I don't mean running down to
18 the basement to fix it. Whether in the automatic mode
19 these are critical to the HPSI pumps.

20 Is that all of that?

21 MR. GIITTER: That is it.

22 MR. KERR: Is there a 100 percent certainty that
23 with these valves open this system would not work?

24 MR. EBERSOLE: I gather there is.

25 MR. KERR: I haven't heard anybody say that.

1 MR. EBERSOLE: You remember the case of --

2 MR. KERR: I am not talking about a case of
3 anything. I am asking a question as to whether there is
4 100 percent certainty.

5 MR. EBERSOLE: You are on the wrong side of the
6 coin. The certainty needs to be that you know that they
7 will, not that you know that they don't.

8 MR. KERR: I want to know, is there a 100
9 percent certainty that they won't work?

10 MR. EBERSOLE: I want to know that they will
11 work. I am not willing to deal with that whether they
12 would not.

13 MR. KERR: I was asking the staff.

14 MR. MICHELSON: It is a good question because
15 you have to know the relevant pressure from the water
16 storage tank versus the --

17 MR. KERR: It isn't clear to me at this point.

18 MR. MICHELSON: On the basis of what is there,
19 you can't tell whether the tank --

20 MR. ALLISON: The licensee claims that they
21 would.

22 MR. MICHELSON: Yes. They have done the test.

23 MR. EBERSOLE: Has he tested it?

24 MR. ALLISON: Not to our knowledge.

25 MR. MICHELSON: You got to test it being already

1 connected to the refueling storage tank as well. I doubt
2 he did it --

3 MR. EBERSOLE: You are saying that it is maybe
4 sufficient?

5 MR. KERR: I don't know. The reason I asked the
6 question is because I want to --

7 MR. EBERSOLE: Has the operator --

8 MR. GIITTER: The only explanation they gave me
9 was the one I provided to you where they determined how
10 long it would take for an operator to get down and manually
11 close those valves.

12 MR. EBERSOLE: The inference you can draw from
13 that is they better get with it because it is going to quit
14 working.

15 MR. REED: I don't think the test of how long it
16 takes the operator to do it has any relevance to the issue.
17 The operator could fall in the stairway and kill himself
18 while en route. Here is a design. If they want to do a
19 test, they look at the relative heads of the two tanks in
20 their position and location and over pressure of the gases.
21 But after all, that is pretty much a standard Westinghouse
22 design for many, many years. I thought everyone had been
23 trained and knew the importance of these valves and their
24 functioning and why they are there.

25 MR. EBERSOLE: I think it goes without saying,

1 we will put this on the list to be discussed at the full
2 committee meeting because of its generic inferences.

3 Is that all there was to that?

4 MR. GIITTER: That is all I had.

5 MR. EBERSOLE: Any further comments?

6 Let's move to the second one.

7 MS. WEGNER: On January 7, 1986, Carolina Power
8 & Light Brunswick phoned in the following 5072 report.
9 Test results from Wyle Laboratory on 11 SRV, six SRV failed
10 to lift at pressures as high as 200 psi above setpoints.
11 Two SRV were satisfactory and three SRVs lifted outside the
12 tolerance band.

13 These test results were significantly different
14 from other licensees' results reported to NRC recently.
15 The NRC's concern was heightened because of the number of
16 valves affected and the extent to which the disc appeared
17 to be stuck.

18 As a bit of background, the two-stage Target
19 Rock safety relief valves were the solution to the problems
20 that had been experienced with the three-stage valves.
21 Two-stage valves exhibited some setpoint drift during
22 testing and became a major concern in July of 1982 when 11
23 of the Hatch 1 SRVs, of which there are 11, failed to open
24 at pressures well above their setpoints following a scram
25 in isolation. Subsequently, three of the valves opened at

1 1180 psig and the other valves were manually opened later
2 in the transient.

3 The owners group that was formed after this
4 event, the General Electric Company and the Target Rock
5 Company, investigated the causes of the setpoint drift and
6 developed recommendations for solutions to the problem.
7 This is a closeup of the two-stage topworks.

8 (Slide.)

9 MS. WEGNER: This shows the labyrinth scale of
10 the disc seating area.

11 The principal causes were determined to be
12 galling in the labyrinth seal area, and corrosion-induced
13 seat-to-disc bonding in this area.

14 MR. MICHELSON: Which area did you point to?

15 MS. WEGNER: Steam side of the disc. The seat
16 area here.

17 MR. EBERSOLE: You said corrosion induced
18 bonding?

19 MS. WEGNER: Yes.

20 The recommended solutions were an enhanced
21 maintenance program and a replacement disc of a material
22 whose oxide film would be less likely to bond to the oxide
23 film of the disc. The seat, sorry. Both the seat and the
24 disc were of a stellite 6 or 6B.

25 MR. EBERSOLE: How long a period had it been

1 before they were unseated? How long does it take for this
2 corrosion and bonding method to stick the valves?

3 MS. WEGNER: As little as three weeks or it has
4 been observed.

5 MR. EBERSOLE: Normally these things don't get
6 exercised except once every two months.

7 MS. WEGNER: The Hatch valves had gone the
8 entire cycle without being exercised.

9 MR. EBERSOLE: What sort of bonding does that
10 bring about?

11 MS. WEGNER: All 11 valves failed to operate
12 until three valves lifted at 1180 psig. Since then we have
13 seen some valves, mostly on the test stand, actuate very
14 much higher than that. Or not actuate at all.

15 MR. REED: Those valves are valves that are
16 brought in from the field. They haven't been exercised but
17 or are they reassembled valves in the test facility? And
18 don't actuate?

19 MS. WEGNER: Okay. The topworks are taken off
20 of the -- off of the main and sent to Wyle Labs. I don't
21 know whether any other facility can do the test or not.
22 That is the only one I am familiar with. The topworks are
23 not disassembled until they get to Wyle. The first test --
24 I am getting ahead of myself here, but the first test that
25 they were doing to determine the setpoint was when the

1 valves came in, they had a body there at Wyle. They took
2 the topworks, mounted it to that body, heated it up until
3 it was in thermal equilibrium and simulated reactor
4 conditions. They did a -- a long time ago they used to do
5 a full-flow steam test on it.

6 MR. REED: They did an as-found-from-the-field
7 test.

8 MS. WEGNER: I am not talking about the
9 Brunswick test. This is the previous test. There has been
10 some changes which create some problems. I am getting
11 ahead of myself there.

12 MR. REED: What I want to know is, how did they
13 do the Brunswick test where the relieve-it point was much
14 elevated?

15 MS. WEGNER: The Brunswick test and the current
16 test are done, were done first by backing the stem off of
17 the disc so the disc would be free-floating, pressurizing
18 under the seat here with nitrogen to determine how much the
19 disc may or may not be stuck. A free-floating disc
20 shouldn't take any more than 5 pounds of nitrogen to lift
21 it.

22 The facility limit at Wyle was around 200 psi.
23 Six of the Brunswick valves did not lift within the
24 facility limit. They shut down the test.

25 MR. REED: That is the point I want to key in on.

1 These are what I call internal pilot-operated relief valves.
2 I don't have much use for those kind of valves unless the
3 environment in which they work has been studied. This
4 environment in which these valves work is probably an
5 environment of hydrogen and oxygen and steam in a
6 condensing recirculating mode. And stripping of the oxygen
7 and hydrogen is taking place up in those cap areas, I would
8 expect. Therefore, when you talk about corrosion bonding,
9 I think you have a very nice set-up for it. You have high
10 oxygen and hydrogen and you are probably going to get all
11 kinds of corrosion and friction factor changes like crazy.
12 I am not so sure that this is a good application of a valve.

13 MR. EBERSOLE: It is not apparent what the main
14 motivating force is for opening the main bonnet.

15 MS. WEGNER: This disc, the pressure under this
16 disc, when it exceeds the set pressure, is determined by
17 the spring and bleed off the pressure here. And that
18 allows this to compress its spring and open.

19 MR. EBERSOLE: So there is an opening factor to
20 the main steam pressure on the big piston. The steam
21 pressure applied to the large piston against the spring.
22 You simply don't show that in the illustration there.

23 MS. WEGNER: It is applied to the pilot.

24 MR. ALLISON: The question is, what lifts the
25 main disc?

1 MR. EBERSOLE: Yes.

2 MS. WEGNER: Frank, can you help me on this? As
3 I understand it, when lifting the pilot takes the pressure
4 off here and allows the main --

5 MR. EBERSOLE: It is just through shaft leakage?

6 MR. CHURNEY: Frank Churney from NRR. It is not
7 shown on this particular slide. There is a tinge on there
8 called the plain piston. It is about the center of the
9 picture. When you open the pilot, you create a delta P.

10 MR. EBERSOLE: Where is the supply side of the
11 delta P?

12 MR. CHURNEY: Maybe the picture doesn't show it
13 real well. There is a supply side to this.

14 MR. EBERSOLE: Okay.

15 MR. CHURNEY: You bleed it off and get enough of
16 a delta P so it pops off.

17 MS. WEGNER: This maintenance program that I was
18 talking about has been in effect for at least one fuel
19 cycle at most of the plants. Since the issuance of
20 information notice 82-83 in December of 1983, the testing
21 results that we have seen for a typical plant show a small
22 number of valves within the tech spec limits which are set
23 pressure plus or minus 1 percent. The majority are within
24 a set pressure plus or minus 5 percent. And most plants
25 would have a single valve stuck. Some maybe more than one.

1 MR. REED: So enhanced maintenance is not the
2 answer to the question.

3 MS. WEGNER: It is not the entire answer.

4 MR. REED: I will go right back to say the
5 problem is the environment in which the valves are being
6 asked to function and the nature of the valve.

7 MS. WEGNER: It is beginning to look like that
8 very much. As the data base grew, it was apparent that the
9 setpoint drift hadn't gone away. The director of division
10 of licensing, NRC NRR, sent a letter to the owners group in
11 March of '85 recognizing the benefits of the enhanced
12 maintenance program but concluding that maintenance alone
13 was inadequate to solve the problem.

14 The next step taken by the owners group was the
15 selection of a replacement material for the pilot disc
16 which would have less tendency to develop this oxide bond
17 with the seat. The material which they eventually selected
18 was a precipitation-hardenable stainless steel disc. The
19 replacement disc had recently become available and had been
20 installed in 50 percent of the Hatch 1 and the Brunswick
21 valves which were tested at Wyle towards the end of 1985.
22 And the beginning of 1986.

23 MR. MICHELSON: Wasn't this the same problem
24 that they had with the three-stage valve and the sticking
25 problem?

1 MS. WEGNER: No, sir. The three-stage valves
2 popped open and stayed open.

3 MR. MICHELSON: They had a problem also of
4 gluing shut.

5 MS. WEGNER: I really don't recall that. I know
6 that has been a problem with the electromatics but not
7 these.

8 MR. MICHELSON: To fix them from going from
9 three-stage to two-stage was just to get away from the
10 sticking open situation?

11 MS. WEGNER: That is right.

12 MR. MICHELSON: Now they got one that sticks
13 closed.

14 MR. REED: I think designers traditionally try
15 to look for different materials but if you haven't changed
16 the environment, is anyone looking at plugging the
17 capillary connection to the pilot and putting a loop seal
18 in that, have an external line come out on the pilot and
19 put a loop seal in there to prevent the oxygen/hydrogen
20 concentration phenomena?

21 MS. WEGNER: No. I have heard mention of
22 putting a pressure switch in there so that the valves would
23 open at a certain pressure, no matter what. But that, too,
24 is talk.

25 MR. MICHELSON: The problem is that I think when

1 you open this valve, you will blow your loop seal out
2 because it vents at the bottom of the pilot there.

3 MR. REED: It certainly will refill. As long as
4 the valve functions properly and seal the hydrogen and
5 oxygen concentration, maybe it will work. I am just making
6 a suggestion. Here is another one of these things that we
7 have talked about. We talked about them among PWR and the
8 problem of internal operating valves.

9 MR. MICHELSON: Well, if we knew what to swing
10 on, we would.

11 MR. EBERSOLE: These valves are typical of
12 boilers.

13 MS. WEGNER: Yes. Quite an enlarged number of
14 the boilers have the Target Rock's. The PWR relief valves,
15 the majority of them are just spring lift valves that I
16 have --

17 MR. EBERSOLE: They are not -- well, but you
18 have electric --

19 MS. WEGNER: I am talking about the main steam
20 safety.

21 MR. EBERSOLE: I am talking about second --

22 MR. REED: She is saying the majority are spring
23 action.

24 MR. CHURNEY: There is one PWR that has
25 pilot-operated safety valves on the primary side. That is

1 Beaver Valley 1.

2 MR. REED: Did you say secondary?

3 MR. CHURNEY: On the primary side. They aren't
4 exactly like this design. My understanding is they are
5 also a two-stage valve. They are more like the valves that
6 are used in the Navy.

7 MR. EBERSOLE: They have to face the problem of
8 corrosion?

9 MR. REED: Well, you got your answer.

10 MR. CHURNEY: They haven't had any real problem
11 with theirs.

12 MR. CHURNEY: A big U-shaped arrangement of the
13 pipe itself.

14 MR. REED: You can just do it on the pilot.

15 MR. CHURNEY: It could be a little tricky on
16 these because they are very small valves. They are right
17 on very short rises on the steam lines.

18 MR. MICHELSON: I think they clear the loop seal
19 also when they actuate.

20 MR. EBERSOLE: The valves on the PWR that you
21 state are there, those are not the safety valves, are they?

22 MR. CHURNEY: On Beaver Valley 1, there are
23 three safety valves on the pressurizer. Not exactly this
24 design, but they are pilot-operated.

25 MR. EBERSOLE: And they are in a borated

1 environment with loop seals?

2 MR. CHURNEY: Yes.

3 MR. REED: I believe that is a Westinghouse
4 design?

5 MR. CHURNEY: It is the only one in the country
6 with those valves.

7 MR. REED: Did you ever ask them why they went
8 to loop seals on pilot-operated relief valves, which is
9 also on another new plant that we just reviewed here about
10 six months ago.

11 MR. CHURNEY: Well, they have gone -- that is
12 true, Westinghouse has gone to pilot-operated PORV on some
13 of the new plant with --

14 MR. REED: With loop seals.

15 MR. CHURNEY: I haven't checked on that.

16 MR. REED: We had another licensee come through
17 here four months ago.

18 MR. CHURNEY: I would imagine it is for the
19 reason you state, to prevent against the boration problem.

20 MR. EBERSOLE: On the secondary sides of the PWR,
21 they have safety valves and then they have to have
22 electromatics to intercept. What do they use for the pilot
23 or manual remote operation of the electromatics?

24 MS. WEGNER: Did you say BWR?

25 MR. EBERSOLE: PWR. The ones which are manual

1 remote operated.

2 MS. WEGNER: PORVs?

3 MR. CHURNEY: They are large PORVs. A lot of
4 them are large air-operated type.

5 MR. EBERSOLE: They are not required to be
6 safety valves.

7 MS. WEGNER: A lot of them use their safeties
8 for that.

9 MR. CHURNEY: They have large relief valves on
10 them.

11 MR. EBERSOLE: But they are just straight
12 air-operated. They are not given the prerogative of being
13 safety valves?

14 MR. CHURNEY: Yes.

15 MR. EBERSOLE: Yet they are probably better than
16 this.

17 MR. CHURNEY: The thing is, it would be very
18 difficult to change these out, for example, and put the
19 large valves on, that are on the BWR 5 and 6s which are
20 more like the big spring safety valves. These are about
21 one-third the size of those. It would be a very difficult
22 thing to change these out. These are mostly on the BWR 4s
23 and a couple of the 5s.

24 MR. EBERSOLE: I guess they don't test these
25 things every X days because they will stick open.

1 MS. WEGNER: After the Hatch incident, there was
2 a requirement for Hatch to open the valves. I believe that
3 was their finding. They did stick open.

4 MR. EBERSOLE: That is a stiff penalty for them
5 to fix the valves.

6 MR. CHURNEY: As she was saying earlier, some of
7 these things start to stick in a couple weeks. So in terms
8 of finding the frequency that would really be from a
9 cost-benefit point of view advantageous, it is not really
10 obvious that it really buys you that much.

11 MR. EBERSOLE: You buy some trouble when you
12 stick them open.

13 MR. REED: I could make a suggestion. We did
14 this at Yankee Rowe 25 years ago when we were studying why
15 pilot-operated relief valves didn't work. You could take
16 an external thermocouple, put it on that solenoid outside
17 the body of the operator, pilot operator, and follow the
18 temperature reduction in time of the external casting of
19 the pilot. That would begin to tell you when you have
20 saturated the space with hydrogen and oxygen and you have
21 stopped the condensate flow and the steam flow up in there,
22 and it will tell you how long it takes to get the sticking
23 condition.

24 In other words, you have got pure hydrogen and
25 oxygen up there. I expect it doesn't take too long. It is

1 amazing how low those temperatures will get. I saw the
2 temperature get hot on Yankee Rowe to 280 degrees
3 Fahrenheit. That tells you something is happening.

4 MR. CHURNEY: That is certainly one variable.
5 On the other hand, most of the test data that we see has a
6 whole spectrum of variation. These things don't just get
7 to one temperature and all of a sudden stick. There is
8 something else going on there, too.

9 MR. REED: If you have a microleak, you will not
10 get complete strip out. You will continue to keep
11 condensation and keep the temperature up and you won't get
12 solid --

13 MR. CHURNEY: Those that do leak, and there
14 seems to be fewer and fewer of them as we go along in time,
15 they don't stick as bad.

16 MR. REED: Hey, you got your answer. All the
17 answers are right in what you just talked about here today.
18 All you got to do is stamp it with a conclusion.

19 MR. CHURNEY: I think the owner group solution,
20 if it turns out that changing the material to one that
21 won't bind, that sounds like a pretty good option. It is a
22 fairly cheap option.

23 MR. EBERSOLE: We could use a buffer gas --

24 MS. WEGNER: That is one of the gases, the
25 particular element in the environment that is giving them

1 trouble.

2 This is a detail of the nitrogen lift pressures
3 of each of the valves at the Brunswick plant as per steam
4 line. It is interesting to note that the C steam line had
5 the best track record. It is even more interesting in view
6 of the fact that the C steam line was isolated for six
7 weeks prior to the outage and was opened approximately a
8 week before the outage. Also mentioned was a minor water
9 chemistry transient during that period of time.

10 MR. MICHELSON: I am confused.

11 MS. WEGNER: It may not be related.

12 MR. MICHELSON: Isn't the safety valve on the
13 reactor side of the steam line isolation valves? So they
14 are all pressurized all the time. The fact that you aren't
15 drawing steam through the C line might be interesting or
16 significant. That is all this is saying. That line was
17 inactive.

18 MS. WEGNER: The line was isolated --

19 MR. REED: Was there leakage through the valve
20 to the main disc on the C line?

21 MS. WEGNER: No. None of these valves leaked.
22 Or the vessel.

23 MR. REED: No microleakage or anything?

24 MS. WEGNER: There was no leakage reported.
25 They have acoustic detectors as well as temperature

1 detectors on the tailpipes to determine leakage. I am not
2 sure of their sensitivity. Temperature rise is what used
3 to be used at Browns Ferry to determine when we were, when
4 the valves were leaking. They were fairly sensitive.

5 MR. MICHELSON: How does the tailpipe
6 temperature detect --

7 MR. REED: I think I have a theory. If you do
8 not pass the steam through that C line and if you have the
9 intimately connected safety valve, no steam is going
10 through there, then stoichiometric quantities are not going
11 through there. You are not feeding the cells, so to speak.
12 You have stopped the flow. And that may relate to it.

13 MR. MICHELSON: You can also argue that the
14 hydrogen and oxygen is rising up and collecting in that
15 area. It is a noncondensable gas. Therefore it is all
16 hydrogen and oxygen up there.

17 MR. EBERSOLE: That is the other side of the
18 coin.

19 MR. MICHELSON: So it also depends on how much
20 that main poppet is leaking.

21 MR. EBERSOLE: Why do you get sticking on the
22 pilot seat without the counterpart and much more serious
23 sticking of the main seat?

24 MS. WEGNER: The main disc? It doesn't see the
25 steam.

1 MR. EBERSOLE: Sure it does. The back side does.
2 Is it that it is a better seal and doesn't leak?

3 MR. MICHELSON: It is that this is a Swiss watch.
4 The pilot of the Swiss watch and the other is a large gear,
5 so to speak.

6 MR. EBERSOLE: That brings up the old Salem
7 problem of what are the force functions and what is the
8 margin to do. This is -- do you remember Salem, the margin
9 of force to make the circuit breakers open? Maybe the
10 margins of force to execute valve clearance are not enough
11 for the pilot.

12 MS. WEGNER: This is a very thin film that forms
13 here. However, the area in which it forms is very small,
14 too.

15 MR. EBERSOLE: What is the forcing function that
16 makes it open? Is it big enough?

17 MS. WEGNER: For one thing, this side of the
18 disc doesn't see the --

19 MR. EBERSOLE: I am talking about the pilot
20 function over here. When I have an overpressure transient,
21 what are the forces versus the static friction and gluing
22 forces that I have to overcome? What is this force balance
23 in this design and what are the margins to overcome this
24 sticking?

25 It is analogous to the old UV trip on the Salem,

1 the ATWSS case, where they had to analyze what force do I
2 need in this case to make those UV trips work versus how
3 much spring tension I had to do that. It is an analysis
4 here of one of the forcing functions to make the valve
5 clear versus the sticking forces I do have to clear.
6 Evidently there has been no analysis of the design in this
7 context.

8 MS. WEGNER: Frank, I don't know about that
9 exact question.

10 MR. CHURNEY: I think the way that the main disc
11 is opened, that what you are talking about there is that
12 there is much more margin -- I don't think that anyone has
13 done anything real analytical with regard to this. I think
14 the operating experience, though, in the way this bonding
15 forms, I think it is fairly intuitively obvious that what
16 you are saying is correct.

17 MR. EBERSOLE: It is almost, it is a mechanical
18 version of the Salem case.

19 MR. MICHELSON: Yes.

20 MS. WEGNER: I know that Salem had a problem.
21 But I am not familiar with the --

22 MR. EBERSOLE: I am talking about the breakers.
23 But it is the same old thing. I got to move something.
24 With what force do I do it?

25 MR. CHURNEY: When it doesn't corrode, it works

1 fine.

2 MR. EBERSOLE: But you have to make an allowance
3 for corrosion?

4 MR. CHURNEY: That is what we are trying to get
5 rid of. In order to do that, I think there would be much
6 more substantial design changes.

7 MR. EBERSOLE: I am sure.

8 MR. CHURNEY: That is why I said, changing the
9 material, assuming that works, is probably the cheapest way.

10 MR. EBERSOLE: Maybe you just need bigger
11 pistons.

12 MR. REED: I tell you what bothers me: We talk
13 about root causes, what really causes valves to malfunction,
14 and we try to set up committees to search for root causes.
15 And we got root causes all around us. But our recognition
16 is pretty damn poor. I have had recognition of this
17 problem for 25 years. And I have been talking about it for
18 25 years. Nobody knocks me down. Any time one of you guys
19 want to knock me down about the environment of hydrogen and
20 oxygen and boron and what it does to internal operator
21 relief valves, I would like to be knocked down because I
22 will get off this kick.

23 MR. EBERSOLE: They will wait until they get a
24 sticking of so many of these. It is just like the list we
25 just had on check valves.

1 MR. REED: Are we lacking perception to get to
2 root causes?

3 MR. EBERSOLE: We are not sensitive to anything
4 unless it produces a drastic physical consequence.

5 MR. REED: I think we are sensitive but we lack
6 the perception to get the real root causes. I could
7 comment on Three Mile Island with respect to that.

8 MR. MICHELSON: I think one of the difficulties
9 might be, I don't believe the agency has any activities on
10 these types of valves like we do on some of the other
11 valves -- no research activities. I think you are
12 depending upon the industry to be doing this and so what we
13 need to inquire into is what is the industry really doing
14 about it? And what is the status of the situation? I
15 don't know if you people have gotten to that stage yet or
16 not.

17 MR. ALLISON: I think what Frank was just
18 telling you is what they are doing. They are changing
19 material. The previous work they have done on the
20 labyrinth seals seems to have solved that problem and the
21 material change will solve the problem and that will be a
22 good solution.

23 MR. CHURNEY: The quickest test program they
24 could come up with was the test on the reactors.

25 MR. ALLISON: It is pretty close to a root cause

1 in that you have the seat and the disc are the same
2 material and so what we think is happening is that the
3 oxide films are the same, they are tight films and so they
4 bond together.

5 MR. EBERSOLE: I didn't hear you say they were
6 the same material.

7 MR. CHURNEY: They are not exactly the same.

8 MR. EBERSOLE: Isn't that a no-no in any design?

9 MR. CHURNEY: I don't think so.

10 MR. ALLISON: A lot of steam system valves have
11 stellite discs.

12 MR. EBERSOLE: Okay.

13 MR. ALLISON: So if the new material is thought
14 to have a weak fragile oxide layer, it is different. And
15 that is the theory anyway.

16 MR. REED: To me the root cause is the
17 environment, the oxygen and hydrogen, and you choose to
18 build the dam down stream of a different material.

19 MR. ALLISON: Well, if the material works, you
20 don't have a root cause.

21 MR. REED: You mean, you don't have an event.

22 MR. ALLISON: Right.

23 MR. REED: But you just said the root cause
24 which is hydrogen and oxygen. You really haven't done
25 anything about that.

1 MR. EBERSOLE: We got to move on. We are going
2 to run out of time.

3 MR. ALLISON: One last thing, these are the set
4 pressures plus the nitrogen pressures. These are the steam
5 pressure plus the nitrogen pressure for the Brunswick
6 valves. And a recent test on the Hatch 1 valves that had
7 the initial incident can show you basically what BWR water
8 chemistry control can do towards solving part of the
9 problem.

10 MR. MICHELSON: Have any of the valves failed to
11 open at all at something approaching what the code would
12 say they must open up, the safety valves?

13 MR. ALLISON: I think the events we are talking
14 about fit what you are asking.

15 MS. WEGNER: The original Hatch incident had
16 eight valves that were supposed to open from 1080 to 1100
17 and failed to open, period.

18 MR. MICHELSON: But as safety valves, they
19 didn't have to open in that range, did they?

20 MR. CHURNEY: According to the code analysis
21 that was done for Hatch, what she said is correct. They
22 opened quite a bit later.

23 MR. MICHELSON: Did they have to open at those
24 levels?

25 MR. CHURNEY: It just so happened that the

1 particular transient involved was a very mild transient,
2 very slow. So we have never had an event where the code
3 pressure limit has been exceeded.

4 MR. MICHELSON: That is the question I am asking.

5 MR. EBERSOLE: Do the ASME code committees on
6 valve, are they aware of the evolution of these valves in
7 actual practice?

8 MR. CHURNEY: WE haven't reconsidered that. We
9 have substantially increased the initial qualifications of
10 the last couple of years for all the safety valves.

11 MR. MICHELSON: Does the code address this
12 particular design or is it simply the need for code safety
13 and certain requirements as to what they must meet?

14 MR. CHURNEY: We have not taken any action to
15 prohibit the use of pilot-operated safety valves. One
16 thing that has come up. You have to realize the way the
17 code is written. The code has to worry about light water
18 reactors. One thing that has come up is the concern about
19 how spring actuated safety valves on liquid. They work
20 lousy on liquid. If you are going to have any liquid
21 transients, these are much better. So there is a lot of
22 tradeoffs.

23 MR. MICHELSON: So the committees are not yet
24 real worried but they are watching the situation? Is that
25 a correct appraisal?

1 MR. CHURNEY: They are watching the situation
2 cautiously. As a matter of fact, there used to be a
3 penalty on the use of pilot valves. You had to put more of
4 them on the system. Recently the penalty was removed but
5 the initial qualification requirements were substantially
6 increased.

7 MR. EBERSOLE: Any further comments on -- what
8 is the committee's feeling about taking this matter to the
9 full committee? Would anyone say no?

10 MR. REED: I agree with you except that I think
11 we need to keep all kinds of pressure on to get the
12 fragmented valve, this misapplied valve situation
13 straightened out. I think it is one of my burning issues
14 and one I wasn't allowed to put on paper because I only
15 could have one.

16 (Laughter.)

17 MR. MICHELSON: You didn't choose to put it on
18 paper.

19 MR. REED: It wasn't the number 1.

20 MR. EBERSOLE: Let's go to the third item.

21 MR. KEISSEL: I am Dick Keissel. I am with the
22 the Office of Inspection and Enforcement. I am here to
23 talk about a series of recent check valve failures that
24 occurred at Turkey Point units 3 and 4. These check valves
25 were in the steam supply system to the aux feed pumps and

1 as you know, Turkey Point only has steam-driven aux feed
2 pumps at this time.

3 The safety significance of this problem is the
4 fact that it could have prevented the aux feed system from
5 functioning properly at Turkey Point, but of a more
6 sweeping nature is that it points out again what happens to
7 check valves, and in this particular case, stop check
8 valves, when they are subjected to very low flow conditions.

9 By way of history, in late November of 1985,
10 Turkey Point became aware of the fact that one of the 12
11 check valves in question was inoperable. They then ran
12 radiographs of the other 11 and found similar failure to
13 two more of the check valves. When they opened up the
14 valves, they found that all of the valves were experiencing
15 signs of mechanical damage from low flow or what they
16 attributed to be low flow conditions in the lines.

17 They replaced the stems -- the disc and the disc
18 guide in 10 of the 12 valves and went back into operation.

19 Then in early January, they discovered that,
20 again, one of the valves had failed. They x-rayed and this
21 time they found that a total of four valves out of the 12
22 had failed. They failed in a similar manner.

23 In addition to making the systems inoperable,
24 the loose parts which were generated by this could also
25 have done damage to the turbine pumps.

1 Because of the generic nature of the problem,
2 that being that we have a potential misuse of this type of
3 valve in an information notice, 82 -- I am sorry, 86-09 was
4 issued, this also referred back to a previous information
5 notice, 82-26 which addressed a similar problem with the
6 steam exhaust valves on the HPSI and RPSI systems which
7 were being subjected to low flow conditions when the pumps
8 were run in a test mode.

9 MR. EBERSOLE: I think there is no question. We
10 want to take this to the full committee and present it as
11 an immediate backup to the relevant problem of check valve
12 failures that we spent the whole morning on. This was
13 again a case of reduced flow and the chattering and damage
14 to valves which caused five of them to fail concurrently.
15 This is just another case of the same sort of event that
16 happened at SONGS.

17 MR. MICHELSON: You just said the licensee
18 thought reduced flow was the problem. I haven't heard any
19 explanation of how reduced flow can cause a failure of this
20 type of valve.

21 MR. EBERSOLE: I read low flow caused vibration
22 and chattering.

23 MR. MICHELSON: It is a little harder to see how
24 low flow damages this valve.

25 MR. KEISSEL: The manufacturer of the valve

1 recommends that they not be used where they see flows of
2 less than 10 percent. These valves are used as isolation
3 valves around the main steam isolation valves to the pumps.
4 And they attribute the low flow condition to leak-by of the
5 isolation valve itself.

6 MR. EBERSOLE: Were you here this morning?

7 MR. KEISSEL: No, sir.

8 MR. EBERSOLE: The failure of the five valves
9 was attributed to a 10 or 15 percent flow reduction.

10 MR. MICHELSON: These are stop checks. Look at
11 the drawings.

12 MR. EBERSOLE: These were deviant from the full
13 design flow conditions just as this is. At least this is
14 blamed as a causative factor that causes resident action
15 and damage to those valves which in a general context is
16 what you are telling me here.

17 MR. KEISSEL: Yes, sir.

18 MR. EBERSOLE: Does the valve vendor state that
19 he will not warrant his valves at flow rates less than X?

20 MR. KEISSEL: I don't know about the statement
21 that he will not warrant the valves below a certain amount.
22 He recommends that they not, that this style valve not be
23 used with less than 10 percent flow.

24 MR. EBERSOLE: So there are full requirements on
25 all valves like this? On those valves? You have full

1 requirement, a recommendation rather than requirement, that
2 they not use these with flows in that range?

3 MR. KEISSEL: Right. The unusual thing here is,
4 of course, we are -- when the system was designed, it was
5 assumed there would be zero flow. And what we were
6 experiencing here was just leak-by of a closed gate valve.

7 MR. EBERSOLE: What is the consequence of
8 failure of these valves.

9 MR. KEISSEL: The system would be declared
10 inoperable -- well, if the valves failed in the open
11 position, there is a possibility that the system would not
12 respond properly to a line break upstream of them. And you
13 couldn't, because you need to be able to pressurize with
14 steam from the other plant.

15 Let me show you. I have a schematic of the aux
16 feed system.

17 MR. EBERSOLE: It would leave it as an open
18 system then on aux feed?

19 MR. KEISSEL: Yes, sir. Now you have three aux
20 feed pumps that share their steam source between the two
21 units. If there were a steam -- if there were a line break
22 upstream, up in this area, failure of these valves then
23 prevent being able to service the pumps with steam from the
24 other unit.

25 MR. EBERSOLE: I see. So I lose the header

1 pressure for steam supply to the aux pumps?

2 MR. KEISSEL: That is correct.

3 MR. EBERSOLE: On a single point basis. Just
4 the failure of one of those valves?

5 MR. KEISSEL: No. Both of them.

6 MR. EBERSOLE: Why is that?

7 MR. KEISSEL: Well, if one of these holds, then
8 a breakdown here would be isolated.

9 MR. EBERSOLE: I thought they were
10 cross-connected.

11 MR. KEISSEL: The cross-connect is through these
12 headers here. So that your steam flow pattern would be
13 from one unit through the header and out.

14 MR. REED: I am having some difficulty
15 recognizing this valve that is called a stop check load
16 valve as a stop check. What it looks to me like is a not
17 too well designed and is used as a stop valve. How tight
18 is that little thing down there? It looks to me like it is
19 tight.

20 Now, didn't you just say that the manufacturer
21 says that it shouldn't be used at flows under 10 percent
22 and didn't you say that its real application is to be open
23 or closed? Not to throttle?

24 MR. KEISSEL: That is correct. It is not a
25 throttling valve.

1 MR. REED: Well, then it is a stop valve.

2 MR. KEISSEL: No, sir. It is a stop check. The
3 valve is in the normally open mode and, therefore,
4 functions as a check valve.

5 MR. REED: It is normally open and -- well --

6 MR. KEISSEL: And therefore, it will act as a
7 check valve, blocking flow above the disc but permitting
8 flow from below the disc.

9 MR. MICHELSON: The drawing is showing it in the
10 locked/closed position.

11 MR. REED: I see there is some way that this
12 assembly can move up and down on the lower part of the stem
13 that isn't obvious in the drawing.

14 MR. MICHELSON: Well, you know how they work.
15 It is obvious, but you have got to crank it out. It is in
16 a locked position.

17 MR. REED: Do you see what I am talking about?

18 MR. KEISSEL: Yes, sir. If this stem is pulled
19 back up, then the disc is allowed to ride up on it. And it
20 is a bit confusing in that the conventional globe valve
21 would have the stem actually filling this piece down here,
22 giving you the color which would permit you to pull it off.

23 MR. REED: And a little looseness down there for
24 a seat.

25 MR. MICHELSON: This one slides up and down.

1 The damage can only occur if the flow is so low that the
2 valve, the weight --

3 MR. KEISSEL: It just sits here and simmers.

4 MR. MICHELSON: That will wear the seat out.
5 But that is an altogether different problem than having
6 damage to the thing from being in the open position and
7 banking against something. This thing here, as long as it
8 isn't fluttering on the seat -- well, what is happening is,
9 it is breaking off that guide stem because it is fluttering
10 enough to --

11 MR. EBERSOLE: I fail to see why one of these
12 valves failing would deny steam supply to the aux feed
13 pumps. Did you not say that was the case?

14 MR. KEISSEL: No, sir. It provides a path by
15 which steam can be lost. And it is not just one. They
16 would have to take out two.

17 MR. EBERSOLE: I didn't see where the blocking
18 device was to prevent -- these are not commonly headered
19 together. I see other check valves up there. Now, it
20 takes more than one valve failure to deny steam pressure to
21 the turbines of the aux feed pumps, right?

22 MR. KEISSEL: Yes, sir.

23 MR. EBERSOLE: It would take more than one valve
24 failure?

25 MR. KEISSEL: Yes.

1 MR. EBERSOLE: So our problem would only be in
2 front of -- this is a safety problem if we lost more than
3 one?

4 MR. KEISSEL: Yes, sir. But we are talking
5 about a common mode.

6 MR. EBERSOLE: You lost one and you might have,
7 with a little less luck, lost them both?

8 MR. KEISSEL: That is correct.

9 MR. EBERSOLE: If I had lost two, would I have
10 lost my turbine pumps?

11 MR. KEISSEL: You could have lost your flow to
12 them assuming that you also then did not have your --

13 MR. EBERSOLE: I believe you said at Turkey
14 Point, I must depend on these three turbine pumps. I don't
15 have any motor pumps?

16 MR. KEISSEL: That is correct.

17 MR. EBERSOLE: So we have another mode of loss
18 of inventory to turbine-driven pumps?

19 MR. KEISSEL: Yes.

20 MR. MICHELSON: Where are the stop checks on
21 your drawing?

22 MR. KEISSEL: Stop checks are this column of
23 valves and this column of valves. (Indicating.)

24 MR. MICHELSON: You are sure those are stop
25 check and not just open gates?

1 MR. KEISSEL: They are defined as stop checks
2 and they were --

3 MR. MICHELSON: Those are normally just
4 maintenance valves for the purpose of repairing that motor
5 operator valve. I didn't think they were stop checks at
6 all. I don't know why they are.

7 MR. KEISSEL: I don't know if this drawing is
8 the current one. These valves were installed in 1983 or
9 1984. And they may have been installed as a replacement
10 for the valves that are there.

11 MR. MICHELSON: I would have guessed the stop
12 check was the valve to the right without a number on it.

13 MR. EBERSOLE: Well --

14 MR. KEISSEL: No, sir. Because the --

15 MR. MICHELSON: Go to the topmost line. I
16 thought that was the stop check.

17 MR. KEISSEL: No, sir.

18 MR. MICHELSON: Okay. I will stand corrected.
19 I am just surprised.

20 MR. KEISSEL: These were the valves and they
21 have been checked by the number. The reports were by valve
22 numbers. These are the two that failed on unit 4. These
23 are the two that failed on unit 3 in January.

24 MR. MICHELSON: They don't need to be check
25 valves. Not by the original design. The checking function

1 is provided by the check valves shown on the drawing.

2 MR. EBERSOLE: I am looking at the two check
3 valves that are on the right side of your drawing there.

4 MR. KEISSEL: Just there and there. However you
5 also have a steam cap back this way. It is a very -- one
6 word might be sophisticated, another word, complicated
7 system.

8 MR. MICHELSON: I don't think there is a steam
9 path back that way though, from the drawing, unless mine is
10 different than yours. That is the same line, it just
11 branches into two branches. If you go further to the right,
12 then there is another check valve.

13 MR. KEISSEL: I don't see the other check valve.

14 MR. MICHELSON: We have probably exceeded the
15 usefulness of this discussion?

16 MR. EBERSOLE: Any comments, anybody?

17 Okay. Thank you.

18 Before you get to this presentation, I suggest
19 that we include in our full committee presentation with the
20 added aspect of defining the degree of jeopardy to aux
21 turbine feed supply which was not at all clear from the
22 presentation from the E&ID. Okay? I don't know what the
23 degree of jeopardy here is. It was quite clear in the
24 SONGS case what was with us. But it is not here.

25 MR. ALLISON: We can explain that a little more.

1 MR. MICHELSON: Would you reconfirm with the
2 licensee which are the stop checks on the drawing and why
3 they are stop checks when they are shown as gates on these
4 drawings.

5 MR. ALLISON: We will do that. I think the
6 discussion of the back leakage has tended to drag out a
7 little bit. I think probably a more realistic threat is
8 loose parts in the turbine.

9 MR. EBERSOLE: That could be, thank you.

10 MR. LICITRA: I am Manny Licitra with NRR. I am
11 here to discuss an event at Palo Verde unit 1 on January 9,
12 1986. Palo Verde unit 1 at the time was in the last stages,
13 final stages of its power ascension program. It was
14 attempting to do a turbine trip test from 100 percent power.
15 For that test, there is a certain feature in the plant
16 called a reactor cutback system. For that test -- they,
17 this enabled the reactor cutback system, because it had
18 been successfully tested from a loss of load test at 100
19 percent -- I also believe they tried it at 80 percent and
20 it succeeded at that level -- so for this test, they did
21 not have the reactor cutback system in operation. What
22 they expected was to have a reactor trip due to high
23 pressurized pressure. That is, the turbine would trip.
24 There would be an automatic transfer of nonessential loads
25 to the grid. The pumps, reactor coolant pumps would stay

1 on and heat would continue to generate. You raise the
2 pressure and you get a trip due to that event.

3 What they got instead is that the house loads
4 did not automatically transfer to the grid because of a
5 frequency mismatch between the grid and the 1E buses.

6 MR. EBERSOLE: Was this a delayed -- we just got
7 through talking about the necessity to hold until you had a
8 voltage decay or you had a very rapid transfer. Which kind
9 of transfer is this?

10 MR. LICITRA: It is a synchronization match.
11 There is also a time element in there. I don't fully
12 understand the circuit myself.

13 MR. EBERSOLE: I think if they do it fast enough,
14 they do it fast enough before it gets out of sync. If they
15 wait too late, they have got to wait for a voltage decay.

16 MR. LICITRA: I think time comes into it.

17 MR. EBERSOLE: You don't have any idea of the
18 time spans we are talking about?

19 MR. LICITRA: No. What I do know is that the
20 system performed as designed. It was not a fault in how it
21 was set up. It was set up according to design, but because
22 of the way it was designed, it did not allow this transfer.
23 When you didn't get the transfer, you lose power to the
24 reactor coolant pumps, the main feedwater pumps, the
25 circulating water pumps, the steam dump for the bypass

1 control system. They are all on non-1E buses.

2 MR. EBERSOLE: Aren't the main feed pumps
3 turbine driven?

4 MR. LICITRA: At least one is. I think they
5 both are.

6 MR. EBERSOLE: So when you say you lose the main
7 feed pumps, you mean the booster pumps?

8 MR. LICITRA: I believe so, yes.

9 Now, when that happened, the pump didn't have
10 power. It is coasting down. And that caused a reactor
11 trip due to a projected, flow projected low DNBR.

12 The steam bypass control system valves did
13 receive a quick open signal but wouldn't close because they
14 lost power.

15 One of the four lowest setting main steam safety
16 valves lifted when the steam generator pressure increased
17 rapidly. And the setting for those lowest safety valves is
18 1250 psig. But only one of the four lifted. It stayed
19 open for about 43 seconds. When that valve receded, five
20 steam bypass control system valves modulated open, stayed
21 open for about 45 seconds, closed and then they had two
22 additional open/close cycles for the next 40 seconds.

23 MR. EBERSOLE: How did they operate when they
24 refused to operate just prior to that? You said but reclosed
25 almost immediately due to loss of power.

1 MR. LICITRA: I believe it is the quick open
2 signal that is on the nonsafety bus.

3 MR. EBERSOLE: Are you telling me the bypass
4 will open in the absence of circulating water? Until you
5 get condenser, low vacuum?

6 MR. LICITRA: That is what happened.

7 MR. EBERSOLE: That is strange, isn't it? You
8 denied the rapid opening right away due to loss of power.
9 Is that a -- is that the forced function, the loss of power
10 that denies bypass?

11 MR. LICITRA: That is what denied it?

12 MR. EBERSOLE: It wasn't loss of vacuum?

13 MR. LICITRA: Well --

14 MR. EBERSOLE: If it isn't the loss of vacuum, I
15 guess I will ask you why, because as long as you have got
16 vacuum, you can bypass.

17 MR. LICITRA: I guess I do not have an answer to
18 that.

19 MR. EBERSOLE: Okay. Go ahead. And then later,
20 you opened -- they modulated open again.

21 By the way, you mentioned that the safety valves,
22 the main steam safety valves lifted. What about the
23 electromatics that are interposed between the safeties and
24 the steam pressure. They are the ones that Palo Verde
25 advertised as being QA and safety grade, et cetera. Why

1 didn't they intercept the opening of the main safety valves
2 on the secondary side or are they, are these valves serving
3 no purpose?

4 MR. LICITRA: Only one of the four valves opened.

5 MR. EBERSOLE: Is it a dual purpose electromatic
6 or PORV safety valve or not? You say safety valves.

7 MR. LICITRA: Yes, they are the safety valves.

8 MR. EBERSOLE: Are they the PORVs, or are they
9 electromatic or are they intended to be operational in
10 front of the safeties?

11 MR. LICITRA: As you know, Palo Verde does not
12 have PORVs.

13 MR. EBERSOLE: I am talking about on the
14 secondary side.

15 MR. LICITRA: I am not able to --

16 MR. EBERSOLE: I have to infer from what you
17 haven't said is that these are multipurpose valves that
18 perform both a safety function and a pressure function
19 which they claim is safety grade. Is that true?

20 MR. LICITRA: The atmospheric dump valves?

21 MR. EBERSOLE: That is the one I am talking
22 about.

23 MR. LICITRA: These are safety valves.

24 MR. EBERSOLE: The atmospheric dumps, then, did
25 not work because they are not automatically piloted to

1 preclude opening of the safeties? Do you follow me? We
2 put electromatics or dump valves on the secondary side to
3 intercept opening of the safeties because we had reclosing
4 problems with the safeties. All right?

5 What did they do? You tell me the main steam
6 safety valves lifted but you didn't tell me what the dump
7 valves did.

8 MR. LICITRA: Let me see if I can get an answer
9 out of the report.

10 MR. EBERSOLE: I wouldn't look it up. I would
11 rather have you plow on through it and we will look at it
12 later.

13 MR. LICITRA: Okay.

14 MR. REED: You are right. Normally the
15 atmospheric dumps will open for the safeties the same as
16 the safeties, unless the pressure, rate of pressure rises
17 too fast. Then the safety will go.

18 MR. EBERSOLE: Right.

19 MR. REED: This is a strange trip here. It is
20 loss of a lot of vital equipment and it may be that the
21 atmospheric dumps also went open but couldn't take care of
22 the release quantity. So a safety valve opened.

23 MR. EBERSOLE: If so, it is not mentioned.
24 Let's go ahead. We won't have time to pursue the details.
25 Go ahead.

1 MR. LICITRA: Well, after the steam bypass
2 control system valves did modulate open, the operators at
3 that time took manual control of the individual valves and
4 stopped a cooldown. Simultaneously or about the same time,
5 they got a main steam isolation signal due to low steam
6 generator pressure. After the cooldown stabilized, the
7 operators reestablished cooldown via a steam generator, two
8 atmospheric dump valves and one auxiliary feedwater pump.

9 MR. EBERSOLE: How did they get low steam
10 generator pressure? It was excess opening of the bypasses?
11 Was it --

12 MR. LICITRA: They didn't have those valves open.
13 They were losing steam through the valves.

14 MR. EBERSOLE: When you say that they were under
15 manual control, they modulated open. They stayed open for
16 45 seconds. And is that, in the course of doing that, did
17 they lose pressure control? You say -- the bullet below
18 that says manual control was taken?

19 MR. LICITRA: About that time, they got a main
20 steam isolation signal, automatic signal.

21 MR. EBERSOLE: Due to low pressure?

22 MR. LICITRA: Yes. They tried to take over
23 control to stop that from happening but it occurred.

24 MR. EBERSOLE: Did the operators inadvertently
25 let the steam pressure ride through the modulation valves

1 too long? I am just curious how they got to low pressure.

2 MR. LICITRA: I do not know the answer.

3 MR. MICHELSON: The inference in your chart is
4 that the steam bypasses were open when they shouldn't be
5 open. That is how you got the low pressure?

6 MR. LICITRA: Yes. The steam bypass was open.

7 MR. MICHELSON: So it must be the steam bypass
8 stuck open?

9 MR. EBERSOLE: That is right. They modulated
10 open and stayed open.

11 MR. MICHELSON: But not because of need but
12 because they --

13 MR. EBERSOLE: They just malfunctioned.

14 MR. MICHELSON: -- malfunctioned and kept
15 oncoming down instead of closing again.

16 MR. LICITRA: That is one of the things they are
17 looking into. Why they did open.

18 MR. EBERSOLE: Had the circulating water pumps
19 started?

20 MR. LICITRA: It is not discussed in their
21 report.

22 MR. EBERSOLE: Okay. Go ahead.

23 MR. LICITRA: About three minutes after the
24 event, at 13:28, they restored power to the 1E buses. And
25 at 14:08, after doing other activities, they got the

1 reactor coolant system pumps started again. One at a time.
2 And the event terminated at 14:49, an hour and a half later.

3 MR. EBERSOLE: This is not very well known at
4 all as to what really transpired.

5 MR. REED: I think it ought to be brought back
6 to the next meeting.

7 MR. EBERSOLE: I think. I think it is too muddy
8 to discuss it any further because there are no positive
9 statements made about what happened. I didn't learn
10 anything about whether or not there were these highly
11 advertised atmospheric dumps which are supposed to be
12 safety grade. Palo Verde was proud of the fact that they
13 said they had safety grade secondary dumps to control the
14 primary pressure up and down. And yet I see no statement
15 to the effect that they worked at all or they were even
16 there. I think just in summary, we will just go to the
17 next one and anticipate seeing this then.

18 MR. HERNAN: I think Manny does have some more
19 material as far as what action is going on. I would like
20 to remind you, though, that it is the rules that we bring
21 these things down.

22 MR. EBERSOLE: This is why I am saying, I don't
23 think we know enough facts here.

24 MR. HERNAN: We will be more than happy to come
25 back. But I kind of get the feeling that the staff is

1 being criticized for bringing something down too early.

2 MR. EBERSOLE: I gather that we don't really
3 know enough yet really.

4 MR. LICITRA: I just received the LER for this
5 event.

6 MR. EBERSOLE: I am not criticizing you for not
7 having all the data. I am just saying, I don't think you
8 have. I don't see the picture very clear as it was handed
9 to you.

10 MR. HERNAN: We know that we don't have all the
11 data. But we didn't want to wait until we do to --

12 MR. EBERSOLE: There are about four or five
13 blank spots here.

14 MR. REED: I think a true -- all that is true,
15 Jesse. Also, we have some sensitivity with respect to Palo
16 Verde systems. So you can read our letters and perhaps
17 tailor the presentation.

18 MR. EBERSOLE: We are most interested in Palo
19 Verde and all of its ups and downs.

20 MR. LICITRA: The utility has not completed its
21 review of this event. They are still looking at different
22 aspects of it. They don't have a bottom line.

23 MR. EBERSOLE: We will get a rerun of this, say,
24 next month, maybe, or whenever.

25 MR. HERNAN: These meetings are every two months.

1 MR. EBERSOLE: Well, who knows. Whatever. Next
2 chance.

3 MR. ALLISON: Next meeting.

4 MR. EBERSOLE: Okay. I am going to put "hold
5 over." Thank you. Let's go to the next one.

6 MR. HERNAN: Did you want him to discuss the
7 action that is going on?

8 MR. EBERSOLE: You have a page 2. I didn't
9 realize that.

10 MR. LICITRA: That just gave the follow-up
11 actions that they are doing.

12 MR. HERNAN: I think that is important to cover.

13 MR. EBERSOLE: Carry on. I didn't know there
14 was a second page.

15 MR. LICITRA: As a follow-up action, they are
16 looking into this synchronization check relay circuit to
17 see what can be done about preventing this problem from
18 occurring. They do not have an answer at this time. But
19 they are looking into it.

20 Because one of the main steam safety valves
21 lifted, they checked the settings on all the valves and
22 they found it okay. So even though the other three didn't
23 lift and one did, apparently it must have been close to
24 that pressure. So they don't see any problem with the
25 settings on the safety valves.

1 They are also considering providing
2 uninterruptible power to the steam dump bypass control
3 system so they won't run into this problem. They still
4 don't have a final answer on that.

5 After the event, and in evaluation, they
6 determined that the reactor coolant system pump goes down
7 faster than design and faster than considered in one of the
8 safety analysis. That being the loss of flow safety
9 analysis.

10 They also found that because of the fast
11 cooldown, the trip, the anticipatory trip occurred faster
12 than they previously projected, so they are competing
13 effects. Since they didn't know what the overall effect is,
14 they made an assumption that the faster cooldown does take
15 place but trips at the same time. They previously assumed
16 and imposed some penalties on themselves until they
17 complete that evaluation.

18 And finally, they reran the turbine trip test on
19 the 24th, but this time they ran it with the 1, non-1E
20 loads powered off at the startup of transformer. So they
21 wouldn't have this problem.

22 MR. EBERSOLE: Okay. And did that one turn out
23 all right?

24 MR. LICITRA: That one worked as expected, as
25 predicted.

1 MR. EBERSOLE: I see. All right. Thank you.
2 Any comments?

3 MR. GIITTER: I am Joe Giitter with the Events
4 Analysis branch of the Office of Inspection and Enforcement.
5 The second event I would like to talk about today is a loss
6 of off-site power that occurred on January 9 at the
7 Palisades plant with one diesel being out of service and
8 only one diesel in the standby readiness mode. Let me go
9 ahead right away to the circumstances.

10 The initial conditions, the unit was in cold
11 shutdown for refueling for about 40 days. About one-third
12 of the fuel was new and two-thirds of the fuel was reloaded,
13 so there wasn't much decayed heat at the time. The head
14 was positioned on the vessel but not tensioned and the
15 vessel was drained about down to the flange level, which is
16 about 12 feet above the top of active fuel. Diesel
17 generator 1-1 was out of service and would have required
18 several hours to make operable. This diesel right here.
19 Emergency diesel generator 1-1.

20 The sequence of events, at about 2:41 -- these
21 are p.m. Eastern Standard Time -- about 2:41, smoke was
22 observed from the conduit on the 1A bus in this general
23 area here. It was later found out that this smoke was
24 caused when a cable shorted to ground and heated up some
25 water that had gotten in the conduit, apparently rain water,

1 and it looked as though it was smoke. The operators
2 immediately de-energized bus 1A which is a nonvital 4160
3 volt bus, this one right here, with the smoke believed to
4 be coming from here. And then because of fear of potential
5 fire or explosion, they decided to go ahead and de-energize
6 this entire rear bus, this 345 KV bus which feeds these
7 three starter transformers. Before doing that though, they
8 -- at 2:56, the operators started and loaded the diesel
9 generator that was in standby readiness. The diesel
10 generator function is required and supplied power to this
11 bus, vital bus 1D. At that point, at 3:08 they did
12 de-energize the rear 345 KV switchyard bus. That caused a
13 loss or caused buses 1C -- well, that was of course not
14 energized -- 1E and 1B to be de-energized.

15 They did have an RHR pump on this and all of
16 their decay heat removal was accomplished by tying the
17 diesel on this single bus here.

18 The licensee declared an unusual event at 3:00
19 and the NRC operations center was notified at about 3:19.

20 At 4:50, there was a shift change and the second
21 shift came on and decided that they were going to establish
22 backfeed to all the main buses and at 4:50 they
23 accomplished this by backfeeding from this front bus
24 through the main transformer through the startup
25 transformer down to the vital buses and to the nonvital

1 buses.

2 And once that was done, they terminated the
3 unusual event and secured the emergency diesel generator
4 that was tied to the 1D bus.

5 In summary, it was a loss of off-site power
6 caused by a voluntary disconnect and it appears that the
7 licensee did everything right.

8 MR. REED: Why do you call it a loss of off-site
9 power? It looks to me like a partial loss at the most.

10 MR. GIITTER: From -- as far as the plant, as
11 far as these buses are concerned, it is a loss of off-site
12 power, even though they didn't physically lose any of these
13 incoming lines.

14 MR. REED: Those lines are right in the
15 switchyard at the facility, I assume. They are the main
16 outgoing lines and incoming lines.

17 I am worried about these statistics that keep
18 piling up on a loss of off-site power and total blackout.
19 I worry that the people that are doing the analytical work
20 are not watching their definitions carefully. To me, I
21 don't see why this is tabbed, called a loss of off-site
22 power. To me it is an internal bus fault in the plant
23 which caused maneuvering and changing of electrical supply.

24 MR. ALLISON: During the time in question, there
25 was no off-site power feeding anything inside the plant.

1 Is that right?

2 MR. GIITTER: That is correct.

3 MR. ALLISON: No off-site power was reaching
4 into the station.

5 MR. REED: Simply because the diesel was on.

6 MR. GIITTER: The unit was shut down. There is
7 no power being supplied back through the --

8 MR. ALLISON: There was no electricity coming
9 from the switchyard into the plant.

10 MR. REED: Are you telling me that both these
11 345 lines are out of service completely?

12 MR. ALLISON: No, they are in the switchyard. I
13 am saying there is no electricity coming from the --

14 MR. EBERSOLE: They drove themselves into this
15 thing.

16 MR. GIITTER: They voluntarily disconnected.

17 MR. EBERSOLE: That is a management decision to
18 drive into it.

19 MR. REED: I would like this not to appear as a
20 loss of off-site power.

21 MR. EBERSOLE: This is not a loss in the context
22 that it was a loss without operator participation. They
23 deliberately drove into it.

24 MR. GIITTER: There may be a terminology problem.

25 MR. EBERSOLE: They decided to risk for a short

1 while that the diesel would hold. And it did. So I agree
2 with Glen that it is really not a loss in the usual context.
3 It is a -- we need to do something about the statistics
4 where you drive into a configuration like this. Somehow we
5 need the statistics to show that.

6 Any other comments?

7 I don't think we -- we will not carry this to
8 the full committee.

9 MR. REED: Agreed.

10 MR. ALLISON: Mr. Ebersole, we will discuss the
11 definition for the statistics purposes with the staff
12 people.

13 MR. EBERSOLE: I think that would be very much
14 in order.

15 Let's take a 10-minute break here. We will be
16 back at 25 after.

17 (Recess.)

18 MR. EBERSOLE: We will resume the meeting. I
19 believe the next event is the Robinson. Mr. Requa.

20 MR. REQUA: Right.

21 MR. REQUA: My name is Bud Requa. I am the
22 project manager for H.B. Robinson Unit 2 and this afternoon
23 I will talk to you about another loss of off-site power
24 coincident with a diesel generator out of service.

25 MR. KERR: I thought Mr. Reed persuaded the

1 staff that this would be a loss of off-site power?

2 MR. REQUA: In quotes.

3 In January about the time this happened, on
4 January 28, the plant was in a closedown for refueling for
5 early February. With a diesel generator out of service, a
6 fault occurred on the emergency bus E2 which caused a spike
7 on the instrumentation bus number 4. A false rod dropped
8 signal was received, causing a turbine runback. The
9 reactor tripped on high pressurizer pressure from 80
10 percent power. At about 9:18, a loss of off-site power
11 occurred coincident with a fast transfer to the startup
12 transformer. We originally worded it that way because at
13 the time we didn't know why we lost off-site power but
14 later we found that the C phase balance relay opened due to
15 a phase mismatch.

16 MR. KERR: What is the significance of the term
17 "loss coincided with fast transfer to startup transformer."
18 Does that mean that it actually didn't transfer to the
19 startup transformer?

20 MR. REQUA: Yes. It happened so fast it
21 couldn't tell what, which happened. But it turned out that
22 the -- at the time they didn't know what happened.

23 MR. KERR: Was the connection made to the
24 startup transformer?

25 MR. REQUA: The connection was made but refused

1 because the relay had opened, refusing it.

2 MR. KERR: Okay.

3 MR. REQUA: At 9:35 -- I am sorry. The A diesel
4 generator automatically started and loaded on bus E1. The
5 reactor coolant pump tripped and natural circulation was
6 established.

7 At this same time frame we received a safety
8 injection signal and the MSIVs were found closed.

9 MR. KERR: What does it mean if there is no
10 off-site power, to have the RRCs tripped?

11 MR. REQUA: We didn't have them.

12 MR. EBERSOLE: When you say "fault on emergency
13 bus E2." The bus fault is a rare thing?

14 MR. REQUA: I understand this is what they were
15 speculating and they still don't know. There are a lot of
16 unknowns on this one still.

17 MR. EBERSOLE: Suppose it had been a bus fault
18 on E1, what would the emergency diesel have done then? Can
19 it get to E2 or is it locked out by circuitry? What I am
20 trying to say is, if it had a true bus fault, that really
21 kills that bus. If that happened to be the unfortunate
22 diesel generator which was working, we would be in trouble,
23 wouldn't we?

24 MR. SWENSON: I am Warren Swenson in NRR. It
25 does not appear to have been a true bus fault per se. I

1 may be playing with the terminology here, but one of the
2 pieces of equipment for something like this that was
3 connected to the bus fault and they had not -- as the day
4 progressed, they had difficulty determining which specific
5 piece of equipment had produced the fault. The whole bus
6 itself apparently did not go dead, but it was sufficient to
7 lock the bus out temporarily.

8 MR. EBERSOLE: But it would have precluded
9 loading the diesel onto it.

10 MR. SWENSON: Apparently, yes.

11 MR. EBERSOLE: If that had been the case and if
12 that had been the diesel still operating, where would we
13 have been then?

14 MR. SWENSON: A station blackout.

15 MR. EBERSOLE: Okay. I just wanted to know how
16 close to trouble we might be. Carry on.

17 MR. REQUA: At this same time frame, about 9:18,
18 we received a safety injection signal, found the MSIVs
19 closed. This is another big unknown. We don't know what
20 happened first as yet. At 9:35 an unusual event was
21 declared and open telephone lines established between the
22 NRC operating center and the Robinson site.

23 At 9:46, the B diesel generator was restored.
24 At this time the reactor coolant temperature was 535
25 degrees F, pressure 2000 psig and the plant was stable.

1 MR. KERR: What good did it do to have the B
2 diesel generator restored if there was a bus fault on bus
3 E2?

4 MR. EBERSOLE: Right.

5 MR. REQUA: I --

6 MR. SWENSON: This is Warren Swenson. As this
7 event progressed, like I said, it apparently was not a true
8 bus fault but the, they shed the loads on that particular
9 bus. And as the event progressed, they reloaded the
10 equipment back on the bus one piece at a time, taking their
11 time and making sure that there were not additional
12 problems that they didn't drop out the bus again. It was
13 not the bus itself, a separate piece of equipment that
14 caused the failure. They didn't want to repeat the process
15 and lose power.

16 MR. KERR: Okay. Thank you.

17 MR. EBERSOLE: I guess sooner or later you will
18 tell me where the fault was.

19 MR. REQUA: I still can't tell you where it was.
20 They still haven't found out.

21 MR. EBERSOLE: That is another one of these
22 hanging cases.

23 MR. MICHELSON: Spurious.

24 MR. REQUA: At 10:52 the pressurizer heaters
25 were restored. At 12:28, not shown on here, the C steam

1 generator PORV was manually opened to balance loop
2 temperature for natural circulation. The valve stuck open
3 due to freezing of the instrumentation lines and they got
4 another safety injection signal on high steam line delta P.
5 The valve was closed a few minutes later by opening the air
6 supply valve and the partial blowdown was secured. At 12:55,
7 the E1 bus was connected to the off-site power. At 16:03,
8 the E2 bus was connected to off-site power.

9 Realigning the electrical system was delayed, as
10 Mr. Swenson said, because they wanted to take extreme care
11 to not load equipment on that may be still full.

12 The plant was taken to hot shutdown, and a day
13 or two later Carolina Power & Light decided to remain shut
14 down for refueling, which is where they are now. Their
15 follow-up is that they are in a 45-day refueling outage and
16 the licensee is investigating the cause of the loss of
17 off-site power with Region 2 reviewing their findings prior
18 to startup.

19 Also, the licensee's and INPO team are
20 investigating the high frequency of reactor scrams at
21 Robinson, of which they had four in January. Region 2 was
22 also evaluating this along with Carolina Power & Light, and
23 the results will be evaluated prior to startup.

24 MR. REED: I would like to just clarify. You
25 say up there, stuck open steam generator PORV. If you were

1 asked to use the words -- instead of PORV -- what does PORV
2 mean to you?

3 MR. REQUA: That is a pressure-operated relief
4 valve?

5 MR. REED: I believe the terminology is -- PORV
6 is power-operated relief valve. I have seen in various
7 descriptions around here and a lot of -- and some news
8 releases, that PORV means "pilot." I want to make sure we
9 have our nomenclature straight. I would have called this
10 an ADV. That is what it is, isn't it, an atmospheric dump
11 valve? Isn't it?

12 MR. REQUA: Yes. Yes.

13 MR. REED: We sort of, I think the terminology
14 goes like this, that PORV or power-operated relief valves
15 are on the primary side of a PPWR. ADVs are on the
16 secondary side. Just nitpicking, thank you.

17 MR. REQUA: I appreciate that.

18 MR. EBERSOLE: Let me ask why a signal is
19 produced caused by closure of main steam isolation valves
20 to produce a safety injection signal, since the first
21 consequence of that is to lose heat transfer and to cause a
22 pressure rise in the primary loop which has nothing to do
23 with inventory.

24 MR. REQUA: That is another one of these
25 mysteries that have to be solved. We don't know; they do

1 not still at this time know why they got that safety
2 injection signal. This was one of the reasons why they
3 didn't want to --

4 MR. EBERSOLE: So that is spurious?

5 MR. REQUA: Right.

6 MR. EBERSOLE: The second signal caused by stuck
7 open, that is due to contraction of the -- or you don't say,
8 it hasn't yet -- there is nothing automatically producing a
9 safety injection signal because that occurred, is there?

10 MR. REQUA: Are you talking about the second --

11 MR. EBERSOLE: The stuck open S/G PORV. That
12 doesn't automatically produce a safety injection signal.
13 Only the secondary effects of it, which is shrinkage?

14 MR. REQUA: Right.

15 MR. EBERSOLE: Which you say was caused by that.
16 As though it were a directly produced signal by this stuck
17 open PORV. Do you mean it is by the secondary effects of
18 it?

19 MR. REQUA: Yes. When these are condensed down,
20 then it shrinks.

21 MR. EBERSOLE: So it is the secondary effects of
22 it. So the first signal was -- I don't know why that was
23 caused. The second issue was legitimate?

24 MR. REQUA: Right.

25 MR. KERR: Did you say why that fast transfer

1 failed to be successful?

2 MR. REQUA: Yes. Because there was a phase
3 mismatch in that the C phase balance relay opened. It says
4 a phase mismatch. I don't know what percentage it is. If
5 it is a certain percent, then the relay opens up and won't
6 accept the transfer, as I understand it. Is that correct?

7 MR. SWENSON: That is my understanding.

8 MR. EBERSOLE: In summary, this is a real, this
9 is a close approach to total blackout. Not like the
10 earlier blackout. This was not invoked by the operators.
11 It happened?

12 MR. REQUA: That is correct.

13 MR. EBERSOLE: So it is a legitimate off-site
14 power failure down to a degraded emergency power supply.
15 And it happened -- it was lucky enough it was on the right
16 crisscrossed pattern of buses.

17 One thing that bugs me, I see about 20 minutes
18 there gone while they figured out whether it was a bus
19 fault or not a bus fault. What were they doing, opening
20 the breakers to clear the bus and verify the bus was clear
21 and then put the loads on one at a time?

22 MR. REQUA: Yes.

23 MR. EBERSOLE: Did they ever find where the bus
24 fault was?

25 MR. EBERSOLE: I take it it was a load fault

1 that didn't clear?

2 MR. REQUA: As of this moment, we don't know.

3 MR. EBERSOLE: We don't know yet. Well, it
4 wasn't enough to clear by independent opening of the
5 circuit breakers? They didn't clear it? You say there was
6 a ground fault. Wait a minute. You say, fault on
7 emergency bus E2.

8 MR. REQUA: No. A spike -- on E2, yes.

9 MR. EBERSOLE: How did you determine that? What
10 was the signal that says there is a fault on that bus?

11 MR. REQUA: As we said before, the bus itself
12 probably was not faulted. It was some equipment on there.

13 MR. EBERSOLE: What is the signal that told you
14 it was a bus fault? How did you conclude it was a fault or
15 even erroneously?

16 MR. SWENSON: I don't think we have all that
17 information. It was either a degraded voltage or loss of
18 power to the bus. And that is a question that --

19 MR. EBERSOLE: You don't know whether it was
20 incoming or outgoing problems?

21 MR. REQUA: No. We don't know.

22 MR. EBERSOLE: Okay.

23 Any questions?

24 MR. REED: No questions. It doesn't look like
25 this should come before committee?

1 MR. EBERSOLE: No. This is just a close
2 approach to loss of power.

3 MR. REED: Did you happen to see that Piper Cub
4 that flew into the high lines last night?

5 MR. EBERSOLE: Maybe it was one of those. A bus
6 fault.

7 Any further -- no questions. Thank you.

8 MR. REQUA: Thank you.

9 MR. EBERSOLE: Our next one is design deficiency.
10 This is a B&W plant?

11 MR. VISSING: Right.

12 MR. EBERSOLE: Feedwater in a B&W plant. That
13 is already interesting, say no more.

14 MR. ALLISON: Mr. Ebersole, I don't think I
15 wrote down an answer about Palisades, but I take it you
16 don't want Palisades --

17 MR. EBERSOLE: No, you are correct.

18 MR. VISSING: I am Guy Vissing with the --
19 project manager for Arkansas Nuclear One, Unit Number 1. I
20 am with the Office of Nuclear Reactor Regulation.

21 I am going to discuss with you today a design
22 deficiency in the emergency feedwater system of ANO 1 which
23 was discovered January 14. The significance of this event
24 would be a potential loss of all emergency feedwater and
25 blowdown of both steam generators during a steam line break

1 MR. EBERSOLE: No. This is just a close
2 approach to loss of power.

3 MR. REED: Did you happen to see that Piper Cub
4 that flew into the high lines last night?

5 MR. EBERSOLE: Maybe it was one of those. A bus
6 fault.

7 Any further -- no questions. Thank you.

8 MR. REQUA: Thank you.

9 MR. EBERSOLE: Our next one is design deficiency.
10 This is a B&W plant?

11 MR. VISSING: Right.

12 MR. EBERSOLE: Feedwater in a B&W plant. That
13 is already interesting, say no more.

14 MR. ALLISON: Mr. Ebersole, I don't think I
15 wrote down an answer about Palisades, but I take it you
16 don't want Palisades --

17 MR. EBERSOLE: No, you are correct.

18 MR. VISSING: I am Guy Vissing with the --
19 project manager for Arkansas Nuclear One, Unit Number 1. I
20 am with the Office of Nuclear Reactor Regulation.

21 I am going to discuss with you today a design
22 deficiency in the emergency feedwater system of ANO 1 which
23 was discovered January 14. The significance of this event
24 would be a potential loss of all emergency feedwater and
25 blowdown of both steam generators during a steam line break

1 with a single failure of one AC bus.

2 I would like to go through the narrative here
3 and then I will show you some schematics that more -- in
4 more detail explain the event. This deficiency was
5 discovered by an inspection team from the Office of
6 Inspection and Enforcement in which they postulated a steam
7 line break concurrent with a loss of the red AC power bus.
8 The turbine-driven and motor-driven emergency feedwater
9 pumps would be lost and there would be a possible blowdown
10 of both steam generators.

11 MR. EBERSOLE: How old is this plant? It is
12 many years old?

13 MR. VISSING: This plant was licensed in April
14 1974.

15 MR. EBERSOLE: So we have got 11 or 12 years?

16 MR. VISSING: Yes. However, I would like to add
17 that this emergency feedwater system has recently been
18 upgraded to a safety grade system and it was partially a
19 result of that upgrade.

20 MR. EBERSOLE: The upgrade in fact ran it into
21 this failure mode?

22 MR. VISSING: Well, yes. I would like to get to
23 that.

24 The design would not meet the single failure
25 criteria. The plant was at 89 percent power at the time,

1 and concurrent with this they had a failure of the diesel
2 generator and they were shut down.

3 The licensee confirmed the existence --

4 MR. KERR: I am sorry. Concurrent with what did
5 the diesel generator fail?

6 MR. VISSING: The diesel generator tripped on a
7 high pressure in the crank case and they had a controlled
8 shutdown to repair the diesel generator. It was the diesel,
9 really.

10 The licensee, to correct this, they did indeed
11 install check valves in the steam lines from both steam
12 generators before startup. Our staff at NRR did review
13 this issue and concurred with the inspection team's
14 findings. I would like to show you the emergency feedwater
15 system of Arkansas. You know that Arkansas Unit 1 is a B&W
16 reactor. The emergency feedwater system is a two-train
17 system. It has the adversity in that one pump is
18 motor-driven and one pump is steam turbine-driven.

19 I wanted you to note that the motor-driven pump
20 is powered from the red bus, and if we take a take a look
21 at the steam system of the turbine --

22 MR. REED: Where is this newly installed check
23 valve? Is that the one right next to the steam generator?

24 MR. VISSING: I haven't shown that yet. Yes.
25 This would be in the steam part of the -- the seem steam

1 system of the emergency feedwater steam turbine.

2 MR. HERNAN: It may be helpful, if you want to
3 use both projectors, you can turn the other one on there.

4 MR. VISSING: Okay. Let's see here. That is
5 the hydraulic part of the system.

6 MR. EBERSOLE: Before you go further, isn't it
7 true that if you have only a two-pump aux feed system, if
8 you lose steam supply to the turbine-driven pump and then
9 you invoke a theoretical AC power supply to the single
10 remaining pump and it doesn't have a transfer capability,
11 you are dead?

12 MR. VISSING: That is right.

13 MR. EBERSOLE: That is just built into the
14 design configuration to begin with?

15 MR. VISSING: That is right.

16 MR. EBERSOLE: So was that not accepted as a
17 basis?

18 MR. ALLISON: The difference here is the steam
19 line break loses the supply to the pump and that is the
20 accident that the system is there to mitigate. It is true
21 you can go down and fail at -- you can fail the
22 steam-driven pump, but that is a failure. However, when
23 you have a steam line break, that is not really a failure.

24 MR. EBERSOLE: Why not?

25 MR. ALLISON: You then need to have a redundant

1 aux feed system to deal with the steam line break.

2 MR. EBERSOLE: Well, then that is not done.

3 MR. ALLISON: Yes, they missed it here.

4 MR. EBERSOLE: Are there not quite a few plants
5 that only have two pumps, aux feed pumps, one of which is
6 turbine-driven?

7 MR. VISSING: That is right.

8 MR. EBERSOLE: Doesn't every one of them face
9 the possibility of loss of steam flow to one pump?

10 MR. ALLISON: If you wait a little, he gets to
11 the check valve question.

12 MR. EBERSOLE: Maybe it is something --

13 MR. VISSING: I would like to show you the
14 scenario that would happen with this configuration if they
15 had a steam line break in the 36-inch line here, and you
16 will note that this valve is a normally opened valve and it
17 is on the red bus. And the motor over here is on the red
18 bus. Now, having the break here, you would then have the
19 valve here normally opened and the valve here opened and
20 you would have a blowdown of the steam generator and no
21 steam to the auxiliary -- the turbine-driven pump.

22 MR. EBERSOLE: Right.

23 MR. VISSING: Therefore -- and also you wouldn't
24 have power to the red -- to the motor-driven pump. So,
25 therefore, you would lose, first you would lose your main

1 feedwater because it would trip off because of the steam
2 line break.

3 MR. EBERSOLE: Sure.

4 MR. VISSING: And then you would lose your
5 emergency feedwater pumps.

6 Now, what is normally done here is what they did
7 do to correct this situation: they, Arkansas, recognized
8 what they did and they installed check valves here and here
9 (indicating) and they switched this, these two pumps, these
10 two valves around so that this would be a closed valve,
11 locked, closed valve and this would be the operating valve
12 that would operate off the red bus.

13 Now, therefore, if you have a postulated break
14 in the 36 inch line, you would then lose the main feedwater
15 pumps, and you would lose -- if you had a single failure in
16 the red bus, then you would lose this valve here, but it
17 would have a check valve and you wouldn't have the blowdown
18 of the steam, of this part over here and you would still
19 have steam to your turbine of the turbine-driven motor.

20 What happened here, in their upgrade of their
21 system, they did initially have in their design such check
22 valves. However, subsequently, because of problems that
23 they had experienced on Unit 2, with check valves
24 chattering, they thought that they were going to have a
25 much more reliable system if they didn't have those check

1 valves, and not recognizing that they didn't adequately
2 look at the single failure criteria.

3 And so they did indeed install check vaives, the
4 swing-type check valves. And they are going to upgrade
5 those check valves with -- when they can -- with the
6 designs that are similar to what they used in Unit 2 to
7 correct the problem.

8 MR. REED: Is there any traceability on --
9 apparently a design decision was made way back when to
10 remove some valves in a very critical system.

11 MR. VISSING: Yes.

12 MR. REED: Is there any traceability as to who
13 was responsible, who verified, approved such a design
14 change?

15 MR. VISSING: Well, that is an issue that isn't
16 altogether clear to us. They explained their -- the
17 scenario during the inspection process and it wasn't
18 altogether clear as to the thoroughness of their review for
19 that change.

20 MR. REED: Do you think it was a designer
21 failure or a utility/owner failure? Who was -- was it the
22 utility that caused the deletion of the valves or the
23 designer?

24 MR. VISSING: The design was originally there.
25 The valves were originally in the design. Subsequently,

1 they were indeed removed and there was a conscious decision
2 to remove them from the design.

3 Now, who indeed were the contributing people
4 that made that decision, I don't know.

5 MR. EBERSOLE: In a turbine-driven aux pump,
6 isn't it just like breathing? When I look at the steam
7 line, I will always see two checks?

8 MR. VISSING: Yes.

9 MR. EBERSOLE: But it wasn't done?

10 MR. VISSING: That is right.

11 MR. EBERSOLE: So they weren't breathing very
12 well. That is astonishing, isn't it?

13 MR. VISSING: Yes.

14 MR. EBERSOLE: How did they escape all this
15 ferocious review in their engineering section? I want to
16 know how it got through?

17 MR. VISSING: I can't answer that. I don't know.

18 MR. EBERSOLE: How did it escape NRC?

19 MR. VISSING: It did not escape NRC. Their
20 original design was submitted to NRC --

21 MR. EBERSOLE: I mean the modification?

22 MR. VISSING: The modification, they did it
23 under a 5059.

24 MR. EBERSOLE: What happens to that?

25 MR. VISSING: We did not review that.

1 MR. REED: I don't see how this could go into
2 5059. It certainly degrades, changes the safety analysis
3 by a lot.

4 MR. MICHELSON: They just didn't recognize it.

5 MR. EBERSOLE: But it is up to them to recognize
6 that. So here is a basic flaw in the whole rationale.
7 Unless they can see it, you will never know. And this
8 would apply to anything.

9 MR. MICHELSON: You see it at the end of the
10 year when you get the yearly report from the utility.

11 MR. REED: This was done some time ago,
12 apparently. This is an old plant.

13 MR. VISSING: The design was originally
14 submitted to us in the latter part of 1981.

15 MR. REED: This modification to take out the
16 checks?

17 MR. VISSING: No, the initial design of the
18 upgrade of the system was submitted to the NRC in December
19 of 1981.

20 MR. EBERSOLE: And it escaped that --

21 MR. VISSING: It had the check valves in that
22 design.

23 MR. EBERSOLE: It had the check valves in 1981?

24 MR. VISSING: Yes.

25 MR. EBERSOLE: And then they took them out.

1 MR. VISSING: The upgrade was installed in the
2 last refueling outage which was in December of -- it was
3 December of 1984.

4 MR. REED: I think I am becoming confused. I
5 think you are talking about the checks being put back in
6 and I am focusing on when, how, and what time were they
7 deleted from the original design. That must have been back
8 in 1974 or -5?

9 MR. VISSING: No. They had submitted an upgrade
10 of the emergency feedwater system in December of 1981. At
11 that time that design had had check valves in the system.
12 The system was not installed until December of 1984.

13 MR. EBERSOLE: You mean it took three years --

14 MR. VISSING: Yes.

15 MR. EBERSOLE: -- for that to materialize?

16 MR. VISSING: That is right. And between the
17 time that the design was submitted to the NRC and the time
18 it was installed, there was a change made in the design.

19 MR. EBERSOLE: How did that get supervised?

20 MR. VISSING: We did not see that change.

21 MR. EBERSOLE: That doesn't come to you?

22 MR. VISSING: No.

23 MR. REED: I guess what you are telling me is
24 that this 12-year old plant had a Three Mile Island backfit
25 modification going and that didn't hit the fan until 1981?

1 Is that right?

2 MR. VISSING: Right.

3 MR. REED: I wonder what they had prior to Three
4 Mile Island.

5 MR. VISSING: I tried to find that out. I don't
6 know.

7 MR. REED: They probably had the right system.
8 That's just a joke.

9 On this one, I see this only as a statement to
10 point out that auxiliary boiler feed systems are very
11 vulnerable to all kinds of problems and design aspects. I
12 don't know that I support auxiliary feed system as the only
13 way to take care of decay heat removal on PWRs.

14 MR. EBERSOLE: I was wondering if we should
15 bring this to the full committee of how important things
16 can slip through a supposedly rigorous review system and
17 and then be picked up as late as this.

18 MR. REED: In the gut issue, the root issue is
19 decay heat removal.

20 MR. EBERSOLE: But here is an explicit --

21 MR. KERR: I don't think we have to convince
22 anybody that decay heat removal is important. What is it
23 that we are trying to persuade the full committee to do?

24 MR. REED: To adopt primary blowdown for certain
25 PWRs?

1 MR. EBERSOLE: But is there an administrative
2 control or move here that is indicated to close these holes
3 in the review process so that we don't let these things lay
4 around like this? What is the NRC action on this in the
5 generic context.

6 MR. KERR: My impression was that this was not
7 done deliberately, it was just that somebody overlooked
8 something. Are we suggesting this they go back and review
9 every plant?

10 MR. EBERSOLE: Aren't there some general rules
11 like breathing, that you always look for two check valves?

12 MR. KERR: Well, there are some general rules
13 like one never makes a mistake.

14 MR. ALLISON: This type of inspection is a good
15 thing to do where you go and look at the design of the
16 system in some detail and find cases like this and take
17 enforcement action and publish information notices. That
18 is really our -- what we are doing.

19 MR. EBERSOLE: What is contemplated here is an
20 enforcement action other than --

21 MR. ALLISON: I don't know specifically. I
22 guess we can find that out.

23 MR. EBERSOLE: What about the quality of the
24 tility review?

25 MR. ALLISON: I think that will get a closer

1 look by the Region now.

2 MR. EBERSOLE: Is that enough?

3 This has been sitting there for how long? Three
4 or four years?

5 MR. ALLISON: Right. About that long.

6 MR. REED: Jesse, I would like to repeat my
7 position, it seems to me that it is worthwhile for the full
8 committee to know that here is another example of the
9 vulnerability of aux feed as the only path of decay heat
10 removal for some reactors.

11 MR. EBERSOLE: Let's put down about five minutes
12 for this one, just to mention it to the full committee.

13 MR. KERR: I will agree to that will if you will
14 assure the full committee that this is being put to them
15 because of Glen Reed.

16 MR. EBERSOLE: Okay. I will mention this in a
17 very quick way.

18 MR. HERNAN: Do you want the presentation or is
19 this just something --

20 MR. EBERSOLE: No. We will make a statement to
21 this effect. You can make it or I will make it. Whatever.
22 Let's go to the next one.

23 MR. WEISS: The next item is the River Bend
24 startup review. It is not an event per se, but it is an
25 action that was taken because we saw significant number of

1 5072 reports for a new plant that was just starting up and
2 we decided to go out and have a look and see if we could
3 divine exactly what was going on.

4 MR. KERR: Will you forgive me if I ask you what
5 a 5072 report is?

6 MR. WEISS: A 5072 report is a report to the
7 operations center made over the emergency notification
8 system. A red phone call. If you go in the control room
9 of every nuclear power plant, there is a red phone. You
10 pick it up and call within either one or four hours of an
11 event occurring. The criteria for 5072 are very similar to
12 those required for LERs. So generally they are the same
13 thing.

14 MR. KERR: Thank you.

15 MR. WEISS: To get to the bottom line first, we,
16 after our visit we came to the conclusion that we will
17 expect the number of events that this plant is producing to
18 decrease; generally we thought their management appeared
19 sound. However, as a check, we asked the licensee to come
20 to the Region 4 for a progress review, and I believe the
21 date is March 4. There were a number of us that went. I
22 was the only representative from IE. Steven Stern, the
23 project manager who is here, and three other individuals
24 from NRR went. The Region 4 section chief, John Jordan and
25 his project manager showed up. John is here.

1 When we visited the site on January 28 through
2 30, we went over with the staff their recent events.
3 Recent scrams and other significant events, examined root
4 causes. We witnessed a shift turnover in the control room.
5 We had a tour of the plant, including the diesel generators
6 and the feedwater system. The feedwater system was
7 particularly important since this plant is having a
8 significant number of problems with their feedwater system.

9 We went to the Fancy Point substation, which was
10 significant because they had a loss of off-site power event
11 early in January that was precipitated at this substation.
12 We witnessed a surveillance procedure on the reactor water
13 coolant system. The largest single contributor was
14 inadvertent isolation of reactor water cleanup. It was
15 also significant from the point of view of the
16 demonstrating their ability to deal with jumper control
17 problems.

18 We also got a walkdown of the control room
19 panels, and that was revealing in a number of ways, not
20 only to familiarize ourselves with the plant, but to also
21 with some of the problems they had. I noticed that they
22 had a 3 by 5 card pasted on the panel with instructions
23 warning the operators to be careful not to have the suction
24 to shut down cooling and LPSI open at the same time. They,
25 like most plants, have had one of those draindown events.

1 In the exit interview, the project manager,
2 Steve Stern, urged the licensee to continue open
3 communication with the NRC. We thought this was important
4 because the licensee was indeed making a significant number
5 of reports that were voluntary in nature and weren't really
6 required by the regulations and we wanted that to continue.

7 There were such things as half scrams and half
8 isolations that told us something about the plant or
9 generic component problems and so forth.

10 We urged the licensee to resolve the outstanding
11 equipment and human factors problems. He is undergoing a
12 significant number of problems, as would any plant during
13 startup. And we did criticize them and urge them to
14 upgrade their communication with other plants, because we
15 thought there was a significant number of problems that if
16 they were not preventable, at least they could have found
17 out earlier by having more open, more frank discussions
18 with their counterparts at other plants, other similar
19 boilers with a year or two more experience. We urged them
20 to conduct these particularly at the lower levels rather
21 than just at the highest levels of plant management.

22 I could discuss a large number of plant-specific
23 problems, but I just want to mention a few to give you a
24 flavor for some of the things that we found. They had a
25 temporary alterations program that I guess was best

1 characterized like a quick 5059 that was maybe appropriate
2 during the latter stages of construction but we thought
3 should come to a halt soon. It was appropriate for an
4 operating plant.

5 They had, like most new boilers, they have more
6 instrumentation than the old boilers and a small number of
7 annunciator windows. One of those small windows had
8 something like a diesel generator problem. There were, I
9 think, over 15 different conditions that could have caused
10 that window to flash, some of which were more in the nature
11 of nuisance alarms and others were more serious. However,
12 they wouldn't get a reflash when a more serious problem
13 came in, and the operators that had asked that this be
14 fixed and it is being fixed.

15 The feedwater problems we thought were the most
16 serious of those that we had seen out there. They had
17 vibration, for example, in the short-cycle loop that this
18 had actually torn an anchor out of the wall. They had a
19 packing leak in that room when we visited it.

20 MR. KERR: What is a short cycle?

21 MR. WEISS: That is a loop that takes you back
22 to the condenser for the purpose of cleaning up the
23 feedwater system. There is both a short cycle and a long
24 cycle, depending on how much of the feedwater system you
25 want to clean up. They had erosion in the long-cycle loop

1 and were installing heavier schedule piping, more
2 erosion-resistant piping. They had sticking of the
3 feedwater regular valves, actual mechanical binding. The
4 operators noticed that they did not actually have real
5 valve position indication in the control room. They had a
6 demand signal. That was being changed.

7 They had steam tunnel ventilation problems. And
8 I understand that they are being rectified with additional
9 coolers. But one of the most interesting aspects of the
10 visit was this was a particularly productive visit in terms
11 of identifying generic problems for us. We are lucky if we
12 get one good problem out of a visit that we can tell other
13 plants about. Here we came up with three that seemed to be
14 interesting.

15 You may recall from reading regional daily
16 reports earlier this year they had a feedwater size
17 isolation valve with its operator fallen off on the floor.
18 There were about three contributing factors to that event
19 that ultimately I think will result in an information
20 notice. There was inadequate thread engagement. The bolts
21 were too short. There is a difference of opinion as to
22 what was the proper torque value between the various
23 vendors involved. And there was also a question of whether
24 the valves should operate or should have been torqued with
25 a valve on its, seat because that appeared to have

1 transferred some torque into the valve stem. Then when the
2 valve was cycled, the torque was relaxed on those bolts.

3 Another generic problem occurred with a
4 particular variety of temperature switch they were using in
5 their reactor water cleanup isolation. The licensee
6 informed us of the need to retrofit in a significant number
7 of capacitors and to add a resistor for the purpose of
8 noise suppression. And it is our understanding at this
9 point that General Electric will be issuing a service
10 information letter on that subject.

11 Now, the fiber --

12 MR. KERR: Was that a new design?

13 MR. WEISS: No. That was one of the things that
14 we thought that they could have learned about if they had
15 been speaking to other late model boilers, would have had
16 similar problems.

17 MR. KERR: GE didn't know about it because GE is
18 just now issuing something from what you said. Or did I
19 misunderstand?

20 MR. WEISS: That is correct. I understand that
21 GE will be issuing something on the subject. Exactly how
22 much GE knew and when they knew it, I am not in a position
23 to say. But we have seen --

24 MR. KERR: Had others previously had the problem
25 and done repairs?

1 MR. WEISS: Yes.

2 MR. KERR: But they just haven't told anybody
3 about it.

4 MR. WEISS: Sometimes when you replace a
5 component, you think, well, maybe it is a random component
6 failure. But after one sees a pattern at several plants,
7 one becomes disillusioned with that point of view and
8 begins to think that there is a generic problem.

9 MR. KERR: I thought it was a matter of
10 redesigning the circuit.

11 MR. WEISS: There was a noise suppression
12 resistor that River Bend thinks is advisable so that when
13 one moves a switch to read to function on the -- this
14 particular temperature switch, one doesn't get a noise
15 spike that causes an inadvertent isolation.

16 I think, I don't know whether other plants have
17 adopted that change. But it is certainly worth telling
18 other people about.

19 There is an interesting problem in the
20 switchyard. The plant added a diverse method of
21 controlling breakers in the switchyard which consisted of a
22 fiber optics multiplex system. They suffered a loss of
23 off-site power event around January 1 of this year. There
24 were no valid targets set that -- in other words, there
25 were no real faults identified, electrical faults

1 identified to cause this event. Testing subsequent to the
2 event has shown that any one of several different kinds of
3 hand-held walkie-talkies will cause tripping of the
4 tone-relaying equipment that is associated with the fiber
5 optics system.

6 The utility has adopted shielding; they
7 installed some plywood panels and put copper shielding
8 around the room that contains the equipment. They have
9 installed an events recorder so that, should it happen
10 again, they will have much more detailed information about
11 it. They have put up signs in the building and on the
12 fence around the substation and installed nonduplicating
13 locks at the entrance. They have trained their people,
14 cautioned their people and supplied additional procedures
15 in the substation for resetting breakers, should the need
16 arise.

17 They are also doing some filtering and
18 separation of power supplies.

19 In general, --

20 MR. KERR: I am a little puzzled. Fiber optics,
21 I thought, transmitted rather high frequency
22 electromagnetic radiation.

23 MR. WEISS: That was the impression I was under.
24 And every time I bring the subject up with an electrical
25 engineer, he says it can't happen. That is why we will

1 probably write an information notice on the subject. What
2 people forget is that at the end of the fiber optics line,
3 at the end of this glass or fiber tube, you will have a
4 demodulator receiver of some kind which will operate in the
5 radio frequency regime.

6 MR. KERR: My point was, it seems to me the
7 difficulty is not with the fiber optics but with the
8 termination?

9 MR. WEISS: With the end, which is exactly right.
10 You may recall that there was two loss-of-off-site-power
11 events, I believe, at Palo Verde that were caused by fiber
12 optics systems.

13 I am reasonably sure that the licensee there did
14 not evaluate whether a walkie-talkie could have
15 precipitated that problem. But that licensee decided to
16 remove breaker control by fiber optics. Now their breaker
17 control is strictly hard wire.

18 In any case, there were several things that
19 pleased us when we went out there. One I wanted to mention
20 is their condition report system. Apparently anyone in
21 plant can write a condition report on any condition and
22 this goes to, directly to the upper level management, which
23 then makes a decision on its ultimate disposition. One of
24 the strengths of their system is their ability to focus
25 resources quickly.

1 One of the things that I was most concerned
2 about when I arrived was their jumper control. They have
3 instated a strong program there of locking cabinets and
4 then when one wants to perform a maintenance procedure or
5 surveillance of some kind, then you go to the jumper
6 control officer who then gives you a serialized tag for
7 each jumper that is installed and there is an open log
8 entry for each jumper which then must be cleared. That
9 is in addition to the double verification that would be
10 performed on order STPs.

11 Another interesting aspect of their jumper
12 control problem was they had a significant number of
13 events that were caused by alligator clips falling off
14 the terminal strips. They tried several different
15 things. They settled on a solution that appears to be
16 quite desirable. They used banana plug, banana jack-type
17 assemblies. They install a banana jack beneath the
18 terminal lugs that are to be used in a surveillance
19 procedure. Then when the banana plug is used for a test
20 instrument, it will not fall out.

21 It also has the added feature, I noticed, of
22 when you open the cabinet, you may see several hundred
23 possible connections, but you see only four brightly
24 colored banana jacks, which greatly cuts down on the
25 possibility for putting it in the wrong place.

1 I have already mentioned the work they did with
2 fiber optics. Another thing I notice that they did in the
3 control room was a large number of their meters were
4 colored in such a way that the normal operating range was
5 something like green and abnormal range was in some other
6 color. And I asked the assistant operations supervisor
7 whose idea that was. He said it was mine. So I think that
8 indicates that the operators are having a substantial
9 feedback into their plant design and management is
10 listening to them.

11 MR. EBERSOLE: That was the plant that provided
12 the number 3 diesel cooling water from the number 2 diesel
13 supplies? Did they ever fix that?

14 MR. WEISS: Yes.

15 MR. EBERSOLE: Okay.

16 MR. WEISS: I noticed a number of interesting
17 design features out there. I haven't gone to that many
18 plants, but it was interesting.

19 MR. KERR: That location is fairly remote. You
20 may be getting all those telephone calls just because they
21 get lonesome and want to call somebody up.

22 MR. REED: Let me try another theory. It seems
23 to me that what I am hearing, because they have lots of
24 events, reportable events, is that there is an aggressive
25 utility, informed, perhaps capable organization that see

1 weaknesses and vulnerabilities in design and they are not
2 just accepting that and laying down with it. Is that what
3 I am hearing?

4 MR. WEISS: That is an entirely possible thing.
5 We have the project manager here who has a series of charts
6 that show that on a month-to-month basis, they have a fair
7 number of reports. But if you look at it from a
8 milestone-to-milestone basis, they are doing pretty well.

9 MR. REED: They have a convergent seam.

10 MR. WEISS: One of the benefits of going out
11 there is that you get some individuals willing to speak
12 very frankly. I had my eyes opened up to some of the
13 techniques that plants use to eliminate reportable events.
14 For example, if you have got a system that you know is
15 cantankerous and is likely to cause a red phone call, one
16 thing you can do is take it out of service, declare it
17 inoperable and perform your surveillances on it while it is
18 inoperable. Then it doesn't become reportable. I hadn't
19 heard of that twist before but now I am a little bit wiser.
20 The plant, by the way, has not been doing that.

21 MR. KERR: I bet Mr. Reed has heard of it.

22 (Laughter).

23 MR. REED: I hadn't really.

24 MR. KERR: I didn't mean that you had done it.
25 I just meant, I bet you had heard of it.

1 MR. REED: I am getting the feeling that you
2 have a couple people probably selected by aptitude testing,
3 well trained, who are causing quite a stir with this new
4 plant and finding a lot of problems.

5 MR. EBERSOLE: You are an optimist.

6 MR. KERR: We have got to have another report on
7 aptitude tests.

8 MR. EBERSOLE: Is that it?

9 MR. WEISS: That's it. Thank you very much.

10 MR. EBERSOLE: I believe we have had a
11 substantial increase in interest. We would like to
12 introduce Bob Benaro, director of the PWR licensing
13 division.

14 MR. BENARO: I would like to get into the Perry
15 earthquake event. This event occurred on January 31st and
16 simultaneously I approached people on the committee to get
17 on the agenda for the committee's reaction or review of
18 what we were doing in safety evaluation of the event. And
19 simultaneously two members of the Congress wrote to you and
20 I think you must have seen those letters by now. I will be
21 talking to Mr. Fraley and others in order to do what I can
22 to expedite the ACRS attention to this matter.

23 The first formal report of the event has just
24 become available today. We had an all-day meeting at the
25 site yesterday on the event. And the owner of the plant is

1 here with his consultants and I have a good number of staff
2 members here and I would like to go right in by turning it
3 over to the owner who will give you a substantive briefing
4 on what happened and what their evaluation of the event
5 shows.

6 So Mr. Murray Edelman, who is the senior vice
7 president, if I recall his title correctly, of Cleveland
8 Electric Illuminating Company, I will turn the floor over
9 to him.

10 MR. EDELMAN: Good afternoon. I am Murray
11 Edelman, vice president of CEI in charge of the Perry
12 project in our nuclear program. I am glad to be here this
13 afternoon on what actions we have taken with respect to the
14 earthquake that occurred in the vicinity of our plant on
15 January 31.

16 Yesterday afternoon, we had the opportunity to
17 brief the NRC staff and their consultants at the site as to
18 what actions we have taken since the earthquake occurred on
19 January 31st. This is the overhead that we used yesterday.
20 What I plan to do is to cover the introduction and the
21 overview of what actions we have taken the plant status and
22 our response that was given by our operations general
23 supervisor yesterday. And a little bit about the
24 earthquake analysis and seismicity that was performed for
25 us by Weston Geophysical. Mr. Holt is here. I am not a

1 geologist but I will try and cover that portion of the
2 program. Then we would like to have Dr. Chen, who was
3 responsible for the design and seismic analysis of plant
4 for Gilbert Associates, our architect engineer, review our
5 design criteria and actual experience that we had during
6 the earthquake on January 31st.

7 As an overview, the event occurred on the 31st,
8 about 11:45 in the morning. Our plant people, even though
9 we do not have an operating license and are about 10 case
10 days away from, in our opinion from receiving a license,
11 even though we're not in an operating mode, chose to go into
12 our emergency procedures for several reasons. One, it is
13 the best way we have learned, through training over the
14 last several years, of marshaling all the resources of CEI,
15 the county, the NRC and the state of Ohio. It gives us the
16 opportunity to ensure accountability of anybody who was in
17 the plant at the time. Since our security system is in
18 full effect, we used that to get a site accountability of
19 everybody on site and we went into our emergency plan and
20 activated our facilities as well as the facilities in
21 Chicago and Washington.

22 We then also sent our people out in the plant
23 after that to assess the status of the plant. We ran
24 numerous plant inspections with our operating people to
25 insure that the plant was in a safe condition. We then

1 downgraded our emergency event from a site emergency down
2 to an alert and after conferences with the state, the NRC
3 and ourselves, we terminated the emergency about 2:30 in
4 the afternoon. At which point in time we instituted our
5 recovery organization, the same as we would have in a
6 normal emergency if one had existed. We are still in that
7 mode where I am the recovery manager to bring the site and
8 response to the technical issues raised from the earthquake.

9 We did conduct numerous walkdowns by our people.
10 About 65 of our people spent the entire evening and next
11 day while the NRC sent people in from both Chicago and
12 Washington in response to a mutually agreed upon
13 confirmatory action letter from Region 3. We froze all
14 equipment and inspected everything and Washington came in
15 to inspect the equipment. After inspections by our people
16 and the NRC, the confirmatory action letter was modified
17 which allowed us to go back to finish our testing and
18 operation of the plant.

19 In addition, immediately after the event
20 occurred, we got a hold of all our special consultants who
21 have worked on the Perry project. This included Gilbert
22 Associates, Weston Geophysical, Mr. Engdahl who
23 manufactures the seismic information; the people from
24 Kinometrics; Dr. Hall, Mr. Stevenson and a number of other
25 outside consultants to review the plant conditions.

1 Close examinations were also prepared in nearby
2 areas to record any aftershocks that may have occurred
3 after the event took place.

4 We also started to compare the plant data that
5 we had recorded during the earthquake to see if it had any
6 engineering significance in our overall design. We did
7 record some high frequency accelerations which we didn't
8 consider to be a problem, which is a conclusion of our
9 report which you have in front of you, because they were
10 low energy, very short duration and low velocity. The
11 subject of the high frequency accelerations is a generic
12 subject which we know the staff is looking at at a number
13 of sites around this country. We have reviewed and are
14 still reviewing the plant structures and equipment to make
15 sure that there is enough conservatism in the design of the
16 plant and considering our loading combinations and
17 allowable stresses.

18 I would like to go through what our operations
19 people looked at in terms of what actions we have taken.

20 As the event started, we had ongoing testing and
21 calibration activity going on. We were preparing to run
22 our division 2 diesel generator testing. We were ready to
23 move the startup sources from the upper pool toward the
24 reactor and we had a number of systems in standby and
25 operating mode throughout the plant. What occurred during,

1 after and while the operation of the event took place is
2 all systems remained operable. All safety systems that
3 were designed to be operating through an earthquake
4 operated through the earthquake -- all relays, all the
5 safety systems we had in the plant.

6 Immediately following that --

7 MR. MAOL: What was the status of the plant at
8 the time the earthquake occurred?

9 MR. EDELMAN: We were in our final surveillance
10 testing. We had moved fuel from the lower pool to the
11 upper pool. We were calibrating our source range monitors
12 in the upper pool and running our final surveillance test
13 on some of our major systems such as the final test that
14 you have to run on diesel generators.

15 We sent our operators out after the event took
16 place and examined the plant to see if there was any
17 structural damage. We did walkdown by maintenance people.
18 A systematic identification of everything in the plant. We
19 asked our people to identify any abnormalities they might
20 see, no matter what they were, whether it was a burned-out
21 lightbulb or a cracked or peeled paint. Each one was
22 evaluated to see if it had any impact on the earthquake
23 itself.

24 We ran site surveys and settlement surveys which
25 we normally run on a monthly basis. Part of our recovery

1 plan. We asked those surveys to be taken the next day to
2 see if we had seen any settlement throughout the plant. We
3 looked at our cooling tower and walked down the structures.
4 We have certain areas in the plant where we have identified
5 what we call seismic violations. One pipe may be too close
6 to another. There were 26 of those that we had not yet
7 fixed so we went and looked at those specifically to see if
8 anything had interacted. Nothing was identified.

9 We studied all the relays that were energized to
10 make sure that they stayed energized through the event, and
11 they were.

12 And we in addition, and consistent with our
13 confirmatory action letter, we put a new procedure in as we
14 were running our surveillances. If any surveillance test
15 didn't pass, we would go back and analyze that to make sure
16 that was not a cause of the earthquake.

17 Since that time, we are running these
18 surveillances, we have not identified any that have worked
19 without our management review or NRC review because of the
20 earthquake itself.

21 Today we are back finishing our surveillances
22 and our preopen test right now. We met with the staff and
23 reviewed our operational readiness. We anticipate to be
24 complete, ready for fuel loading in about 10 days.

25 Now I would like to cover some general USGS data

1 on the status of the earthquake itself.

2 MR. KERR: Excuse me. One of the things that we
3 have encountered in discussion of seismic event and fix, at
4 least those that might be hypothesized, is the possibility
5 that relay chatter will occur and relays will put things in
6 modes of operation that are unexpected or unusual.

7 Did your investigation include any effort to see
8 whether that sort of thing had occurred?

9 MR. EDELMAN: To the best of my knowledge, yes,
10 and to the best of my knowledge we found nothing where that
11 occurred. The relay that did trip in the field was one
12 that was on our generator breaker which was supposed to
13 trip and the volt damage to it was off at the time and
14 would not go back. But of all of our safety systems, we
15 had no relay chatter or anything go into a different mode
16 because of the earthquake.

17 MR. KERR: Thank you.

18 MR. MICHELSON: Were all of the safety systems
19 fully energized and armed at the time of the earthquake so
20 that you could see if relay chatter was causing anything
21 unusual to happen?

22 MR. EDELMAN: I don't think all of our systems
23 were energized but I can give you a list of about 40 that
24 were. Our control rod drives --

25 MR. BENARO: For convenience, it is on page 3.6

1 of that big report. Section 3, page 3.6.

2 MR. EDELMAN: I think we listed in there all the
3 safety systems that were energized.

4 MR. MICHELSON: Of those that were energized,
5 was there any potential for relay chatter to even occur?

6 MR. BENARO: Ask him, not me.

7 MR. MICHELSON: Have you actually analyzed your
8 system to see if there was a potential to observe the
9 effects of relay chatter to know if there was even a
10 question about it?

11 MR. EDELMAN: Our manager of engineering is here.

12 MR. STEAD: We have looked at that. In fact, at
13 the time the event occurred, we were in preparation for a
14 response time testing and it was fully lined up and in a
15 standby mode ready to do the test. This is where you
16 actually initiate a signal to the bus and put all the loads
17 it after the diesel starts. All the systems were lined
18 up, ready to go into operation, waiting for a LOCA signal
19 to initiate. So all those relays were in position whereby
20 any movement to have started a LPSI pump or a high pressure
21 injection pump or caused a valve to open or close. So
22 those things are all in that position. So any of those
23 systems that are related to emergency core cooling, which I
24 think is probably the best test, in response to your
25 question, were in a mode that that could have happened and

1 wouldn't be immediately recognized by the control room
2 operators by indication in the control room. We saw no
3 indication of that during the event or after the event.

4 MR. MICHELSON: Not knowing the details of your
5 particular test, it is a little hard to see how the systems
6 were fully armed, though, because in order to be so, there
7 must be certain temperature pressure permissives, et cetera,
8 in the system. You went in and jumpered out a great deal
9 of ECCS initiating pressure or temperature.

10 MR. EDELMAN: If a plant is not running, you
11 can't have some of those.

12 MR. MICHELSON: But within the spectrum of what
13 you had, you did not see any relay chatter effects and you
14 were already armed and ready to go on that?

15 MR. STEAD: That is correct.

16 MR. MICHELSON: Thank you.

17 MR. EDELMAN: The data I am showing up here, all
18 this information and slides that we have are all in the
19 report that we have. What we have handed out to the staff
20 and yourself today is the USGS data which locates the type
21 and latitude and longitude of the earthquakes, the depth of
22 the earthquake and based on 64 stations worldwide, the
23 magnitude on the Richter scale was about 4.96. It was
24 located in Geauga County about 11 miles from the plant site.

25 MR. MICHELSON: I am assuming that you observed

1 no nonsafety systems' spurious operation?

2 MR. STEAD: No, we did not. We had a strip of
3 our instrument air compressor on high vibration.

4 MR. MICHELSON: I am not sure what you mean.
5 Was it induced by the earthquake?

6 MR. STEAD: Yes. It was a shaft vibration line.

7 MR. MICHELSON: That is the sort of thing you
8 are looking for, just like relay chatter is induced by the
9 earthquake.

10 MR. STEAD: This was in the normal mode of its
11 operation. It is a centrifugal compressor.

12 MR. MICHELSON: What I am asking you, was there
13 anything unusual that happened in the plant that might have
14 been coming from the effects of the earthquake?

15 MR. EDELMAN: The only two things that tripped
16 that we describe in our report are the instrument air
17 compressor and a building heating boiler which tripped.
18 All other equipment remained in operation.

19 MR. STEAD: I think on the next page is a list
20 of all the nonsafety systems that were in operation at the
21 time and gave no indication of any spurious operations.

22 MR. MICHELSON: Your air system was nonessential?

23 MR. STEAD: That is right.

24 MR. KERR: I know you don't like this, but it
25 seems to me the data that you are collecting is rather

1 important in terms of sort of a general indication of what
2 happened.

3 MR. MICHELSON: What you have to compare it with
4 is what is the design basis seismic situation, which I
5 assume you are going to tell us about in a minute.

6 MR. SIESS: Have you got any idea of what the
7 range is all about?

8 MR. EDELMAN: I didn't hear the question.

9 MR. SIESS: Do you have any idea of what the
10 range of natural frequencies are for relays?

11 MR. EDELMAN: For relays? I do not know.

12 MR. KERR: That is an easy question to answer.
13 The answer is no.

14 MR. EDELMAN: The map of the site area which is
15 in your book shows the plant site on the top, a 5- and a
16 10-mile radius ring. The epicenter was here on January
17 31st. The recorded aftershocks were about three miles west
18 of the epicenter. The highest one I believe is about 2.4.
19 We had no additional readings from these aftershocks on any
20 of our plant instrumentation.

21 This slide, the site at Perry is located -- and
22 this is kind of a skewed picture -- we are showing the
23 focus of the epicenter about 11 miles offset from the site
24 and about 5- to 6000 feet below or 30,000 feet below the
25 surface of the earth in the Precambrian rock. The site is

1 actually located on top of undifferentiated Paleozoic
2 sedimentary rocks on shale, as I call it.

3 During the -- we did extensive review of the
4 seismology during the PSAR and FSAR stage of the plant. We
5 did find geological anomalies which were glacially formed
6 folds in the sedimentary rock well above the Precambrian
7 rocks and the earthquake occurred down here. Our people
8 have looked at it and the conclusion that our geologists
9 and seismologists have reached from their analysis is that
10 the tectonic approach that we took in our PSAR and FSAR
11 stage is still valid. That there is no capable fault, no
12 tectonic structure. That our safe shutdown earthquake
13 intensive scale is 7. That our site-specific spectrum was
14 5.3.

15 We did see, based on extensive instrumentation
16 that we had in place and operating at the time, an
17 exceedance and short duration of a high frequency. That is
18 about 20 Hertz of a spike on the upper levels of the
19 containment building. Dr. Chen will go through that in
20 detail. But that was, again, high frequency and was above,
21 exceeded the 84 percentile spectrum that was put in the
22 FSAR.

23 Dr. Chen now, I have gone through this pretty
24 quickly to allow Dr. Chen enough time to review the details
25 of the specifics of the site and the design of the plant.

1 I would like to turn it over now to Dr. Chen, who is our
2 structure recall designer for our plant.

3 MR. CHEN: I am the manager of the civil
4 structural department of Gilbert. Before we go into a
5 detailed discussion of the comparison of this 1986 Ohio
6 earthquake event versus our design, I would like to
7 summarize the nature of the earthquake which will give all
8 of us a proper perspective of the size of the earthquake.

9 The recorded 1986 Ohio earthquake is of the
10 nature of high frequencies, low velocity, low displacement
11 and low energy, short duration earthquake. In comparison
12 with the kind of design earthquake we used for Perry, it is
13 of the broad frequency band: long duration, high velocity,
14 high displacement and high energy earthquake.

15 To show you how we reached this conclusion, we
16 will show you the comparison of the recorded time history
17 versus the time history we used in design. This time
18 history at the top is our design time history in the
19 north/south direction on the top of the foundation mat.

20 The one at the bottom is the recorded time
21 history in the same direction, at the same location. As
22 you can see, at the top the design time history has a
23 duration of 22 seconds. The recorded time history with the
24 strong motion, part of the record is less than one second.
25 And the one at the bottom has much higher frequency content.

1 The high frequency content which translates into low
2 velocity and low displacement.

3 This is the north/south component. We will show
4 you the rest of the components.

5 This one is east/west. As you can see, the
6 expiration value for east/west is also lower than the
7 design time history. Not only the duration is shorter.
8 The next one would be the vertical component. Also of
9 similar nature. Also the scores were low.

10 MR. REED: In the lower graph, does it actually
11 stop and then is it a straight line on the right or?

12 MR. CHEN: Totally stopped. Whatever is left is
13 the background noise.

14 MR. REED: Okay.

15 MR. CHEN: Next we show you the comparison of
16 the upper elevation which is at the steel containment.
17 This one is also north/south component.

18 Similar conclusion, that the duration of the
19 recorder is much shorter and that frequency is much higher.
20 There is some exceeders in the expiration which is a 20
21 Hertz region. We will come to discuss that comparison
22 later.

23 The next one is in east/west direction. As you
24 can see, the acceleration is also less than what we used in
25 design.

1 This one is in the vertical direction, a similar
2 conclusion.

3 Then in comparison, we can see our seismic
4 design basis is of the nature of broad band frequency
5 design with smoothed 84.1 percentile spectrum. And it has
6 much higher energy and long duration.

7 The spectrum we used I think everybody is
8 familiar with.

9 Next we will show you the location of those
10 instruments. And the type of the instrument. At the top
11 of the Kinometrics SMA-3, time history recorder. They are
12 located at the top of the reactor building map and also at
13 the elevation 686 of containment. The three at the bottom
14 are the Engdahl recorders. One out of the three during the
15 earthquake was in maintenance. That is why there was no
16 record of the other one.

17 There are four more instruments on this table.
18 These four instruments are Engdahl response recorders.
19 They are located at reactor building foundation mat,
20 reactor building 630 platform and the other two are at the
21 basement of aux building.

22 This one shows you the location in the plant
23 view of those recorders. 1 and 2, for example here, are
24 the triaxial time history recorder at the top of the
25 foundation mat and at the steel containment and the rest

1 are Engdahl instruments.

2 This one shows you the elevation view of the
3 location of the instruments. 1 and 2 are Kinematics
4 triaxial time history recorders. And the rest are Engdahl
5 instruments.

6 MR. MOELLER: The 4, 7 and 8 are different, are
7 they?

8 MR. CHEN: 4, 7, and 8. 3 and 4 -- let me see.
9 3 and 4 are the peak spectrum recorders. 5, 6, 7, 8 are
10 the triaxial response spectrum recorders. One records the
11 peak. One records the response at 12 discrete frequencies.

12 All those instruments with regard were used in
13 the comparison with our design data. The first design
14 barrier we compare with is the so-called ZPA variable which
15 means zero period acceleration.

16 The conclusion of this comparison is that the
17 recorded ZPA value varied from way below OBE value to 74
18 percent of the SSE values.

19 Except at containment vessel elevation 686, as
20 we showed earlier in the time history comparison. But at
21 this point, the relative displacement, in other words, the
22 stresses is very low.

23 The reason for that is because the nature of the
24 earthquake is of high frequency and low displacement
25 earthquake.

1 Now we will show you the table, how we reached
2 this conclusion.

3 There are the five columns and the five
4 different locations of the recorders with the ZPA values.
5 The first column is at the foundation mat of the aux
6 building. The second column is at the foundation level of
7 the reactor building. The third column is at the top of
8 the recirculation pump. The fourth column is at the
9 elevation 630 of the reactor building. And the fifth
10 column is elevation 686 of the steel containment. And the
11 first row here is in the north/south direction. And the
12 second row is in the east/west direction. And the third
13 row is in the vertical direction. Since during the seismic
14 design we considered three components simultaneously, the
15 proper comparison is the square root of sum of squares
16 which is at the fourth row here.

17 If we look at the SRSS comparison here, at a
18 foundation mat of aux building, the recorded value is
19 comparable to OBE value. At the foundation mat of the
20 reactor building, the recorded value is between OBE and SSE.
21 At the top of recirculation pump, the recorded value is way
22 below OBE value. And at elevation 630 of reactor building,
23 the record in the vertical direction cannot be determined.
24 So the only thing we can compare is in the north/south and
25 east/west direction. In these two directions, the recorded

1 values are below OBE value.

2 The only thing of some exceedance is in the last
3 column in the reactor building elevation 686. The SRSS
4 value of the recorded acceleration is comparable to SSE
5 with slight, less than 4 percent exceedance.

6 Now we were looking to dislocation about its
7 relative displacement. At elevation 686, with the recorded
8 value exceeding the design value by less than 4 percent, we
9 are looking at a displacement. The first column is the
10 displacement at the foundation mat. The second column is
11 the displacement at the elevation 686. And the third
12 column is the difference which is the so-called relative
13 displacement. Relative displacement is a measure of
14 stresses in the containment.

15 If we look at a comparison in the last row,
16 which is the SRSS value, the relative displacement is about
17 one-half of OBE value. So that is why we said that the
18 nature of this earthquake is of very small displacement,
19 even though the acceleration is high, the induced stress is
20 low.

21 In addition to the comparison of ZPA values, we
22 also compared response spectra. This is the conclusion of
23 our response spectra comparison.

24 First, Perry design spectra are far above the
25 recorded spectra in the frequency range below 14 Hertz.

1 Second, certain recorded response spectra
2 exceeded design spectra around the frequency region of 20
3 Hertz. But, this exceedance at 20 Hertz corresponding to
4 very small displacement, for example, at the foundation mat,
5 which is less than 3/100ths of an inch, because of this
6 small displacement at 20 Hertz, it doesn't really have any
7 engineering significance. Also, the recorded velocity
8 spectra, which is a measure of energy input, is also much
9 lower than the design velocity spectra. The north/south
10 components of the foundation mat of the reactor mat -- by
11 the way, this is a paper used in 160. I presume everybody
12 is familiar with this type of paper.

13 At the frequency region below 14 Hertz, this is
14 the design spectra. This is the recorded spectra. As we
15 can see here, the design spectra is far above the recorded
16 spectra, except with this spike here, which corresponds to
17 20 Hertz. But if we look at the displacement value at this
18 spike, which is somewhere here, it is 2 times 10 to the
19 minus 2 inches, that is .02 inch, 2/100th of an inch
20 spectra displacement. It doesn't really have any
21 engineering significance because of the low displacement.

22 This north/south component -- we will look at
23 the east/west components in the same location. The
24 exceedance is even less in the high frequency region here.
25 Same thing in the low frequency region. Design is well

1 exceeded by the design spectra. Again, the peak
2 displacement here is about 1.5 times 10 to the minus 2.
3 That means .015 inch, which is very small.

4 Next we will look at vertical component at the
5 top of the foundation mat. Same thing. Below 14 Hertz,
6 the recorded spectra is way under the design spectra.
7 Again, with a 20 Hertz spike here which corresponded to
8 about 1.5 times 10 to the minus 2. In other words, .015
9 inch. Which is very small.

10 I will now show the rest of the comparisons
11 which are all in the book.

12 After this comparison, we want to show you why
13 this earthquake is insignificant. First of all, all the
14 energized equipment went through the earthquake as designed.
15 Second, as to the other industrial design criteria. During
16 the blasting or pile-driving operation, the criterion used
17 for nondamage, nondamage threshold of non-engineered
18 building is 1 inch per second. The maximum recorded
19 velocity at the site on the foundation mat is only .87 inch
20 per second. That means that the maximum recorded velocity
21 on site is less than what people would experience during a
22 pile-driving operation.

23 Another thing is, in comparison with IEE 344
24 which is the seismic qualification of class 1E components
25 in a nuclear power plant, section 77.5 of this IEE 344

1 prohibits the use of shock tests to qualify the equipment
2 for the reason of high frequency and short duration input.

3 MR. MICHELSON: I guess one can say from that
4 that I guess we can't derive too much comfort from the fact
5 that there were no electrical disturbances in terms of
6 relay chatter or whatever. So I guess it still leaves us
7 without any good data on responses of electronic equipment
8 of that type.

9 MR. EBERSOLE: My experience in listening to
10 this is that you thought maybe in the beginning you had
11 something here and then when you analyzed it, you found you
12 didn't.

13 MR. CHEN: From the plant safety point of view,
14 you are right. It is nothing.

15 MR. EBERSOLE: But you didn't know that.

16 MR. CHEN: We didn't know until we looked into
17 it.

18 MR. EBERSOLE: I guess we have to take that sort
19 of news to the full committee. There is a special session
20 set up for it.

21 MR. CHEN: Yes, sir.

22 MR. MICHELSON: So it is inconclusive from the
23 viewpoint of providing us some indirect evidence of
24 survivability of these plants from the electrical relay
25 chatter viewpoint at least.

1 MR. CHEN: You are right, sir.

2 MR. EBERSOLE: And that is because of the
3 absence of any duration.

4 MR. CHEN: Short duration and high frequency
5 input.

6 MR. SIESS: I still think the high frequency
7 might have been a better test of relay chatter, but
8 something else.

9 MR. KERR: You only need one half cycles.

10 MR. SIESS: You had several cycles of the high
11 frequency. But somebody has got to tell me more about --

12 MR. MICHELSON: You could go back and do some --

13 MR. SIESS: With respect to relays --

14 MR. MICHELSON: You might be able to do some
15 laboratory work to correlate --

16 MR. SIESS: If it turns out they are sensitive
17 to high frequency, we could probably do some pile-driving
18 and not wait for an earthquake.

19 MR. ETHERINGTON: Or just a couple sticks of
20 dynamite at the appropriate distance.

21 MR. EBERSOLE: But you did find one point where
22 you had high acceleration on top of containment?

23 MR. CHEN: Yes, but that high acceleration
24 corresponded to 20 Hertz with very low velocity and
25 displacement.

1 MR. SIESS: What was the frequency of those
2 angle brackets that were held --

3 MR. CHEN: After the earthquake event, the
4 vendor, which is Kinometrics, came in and took some tests
5 of the brackets. The conclusion at that time was around
6 100 Hertz.

7 Well, there are other slides. I don't think
8 there is any need to show you here because I think you have
9 seen them 100 times.

10 MR. EBERSOLE: In view of the fact there is
11 going to be a full committee presentation by some sort of
12 edict that I don't really understand, I guess we can cover
13 that tomorrow.

14 MR. CHEN: Okay.

15 Now the conclusion here we have is, again, this
16 1986 Ohio earthquake is of such a short duration, high
17 frequency, low velocity, low displacement and low energy
18 event it really doesn't have any engineering significance.
19 Thank you.

20 MR. EBERSOLE: Thank you.

21 MR. ETHERINGTON: Using the same basis of
22 evaluation, how much does the addition of this earthquake
23 to the previous history of earthquakes add to the SSE
24 acceleration?

25 MR. CHEN: How does this compare with SSE?

1 MR. ETHERINGTON: Is it a significant addition
2 to previous history of seismicity in the region?

3 MR. EDELMAN: Would you like to respond to that,
4 Dick? Dick Holt from Western Geophysics.

5 MR. HOLT: It certainly adds to our data base of
6 eastern United States earthquakes of which we have very few.
7 We have some records from the New Brunswick series of
8 earthquakes and some from New Hampshire. This is the other
9 addition.

10 MR. EDELMAN: The inclusion of this event would
11 not change our design. That is what I would like to go
12 through now briefly. This proof test, which may not have
13 proved everything that we might have looked for as far as
14 equipment chatter since it was such a short duration, took
15 place at the plant, the structures and the systems were
16 unaffected by the earthquake. It does not change any
17 conclusion as to the geology and seismology of our site.
18 The design earthquake bounds of the 1986 event and that the
19 inclusion of the event does not change the design basis;
20 that the plant seismic capability is there to accommodate
21 the January earthquake, specifically this earthquake of
22 short duration which we have covered; and that we have a
23 number of follow on confirmatory programs that we at CEI
24 are participating with the rest of the industry to gather
25 as much information as we can.

1 We have worked with EPRI to gather as much data
2 as they can and worked with us and provide our data to the
3 staff and to EPRI and to USGS for additional what we think
4 might be useful to the industry. Even though it proved
5 there was no damage to our plant. We are part of the
6 seismic owners group, CEI, and we are dealing with them in
7 providing the data. They have been on site. The EPRI
8 people looking at our data, analyzing, and we are providing
9 all that information to them. We worked closely with all
10 these people to provide that data. We think it will
11 provide additional basis of information for the industry.
12 I am not very happy that we were the plant to do a proof
13 test 10 days prior to fuel load, but it did prove that the
14 plant was designed and capable of doing that.

15 MR. EBERSOLE: What happened to the people in
16 the control room? Did the swivel chairs roll at all and
17 the emergency manuals fall out of the bookcases.

18 MR. EDELMAN: Nothing. No, sir. None of that
19 happened.

20 MR. EBERSOLE: You couldn't even feel it.

21 MR. EDELMAN: We looked at our control room, no
22 spurious annunciators. When I was recovery manager on site
23 that evening, I talked to the shift that actually went on,
24 I talked to the shift on after that. They said they
25 noticed no spurious alarms in the control room. They knew

1 the buildings shook.

2 MR. EBERSOLE: No lights flickered?

3 MR. EDELMAN: No. We did have the alarm that
4 went off which allowed us to go into our emergency
5 procedures. But they reacted very well and knew what to do
6 and followed the procedures. There were no spurious
7 actions in that respect.

8 MR. KERR: If you are asking was it felt, it was
9 felt.

10 MR. EDELMAN: It was felt.

11 MR. EBERSOLE: In the control room they even
12 felt it?

13 MR. EDELMAN: Yes. It was felt.

14 MR. SIESS: Could I follow up on
15 Mr. Etherington's questions. You have a map in here,
16 figure 4.3, and there is nothing in the area of the site
17 the size of 6 historically.

18 MR. EDELMAN: I think I have a copy right there.

19 MR. SIESS: This shows 5 as the highest.

20 MR. EDELMAN: The site -- there were two
21 earthquakes used to bound our site consideration. One is
22 the Attica earthquake in New York and the one is the Anna
23 earthquake.

24 MR. SIESS: But in your immediate vicinity, this
25 is the highest?

1 MR. EDELMAN: Yes.

2 MR. SIESS: There would be no instrumental
3 records for any of those other earthquakes?

4 MR. EDELMAN: Not to my knowledge.

5 MR. SIESS: This just bears out my theory that
6 nuclear plants attract earthquakes.

7 (Laughter.)

8 MR. EDELMAN: I guess I will not comment on that.

9 That concludes our remarks and with some
10 direction from you or from your staff as to how much detail
11 we covered tonight that you would like covered, it was
12 about a half hour presentation to the full committee.

13 MR. EBERSOLE: That is about the best I can
14 define it.

15 MR. EDELMAN: I don't know if the staff wishes
16 to make any comments now. Mr. Stefano is our project
17 manager.

18 MR. STEFANO: Good afternoon. I am John Stefano.
19 I am the Perry project manager. Have been the project
20 manager since February 1982. I had the pleasure of
21 presenting the initial SSER to the SACRS Subcommittee which
22 was headed at the time by Dr. Ray and Dr. Ebersole was on
23 that committee.

24 All I intend to do right here is to try to give
25 you some sort of a feeling for where the NRC staff is

1 coming from; what they are going to be doing since we have
2 received this information. The books that you have before
3 you are hot off the press. We received them the same time
4 you did. There are additional copies here which can be
5 disseminated tomorrow if need be or anybody else you need
6 to disseminate them with today. We have additional copies
7 back at my office.

8 I would like to say that immediately upon being
9 notified of the earthquake, an inspection team was
10 immediately assembled by Region 3. They were dispatched
11 immediately, the next day, to the plant site to begin their
12 investigation of plant damage. NRR joined them the same
13 day. I was a member of the NRR team that went out there.
14 We spent the first and second day going through the plant
15 from a preliminary standpoint. Our initial findings in
16 walking through the plant at that time, which was around
17 the 2nd, 1st and 2nd of February, was to confirm pretty
18 much what the utility found by way of minimal damage. We
19 did see some hairline cracks in concrete, most of which I
20 understand the utility has records of as having occurred
21 prior to the earthquake. We did confirm the leak in the
22 flange of the hot water space heating tank which is
23 nonseismic supported. And I understand that certain of us
24 went out to check the circuits that tripped which were
25 designed to trip.

1 Where we are right now is in the very
2 preliminary early stages of our review. We really do not
3 have a position on what the utility has analyzed thus far.
4 We will certainly use what the utility has given us. We
5 will also use the resources we have available within
6 research, within NRR, our consultants, to do our own
7 independent assessment of what we found and to hopefully
8 present -- come to a conclusion that is similar to the
9 utility's. We recognize very well that they are in a
10 near-term licensing condition and we do intend to try to
11 support that the best we can. We want to assure you, we
12 are not going to rush this because they are 10 days away
13 from licensing.

14 Essentially, the actions planned are as noted on
15 this sheet. We are in the initial process of
16 characterizing what that earthquake means to basically
17 reaffirm the seismological and geological assumptions that
18 we used in initial plant design basis, as is described in
19 the FSAR and as we have evaluated in our SER, issued in May
20 have 1982.

21 In terms of this, we will also include a
22 structural design review where we will be comparing the
23 measured versus predicted responses, the effect and impact
24 of this so-called short duration high frequency exceedance
25 to the design basis of the structures themselves.

1 In addition to that, we will be looking at
2 piping and equipment which may be sensitive in this high
3 frequency region to see if there is any impacts there.

4 We have amassed a team of our research people,
5 people within NRR -- to name a few, Dr. Leon Rider; we have
6 Mr. Bob Herman, who is heading up our mechanical equipment
7 qualification design group; we have Phyllis Sobel and we
8 have Arnold Lee, who are also, by the way, here to answer
9 any specific questions you may have.

10 All this we hope will culminate in obtaining
11 some preliminary internal findings by the 21st of this
12 month which will be a week from this Friday. I plan to
13 amass all of the people within NRR, NRC only, to try to
14 come up with a picture of where we are.

15 I want to emphasize that the follow-up dates on
16 SSER issue and Perry licensing are strictly very rough
17 estimates and targets. Those dates really can't be firmed
18 up until we meet on the 21st to decide where we really are
19 on this thing.

20 As I understand it from our seismologists and
21 geologists, this is the first plant outside of California
22 where an earthquake occurred and there were instruments
23 inside that were used to record it as opposed to trying to
24 set charges outside someplace to see what the response
25 would be in the building. So we do have -- we really have

1 a unique set of data here. I am not sure at this point
2 whether we really understand what it means. So I think
3 when you look at SSER data and Perry licensing date, that
4 is really at this point sort of red.

5 However, we do wish to indicate to the ACRS that
6 we will try to get your oversight of this draft SER as we
7 put it out. Hopefully before the 7th. And we would
8 request your assistance in that regard, if you could
9 provide that to us.

10 Let us know where we are going, is there
11 anything we are not covering, what is good and what is not
12 good before we finalize that. It is my intent to try to
13 beat that 7/7 date with a draft SER if we can do that.

14 One last point. Just coming here, in fact after
15 coming here we found out that there are some preliminary
16 unconfirmed report received from the USGS that there are
17 some indications -- at least they think that the earthquake
18 may have been precipitated by an underground injection
19 plant which apparently is located somewhere between the
20 plant site and the site of the earthquake. We don't know
21 any specifics about that. As I say, this is just unconfirmed.
22 We are looking into that. As I understand it, the
23 injection is of agricultural waste which is injected quite
24 a large depth into the ground, I understand something like
25 6000 feet below ground. So I don't know if that has any

1 input at all as to what we are finding here or any measure
2 whatsoever. I just thought I would let you know that
3 because we just found that out.

4 Are there any questions?

5 MR. SIESS: I have got two questions. I don't
6 know who can answer that. The first one is fairly simple.
7 Was there any instrumentation in the free field?

8 MR. STEAD: To the best of my knowledge, no.

9 MR. RIDER: There was a dam some seven
10 kilometers to the south. There is a hospital in Erie,
11 Pennsylvania which may have recordings of that. There are
12 two records in distance which were not in the free field.

13 MR. SIESS: The seismic analysis and design,
14 what structures, components or systems would be affected by
15 the portion of the reg guide spectrum in the range above 15
16 Hertz?

17 MR. CHEN: We just found reactor building as
18 second higher.

19 MR. SIESS: How much would that affect the
20 design?

21 MR. CHEN: As we just showed, in comparison with
22 the steel containment, even though acceleration was
23 exceeded, relative displacement is below OBE value.

24 MR. SIESS: The design of the building would be
25 forces from mode 22, I think that is the one, the 18 Hertz

1 mode --

2 MR. CHEN: We took the -- in the original design
3 we took the modes out to 33 Hertz.

4 MR. SIESS: How much contribution did you get
5 from the modes above --

6 MR. CHEN: The contribution, the participation
7 factor at the mode of 18.4 Hertz is somewhat, about
8 one-third to one-half of the first one. So as to
9 contribution to which building, we haven't looked into them
10 and determined that. So the only one we have looked into
11 in detail is the containment which we showed the
12 displacement.

13 MR. SIESS: And the piping wouldn't be falling
14 in that range?

15 MR. CHEN: Piping, usually the frequency range
16 is lower. Especially for this kind of displacement,
17 usually the piping has a gap of about 1-1/16 of an inch.

18 MR. SIESS: Thank you.

19 MR. EBERSOLE: Any further questions?

20 MR. BENARO: I would just like to add one thing.
21 This is indeed a very valuable data point for eastern
22 earthquakes and we are trying as we go into this thing to
23 break our attention into two categories. One is Perry
24 plant-specific questioning, whether the seismic design
25 basis and structural design are appropriate for Perry. But

1 secondly, there are a lot of things that we could learn
2 from this about earthquake instrumentation or it doesn't
3 make sense to put so many frequency range meters of
4 earthquake response in a control room and have the shift
5 supervisor interpret what they mean. There are many
6 generic lessons to be learned. We are trying to not lose
7 those and I am sure the committee will be interested in
8 that for its follow-on value.

9 MR. EBERSOLE: Would that be something that
10 might be mentioned tomorrow?

11 MR. BENARO: I was just going to make the same
12 point tomorrow.

13 MR. EBERSOLE: Well, all I can point out is that
14 tomorrow -- well, we are only 30 minutes tomorrow. From
15 what I heard, the operator deserves at least 20 of that and
16 the staff 5 and perhaps you can cover the other 5. How is
17 that?

18 MR. BENARO: I would say 25 and 5.

19 MR. STEFANO: Exactly.

20 MR. EBERSOLE: That is the kind of ratio we are
21 heading for.

22 MR. HERMAN: We will take a look at the
23 equipment.

24 MR. SIESS: That was the containment building.

25 MR. CHEN: Yes, sir.

1 MR. SIESS: To what extent do the seismically
2 calculated stresses govern the design of that construction?

3 MR. CHEN: Very small. The loss of coolant
4 pressure design, thickness of the shell -- it is a small
5 portion of that.

6 MR. EBERSOLE: Thank you.

7 There may be people who would want to go out.
8 We are going into other topics. I will just pause for a
9 minute if you want to clear.

10 (Pause.)

11 MR. GREENMAN: Good evening. I am Ed Greenman
12 from the division of reactor projects in Region 3. I have
13 with me Jeffrey Wright. The topical area on the agenda is
14 the Fermi 50.54 improvement program, which while again not
15 an event, was the culmination of a number of events and a
16 number of problems at the Fermi station. I think it might
17 be helpful in the way of background to go over a very, very
18 brief history of what has transpired at the Fermi station
19 since March of last year culminating in the issuance of the
20 50.54 letter in late December this year.

21 The lower power license for Fermi was issued on
22 March 20, 1985. It was a Commission briefing for the full
23 power license on July 10 of last year. And the license was
24 issued on July the 15th.

25 On July 1, the evening of July 1, into July 2, a

1 premature criticality event occurred. The NRC was not
2 aware of that event at the time of the Commission briefing.
3 Nor was it mentioned at the Commission briefing. That
4 event was not significant in and of itself technically.

5 MR. KERR: I have heard reports of this
6 statement before. It seems to me, in fairness to the
7 licensee, you should point out that although you perhaps
8 were not aware of it being a criticality event, I must say
9 I am still skeptical that the thing ever went critical.
10 You certainly did know that an event had occurred.

11 MR. GREENMAN: That is a correct statement.
12 Nonetheless the Commission was not briefed on that event by
13 either the NRC or the licensee at the time.

14 MR. KERR: The resident inspector was. He knew
15 the details of the event, he knew about the rad withdrawal
16 and that there had been instrumentation observed.

17 MR. GREENMAN: As I know the Subcommittee is
18 aware, that subject is still under discussion and is part
19 of an OIA investigation internal to the staff.

20 At the time the full power license was granted,
21 the NRC's view of licensee performance was favorable.
22 There had been minimal operational-type events. There had
23 been minimal difficulties in making a transition from an
24 engineering organization into an operational phase. Since
25 the time the license was issued and subsequent to

1 notification of the premature criticality, a confirmatory
2 action letter was issued by Region 3 that restricted power
3 operation of that utility to 5 percent power. The utility
4 still has not operated above 5 percent power. There was no
5 operation up until a scheduled shutdown which occurred in
6 October of last year which was scheduled to do work on a
7 remote shutdown panel. That outage was originally
8 anticipated to have been concluded late November, early
9 December of 1985 and the utility still remains in a
10 shutdown condition today.

11 Projected availability from the standpoint of
12 resolution of technical issues is now anticipated to be
13 sometime in late February or early March, dependent upon
14 resolution of some engineering issues which I will discuss
15 a little bit later.

16 MR. MOELLER: When you say the utility or the
17 plant remains shut down, that is in accord with NRC
18 regulations?

19 MR. GREENMAN: They are shut down with the
20 constraints of the confirmatory action letter which
21 restricts them to 5 percent power. They are also shut down
22 within the constraints of the 50.54 approach. However,
23 there are a number of technical issues. I guess my view is
24 from what we know today, the diesel generators which we
25 briefed the Subcommittee on a month or so ago still remains

1 as a critical path issue for the utility, dependent upon
2 the resolution of the engineering issues.

3 As I mentioned, we briefed you on the diesel
4 generators a month or so ago. Nothing really new has
5 happened with respect to the diesel generators. They have
6 embarked upon a demonstration program for the NRC involving
7 two of the four Fairbanks Morris diesels. They recently
8 encountered a situation where they identified a portion of
9 a scraper ring on the top of one of the crank lines,
10 reevaluated and reinspected all of the pistons and did not
11 find any damage. We have also recently identified a case
12 of a viscosity change in the oil, which was a Shell product,
13 an additive type product, where foaming was encountered in
14 the oil. And they are involved in their test runs.

15 The utility has submitted an action plan to the
16 NRC. We have just received that within the last few days
17 and we have not made a determination as to the
18 acceptability of that plant.

19 It involves a series of starts and extended runs
20 to demonstrate the reliability of the diesel generators.
21 It will also involve our assessment of what types of
22 inspections they do after the fact to assure the
23 operational capability of those diesel generators.

24 Since the plant started up, we have also
25 encountered cracking in the turbine bypass lines. That

1 piping has been replaced with nominal one-inch wall
2 thickness. NRC inspection of that area is still in
3 progress.

4 There was a major failure of one of the two
5 feedwater pumps at that utility. The south feedwater pipe,
6 it is a TDI product. It experienced excessive vibration.
7 The root cause, the licensee and we have attributed to
8 failure on the part of the engineering department to
9 translate warmup instructions into the operations procedure.
10 Also an inadequate engineering assessment of the meaning of
11 the vibration alarms and the fact that the computer that
12 monitored what the vibration alarms were telling them was
13 scaled off by about 2.5.

14 This resulted in catastrophic bearing failures,
15 problems with the pedestal and a number of other issues.
16 That particular feed pump has been restored and is ready to
17 be returned to service and I think it will perform
18 acceptably.

19 There is an outstanding issue with NRR that the
20 licensee has requested a waiver for inability to meet
21 general design criteria 56 on the traversing in-core probe.
22 NRR is reviewing that request. One possible solution to
23 that would be the installation of two ball check valves
24 outside of containment and a request for relief to meet GEC
25 56 until the first refueling outage.

1 One personnel error has occurred that involved a
2 rupture of the condensate storage tank up near the top of
3 that particular tank and the loss of about 100,000 gallons
4 of water.

5 The weld failure has not been repaired. The licensee
6 is planning on using that as is and we are still
7 in the process of evaluating the acceptability of that.

8 MR. REED: On one bullet up there you have the
9 south reactor feed pump turbine. Is that a main feed pump
10 turbine?

11 MR. GREENMAN: Yes.

12 MR. REED: Then you have the condensate storage
13 tank. Are these safety-related pieces of equipment?

14 MR. GREENMAN: They are balance of plant
15 equipment. Feedwater pumps and turbines are not
16 safety-related. The same thing is true of the condensate
17 storage tank.

18 MR. REED: And they could run at 60 percent
19 power with that south reactor feed pump out of service?

20 MR. GREENMAN: They could run at reduced power
21 on one pump. However, I would emphasize that the
22 engineering repairs and the reviews of those repairs have
23 been completed and that is simply awaiting testing now to
24 return to service.

25 The same problem was not encountered on the

1 north feed pump. When we looked at all of the engineering
2 calculations, all of the alignments, they were all aligned
3 properly.

4 MR. REED: I am having a little problem why you
5 looked at all the engineering calculations on the pump. It
6 is not in the NRC jurisdiction, is it?

7 MR. GREENMAN: We have encountered a number of
8 problems with calculations at the Fermi station. That was
9 also the subject -- with respect to the south feedwater and
10 pump, that was also the subject of a specific allegation
11 that the NRR received from an outside source.

12 MR. REED: If it was an allegation, would it be
13 in your horizon?

14 MR. GREENMAN: As far as a regulatory
15 requirement, no, I don't have any regulatory requirement.

16 MR. REED: I know there is a study going on or
17 will be a study on regulatory involvement in balance of
18 plant. It seems to me that we are already involved. So
19 why the study?

20 MR. GREENMAN: I think we are already involved.
21 I think it is also of value to note that even though that
22 is nonsafety-related, every time you have a problem with
23 components of that type, you also put yourself at risk on
24 challenges to safety systems in the plant.

25 MR. REED: If you ran at 60 percent power, one

1 boiler feed pump.

2 MR. EBERSOLE: Loss of one source of coolant
3 water, you are not supposed to run that.

4 MR. REED: I am worried about empire building
5 here.

6 MR. EBERSOLE: If you only have one feed pump
7 continuously, wouldn't you worry about that?

8 MR. REED: I can look at these as indicators
9 that they have equipment trouble on the secondary side and
10 they have equipment trouble on the safety-related side.
11 But I worry that what we are doing is creating a stairway
12 to total involvement in, unto the toilet.

13 MR. EBERSOLE: On the other hand, the feedwater
14 system is an entity.

15 MR. REED: The reason I worry about it is
16 because I really think that the Nuclear Regulatory is over,
17 in over their heads a great deal right now. That if we
18 were to settle down to the real safety-related stuff and
19 stay with it and do it right, we wouldn't have any time to
20 be fiddling around in these other areas.

21 MR. EBERSOLE: If you did that, what you would
22 have is great safety stuff that would run every time you
23 needed it, every day.

24 MR. REED: Right. And that takes care of the
25 core and we wouldn't have any problems with the core.

1 MR. EBERSOLE: But every day is too often.

2 MR. KERR: I am going to urge that this
3 discussion continue.

4 MR. EBERSOLE: Thank you, sir.

5 MR. GREENMAN: Other problems that have been
6 encountered by the utility involve either an absence of
7 sufficient documentation at the time to support the reviews
8 of environmental qualifications and absence of
9 documentation to support the adequacy of seismic reviews,
10 absence of reviews and potential problems with the
11 calculation for concrete embedments and the hangers that
12 they are hooked to, which have a potential impact on safety
13 systems, problems with one of the RHR pumps, which appears
14 to be in one case a manufacturing defect, which has been
15 resolved with replacement of the motor. There is a
16 potentially generic issue there which the NRC is reviewing
17 on whether or not the laminated material was the correct
18 application.

19 MR. EBERSOLE: You are looking at this plant
20 pretty much the way Vogtle was being looked at for startup
21 readiness review.

22 MR. GREENMAN: Yes, sir. And in this case I
23 think it has been a combination of initiation on the part
24 of the NRC, various questions and problems identified and
25 then an approach by the licensee to resolve them.

1 MR. EBERSOLE: What is wrong with the remote
2 shutdown panel?

3 MR. GREENMAN: The problem with that, that
4 installation, that is what the October shutdown was
5 scheduled to do. The startup or the completion of the
6 outage was delayed when during the design reviews it was
7 identified that there was some inadequacies in a couple of
8 areas with separation and fire protection issues. And that
9 has been resolved and the last couple of modifications on
10 that particular issue are just undergoing a final details
11 design review right now.

12 The most recent development is a finding that
13 occurred in late January where changes, modifications,
14 stress reports and calculations to drawings were not
15 updated since September of 1984. The impact of this is not
16 fully known at this point in time. The licensee is doing
17 an extensive evaluation and will be meeting with the NRC
18 this Friday to discuss the results of their evaluation.

19 It did result in an immediate impact from the
20 standpoint of the Detroit Edison Company in declaring
21 certain systems inoperable. This involved fire protection
22 systems and ECCS systems.

23 MR. MICHELSON: What is the problem on the RHR
24 pump?

25 MR. GREENMAN: The RHR pump motor problem, there

1 was a seizure that broke off a couple of components in the
2 pump. It was shipped off-site and a spare motor from
3 Brown's Ferry was brought in.

4 MR. MICHELSON: This related to a bearing
5 clearance problem and so forth?

6 MR. GREENMAN: The initial installation, the
7 pressure plate when it was installed in the pressure
8 fingers were unbalanced on the Fermi pump and they broke
9 and that gave a short circuit in the motor. It is these.

10 MR. MICHELSON: The thrust bearing failed? Is
11 that what you are saying?

12 MR. GREENMAN: No. Not on the Fermi facility.
13 It was a problem in windings.

14 MR. MICHELSON: I am sorry. Okay. It is
15 entirely a motor problem.

16 MR. GREENMAN: Yes, sir.

17 MR. MICHELSON: That is not generic to any other
18 plant then?

19 MR. GREENMAN: Well, the use of an epoxy might
20 be generic to some other facilities. And the Office of
21 Inspection and Enforcement is looking at that right now.

22 MR. MICHELSON: I see. Thank you.

23 MR. EBERSOLE: Is that it?

24 MR. GREENMAN: On the technical issues
25 themselves.

1 Performance issues at the utility can be
2 characterized into several broad areas. Detroit Edison has
3 experienced a number of personnel errors; they have had
4 problems with implementation and direction of their
5 security program. While that particular topic was very
6 briefly addressed in their response to the 50.54 efforts, a
7 separate improvement program and a meeting will be held
8 with the NRC to discuss that. So their resolution of that
9 area is not known at this point in time.

10 An inability to disposition known problems, this
11 is all part and parcel of the engineering issues that we
12 have encountered. It is taking them a long time to resolve
13 the feedwater pump problem. It is taking them a long time
14 to resolve the diesel generator problem. It is taking them
15 a long time to work their way out of engineering
16 calculations and design reviews to satisfy themselves if
17 all of their initial reviews were adequate. On the up side
18 of that, to date none of the engineering reviews, reviews
19 that have been done, have resulted in any situation that
20 has required any hardware change at that plant. Phrasing
21 that another way is that there was no hardware impact as
22 the result of not doing the appropriate level of review or
23 not documenting the appropriate level of review to date.

24 Ineffective communications, I think the example
25 of the feedwater pump, I think problems with communications

1 that resulted in transfer of information with respect to
2 the premature criticality all fall into that arena.

3 To give you an idea of the personnel errors, we
4 did a review from March 20 to December 25 of the 78
5 licensee event reports. 41 of those involved personnel
6 errors. Taking two subsets of that, from July 10 through
7 September 10, nine of the 25 involved personnel errors;
8 from September to November 25, almost half, eight of the 17,
9 involved personnel errors.

10 Personnel errors in and of themselves on a new
11 plant, people don't always perform perfectly. It has
12 manifested itself at Fermi in a situation where there have
13 been multiple violations of technical specification
14 requirements, problems with meeting limiting conditions for
15 operations in one case it involved having an ECCS system
16 out of service.

17 MR. MICHELSON: Have you looked at other plants
18 from the viewpoint of seeing whether this number of
19 personnel errors in relation to total LERs is out of normal?

20 MR. GREENMAN: The number of personnel errors is
21 out of normal. I wouldn't be in a position to say that
22 total number of LERs for that time frame is out of normal.

23 MR. MICHELSON: You say that personnel error
24 were out of order. I was kind of under the impression that
25 about 40 percent of the LERs involve personnel error and

1 looking at your chart, about 40 percent of them involve
2 personnel error.

3 MR. GREENMAN: In some cases we have exceeded 50
4 percent.

5 MR. MICHELSON: Give or take 10 on something
6 like that is not unusual.

7 MR. GREENMAN: I think that figure is a figure
8 that you have to be careful for. I say that for this
9 reason: There is a disparity in the way licensees classify
10 personnel errors. And --

11 MR. MICHELSON: These are the new LERs we are
12 dealing with here. Whose classification of personnel error
13 are you using? The one on the data base that NRC maintains
14 or are you using the one off the LER?

15 MR. GREENMAN: The one off the LER.

16 MR. MICHELSON: If you use it off the sequence
17 coded data base, that is where the 40 percent numbers come
18 from?

19 MR. GREENMAN: That is correct.

20 MR. MICHELSON: That is not unusual to see that
21 high number of other plants. That is why I wondered why
22 Fermi is different.

23 MR. GREENMAN: It is unusual when you look at
24 what the personnel errors caused.

25 MR. MICHELSON: This is just a nose count here.

1 MR. GREENMAN: I am not trying to compare
2 utility A to utility B.

3 MR. MICHELSON: I was just trying to figure out
4 why Fermi was pointed out for this particular problem.

5 MR. GREENMAN: It is the types of personnel
6 errors.

7 Given all of this, in December of this year, the
8 NRC collective views of Region 3, NRR and IE, we issued a
9 50.54 letter to the utility requesting additional
10 information on how they would address certain issues. The
11 basic items that that particular letter addressed,
12 requested the utility to provide information on were the
13 adequacy of their management structures and systems to
14 operate the plant, the actions that they had taken and
15 planned to take to insure their readiness to restart and
16 support power ascension to operate the plant, and what
17 short-term and long-term actions they plan to take to
18 improve not only their regulatory performance but their
19 operational performance.

20 The licensee responded formally by letter,
21 January 29 of this year, and acknowledged that there was a
22 need for improvement.

23 The basic bullets that were contained in their
24 response were as follows: The chief executive officer,
25 chairman of the board, in conversations with Region 3 and

1 in his letter, assumed the direct management and control to
2 support the restart effort. As a matter of fact, he is
3 planning as chairman of the board to spend three to four
4 mornings a week at that plant. He also directed the
5 president of the company to oversee the quality assurance
6 program as another senior manager.

7 He tasked the organization to form an
8 independent overview committee consisting of outside
9 consultants, including a member of the MAC organization
10 that had been on site before, to independently make
11 recommendations to him and to the board of directors. That
12 oversight committee held their first meeting and briefing
13 on February 7 a week ago last Friday. We are expecting to
14 have a copy of their report shortly. We don't have it at
15 this date so I don't have any information as to what the
16 overview committee told the board of directors and the
17 chairman.

18 He has also established a reactors operations
19 improvement plan which contains some 60-odd different areas
20 which the utility has addressed to improve all aspects of
21 their operation. A number of those have been completed and
22 are under review by the Region 3 office. That particular
23 program is in place.

24 MR. EBERSOLE: Is there anything like a safety
25 review staff like we hear about with TVA that is

1 contemplated?

2 MR. GREENMAN: Not what I would characterize as
3 a safety -- the independent oversight committee, but not a
4 safety review staff that goes beyond the normal
5 organization.

6 There have been some managerial changes that
7 have been made to strengthen their performance and there
8 are more contemplated. As an example, the utility is going
9 outside to seek a senior vice presidential level type
10 individual to move into that organization. That would
11 result in a pyramid of almost two-on-one senior vice
12 presidents on-site reporting to the corporate office. Both
13 in the engineering support as well as operations.

14 The utility is also developing a nuclear
15 operations improvement plan with full implementation of
16 that anticipated in May of this year.

17 One thing that is significant, in order to go into
18 a power escalation phase, the combination of
19 recommendations from the on-site management organizational
20 structures, the combinations of recommendations and changes
21 that are put in place and accepted from the overview
22 committee will all be given to the chief executive officer
23 and he will personally authorize any change in power.

24 MR. REED: I am sitting here having some deep
25 thoughts about what I see up here. The CEO of this company

1 is a long time involved, old-time nuclear person. We won't
2 mention any names. That company established years ago a
3 safety review board right at the top, very top level of the
4 company and had a nationally known person who was a member
5 of the board with the CEO as president. It also had an
6 in-between plateau of safety experts and reviewers who met
7 on a regular basis. What I see up here is more of the same.
8 I would be looking for a different solution. It seems to
9 me over the years they have had all this stuff with great
10 coupling and nationally known people and so on. Maybe
11 there is something different rather than more plateaus and
12 reshuffling of review boards and things like that.

13 I have to say that I may have a slight conflict
14 of interest here. I did serve for a short term on one of
15 their boards. Then I unfortunately made the mistake of
16 joining the ACRS. So do you think this is going to
17 determine something or improve something? To me, I am
18 quizzical.

19 MR. GREENMAN: I think the fact that the Detroit
20 Edison Company perceives that strengthening of management
21 controls are needed is positive. I think the fact that
22 they have established an independent overview group is
23 positive. I am not of the opinion, based on the results
24 that we have seen to date -- and part of this program is
25 very, very new -- that the problems are solved at Fermi.

1 They have identified a number of goals.

2 MR. REED: They are the company that in addition
3 -- which I thought was way up front in management -- they
4 are the company that put all their offices on the job site
5 in a special building and only a mile away from the plant.
6 What I would think from my recollection is that this thing
7 was just overloaded with management review and attention
8 and so on. Is there something fundamental here that maybe
9 is related to their large number of LERs or human errors or
10 something?

11 MR. KERR: Wait a minute. We don't necessarily
12 have a large number of LERs.

13 MR. REED: The proportions are the same.

14 MR. GREENMAN: I think I can only respond that
15 given all of that, their performance has been disappointing.

16 MR. EBERSOLE: Can you come in on the
17 accountability problem. Who is in charge of what? Can you
18 check back to the accountability locus in this
19 organizational structure?

20 MR. GREENMAN: I think accountability, I think
21 accountability, it is clear that accountability and where
22 accountability rests in response to the 50.54 letter, I
23 think it was clear that accountability was established
24 between engineering organizations and operational
25 organizations at the time the facility was licensed. It is

1 not clear that communications were adequate. It is not
2 clear that the organizations talked to each other properly.

3 MR. EBERSOLE: That is the perennial problem:
4 Who is in charge of that?

5 MR. REED: I just can't figure this out. These
6 people were the first people to put their total engineering
7 and offices on the job site right at the plant. All kind
8 of company were supposed to be there, if I was an
9 inspection person, I would be looking for some key here.
10 If they in fact have gotten more real problems than they
11 should have at this point in time.

12 We talked about River Bend. It is a boiling
13 water reactor and somebody said, they have got a lot of
14 problems. We tried to explain that away. But here is
15 another boiling water reactor, perhaps a little earlier
16 vintage. I am not saying it is reactor-related. You look
17 at the diesels, hey, we know what that is related to:
18 lousy manufacturing and design. And that is throughout the
19 industry. Maybe if you threw away some of these
20 discardable aspects, you could get down to whether or not
21 they need to do a complete reorganization of what looked to
22 be outstanding at one time.

23 I could throw in the other thing, do they use
24 aptitude testing for their rank and file people and their
25 management?

1 MR. EBERSOLE: Is that it?

2 Any further comments?

3 Let me make a proposal to shorten this meeting
4 by asking Ron Hernan a question. I believe we are going to
5 be obligated to take the tech spec improvement program to
6 the full committee in any case. And that your observations
7 on it will be just as comprehensive then as they would be
8 now.

9 MR. HERNAN: The way it is, there is agreement,
10 the leader of the tech spec improvement group will be here
11 Friday with his people to make the presentation.

12 MR. MICHELSON: How much time is he going to
13 have?

14 MR. HERNAN: We would like to have a half hour
15 for him.

16 MR. EBERSOLE: Since we have an hour and a half
17 anyway.

18 MR. MICHELSON: Are we going to get the fire
19 protection questions out of the way at that time then?
20 They have questions on fire protection in tech spec changes?

21 MR. HERNAN: I personally don't think we are
22 going to get into that much detail.

23 MR. MICHELSON: Well, when are we going to hit
24 it?

25 MR. HERNAN: Our purpose of being here today and

1 Friday is to follow up on Harold Denton's comments to the
2 full committee last month.

3 MR. MICHELSON: I thought this was following up
4 on my request.

5 MR. HERNAN: Mr. Denton said that we are kind of
6 at a milestone point in the tech spec program and we will
7 come down and tell the committee.

8 MR. MICHELSON: I had some concerns on taking
9 the fire protection aspects out of the tech specs and I
10 guess putting them back in to the FSAR itself somehow, and
11 how this was going to work in view of the kind of details
12 associated with fire protection tech specs.

13 MR. HERNAN: We may be able to address that
14 question fairly simply on Friday. There is some discussion
15 in the Commission paper which we --

16 MR. MICHELSON: That wasn't too hopeful. I
17 don't think they have much details understood of what a
18 fire protection tech spec was.

19 MR. EBERSOLE: Let me poll the full committee
20 for a second. We have an internal conference going on.

21 MR. MICHELSON: Let's ignore them.

22 MR. EBERSOLE: I am granting a 30-minute
23 presentation for the tech specs Friday, okay?

24 MR. HERNAN: Okay.

25 MR. EBERSOLE: We will put out a block of time

1 for a half an hour or so for that. There are three other
2 topics then that I have marked which I am going to suggest
3 we carry to tech specs, that is McGuire, Turkey Point, ANO
4 1. And they will get about 10 to 15 minutes apiece. That
5 will leave ample time to cover the tech specs.

6 MR. REED: I thought we had McGuire,
7 Brunswick --

8 MR. EBERSOLE: We have McGuire, Brunswick, and
9 ANO 1.

10 MR. REED: Yes.

11 MR. EBERSOLE: And that is it. We are going to
12 automatically get Perry, the earthquake, the prior day.
13 That ought to do it. Any further comments? No further
14 comments?

15 MR. HERNAN: On Brunswick and ANO 1, you do not
16 need a staff presentation for that?

17 MR. EBERSOLE: No.

18 MR. HERNAN: So you need staff on McGuire and
19 Turkey Point.

20 MR. EBERSOLE: Yes.

21 MR. ALLISON: No staff on ANO 1?

22 MR. EBERSOLE: Let's see. That is a design
23 deficiency. I didn't say any staff support on that. That
24 is that single failure design problem. I think we can just
25 get staff support on that.

1 MR. HERNAN: We -- you decided earlier in the
2 meeting that we didn't need it.

3 MR. EBERSOLE: That is the single failure --

4 MR. REED: What we said was, have a full
5 committee quick statement of the complexity and
6 vulnerability of auxiliary feed and whether or not maybe we
7 ought to be thinking beyond auxiliary feed.

8 MR. KERR: Do you want all this recorded?

9 MR. EBERSOLE: Off the record.

10 (Whereupon, at 6:00 p.m., the meeting was
11 concluded.)

12

13

14

15

16

17

18

19

20

21

22

23

24

25

CERTIFICATE OF OFFICIAL REPORTER

This is to certify that the attached proceedings before the UNITED STATES NUCLEAR REGULATORY COMMISSION in the matter of:

NAME OF PROCEEDING: ADVISORY COMMITTEE ON REACTOR SAFEGUARDS
SUBCOMMITTEE ON REACTOR OPERATIONS

DOCKET NO.:

PLACE: WASHINGTON, D. C.

DATE: WEDNESDAY, FEBRUARY 12, 1986
:

were held as herein appears, and that this is the original transcript thereof for the file of the United States Nuclear Regulatory Commission.

(sig) Rebecca E. Eyster
(TYPED)

REBECCA E. EYSTER

Official Reporter
ACE-FEDERAL REPORTERS, INC.
Reporter's Affiliation

NRR STAFF PRESENTATION TO THE ACRS

SUBJECT: PERRY EARTHQUAKE

DATE: January 31.1986

PRESENTER: JOHN J. STEFANO

PRESENTER'S TITLE/BRANCH/DIV: PROJECT MANAGER/PD#4/DBL/NRR

PRESENTER'S NRC TEL. NO.: 492-9473

SUBCOMMITTEE: OPERATIONS

- RESULTS OF INDEPENDENT NRC WALKDOWN OF PLANT - CONFIRMS CEI FINDINGS OF NO SIGNIFICANT PLANT DAMAGE
- NRC ASSESSMENT OF EVENT IN EARLY STAGE OF REVIEW - ACTIONS PLANNED ARE:
 - CHARACTERIZING EARTHQUAKE TO REAFFIRM SEISMOLOGIC/ GEOLOGIC ASSUMPTIONS USED FOR PLANT DESIGN BASIS AS DESCRIBED IN FSAR/SER
 - STRUCTURAL DESIGN REVIEW:
 - COMPARISON OF MEASURED/PREDICTED RESPONSES
 - EFFECT/IMPACT OF SHORT DURATION/HI FREQUENCY EXCEEDANCE OF DESIGN BASIS SPECTRA ON STRUCTURES
 - PIPING/EQUIPMENT DESIGN REVIEW:
 - COMPARISON OF MEASURED/DESIGN BASIS SEISMIC LOADS
 - EFFECT AND QUANTITATIVE ASSESSMENT OF IMPACT OF SHORT DURATION/HI FREQUENCY EXCEEDANCE ON PLANT PIPING/EQUIPMENT
- SCHEDULED ACTIONS
 - NRC STAFF/CONSULTANTS PRELIM. FINDINGS/DATA NEEDS 2/21/86
 - PERRY SPECIFIC DESIGN BASIS
 - OTHER RECOMMENDED GENERIC ACTIVITIES
 - SSER ISSUED 3/7/86
 - PERRY 1 LICENSING TARGET 3/14/86

PROPOSED REVISION OF 10 CFR PART 20

"STANDARDS FOR PROTECTION AGAINST RADIATION"

ROBERT E. ALEXANDER

CHIEF, HEALTH EFFECTS AND OCCUPATIONAL RADIATION PROTECTION

OFFICE OF NUCLEAR REGULATORY RESEARCH

JANUARY 16, 1986

REASONS FOR REVISING PART 20

- o UPDATE PRESENT PART 20 PROMULGATED IN 1957
- o IMPLEMENT APPROPRIATE CURRENT RECOMMENDATIONS OF ICRP
- o IMPLEMENT EPA PROPOSED FEDERAL RADIATION PROTECTION GUIDANCE FOR OCCUPATIONAL EXPOSURES
- o IN GENERAL --
 - TO ESTABLISH A SCIENTIFICALLY SOUND AND EXPLICIT HEALTH PROTECTION BASIS FOR PART 20 STANDARDS AND OTHER NRC REGULATORY ACTIONS

NEEDED IMPROVEMENTS IN THE PRESENT PART 20

- o UNIFORM RISK BASED STANDARD FOR DOSE & OTHER LIMITS
- o UPDATE NUCLIDE INTAKE LIMITS (MPC'S)
- o DELETE 5(N-18) RULE PERMITTING 12 REMS/YR
- o INTEGRATED LIMITS FOR INTERNAL AND EXTERNAL DOSES
ESPECIALLY IMPORTANT FOR NMSS LICENSEES
- o PROVIDE EXPLICIT DOSE LIMITS FOR MEMBERS OF THE PUBLIC
- o PROVIDE A CUTOFF ON COLLECTIVE DOSE (PERSON-REM) CALCULATIONS RATHER THAN
INTEGRATE OVER INFINITE TIME AND SPACE

RISK COMPARISON: CURRENT 10 CFR PART 20 AND ICRP 26

1. CURRENT 10 CFR PART 20 PERMITS EXTERNAL WHOLE BODY DOSE OF 5 REM/YEAR (IN CERTAIN INSTANCES UP TO 12 REM/YEAR) AND IN ADDITION 15 REM/YEAR TO ANY ORGAN FROM INTERNALLY DEPOSITED RADIONUCLIDES (30 REM/YEAR TO BONE AND THYROID, 5 REM/YEAR TO GONADS).
2. ONLY THE DOSE TO THE ORGAN RECEIVING THE MAXIMUM DOSE (THE "CRITICAL ORGAN") IS LIMITING. RISKS TO ORGANS RECEIVING LOWER DOSES FROM THE SAME RADIONUCLIDE INTAKE ARE NOT CONSIDERED.
3. ICRP-26 LIMITS THE DOSE FROM ALL SOURCES: EXTERNAL PLUS INTERNAL (CONSIDERING ALL IRRADIATED ORGANS) TO 5 REM/YEAR "EFFECTIVE". 5 REM/YEAR "EFFECTIVE" MEANS THAT THE TOTAL RISK TO THE INDIVIDUAL EQUALS TO RISK FROM 5 REM/YEAR FROM EXTERNAL RADIATION ALONE.
4. THE PARAMOUNT CONSIDERATION IS THE RISK TO AN INDIVIDUAL AND NOT THE DOSE TO A SINGLE ORGAN. IF ONLY A SINGLE ORGAN IS IRRADIATED, HIGHLY UNLIKELY IN PRACTICE, THE ICRP DOSE LIMITS FOR THAT ORGAN ARE IN CERTAIN CASES HIGHER THAN PERMITTED BY CURRENT 10 CFR PART 20. THE RISK UNDER THOSE LIMITS, HOWEVER, NEVER EXCEEDS THAT OF 5 REM/YEAR OF EXTERNAL WHOLE BODY IRRADIATION.
5. IN ACTUAL CASES WHERE MULTIPLE ORGANS ARE IRRADIATED, FROM INTERNAL AND EXTERNAL RADIATION, THE TOTAL EFFECTIVE DOSE AND THE RISK WILL BE LOWER UNDER ICRP-26 SYSTEM OF DOSE LIMITATION.

RISK COEFFICIENTS COMPARISON

ICRP 26

CANCER

MODEL USED: LINEAR
ABSOLUTE PROJECTION

RISK PER REM

12.5×10^{-5}

GENETIC EFFECTS
(FIRST TWO GENERATIONS)

4×10^{-5}

BEIR III

CANCER

MODELS PRESENTED: LINEAR
ABSOLUTE PROJECTION

16.7×10^{-5}

LINEAR
RELATIVE PROJECTION

50.1×10^{-5}

LINEAR QUADRATIC
ABSOLUTE PROJECTION

7.7×10^{-5}

LINEAR QUADRATIC
RELATIVE PROJECTION

22.6×10^{-5}

GENETIC EFFECTS
(FIRST TWO GENERATIONS)

3×10^{-5}

NOTE: ALL MODELS ASSUME "NO THRESHOLD"

BRIEF HISTORY OF RULEMAKING

- o 1977 PUBLICATION OF ICRP-26
- o 1979 NMSS MEMO TO RES SUGGESTED REVISION OF PART 20
- o INTEROFFICE WORKING GROUP, SCOPED EFFORT, IDENTIFIED ISSUES
- o MARCH 1980 ANPR
- o ESTABLISHMENT OF DRAFTING GROUP
- o EPA DRAFT GUIDANCE ON OCCUPATIONAL EXPOSURES -- SECY-81-232 & COMMISSION RESPONSE
- o MEETINGS WITH INTERESTED PARTIES
- o NCRP/ACRS RECOMMEND WAITING FOR NCRP RECOMMENDATIONS, NEG. EDO RESPONSE
- o INTERNAL NRC REVIEW, COMMENT, CONCURRENCE

ICRP-26 SYSTEM OF DOSE LIMITATION

- o JUSTIFICATION OF ANY RADIATION EXPOSURE
- o OPTIMIZATION OF RADIATION PROTECTION
- o LIMITATION OF DOSES
 - "EFFECTIVE DOSE EQUIVALENT" CONCEPT
 - COMBINES INTERNAL AND EXTERNAL DOSES
 - INCLUDES ALL ORGANS, WEIGHTING FACTORS
 - BASED ON RISK

MAJOR CHANGES IN PROPOSED REVISION

EXTERNAL OCCUPATIONAL DOSE LIMITS, WHOLE BODY

1.25 REMS/QTR

3 REMS/QTR

AND

5 REMS/YR

OR

AND

CHANGE TO

3 REMS/QTR AND

"PLANNED SPECIAL EXPOSURES"

5 REMS/YR AVERAGE

5 ADDITIONAL REMS/YR

WITH SPECIAL JUSTIFICATION

5(N - 18) FORMULA

25 REMS LIFETIME LIMIT FOR SUCH
EXPOSURES

0 SLIGHTLY MODIFIED ICRP-26 CONCEPT

ANNUAL LIMIT INCLUDES INTERNAL DOSE

OTHER EXTERNAL OCCUPATIONAL DOSE LIMITS

EXTREMITIES:	18-3/4	REMS/QTR	<u>CHANGE TO</u>	50	REMS/YR
SKIN:	7-1/2	REMS/QTR	<u>CHANGE TO</u>	50	REMS/YR
LENS: *	1.25	REMS/QTR, OR	<u>CHANGE TO</u>	15	REMS/YR
	3	REMS/QTR AND			
	5	REMS/YR AVERAGE			

0 CHANGES FULLY CONSISTENT WITH ICRP-26

* TREATED AS PART OF WHOLE BODY

INTERNAL OCCUPATIONAL DOSE LIMITS

QUARTERLY INTAKE LIMITS FOR EACH NUCLIDE

CHANGE TO

ANNUAL INTAKE LIMITS FOR
EACH NUCLIDE

(COMPLIANCE PREVENTS MOST HIGHLY EXPOSED
ORGAN FROM EXCEEDING ITS OLD ICRP DOSE LIMIT)

(COMPLIANCE PREVENTS RISK
TO ALL AFFECTED ORGANS
FROM EXCEEDING THAT FROM
5 REMS/YR TO WHOLE BODY)

LIMITS MUST INCLUDE
EXTERNAL DOSE

0 CHANGES FULLY CONSISTENT WITH ICRP-26

INTERNAL OCCUPATIONAL DOSE CONTROL

- 0 CHANGES WOULD PRIMARILY AFFECT NMSS LICENSEES
- 0 RISK FROM AIRBORNE NUCLIDES AT NPP'S IS SMALL (98% ORGAN BURDENS < 2% OF PERMISSIBLE)
- 0 INTAKE LIMITS FOR SOME NUCLIDES WOULD BE LOWERED, PRIMARILY ALPHA EMITTERS
ENCOUNTERED IN NMSS-LICENSED FACILITIES, E.G. URANIUM - FACTOR OF 6,
THORIUM - FACTOR OF 60,
AMERICIUM - FACTOR OF 50
- 0 INTAKE LIMITS FOR SOME NUCLIDES WOULD BE INCREASED, PRIMARILY BETA EMITTERS
- 0 SPECIAL PROVISIONS IN REVISED PART 20 FOR ALPHA EMITTERS DIFFICULT TO MEASURE AT
NEW LIMITS (ANNUAL DOSE CONTROL RATHER THAN 50-YEAR INTEGRATED DOSE)
- 0 ALL CHANGES CONSISTENT WITH ICRP-26

OCCUPATIONAL ALARA CONCEPT

§20.1 (c) SAYS EXPOSURES
SHOULD BE MAINTAINED ALARA

CHANGE TO

REQUIREMENT TO DEVELOP,
DOCUMENT AND IMPLEMENT A
RADIATION PROGRAM THAT
INCLUDES ALARA

INVESTIGATION LEVELS

CONCEPT NOT USED IN PRESENT
PART 20

CHANGE TO

INVESTIGATION LEVELS BELOW
REGULATORY LIMITS REQUIRED --
SET BY LICENSEE

DE MINIMIS EXPOSURE LEVELS

PRESENT PART 20 SETS LEVELS
BELOW WHICH CERTAIN REQUIREMENTS
DO NOT APPLY: THESE LEVELS
ESTABLISH CONTROL POINTS, NOT
TRIVIALITY

RETAIN SIMILAR
LEVELS BUT ADD:

PROPOSED PART 20 WOULD SET A
CUT OFF LEVEL OF 1 MREM FOR
COLLECTIVE DOSE CALCULATIONS

NO DE MINIMIS LEVEL IS PROPOSED
FOR INDIVIDUAL WORKER EXPOSURES

UK NATIONAL RADIOLOGICAL PROTECTION
BOARD IN JANUARY 1985 ADVISED USE
OF THE FOLLOWING DE MINIMIS LEVELS:

5 MREM/YR INDIVIDUAL MEMBERS OF
THE PUBLIC (1% OF ANNUAL
DOSE LIMIT FOR PUBLIC)

0.5 MREM/YR WHERE THE INDIVIDUAL MAY
BE EXPOSED TO SEVERAL
"DE MINIMIS" SOURCES

PROTECTION OF THE PUBLIC

RADIATION LEVELS IN UNRESTRICTED AREAS

PRESENT PART 20 (TO AN INDIVIDUAL):

- 2 MREMS IN ANY HOUR
- 100 MREMS IN ANY 7 DAYS
- 500 MREMS IN A CALENDAR YR
(IMPLIED)

RADIOACTIVITY IN EFFLUENTS

PRESENT PART 20 (ANY TYPE FACILITY):

- PRESCRIBED CONCENTRATION VALUES,
AVERAGED OVER 1 YR
- ADDITIONAL LIMITATIONS IF FOOD
PATHWAY INCREASES DAILY INTAKE
- COMPLIANCE WITH 40 CFR PART 190
REQUIRED OF FUEL CYCLE/LWR LICENSEES

RADIATION LEVELS AND RADIOACTIVITY CONCENTRATIONS IN UNRESTRICTED AREAS

- 500 MREMS/YR, EXPLICIT, EFFECTIVE
DOSE FROM ALL EXTERNAL/INTERNAL
SOURCES
- 100 MREM/YR REFERENCE LEVEL

CHANGE TO

- PRESCRIBED CONCENTRATION VALUES
MODIFIED AND RETAINED

CONTROVERSIAL ISSUES

IN THE PROPOSED

10 CFR PART 20

- PROTECTION OF EMBRYO/FETUS
- DE MINIMIS LEVELS
- ANNUAL EXPOSURE REPORTS
- OPTIONAL IMPLEMENTATION PERIOD
- COMMITTED VS. ANNUAL DOSE

PROTECTION OF AN EMBRYO/FETUS

ISSUE: PROTECTION OF AN EMBRYO/FETUS AGAINST OCCUPATIONAL
RADIATION EXPOSURE OF PREGNANT WORKER.

EFFECTS OF MATERNAL FACTORS ON PREGNANCY OUTCOME

<u>FACTOR</u>	<u>EFFECT</u>	<u>NUMBER OCCURRING FROM NATURAL CAUSES</u>	<u>EXCESS OCCURRENCES DUE TO MATERNAL FACTOR</u>
<u>RADIATION RISK</u>			
<u>CHILDHOOD CANCER</u>			
RADIATION DOSE OF 1000 MILLIREMS RECEIVED BEFORE BIRTH	CANCER DEATH	1200 PER MILLION	600 PER MILLION
<u>ABNORMALITIES</u>			
A. RADIATION DOSE OF 1000 MILLIRADS RECEIVED DURING SPECIFIC PERIODS AFTER CONCEPTION.			
4-7 WEEKS	SMALL HEAD SIZE	40 PER THOUSAND	5 PER THOUSAND
8-11 WEEKS	" " "	40 PER THOUSAND	9 PER THOUSAND
B. RADIATION DOSE OF 1000 MILLIRADS RECEIVED DURING THE FOLLOWING PERIOD AFTER CONCEPTION			
8-15 WEEKS	MENTAL RETARDATION	4 PER THOUSAND	4 PER THOUSAND

EFFECTS OF MATERNAL FACTORS ON PREGNANCY OUTCOME (CONT.)

<u>FACTOR</u>	<u>EFFECT</u>	<u>NUMBER OCCURRING FROM NATURAL CAUSES</u>	<u>EXCESS OCCURRENCES DUE TO MATERNAL FACTOR</u>
<u>NONRADIATION RISKS</u>			
<u>OCCUPATION</u>			
WORK IN HIGH RISK OCCUPATIONS	STILLBIRTH OR SPONTANEOUS ABORTION	200 PER THOUSAND	90 PER THOUSAND
<u>ALCOHOL CONSUMPTION</u>			
2-4 DRINKS PER DAY	FETAL ALCOHOL SYNDROME	1-2 PER THOUSAND (TOTAL BIRTHS)	100 PER THOUSAND
4-10 DRINKS PER DAY	FETAL ALCOHOL SYNDROME	1-2 PER THOUSAND (TOTAL BIRTHS)	200 PER THOUSAND
MORE THAN 10 DRINKS PER DAY (CHRONIC ALCOHOLIC)	FETAL ALCOHOL SYNDROME	1-2 PER THOUSAND (TOTAL BIRTHS)	350 PER THOUSAND
MORE THAN 10 DRINKS PER DAY (CHRONIC ALCOHOLIC)	PERINATAL	23 PER THOUSAND	170 PER THOUSAND

EFFECTS OF MATERNAL FACTORS ON PREGNANCY OUTCOME (CONT.)

<u>FACTOR</u>	<u>EFFECT</u>	<u>NUMBER OCCURRING FROM NATURAL CAUSES</u>	<u>EXCESS OCCURRENCES DUE TO MATERNAL FACTOR</u>
<u>SMOKING</u>			
-	BABIES AT BIRTH TEND TO WEIGH' LESS THAN BABIES OF NON SMOKERS	-	-
LESS THAN 1 PACK PER DAY	PERINATAL INFANT DEATH	23 PER THOUSAND	5 PER THOUSAND BIRTHS
ONE PACK OR MORE PER DAY	PERINATAL INFANT DEATH	23 PER THOUSAND	10 PER THOUSAND BIRTHS

PROTECTION OF EMBRYO/FETUS
PRINCIPAL ALTERNATIVES

- INFORMED CONSENT (PRESENT NRC POSITION)
 - ONUS FOR PROTECTION ON WORKER
- LOWER DOSE LIMIT FOR ALL WORKERS
 - HIGHER COLLECTIVE DOSES AND COSTS
- LOWER DOSE LIMIT FOR ALL WOMEN
 - JOB DISCRIMINATION, INAPPROPRIATE LIMIT FOR SOME WOMEN
- LOWER DOSE LIMIT FOR FERTILE WOMEN
 - JOB DISCRIMINATION, INVASION OF PRIVACY
- LOWER DOSE LIMIT FOR WOMEN KNOWN TO BE PREGNANT
 - JOB DISCRIMINATION, INVASION OF PRIVACY, MODERATE OVEREXPOSURE POTENTIAL
 - ONUS FOR PROTECTION ON EMPLOYER
- LOWER DOSE LIMIT FOR WOMEN DECLARED TO BE PREGNANT
 - JOB DISCRIMINATION, HIGHER OVEREXPOSURE POTENTIAL
 - ONUS FOR DECLARATION ON WORKER

EPA IS PROPOSING THE FINAL ALTERNATIVE IN NEW GUIDANCE TO FEDERAL AGENCIES

PROPOSED EMBRYO/FETUS LIMIT

- PROVIDES DOSE LIMIT OF 0.5 REM TO EMBRYO/FETUS FOR ENTIRE GESTATION PERIOD.
- DECLARATION OF PREGNANCY WOULD BE VOLUNTARY.
- ONCE DECLARED, THE RESPONSIBILITY OF MEETING LIMIT WOULD SHIFT TO LICENSEE.
- AN ADDITIONAL 0.05 REM TO THE EMBRYO/FETUS PERMITTED IF EMBRYO/FETUS LIMIT HAS BEEN EXCEEDED BEFORE DECLARATION OF PREGNANCY.
- WOMEN WHO CHOSE NOT TO DECLARE THEIR PREGNANCIES WILL BE SUBJECT TO THE SAME OCCUPATIONAL LIMITS AS ANY OTHER NUCLEAR WORKER.
- CONSISTENT WITH EPA PROPOSED FEDERAL GUIDELINES, NCRP, ICRP, PREVIOUS COMMISSION GUIDANCE AND OTHER FEDERAL AGENCIES.

IF MINIMUM LEVELS

- ISSUES:
1. SHOULD CALCULATIONAL "CUTOFF" LEVEL FOR COLLECTIVE DOSE ASSESSMENTS BE ESTABLISHED?
 2. IF ESTABLISHED, AT WHAT LEVEL SHOULD THE CUTOFF BE SET?

USE OF DE MINIMIS DOSE CONCEPT

- * GENERALLY, DE MINIMIS DOSE MEANS A DOSE WHICH HAS AN ATTENDANT RISK SO LOW THAT IT DOES NOT WARRANT REGULATORY ATTENTION.
- * THERE ARE MANY POTENTIAL APPLICATIONS OF DE MINIMIS CONCEPT.
- * NEITHER EXISTING NOR PROPOSED FEDERAL GUIDANCE INCLUDES ANY APPLICATION OF DE MINIMIS CONCEPT.
- * DE MINIMIS DOSE CONCEPT IN PROPOSED 10 CFR PART 20 REVISION IS VERY LIMITED - ONLY FOR CALCULATIONAL "CUTOFF" FOR COLLECTIVE DOSE ASSESSMENTS.
- * COLLECTIVE DOSE ASSESSMENTS ARE A MAJOR CONSIDERATION IN DECISIONS ABOUT:
 - BALANCE BETWEEN INDIVIDUAL DOSE AND POPULATION DOSE IN DETERMINING ALARA.
 - CHOICES AMONG AVAILABLE OPTIONS FOR PROVIDING RADIATION PROTECTION.

DE MINIMIS LEVELS IN UNITED KINGDOM

- 5 MREMS/YR, INDIVIDUAL DOSE FROM ALL NON-MEDICAL, CONTROLLED SOURCES (RISK OF 10^{-6} /YR, MORTALITY)
- 0.5 MREM/YR, INDIVIDUAL DOSE FROM ANY ONE NON-MEDICAL, CONTROLLED SOURCE
- INDIVIDUAL DOSES LESS THAN 0.5 MREM/YR NOT INCLUDED IN COLLECTIVE DOSE ESTIMATES USED FOR APPROVAL PURPOSES IF COLLECTIVE DOSE IS LESS THAN 100 PERSONREMS

THESE LEVELS WILL AFFECT:

- GOVERNMENT APPROVALS
- DESIGN AND PLANNING
- OPERATIONS
- WASTE MANAGEMENT
- DECOMMISSIONING
- THE DEGREE OF REASON EMPLOYED IN RADIATION PROTECTION
- UNNECESSARY EXPENDITURE OF RESOURCES
- DECISIONS OTHERWISE AFFECTED UNDULY BY TRIVIAL CONCERNS
- EXAGGERATED PROTECTIVE MEASURES THAT EXACERBATE OTHER HAZARDS
- PUBLIC UNDERSTANDING THAT RADIATION RISK IS DOSE-DEPENDENT

PROPOSED RULE IN PART 20 WOULD ALLOW A 1 MREM/YR CUT OFF IN COLLECTIVE DOSE CALCULATIONS (QUASI DE MINIMUS LEVEL)

QUASI DE MINIMIS RULE IN PROPOSED 10 CFR PART 20

- 1 MREM/YR CUT OFF IN COLLECTIVE DOSE CALCULATIONS MADE TO OBTAIN NRC APPROVALS (COMPARABLE UK LEVEL IS 0.5 MREM/YR)
- WOULD ELIMINATE CONSIDERATION OF VERY LOW DOSES DELIVERED AT VERY LOW DOSE RATES OVER EXTREMELY LONG PERIODS OF TIME TO EXTREMELY LARGE NUMBERS OF PEOPLE
- COLLECTIVE DOSES CALCULATED FROM INDIVIDUAL DOSES LESS THAN 1 MREM/YR ARE A HIGH PERCENTAGE OF THE TOTAL
- RISKS ASSOCIATED WITH 1 MREM/YR OR LESS SHOULD BE OF NO CONCERN TO THE EXPOSED INDIVIDUAL (ONE-FIFTH OF THE COMPARABLE LEVEL ADOPTED IN UK), ARE TRIVIAL WITH RESPECT TO REGULATORY CONCERN, AND SHOULD NOT AFFECT DECISION-MAKING PROCESSES
- IF A LONG-LIVED RADIONUCLIDE WERE RELEASED SUCH THAT EVERY US CITIZEN CONTINUOUSLY RECEIVED 1 MREM/YR (WORST CASE), THE THEORETICAL NUMBER OF PREMATURE DEATHS PER YEAR WOULD BE ABOUT 21 IN A POPULATION OF 220,000,000 PEOPLE.
- THE US DEATH RATE FROM CANCER IS ABOUT 400,000 PER YEAR AND FROM ALL CAUSES IS ABOUT 2,000,000 PER YEAR.

WHY ESTABLISH CALCULATIONAL CUTOFF DOSE?

- ° WILL PROVIDE A CONSISTENT BASIS FOR LIMITING THE EXTENT OF ASSESSMENT OF COLLECTIVE DOSES.
- ° WILL REDUCE SUBJECTIVITY OF UNIFORMS AND UNCERTAINTIES LEADING TO POTENTIALLY INCORRECT JUDGMENTS:
 - UNCERTAINTIES ASSOCIATED WITH DISTANCES FAR FROM THE SOURCE.
 - UNCERTAINTIES ASSOCIATED WITH LONG PERIODS OF TIME.
 - VANISHINGLY SMALL RISKS TO THE EXPOSED INDIVIDUAL, I.E., DE MINIMIS.
- ° WILL SIGNIFICANTLY REDUCE RESOURCE COMMITMENTS.

APPLICATION OF DE MINIMIS CONCEPT TO INDIVIDUALS

- WOULD ESTABLISH ANNUAL DOSE LEVEL SO SMALL THAT INDIVIDUALS USUALLY WOULD NOT CONSIDER THE RISK IN ARRIVING AT DECISIONS REGARDING THEIR ACTIONS.
- APPLICATIONS WOULD BE MUCH BROADER THAN CALCULATIONAL "CUTOFF".
- NO REGULATORY ACTIONS WOULD BE IMPOSED FOR DOSES BELOW THIS LEVEL.
- COST REDUCTIONS WOULD BE APPRECIABLE (E.G., RADWASTE DISPOSAL, EFFLUENT PROCESSING).
- WAS CONSIDERED DURING DEVELOPMENT OF PROPOSED RULE.
- COULD RESULT IN:
 - UNAPPROVED INCORPORATION OF RADIOACTIVE MATERIALS INTO CONSUMER PRODUCTS.
 - RELEASE OF VERY LOW-LEVEL WASTE STREAMS WITHOUT EVALUATION.
 - RAISING LEVELS, AS IN NPP TECHNICAL SPECIFICATIONS, AT WHICH CERTAIN CONTROLS OR EQUIPMENT MUST BE INSTALLED OR OPERATED.
- SUPPLEMENTAL INFORMATION OF PROPOSED RULE DISCUSSES AND SPECIFICALLY REQUESTS COMMENTS.

STAFF RECOMMENDATIONS

- ° ESTABLISH A CUTOFF LEVEL OF 1 REM/YR ON INDIVIDUAL DOSES TO BE USED IN THE CALCULATION OF COLLECTIVE DOSE ESTIMATES FOR REG PURPOSES.
- ° SPECIFICALLY REQUEST PUBLIC COMMENT ON THIS ISSUE AND ON A DE MINIMIS LEVEL FOR INDIVIDUALS.

REPORTING OF WORKER DOSES

- ISSUES:
1. SHOULD THE NRC REQUIRE ALL LICENSEES TO REPORT ANNUAL DOSES OF ALL MONITORED WORKERS TO NRC?
 2. SHOULD THE NRC REQUIRE ALL LICENSEES TO REPORT ANNUAL DOSES TO WORKERS (WITHOUT REQUEST)?

EXPOSURE REPORTS

- THE NATIONAL INTEREST

- THE FEDERAL GOVERNMENT IS EXPECTED TO BE INFORMED, AND TO DISSEMINATE INFORMATION, REGARDING HEALTH AND SAFETY IN THE WORKPLACE
- DOL BUREAU OF LABOR STATISTICS (RADIATION EXPOSURE NOT INCLUDED)
- EXPOSURE DATA ARE VITAL IN PLANNING FOR THE ADMINISTRATION OF JUSTICE (WORKMANS COMPENSATION, TORT LAW)

- NRC INTERESTS

- NRC IS PRIMARY SOURCE OF INFORMATION FOR CONGRESS, ADMINISTRATION, OTHER FEDERAL AGENCIES, STATE GOVERNMENTS, LABOR UNIONS, SCIENTIFIC AND INDUSTRIAL ORGANIZATIONS, SPECIAL INTEREST GROUPS, NEWS MEDIA, UNITED NATIONS, FOREIGN GOVERNMENTS, AMONG OTHERS
- DATA BASE FOR DECISIONS REGARDING: BUDGET NEEDS; RESEARCH AND STANDARDS DEVELOPMENT PRIORITIES; EVALUATING LICENSEE PERFORMANCE; AREAS TO EMPHASIZE IN LICENSING; INSPECTION AND ENFORCEMENT PRIORITIES
- DATA BASE FOR FACTORING WORKER RISKS INTO DECISIONS ON PLANT SAFETY REQUIREMENTS
- DATA BASE FOR CONTROLLING POTENTIAL TRANSIENT WORKER PROBLEMS
- TRIGGERING TIMELY CORRECTIVE ACTION
- DATA BASE FOR EVALUATION OF RADIOLOGICAL RISKS IN NRC-LICENSED ACTIVITIES AND LICENSEE PERFORMANCE

EXPOSURE REPORTS...CONTINUED

- INDUSTRY INTEREST

- UNBIASED GOVERNMENT DATA ARE USED BY INDUSTRY TO VERIFY THAT SAFE WORKING CONDITIONS ARE MAINTAINED
- DATA ARE USED BY INDUSTRY TO IDENTIFY ITS STRONG AND WEAK PERFORMERS AND TO EFFECT IMPROVEMENTS

- WORKER INTEREST

- ASSURANCE THAT HEALTH PROTECTION IS ADEQUATE, AS SUPERVISED BY GOVERNMENT
- CONFIDENCE THAT ADEQUATE LEGAL RECORDS ARE AVAILABLE IF NEEDED
- GOVERNMENT TERMINATION OF UNSAFE CONDITIONS

PRESENT WORKER DOSE REPORTING REQUIREMENTS

0 ANNUAL STATISTICAL SUMMARY REPORTS--FROM 7 CATEGORIES OF LICENSEES

- LICENSEE IDENTIFICATION ONLY.
- NUMBER OF WORKERS RECEIVING DOSES WITHIN SPECIFIED DOSE RANGES.

0 REPORTS ON TOTAL DOSE RECEIVED BY WORKERS WHO TERMINATED EMPLOYMENT--FROM SAME 7 CATEGORIES OF LICENSEES.

- LICENSEE IDENTIFICATION
- WORKER IDENTIFICATION (NAME, SS NO., BIRTH DATE)
- PERIOD OF EMPLOYMENT
- MAGNITUDE AND TYPE OF RADIATION DOSE.

0 REPORTS ON DOSES RECEIVED BY WORKERS WHEN LIMITS ARE EXCEEDED

- LICENSEE IDENTIFICATION
- WORKER IDENTIFICATION
- TIME OF EXPOSURE
- MAGNITUDE AND TYPE OF RADIATION DOSE.

0 REPORT TO WORKER FROM ANY LICENSEE UPON REQUEST FROM WORKER

- MAGNITUDE AND TYPE OF RADIATION DOSE RECEIVED IN YEAR.

0 COPY REPORT TO WORKER WHENEVER INFORMATION REPORTED TO NRC BY NAMED INDIVIDUAL.

STAFF USES OF REPORTED RADIATION EXPOSURE DATA

THE DATA OBTAINED FROM PRESENT REPORTING REQUIREMENTS PERMIT ESTIMATES OF:

- 0 SIZE OF RADIATION WORKFORCE.
- 0 MAGNITUDE OF ANNUAL COLLECTIVE DOSE.
- 0 TRENDS OF EXPOSURES
 - COMPARISON OF DATA BY TYPE OF LICENSEE, AND BY LICENSEE WITHIN EACH TYPE
 - DOSE DISTRIBUTION VARIATION WITH TIME.
- 0 TRANSIENT WORKER DOSES.

EXAMPLES OF SPECIFIC USES OF REPORTED EXPOSURE DATA

0 MONITORING OF TRANSIENT WORKER OVEREXPOSURES

- INDIVIDUAL WORKING AT MULTIPLE PLANTS DURING A QUARTER IS COMMON.
- OVEREXPOSURES ARE KNOWN TO BE EXTREMELY RARE.

0 EXTENT OF ALLEGED RADIOACTIVITY PROBLEMS FOR NPP'S WORKERS

- NO OVEREXPOSURES REPORTED TO DATE.
- 95% OF THE REPORTED MEASUREMENT RESULTS FOR INTERNALLY DEPOSITED RADIOACTIVITY ARE LESS THAN 2% OF "PERMISSIBLE" QUANTITY.
- THEREFORE FEW NRC RESOURCES NEED BE EXPENDED FOR PROTECTION IN THIS AREA.

ALTERNATIVES

- 0 CONTINUE PRESENT REQUIREMENTS
- ANNUAL STATISTICAL SUMMARY REPORTS TO NRC FROM 7 LICENSE CATEGORIES
- TERMINATION REPORTS TO NRC FROM 7 LICENSE CATEGORIES (COPY TO WORKER).
- 0 EXPAND PRESENT REQUIREMENTS TO INCLUDE ALL LICENSEES
- 0 REQUIRE ANNUAL EXPOSURE REPORTS FOR EACH INDIVIDUAL WORKER TO THE WORKER FROM:
 - 7 LICENSE CATEGORIES
 - ALL LICENSEES.
- 0 REQUIRE ANNUAL EXPOSURE REPORTS FOR EACH INDIVIDUAL WORKER TO THE WORKER AND NRC FROM:
 - 7 LICENSE CATEGORIES
 - ALL LICENSEES.
- 0 TIGHTENING OF REQUIREMENT FOR ANNUAL REPORTS OF NAMED INDIVIDUAL WORKER:
 - INCLUDE IN FINAL RULE (PART 20)
 - REVISE PART 19 SEPARATELY (IF REPORT ONLY TO WORKER IS REQUIRED BUT NOT IN PART 20).

REPORTING OF WORKER DOSES CONSIDERATIONS

- 0 PRESENT REPORTING REQUIREMENTS PROVIDE INCOMPLETE DATA, E.G.,:
- NO ROUTINE OCCUPATIONAL EXPOSURE INFORMATION IS REPORTED BY MANY NRC LICENSEES, INCLUDING MEDICAL INSTITUTIONS. (MEDICAL WORKERS RECEIVE ABOUT HALF OF THE ANNUAL COLLECTIVE OCCUPATIONAL DOSE).
 - NO ROUTINE OCCUPATIONAL EXPOSURE INFORMATION IS REPORTED BY THE AGREEMENT STATE LICENSEES. (AGREEMENT STATES REGULATE LICENSEES HAVING ABOUT 200,000 OF THE 500,000 WORKERS MONITORED).
 - DATA SAMPLE FOR INTERNAL EXPOSURES TO ALPHA EMITTERS TOO SMALL AND UNTIMELY FOR STAFF NEEDS.
- 0 THE EPA PROPOSED FEDERAL GUIDANCE WOULD REQUIRE EMPLOYERS TO REPORT WORKER ANNUAL DOSES TO THE WORKER WITH NO REQUIREMENT ON REPORTING TO ANY FEDERAL AGENCY.
- EPA PROPOSED FEDERAL GUIDANCE MAY NOT BE FINALIZED FOR SOME TIME.

STAFF RECOMMENDATIONS

- 0 CONTINUE THE PRESENT REQUIREMENT FOR ANNUAL STATISTICAL SURVEY REPORTS AND TERMINATION REPORTS FROM 7 CATEGORIES OF LICENSEES WHOSE EMPLOYEES ARE CONSIDERED TO ACCEPT THE HIGHEST RISKS.
- 0 SPECIFICALLY REQUEST COMMENTS ON THIS ISSUE.
- 0 COMPLY WITH NEW FEDERAL GUIDANCE (ANNUAL EXPOSURE REPORT TO EACH WORKER) BY ATTENDING REGULATIONS AFTER NEW FEDERAL GUIDANCE IS ISSUED.

OPTIONAL IMPLEMENTATION PERIOD

ISSUE: SHOULD THERE BE A TRANSITION PERIOD, FOLLOWING PUBLICATION OF THE NEW PART 20 AS A FINAL RULE, DURING WHICH COMPLIANCE WITH EITHER THE PRESENT OR NEW PART 20 WOULD BE ACCEPTABLE?

COMMITTED VS ANNUAL DOSE

ISSUE: SHOULD CONTROL OF LONG-LIVED RADIOACTIVE MATERIAL
INTAKES BE BASED ON THE DOSE ACTUALLY RECEIVED
EACH YEAR OR ON THE DOSE INTEGRATED OVER A PERIOD
OF 50 YEARS?

COMMITTED VS ANNUAL DOSE FOR CONTROL
OF LONG-LIVED AIRBORNE RADIONUCLIDES
BY FEDERAL AGENCIES

- CONTROVERSY HIGHLIGHTED BY EPA/DOE/NRC REACTION TO ICRP-26
- ICRP HAS ALWAYS USED COMMITTED DOSE TO INTERNAL ORGANS (50-YR INTEGRATED DOSE), INCLUDING ICRP-26
- AEC-REG./NRC HAVE ALWAYS USED COMMITTED DOSE
- AEC/ERDA/DOE HAVE USED COMBINATION OF COMMITTED AND ANNUAL DOSE
- EPA, IN NEW GUIDANCE TO FEDERAL AGENCIES, IS PROPOSING COMBINATION OF COMMITTED AND ANNUAL DOSE
- 10 CFR PART 20 REVISION WOULD USE COMBINATION OF COMMITTED AND ANNUAL DOSE
- FEDERAL AGENCIES ARE IN AGREEMENT ON THIS ISSUE
- THE DEGREE OF PROTECTION PROVIDED FOR NRC-LICENSEE AND DOE-CONTRACTOR WORKERS WOULD CONTINUE TO BE VIRTUALLY THE SAME.

COMMITTED VS ANNUAL DOSE CONTROVERSY
IN HEALTH PHYSICS COMMUNITY

- THIS ISSUE INVOLVES CAREER INTERFERENCE, INTERNAL DOSE RECORDS AND REPORTS TO EMPLOYEES IN THE MANAGEMENT OF LARGE DEPOSITIONS; NOT COVERED IN FEDERAL GUIDANCE.
- HEALTH PHYSICS COMMUNITY DIVIDED ON THIS ISSUE.
- ISSUE WILL BE VOTED ON BY THE HEALTH PHYSICS SOCIETY -- THE FIRST TIME VOTING OF THIS TYPE HAS BEEN HELD.
- THE RESULTS OF THIS VOTE WILL BE INFLUENTIAL ON THE STAFF AS PUBLIC COMMENTS ON 10 CFR PART 20 ARE ANALYZED.

CAREER INTERFERENCE: RECORDING: REPORTING

- A WORKER ACCIDENTALLY RECEIVING A SUFFICIENTLY LARGE INTAKE WOULD RECEIVE AN EFFECTIVE DOSE EQUIVALENT LARGER THAN THE 5 REMS PER YEAR LIMIT THE REST OF HIS/HER LIFE.
- SINCE THE RISK FROM THIS DEPOSITION WOULD NOT BE ALTERED BY SUBSEQUENT INTAKE OR EXTERNAL EXPOSURE LIMITATIONS, WHILE CAREER INTERFERENCE COULD IMPOSE SEVERE ECONOMIC (AND OTHER) PENALTIES, PRESENT NRC REGULATIONS (AND THE NEW PART 20) WOULD, AT THE BEGINNING OF THE NEXT QUARTER (YEAR) DISREGARD THE PRESENCE OF THIS DEPOSITION.
- THE LICENSEE WOULD BE REQUIRED TO RECORD THE INTAKE AND AN ESTIMATE OF THE COMMITTED DOSE EQUIVALENT (EFFECTIVE COMMITTED DOSE EQUIVALENT AFTER REVISED PART 20 BECOMES EFFECTIVE).
- THE LICENSEE WOULD BE REQUIRED TO REPORT THIS INFORMATION TO THE NRC AND TO THE WORKER.
- FOR CERTAIN NUCLIDES DIFFICULT TO MEASURE IN QUANTITIES ASSOCIATED WITH THE DOSE COMMITMENT, RECORDING AND REPORTING OF THE ANNUAL EFFECTIVE DOSE WOULD BE ALLOWED BY THE NEW PART 20, AND LARGER INTAKES WOULD BE ALLOWED UNDER PRESCRIBED CONDITIONS.
- INDIVIDUAL DETERMINATIONS WILL BE CONTINUED FOR DOE WORKERS SO EXPOSED, INCLUDING COMPENSATORY DOSE LIMITATIONS IF CONSIDERED NECESSARY BY DOE MEDICAL AUTHORITIES.
- DOE WILL CONTINUE TO RECORD AND REPORT ANNUAL DOSES.

ESTIMATED COST TO LICENSEES* OF IMPLEMENTING 10 CFR PART 20 REVISION

\$33,000,000	INITIAL COST
\$ 7,800,000	ANNUAL COST

BASED ON NRC/EPA CO-SPONSORED CONTRACT THAT SURVEYED LICENSEES

* INCLUDES AGREEMENT STATE LICENSEES

PERSPECTIVE ON ESTIMATED COSTS

- o MUCH OF ECONOMIC IMPACT THAT IS ASSIGNED TO PROPOSED REVISION OF PART 20 HAS BEEN, IS BEING, OR WILL BE COMMITTED WHETHER OR NOT REVISION IS PROMULGATED.
- o MANY LICENSEES VOLUNTARILY IMPLEMENTING RECOMMENDATIONS OF ICRP 26 AND 30, BECAUSE RECOGNIZED AS "GOOD PRACTICE" AND LIKELY TO BE HELPFUL IN MITIGATING LIABILITY CLAIMS
- o COST OF SPECIAL EQUIPMENT, SUCH AS LUNG COUNTERS, PROCESS CHANGES, ROBOTICS, AND OTHER MAJOR MODERNIZATION ACTIVITIES, HAVE AND WILL BE "CHARGED" TO THE PART 20 REVISION, ALTHOUGH THEY ARE NOT REQUIRED AND WOULD BE INCURRED ANYWAY FOR OTHER REASONS
- o ESTIMATED COSTS TAKE NO CREDIT FOR SAVINGS FROM CHANGES IN TECH SPECS, LIC. CONDITIONS, ETC. THAT COULD RESULT FROM PROMULGATION OF PROPOSED REVISION

BENEFITS OF PROPOSED REVISION

- (REGULATION WILL REFLECT ICRP COHERENT RISK-BASED SYSTEM AND USE WIDELY-ACCEPTED CONTEMPORARY SCIENTIFIC KNOWLEDGE
- o ANNUAL AND LIFETIME DOSES TO WORKERS RECEIVING HIGHEST EXPOSURES & WORKERS IN URAN. MILLS & FUEL FABR. WILL BE REDUCED
- o WILL PROVIDE METHOD FOR SUMMING EXTERNAL AND INTERNAL EXPOSURES -- ESPECIALLY IMPORTANT FOR SOME NMSS LICENSED ACTIVITIES
- o PUBLIC DOSE LIMITS ARE CLEARLY IDENTIFIED
- o WORKERS AND PUBLIC SHOULD BETTER UNDERSTAND HEALTH RISK BASE AND PROTECTION PROVIDED
- o CUTOFF ON COLLECTIVE DOSE EVALUATIONS WOULD ELIMINATE CONSIDERATION OF INSIGNIFICANT HEALTH RISKS
- o IMPROVES REQUIREMENTS ON RADIATION SAFETY; E.G., TO PREVENT ACCESS TO VERY HIGH RADIATION AREAS, POSTING OF AREAS USED FOR MEDICAL RADIATION TREATMENTS, REQUIRED APPLICATION OF ALARA
- o WOULD INTRODUCE SI (METRIC) RADIATION UNITS INTO NRC REGS

STAFF RECOMMENDATIONS

- o CONCURRED IN BY ALL OFFICES INVOLVED
- o PROPOSE EXTENDED IMPLEMENTATION PERIOD OF 5 YEARS FROM PUBLICATION OF FINAL RULE
- o PUBLISH PROPOSED REVISION OF PART 20 FOR PUBLIC COMMENT
- o SPECIFICALLY REQUEST COMMENTS ON CONTROVERSIAL ISSUES
- o ALLOW EXTENDED PERIOD (120 DAYS) FOR COMMENT


Agenda for ACRS Subcommittee
Meeting on February 12, 1986
1:30 p.m.
Room 1046, H Street

RECENT SIGNIFICANT EVENTS

<u>Date</u>	<u>Plant</u>	<u>Event</u>	<u>Presenter/Office telephone</u>	<u>Page</u>
11/3/85	McGuire 1	Start-Up with Degraded HPSI System	J. Giitter, IE 492-9001	2
1/7/86	Brunswick 2	Target Rock Two-Stage SRV Setpoint Drift	M. Wegner, IE 492-4511	4
1/7/86	Turkey Point	Stop Check Valve Failures	R. Kiessel, IE 492-8119	5
1/9/86	Palo Verde 1	Reactor Trip	E. Licitra, NRR 492-8599	8
1/9/86	Palisades	Loss of Offsite Power	J. Giitter, IE 492-9001	10
1/28/86	Robinson	Loss of Offsite Power	G. Requa, NRR 492-9798	13
1/14/86	ANO 1	Design Deficiency in Emergency Feedwater System	G. Vissing, NRR 492-8796	14
1/29/86	Riverbend	Review Of Start-Up Test Program	E. Weiss, IE 492-9005	18
1/31/86	Perry	Earthquake	J. Stefano, NRR 492-9473	20
	Fermi	50.54(f) Improvement Program	E. Greenman, Reg 3 312-790-5518	NOT IN PACKAGE
	----	Technical Specification Improvement Program	R. Hernan, NRR 492-9519	21

McGUIRE UNIT 1 - START-UP WITH DEGRADED HPSI SYSTEM
NOVEMBER 3, 1985 (J. GLITTER, IE)

- ° PROBLEM: FAILURE TO REPAIR VCT ISOLATION VALVE MOTOR OPERATORS PRIOR TO START-UP WOULD HAVE PREVENTED VCT ISOLATION ON SI SIGNAL.
- ° SAFETY SIGNIFICANCE: HPSI MAY NOT HAVE FUNCTIONED AS REQUIRED ON A REAL DEMAND.
- ° DISCUSSION:
 - AT 0640 ON NOVEMBER 2, A LOSS OF INST. AIR (SHARED BY BOTH UNITS) CAUSED BOTH UNITS TO TRIP AND SAFETY INJECTION IN UNIT-1.
 - VCT ISOL. VALVES CLOSED AS REQUIRED; HOWEVER, THE VALVE MOTOR OPERATORS WERE LATER FOUND BURNED OUT.
 - PRIOR TO START-UP, OPERATORS MANUALLY OPENED VALVES, BUT DID NOT REPAIR THE MOTOR OPERATORS.
 - UNIT START-UP COMMENCED AT ABOUT 0600 ON 11/3. THE UNIT WAS IN MODE 2 FOR ABOUT 6 HOURS.
 - TWO MAJOR CONCERNS 1) IS BORON CONC. LESS THAN THAT ASSUMED IN SAFETY ANALYSIS? AND 2) COULD VCT COVER (H_2 AND N_2) BECOME ENTRAINED IN THE CHARGING PUMP SUCTION PATH RESULTING IN GAS BINDING OF PUMPS?
 - NRC (OP CENTER) WAS NOTIFIED AT 1218 ON 1/14/86.
- ° FOLLOW-UP:
 - VALVE OPERATOR REPAIRED.
 - REVIEWED DESIGN OF OTHER MOTOR OPERATED VALVES IN PLANT.
 - PERFORMED TEST TO DETERMINE TIME REQUIRED FOR OPERATOR TO CLOSE ISOLATION VALVES. TIME REQUIRED WAS 19.4 MINUTES. AT 20 MINUTES VCT LEVEL WAS AT 20%.



BRUNSWICK 2

TARGET ROCK TWO-STAGE SRV SETPOINT DRIFT, 1/7/86, MARY S. WEGNER

- 1/7/86 CP&L REPORTED 6/11 BSEP 1 VALVES LIFTED AT 200 PSIG OVER SETPOINT AT WYLE LAB
- HISTORY
 - THREE STAGE VALVE SPURIOUS OPENINGS AND FAILURE TO RESEAT
 - TWO STAGE REPLACEMENT BEGUN 1978
 - HATCH 1 HAD 11 OF 11 FAILED TO OPEN AT SETPOINT
 - OWNERS GROUP FORMED TO INVESTIGATE PROBLEM, POSE SOLUTION
 - CAUSE ATTRIBUTED TO LABYRINTH SEAL GALLING AND SEAT-TO-DISC BONDING
 - ENHANCED MAINTENANCE SUGGESTED
 - RECURRING PROBLEMS
 - NRR LETTER TO OWNERS GROUP
 - SEAT REPLACEMENT PROGRAM
- THE BRUNSWICK INCIDENT
 - WYLE TESTING
 - OBSERVATIONS AT WYLE
- HATCH 1 RESULTS
- MILLSTONE 1 RESULTS
- GENERIC ISSUE B55

TURKEY POINT UNITS 3 AND 4 - STOP CHECK VALVE FAILURES
NOV. 1985 THRU JAN. 1986 - (R. KIESSEL, IE)

PROBLEM: AFW STOP CHECK VALVE GUIDE PIN FAILURES


SAFETY SIGNIFICANCE: AFW VALVE/SYSTEM CONCERNS AND GENERIC
IMPLICATIONS OF LOW FLOW THROUGH
CHECK VALVES

CIRCUMSTANCES:

- BETWEEN NOV. 1985 AND JAN. 1986, NUMEROUS FAILURES OF STOP CHECK VALVES IN STEAM SUPPLY SYSTEM TO AFW PUMPS
- STOP CHECK VALVES LOCATED UPSTREAM AND DOWNSTREAM OF MOTOR OPERATED VALVES THAT OPENS WHEN REQUIRED TO INITIATE FLOW
- STOP CHECK NORMALLY OPEN - PREVENTS BACKFLOW IN EVENT OF STEAM LINE BREAK
- MODE OF FAILURE - DEGRADATION OF DISC AND DISC NUT
- FAILURE DUE TO LOW STEAM FLOW CONDITIONS CAUSED BY SLIGHT LEAKAGE OF NORMALLY CLOSED MOV
- LOW FLOW CAUSED VIBRATION AND CHATTERING BREAKING DISC GUIDE FROM DISC
- LOOSE DISC GUIDE PREVENTED FULL CLOSURE AND FULL OPENING OF VALVE. ALSO FREE TO TRAVEL

FOLLOWUP:

- AFW SYSTEM WAS INSPECTED
- ALL MISSING GUIDE PINS LOCATED AND REMOVED
- ALL VALVES REPAIRED WITH HIGHER STRENGTH MATERIAL USED IN DISC GUIDE
- FAILURE ANALYSIS AND METALLURGICAL EXAMINATIONS PERFORMED
- LICENSEE COMMITTED TO REGULAR RADIOGRAPHIC EXAMINATION OF VALVES
- LICENSEE CONSIDERS THIS AS INTERIM REPAIR PENDING COMPLETION OF THE STUDY BY ITS AFW ENHANCEMENT TASK FORCE
- INFORMATION NOTICE 86-09, "FAILURE OF CHECK AND STOP CHECK VALVES SUBJECTED TO LOW FLOW CONDITIONS" WAS ISSUED FEBRUARY 3, 1986



PALO VERDE UNIT 1 - COMPLICATIONS
FOLLOWING TURBINE TRIP TEST
FROM 100% POWER
JANUARY 9, 1986 - (E. LICITRA, NRR)

CIRCUMSTANCES:

- ° TURBINE TRIP TEST STARTED FROM 100% (2250 PSI AND 565°F COLD LEG) AT APPROXIMATELY 13:25
- ° NON 1E HOUSE LOADS FAILED TO TRANSFER TO OFFSITE POWER DUE TO FREQUENCY MISMATCH BETWEEN GRID AND NON 1E BUSES
- ° POWER LOSS AFFECTED RCS PUMPS, MFW PUMPS, CIRCULATING WATER PUMPS AND STEAM DUMP/BYPASS CONTROL SYSTEM
- ° REACTOR TRIP DUE TO FLOW PROJECTED LOW DNBR
- ° STEAM BYPASS CONTROL SYSTEM (SBCS) VALVES RECEIVED QUICK OPEN SIGNAL BUT RECLOSED ALMOST IMMEDIATELY (DUE TO LOSS OF POWER)
- ° ONE OF THE FOUR LOWEST SETTING (1250 PSIG) MAIN STEAM SAFETY VALVES LIFTED WHEN SG PRESSURE INCREASED RAPIDLY - STAYED OPEN FOR 43 SECONDS
- ° WHEN SAFETY VALVE RESEATED, FIVE SBCS VALVES MODULATED OPEN - STAYED OPEN FOR 45 SECONDS WITH TWO ADDITIONAL OPEN/CLOSE CYCLES DURING NEXT 40 SECONDS
- ° MANUAL CONTROL TAKEN OF INDIVIDUAL SBCS VALVES TO STOP COOL-DOWN - ALSO MSIS OCCURRED DUE TO LOW SG PRESSURE
- ° AFTER STABILIZATION, OPERATOR REESTABLISHED COOLDOWN VIA ONE SG, TWO ADVs AND ONE AFW PUMP
- ° POWER RESTORED TO NON 1E BUSES AT 13:28 (3 MINUTES AFTER START OF EVENT)
- ° RCS PUMP FLOW RESTORED AT 14:08
- ° EVENT TERMINATED AT 14:49

FOLLOW UP:

- ° CONSIDERING DESIGN CHANGE TO SYNCHRONIZATION CHECK RELAY ASSOCIATED WITH AUTO TRANSFER
- ° MAIN STEAM SAFETY VALVE SETTINGS CHECKED AND FOUND OK
- ° CONSIDERING UNINTERRUPTABLE POWER TO STEAM DUMP/BYPASS CONTROL SYSTEM
- ° RCS PUMP COASTDOWN FOUND FASTER THAN DESIGN - ONLY AFFECTS LOSS-OF-FLOW SAFETY ANALYSIS
- ° COLSS AND CPC PENALTIES IMPOSED WHILE CE EVALUATES FAST COASTDOWN EFFECT
- ° TURBINE TRIP TEST SUCESSFULLY RERUN ON JAN 24, 1986 (NON 1E LOADS POWERED OFF OF STARTUP TRANSFORMER)

PALISADES - LOSS OF OFF-SITE POWER

JANUARY 9, 1986 (J. G. GLITTER)

° PROBLEM

LOSS OF OFF-SITE POWER WITH 1 DIESEL-GENERATOR OUT OF SERVICE.
VOLUNTARY DISCONNECT FROM GRID DUE TO STEAM OBSERVED FROM
4160V SYSTEM.

° SAFETY SIGNIFICANCE:

LOSS OF OFF-SITE POWER WITH 1 OF 2 D/Gs OUT OF SERVICE (TORN
DOWN); VESSEL DRAINED DOWN TO APPROXIMATELY FLANGE LEVEL;
HEAD NOT TENSIONED.

° CIRCUMSTANCES:

INITIAL CONDITIONS:

- UNIT HAD BEEN IN COLD SHUTDOWN FOR REFUELING SINCE
NOVEMBER 30, 1985 (40 DAYS).
- HEAD WAS POSITIONED ON VESSEL BUT NOT TENSIONED. VESSEL
WAS DRAINED TO APPROXIMATELY FLANGE LEVEL (~12 FT ABOVE
FUEL).
- D/G 1-1 WAS OUT OF SERVICE (WOULD HAVE REQUIRED SEVERAL
HOURS TO MAKE OPERABLE).

SEQUENCE: (TIMES ARE PM, EST)


- 2:41 - "SMOKE" (STEAM) OBSERVED FROM CONDUIT ON THE 1A
BUS. OPERATORS IMMEDIATELY DE-ENERGIZED NON-VITAL 4160V
BUS 1A. IT WAS DECIDED TO DE-ENERGIZE THE R 345 KV
SWITCH YARD (S/Y) BUS. (DE-ENERGIZING ALL 3 S/U XFMRS.)
- 2:56 - OPERATORS STARTED AND LOADED D/G 1-2 ON THE 1D BUS.
- 3:08 - R 345 KV S/Y BUS DE-ENERGIZED. 1B, (IE NON-VITAL
BUSES) LOST. 1C VITAL BUS LOST. 1D POWERED FROM 1-2 D/G,
UNUSUAL EVENT (UE) DECL'D AT 3:00 AND NRC OP CENTER
NOTIFIED AT 3:19.

- 4:50 - BACKFEED ESTABLISHED TO ALL BUSES THRU MAIN TRANSFORMER AND STATION POWER TRANSFORMER. UE TERMINATED AT 5:00.

° FOLLOW UP:

CABLE BETWEEN 4160 V BUS 1A AND STARTUP TRANSFORMER 1-2 WAS REPLACED PRIOR TO ELECTRICAL REALIGNMENT.

SIMPLIFIED ELECTRICAL DISTRIBUTION DIAGRAM FOR PALISADES



H. B ROBINSON UNIT 2 - REACTOR TRIP WITH LOSS OF OFFSITE POWER
JANUARY 28, 1986 (G. REQUA, NRR)

PROBLEM

LOSS OF OFFSITE POWER (LOOP) WITH "B" EDG OUT OF SERVICE

SAFETY SIGNIFICANCE

PRECURSOR TO STATION BLACKOUT

DISCUSSION

09:17 WITH "B" EDG OUT OF SERVICE, FAULT ON EMERGENCY BUS E-2
CAUSED SPIKED ON INSTRUMENT BUS #4. FALSE RCD DROP SIGNAL
CAUSED TURBINE RUNBACK. REACTOR TRIPPED ON HIGH
PRESSURIZER PRESSURE.

09:18 LOSS OF OFFSITE POWER COINCIDED WITH FAST TRANSFER TO
START UP TRANSFORMER. "A" EDG STARTS & LOADS ON BUS E-1.
RCP's TRIPPED. NATURAL CIRCULATION ESTABLISHED.

09:35 UNUSUAL EVENT DECLARED - OPEN TELEPHONE LINE ESTABLISHED
BETWEEN NRC OPERATIONS CENTER AND ROBINSON SITE

09:46 "B" DIESEL GENERATOR RESTORED

10:52 PRESSURIZER HEATERS RESTORED

12:55 E-1 BUS CONNECTED TO OFFSITE POWER

16:03 E-2 BUS CONNECTED TO OFFSITE POWER. REALIGNMENT OF
OFFSITE POWER DELAYED BY

1. TWO SI SIGNALS - 1ST SIGNAL CAUSED BY CLOSURE OF MSIVs;
SECOND SIGNAL CAUSED BY STUCK OPEN S/G PORV
2. ADDITIONAL BREAKER PROBLEM BETWEEN #3 BUS & E-2
3. OPERATOR DECISION TO PROCEED WITH CAUTION IN
RESTORING ELECTRICAL CONFIGURATION

PLANT WAS TAKEN TO HOT SHUTDOWN. CP&L DECIDED TO SHUTDOWN FOR
REFUELING ONE WEEK EARLY

FOLLOWUP

- ° PLANT IN 45 DAY REFUELING OUTAGE; LICENSEE INVESTIGATING CAUSE
OF LOOP; REGION II WILL REVIEW PRIOR TO RESTART
- ° LICENSEE & INPO TEAM FORMED TO INVESTIGATE HIGH FREQUENCY OF
REACTOR SCRAMS AT ROBINSON; REGION II TO EVALUATE RESULTS PRIOR
TO RESTART

ARKANSAS NUCLEAR ONE UNIT 1 - DESIGN DEFICIENCY IN
EMERGENCY FEEDWATER SYSTEM (EFW)
JANUARY 14, 1986 - (G. VISSING, NRR)

PROBLEM:

- DESIGN DEFICIENCY IN THE EMERGENCY FEEDWATER SYSTEM (EFW)

SIGNIFICANCE:


- POTENTIAL FOR LOSS OF ALL EFW AND BLOWDOWN OF BOTH STEAM GENERATORS, DURING STEAM LINE BREAK WITH SINGLE FAILURE OF ONE A/C BUS

CIRCUMSTANCES:

- DEFICIENCY DISCOVERED BY IE INSPECTION TEAM
- DURING POSTULATED STEAM LINE BREAK CONCURRENT WITH LOSS OF RED A/C POWER BUS, TURBINE DRIVEN AND MOTOR DRIVEN EFW PUMPS WOULD BE LOST
- POSSIBLE BLOWDOWN OF BOTH S/Gs
- DESIGN DOES NOT MEET THE SINGLE FAILURE CRITERION
- PLANT, AT 89% POWER AT THE TIME OF THE DISCOVERY, WENT INTO CONTROLLED SHUTDOWN DUE TO FAILURE OF EDG


FOLLOWUP:

- LICENSEE CONFIRMED EXISTENCE OF DESIGN DEFICIENCY
- LICENSEE TO INSTALL CHECK VALVES IN STEAM LINES FROM EACH OTSG BEFORE STARTUP.
- NRR (PEICSB) REVIEWED ISSUE AND CONCURRED WITH INSPECTION TEAM'S FINDINGS




ANO-I EFW SYSTEM DESIGN

15



ANO-1 EFW DESIGN (STEAM SYSTEM)



EFW DESIGN CORRECTION

RIVERBEND START-UP REVIEW
(Eric Weiss, IE)

CONCERN: NUMBER OF REPORTABLE EVENTS SINCE OPERATING LICENSE

CONCLUSION: NUMBER OF EVENTS SHOULD DECREASE

RIVERBEND MANAGEMENT APPEARS SOUND

SHOULD MEET IN REGION 4 TO REVIEW PROGRESS IN ONE
MONTH

NRC SITE VISIT JANUARY 28 - 30, 1986

REPORTABLE EVENTS REVIEW WITH PLANT STAFF

SHIFT TURNOVER

DIESEL GENERATORS

FEEDWATER SYSTEM

FANCY POINT SUBSTATION

SURVEILLANCE PROCEDURE ON RWCUS

CONTROL ROOM PANEL WALKDOWN

URGED LICENSEE TO:

CONTINUE OPEN COMMUNICATION WITH THE NRC

RESOLVE OUTSTANDING EQUIPMENT AND HUMAN FACTORS PROBLEMS

UPGRADE COMMUNICATION WITH OTHER PLANTS

PLANT SPECIFIC PROBLEMS

TEMPORARY ALTERATION PROGRAM SHOULD BE STOPPED

ANNUNCIATOR REFLASH

FEEDWATER - VIBRATION, EROSION, STICKING FW REG VALVES

STEAM TUNNEL VENTILATION

POTENTIALLY GENERIC PROBLEMS

VALVE OPERATOR PROBLEM

TEMP SWITCH PROBLEMS

FIBER OPTICS SYSTEM INTERFERENCE

EXAMPLES OF PROBLEM RESOLUTION

CONDITION REPORT SYSTEM

JUMPER CONTROL - TAGS, LOGS, BANANA PLUGS

FIBER OPTICS - SHIELDING, GROUND LOOP ELIMINATION, EVENTS
RECORDING, SIGNS AND NON-DUPLICATING LOCKS

COLOR ON METERS

PERRY 1 AND 2 - EARTHQUAKE
JANUARY 31, 1986 (J. STEFANO, NRR)

PROBLEM

EARTHQUAKE MEASURING 5.0 ON RICHTER SCALE WITH EPICENTER APPROXIMATELY 10 MILES FROM SITE.

SIGNIFICANCE

- EVENT MAY BE OUTSIDE DESIGN ENVELOPE

CIRCUMSTANCES

- PLANT CONSTRUCTION COMPLETE-WAS UNDERGOING SYSTEM SURVEILLANCE/ OPERATIONAL READINESS TESTS FOR LICENSING. (NUMEROUS SAFETY SYSTEMS WERE IN OPERATION).
- SEISMIC INSTRUMENTS WERE BEING CALIBRATED AT TIME OF EVENT.
- TWO NON-SAFETY EQUIP. TRIPPED ON PROTECTIVE SIGNAL AS DESIGNED; SOME HAIRLINE CONCRETE CRACKS OBSERVED IN AUX., INTERMED. AND RADWASTE TREATMENT BLDGS. PIPE FLANGE ON WATER TANK IN RADWASTE BLDG. LEAKING.
- PRELIM. DATA SEEMS TO INDICATE SHORT DURATION (<1 SEC) SEISMIC MOTION MAINLY FALLS WITHIN OBE/SSE DESIGN SPECTRUM EXCEPT POSSIBLY AT HIGH FREQUENCY RANGE (>15Hz)

FOLLOWUP

- NRR/REG.III TEAM VISIT TO SITE TO LOOK FOR DAMAGE & OBTAIN SEISMIC DATA ON 2/1/86 - 2/2/86
- NRR/REG.III FOLLOWUP VISIT TO SITE ON 2/5/86 - 2/7/86
- CEI ANALYSIS UNDERWAY TO DETERMINE TO WHAT EXTENT PLANT STRUCTURE/COMPONENT DESIGN WAS EXCEEDED.
- PLANT LICENSING DECISION PENDING NRC STAFF EVALUATION AND DETERMINATIONS RE EVENT.

NRR TECHNICAL SPECIFICATION IMPROVEMENT PROGRAM (TSIP)

(E. Butcher, NRR, DHFT)

NEED FOR TSIP

- TOO MANY SPECS - LESS IMPORTANT ONES THUS
DETRACTING FROM IMPORTANT ONES
- SIZE AND COMPLEXITY OF TS
- INDUSTRY AVAILABILITY RECORD
- NOT OPERATOR ORIENTED
- FINDINGS OF NUREG-1024 "TECHNICAL
SPECIFICATIONS-ENHANCING THE SAFETY IMPACT"

PROBLEM IDENTIFICATION

- IDENTIFIED PROBLEMS BY INTERVIEWS, DOCUMENT
REVIEWS, AND CONTRACTOR ASSISTANCE
- IDENTIFIED THREE PROBLEM AREAS
 - LACK OF WELL-DEFINED CRITERIA FOR TS
 - HUMAN FACTORS AND TECHNICAL WEAKNESSES
 - RELUCTANCE OF THE NRC STAFF TO USE TOOLS
OTHER THAN TS

TECHNICAL SPECIFICATION IMPROVEMENT PROJECT
RECOMMENDATIONS

- (1) A COMMISSION POLICY STATEMENT SHOULD BE ISSUED WHICH DEFINES THE SCOPE AND PURPOSE OF TECHNICAL SPECIFICATIONS AND ENCOURAGES LICENSEES TO IMPLEMENT A PROGRAM TO UPGRADE THEIR TECHNICAL SPECIFICATIONS."
- (2) THE NRC SHOULD GIVE INCREASED ATTENTION TO CHANGES MADE BY LICENSEES USING THE 10 CFR 50.59 PROCESS.
- (3) THE NRC SHOULD REVIEW AND REVISE THE STANDARD TECHNICAL SPECIFICATIONS TO CORRECT HUMAN FACTORS AND OTHER TECHNICAL WEAKNESSES THROUGH A PROGRAM OF TECHNICAL ASSISTANCE AND DEDICATED IN-HOUSE TECHNICAL RESOURCES.
- (4) THE NRC SHOULD ENCOURAGE THE CONTINUED DEVELOPMENT AND APPLICATION OF PROBABILISTIC RISK ASSESSMENT METHODS TO ADDRESS TECHNICAL SPECIFICATIONS REQUIREMENTS."

CRITERIA FOR TS CONTENT

- AN INSTALLED SYSTEM THAT IS USED TO DETECT, BY MONITORS IN THE CONTROL ROOM, A SIGNIFICANT ABNORMAL DEGRADATION OF THE REACTOR COOLANT PRESSURE BOUNDARY.
- A PROCESS VARIABLE THAT IS AN INITIAL CONDITION OF A DBA ANALYSIS.
- A STRUCTURE, SYSTEM, OR COMPONENT THAT IS PART OF THE PRIMARY SUCCESS PATH OF A SAFETY SEQUENCE ANALYSIS AND FUNCTIONS OR ACTUATES TO MITIGATE A DESIGN BASIS ACCIDENT.

ONGOING ACTIVITIES

- TRIAL USE OF TSIP CRITERIA
- MEETINGS WITH INDUSTRY OWNERS GROUPS AND AIF
- SHORT TERM IMPROVEMENTS TO EXISTING STS
 - FIRE PROTECTION TECHNICAL SPECIFICATION
 - ACTION STATEMENTS FOR MISSED SURVEILLANCE TESTS
 - BWR RPS SURVEILLANCE INTERVALS AND AOTs (NEDC-30851P)
 - BWR ECCS INSTRUMENTATION SURVEILLANCE INTERVALS AND AOTs (NEDC-30936P)
- EVALUATION OF COMMENTS ON TSIP REPORT

FUTURE ACTIVITIES

- DETAILED IMPLEMENTATION PROGRAM PLAN - 03/86
- PROPOSED COMMISSION POLICY STATEMENT - 06/86
- ULTIMATE LONG TERM OBJECTIVE

"A COMPLETE REWRITE/STREAMLINING"
OF THE EXISTING STS BASED ON THE
RECOMMENDATIONS OF THE TSIP REPORT

BRIEFING FOR ACRS

Fermi 2

Wednesday February 12, 1986

Region III

FERMI HISTORY

<u>Significant Events</u>	<u>Date</u>
Low Power License	March 20, 1985
Premature Criticality Event	July 1, 1985
Commission Briefing	July 10, 1985
Full Power License	July 15, 1985
Unit Shutdown for Planned Outage	October 11, 1985
Projected Availability for Startup	March, 1986**

** This may be delayed, dependent upon resolution of
Stress Report and Hanger Design Calculations.
(PNO-III-86-011)

TECHNICAL ISSUES

- o Diesel Generators
- o Turbine Bypass Lines
- o South Reactor Feed Pump Turbine
- o TIP Purge Line
- o Condensate Storage Tank
- o Remote Shutdown (3-L) Panel
- o Environmental Qualifications/Review
- o Seismic Review
- o Concrete Embedments
- o RHR Pump
- o Outdated Stress Reports and Hanger
Calculations

PERFORMANCE ISSUES

- o Excessive Personnel Errors
- o Security Program Implementation
- o Failure to Disposition known Problems
- o Ineffective Communications

Fermi 2

PERSONNEL ERRORS

A Review of 78 LERs

<u>Covered During</u>	No. of <u>LERs</u>	No. of LERs Caused by <u>Personnel Errors</u>
03/20/85-11/25/85	78	41
07/10/85-09/10/85	25	9
09/10/85-11/25/85	17	8

10 CFR 50.54(f) LETTER

- Adequacy of Management and Management Structures and Systems
- Actions to Ensure Readiness to Restart and Power Ascension
- Actions to Improve Regulatory and Operational Performance

LICENSEE RESPONSE

- o CEO Assumes Direct Management Control
- o Independent Overview Committee
- o Reactor Operations Improvement Plan
- o Nuclear Operations Improvement Plan
- o CEO to Authorize Power Escalation
- o Single A/E On Site
- o Independent Overview by Corporate Officers
- o Plan to Hire A Senior VF




Figure 2 Target Rock Two-Stage Pilot Actuated, Safety/Relief Valve






Figure 3 Topworks of Target Rock Two-Stage Safety/Relief Valve




LOCATION OF BSEP 2 SRV BY N₂ PRESSURE

SRV TEST RESULTS



KEY: * - SETPOINT
 0 - SP + N2 PRESS
 S - STEAM PRESS
 X - N2 + STEAM PRESS



PERRY POWER PLANT

JANUARY 31, 1986 EARTHQUAKE
SEISMIC EVENT EVALUATION

SEISMIC EVENT EVALUATION

REPORT

PERRY NUCLEAR POWER PLANT

DOCKET NOS. 50-440; 50-441

THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

FEBRUARY 1986

TABLE OF CONTENTS

1.0	INTRODUCTION
2.0	OVERVIEW OF EVENT
3.0	PLANT STATUS AND IMPACT ASSESSMENT
4.0	EARTHQUAKE ANALYSIS AND SITE SEISMICITY
5.0	SEISMIC INSTRUMENTATION DATA EVALUATION
6.0	PLANT SEISMIC DESIGN EVALUATION
7.0	CONFIRMATORY PROGRAMS
8.0	SUMMARY & CONCLUSIONS
APPENDIX A:	Strong-Motion Data from the Perry Nuclear Power Plant Seismic Instrumentation (Kinematics)
APPENDIX B:	Report on the Peak Shock Recorders and Peak Acceleration Recorders Installed at the Perry Nuclear Power Plant during the Seismic Event on January 31, 1986 (Engdahl Enterprises)
APPENDIX C:	A Preliminary Evaluation of the Significance of the Seismic Event on January 31, 1986 at the Perry Nuclear Power Plant (Stevenson)
APPENDIX D:	Response Spectra Plots
APPENDIX E:	Results of Specific Inspections Evaluation of Walkdown Items Plant Settlement Readings Seismic Clearance Walkdown Cooling Tower Walkdown Review of Energized Circuits

1.0 INTRODUCTION

The purpose and scope of this report is to provide the results of The Cleveland Electric Illuminating Company seismic event evaluation for the Perry Nuclear Power Plant. The discussions contained herein provide the basis for CEI's conclusions that the January 31, 1986 earthquake in the vicinity of the Perry site:

- 1) did not adversely effect the plant structures, systems or components,
- 2) was within the design capability of the Perry Nuclear Power Plant, and
- 3) does not change the licensing basis or conclusions regarding the site geology, seismology or design basis earthquake.

This evaluation report addresses the key issues related to the January 31 earthquake including the immediate response to the event, and the plant status and impact assessments following the earthquake. Detailed evaluations of the geological and seismological implications of this event and an analysis of the plant seismic design basis capabilities are presented. In addition, a description is provided of the confirmatory programs to monitor post seismic event activity, to continue the evaluations to identify any earthquake related effects, and to participate in generic industry studies.

Event

At approximately 11:48 a.m. on January 31, 1986, an earthquake occurred, which was located about 10 miles south of the Perry site and had a Richter magnitude of approximately 5.0. CEI implemented the Perry emergency plan in response to the seismic event as described in the attached chronology. A site area emergency was declared as a precautionary measure for site personnel accountability and for informational notification to local officials. Timely notifications were made and plant staff responded professionally and successfully implemented the plant procedures for this type of an event.

Plant Response and Assessments

Immediately following the earthquake, plant operations personnel were dispatched into the plant to survey for any major damage. The initial reports indicated no damage. Subsequently, a team of approximately 65 engineers and technicians was organized to perform a detailed walkdown of all plant areas. These inspections found no damage to any systems, structures or components. The hairline cracks in concrete walls that were observed have been reviewed and found to be typical of reinforced concrete structures which have not experienced seismic events. Numerous safety-related systems in operation or standby readiness continued to operate without incident.

Earthquake Analysis

Based on United States Geological Survey (USGS) recorded data, the earthquake of January 31, 1986 was centered about 10 miles south of the Perry Site and had a Richter magnitude of 4.96. This is a lesser magnitude than the earthquakes for which the Perry Plant has been analyzed and had substantially lower total energy content than the

Perry design response spectra. The January 31 earthquake is consistent with the previously established geology and historical seismicity of the region, as described in the Final Safety Analysis Report. The earthquake does not change the conclusions of the FSAR on the geology and seismicity of the site area.

Seismic Design Evaluation

Acceleration data taken from the in-plant seismic recorders showed recorded floor response spectra in certain locations outside the design spectra at high frequencies. The design spectra are based on a statistical envelope of historical earthquakes (84th percentile) and, therefore, some instances of recorded responses exceeding predicted floor responses are expected. The possibility of high frequencies outside the spectra has been evaluated at other nuclear plant sites and concluded to have insignificant effect on plant structure and components.

CEI analysis shows the high frequency accelerations involved are of a very short duration and the velocities are well below those which could cause damage even to non-engineered structures. The total energy associated with these high frequency accelerations is small, and therefore has no adverse impact on plant structures and equipment. Thus, the high frequency accelerations have no engineering significance and the effects of the earthquake experienced at Perry are well within the seismic capability of the plant.

January 31, 1986 Earthquake

Chronological Summary of Events

<u>Time of Occurrence</u>	<u>Event</u>
11.46:42.3 (USGS data)	Seismic event occurs
1148	Control room reports noise & vibration to to Systems Operation Center
1150	Main generator breaker reported open, isolating main and auxiliary transformer, automatically shifting to startup transformer. Auxiliary boiler trips noted Seismic alarms received in P680
1155	Trip of instrument air compressor noted
1200	Visual inspection of lower areas of Turbine Building, Auxiliary Building, Intermediate Building and transformer yard satisfactory
1201	Shift Supervisor sounds Plant Emergency Alarm
1204	Visual inspection of Turbine Building, Turbine Power Complex, Intermediate Building, Auxiliary Building and Control Complex satisfactory.
1206	Shift Supervisor declares precautionary Site Area Emergency, makes Evacuation Announcement.
1211	Auxiliary boiler restarted
1216	Notifications to CEI emergency personnel pursuant to Emergency Plan began
1218	Initiated retrieval of seismic plates and magnetic tapes from seismic instrumentation
1219	Visual inspection of service water and emergency service water pump house satisfactory
1225-1240	Initial notifications of Site Area Emergency provided to Lake, Geauga and Ashtabula counties, the State of Ohio, Coast Guard, NRC
1230	Visual inspection of cooling towers and basins satisfactory
1232	Operational Support Center (OSC) activated

Time of OccurrenceEvent

1235	Technical Support Center (TSC) activated
1251	Initial inspections of all Unit 1 and Common areas completed with satisfactory results, only minor problems noted.
1254	Visual inspection of suppression pool satisfactory
1257 - 1301	TSC completes precautionary Site Area Emergency Follow-up Notifications to Counties, State, Coast Guard
1300	Walkdown of all Unit 1 areas has finds no major equipment damage and noted minor flange leaks.
1302	Site Area Emergency downgraded to Alert
1303 - 1315	Initial Notification of downgrading to Alert made to Counties, State, Coast Guard and NRC.
1305	Three teams dispatched for additional system walkdowns; six maintenance teams dispatched to investigate equipment
1340 - 1401	Follow-up notification of Alert status provided to Counties, State, Coast Guard and NRC
1341	INPO contacted
1420	NRC - Bethesda and Region III concur on termination of emergency
1425	Termination of Emergency Event
1431 - 1442	Termination of Emergency Event reported to Counties, State, Coast Guard, & NRC.
1440	INPO notified of termination of Emergency Event
1531	Deactivated TSC.
1552	Seismic alarm P969 reset
1630	Recovery organization met to review seismic event, emergency response and confirmatory actions.

RECOVERY ORGANIZATION

RECOVERY
MANAGER

M. R. EDELMAN

M. D. LYSTER
A. KAPLAN

EMERGENCY
PLAN
ACTIONS

S. F. HENSICKI

OPERATIONS

R. A. STRATMAN

M. W. SHYLER

MAINTENANCE
AND
WORK ORDERS

D. J. TAKACS

M. COHEN
S. R. LEIDICH

ENGINEERING

F. R. STEAD

LICENSING

E. M. BUZZELLI

L. D. BECK

PUBLIC
RELATIONS
AND
MEDIA

M. E. COLEMAN

R. L. FARRELL

3.0 PLANT STATUS AND IMPACT ASSESSMENTS

3.1 PLANT STATUS

Prior to the earthquake that occurred on January 31, 1986, numerous testing, calibration, and work completion activities were being conducted in preparation for fuel load. One major activity was preparation for the Division II Diesel Generator response time testing. As part of this work, all of the safety related components powered from the Division II Diesel were energized and in standby readiness. All of this equipment behaved normally through the event; that is, there were no spurious starts or alarms. Preparations were also underway to move the startup sources. This work had not yet begun when the seismic event occurred. The sources were never actually moved, and remained stored in the upper pools.

In support of the ongoing test and surveillance activities, a significant number of systems were in operation. In addition, numerous other systems were energized and in the standby mode. Lists of the specific safety and non-safety systems energized or operating prior to and during the earthquake are included as Tables 3.1 and 3.2. All of the operating safety-related systems continued to operate through the event. None of the safety-related systems in the standby mode experienced any spurious initiations.

As noted in Table 3.2, a large number of non-safety systems were operating or in the standby mode, and maintained their status throughout the event. Two non-safety items tripped on protective signals as intended by the design. These were the Unit 1 instrument air compressor, which tripped on high vibration, and the auxiliary steam boiler, which tripped due to actuation of one of its protective

circuits. The instrument air compressor is a centrifugal machine that operates at greater than 40,000 rpm and as part of its protective devices has a very sensitive vibration switch. The auxiliary steam boiler has several protective circuits of which one tripped during the earthquake. The boiler was successfully restarted after the event.

The only other non-safety items of equipment that tripped during the earthquake were the Unit 1 main and auxiliary transformers, which tripped due to the closing of the generator protection relays. These relays although open at the time of the seismic event, did not have voltage applied as a result of an ongoing outage. Laboratory testing of these relays since the event has confirmed that the presence of voltage on the relays significantly increases the force required to close these relays. Had the voltage been supplied to these relays, they would not have closed during the event. This is substantiated by the fact that other similar open relays with voltage applied did not close during the event.

Investigation is ongoing to determine the cause of an indicated 1 1/2 inch increase in suppression pool level. No basis for a physical change in the water level has been identified. The water level transmitters were found to be out of calibration, though not enough to account for the entire indicated level increase. The same transmitters in other applications did not show any anomalous behavior.

In addition to the emergency plan actions previously discussed, immediately following the event the plant operators performed initial surveys of the plant. Areas visually inspected included the Transformer Yard, lower elevations of the Turbine, Auxiliary, Intermediate and Radwaste Buildings, as well as the Control Complex, Turbine Power Complex, Heater Bay and Water Treatment Building. The reports back to the Control Room indicated that the areas were found in satisfactory condition with no major damage. In addition, the General Supervisor of Operations and the Senior Operations

Coordinator made a specific survey of below grade areas. They found no unusual or abnormal conditions. Further steps taken to assess and evaluate the status of the plant included additional walkdowns by teams of plant maintenance personnel dispatched from the Operations Support Center.

3.3 PLANT IMPACT ASSESSMENT

As part of CEI's response to the earthquake, a team of approximately 65 engineers and technicians was organized on the evening of January 31 to perform systematic and thorough walkdowns of all plant areas. These walkdowns were performed using drawings of each area and checklists of components to inspect for any abnormal conditions. These included such items as piping, hangers, snubbers, valves, pumps, instrumentation and other components. The results of these walkdowns were recorded and compiled into a list of approximately 480 observations, many of which were later determined to be preexisting conditions. None of the observations involved structural damage to the plant or equipment. The 480 observations are typified by minor hairline cracks in concrete, burned out light bulbs and leaking valve or piping flanges, all of which are normal and expected conditions that would be identified in any comprehensive walkdown.

In the inspections that were conducted following the earthquake, plant personnel were instructed to document all unusual or abnormal conditions. Those conducting the inspections did not attempt to determine whether the conditions were the result of the earthquake; instead, discrepant conditions regardless of potential cause were documented to insure that the status of the plant following the earthquake would be fully documented for subsequent evaluation by engineering. Each of the observed discrepant conditions was subsequently evaluated by engineering to determine whether the condition was caused by the earthquake and whether rework or repair was required. The engineering evaluation of the items concluded that 77% were preexisting conditions, and only two minor items, were directly attributable to the earthquake. The remainder,

approximately 100 items, have been classified as indeterminate, i.e., it could not be definitively established that the condition existed prior to the earthquake. About 25% of the approximately 480 items will need rework or repair. (See Appendix E). These will be processed in accordance with a special procedure instituted in response to the earthquake.

A number of other inspections were also performed to determine the effect, if any, on specific plant structures and conditions. A site survey was performed to assess any impact of the earthquake on the site environs, and in particular on the shoreline bluff. No evidence of any earthquake impacts could be found.

A survey of settlement monitoring points was ordered to determine if the earthquake had any effect on building settlement. Monitoring points at various locations around the perimeter of the plant buildings are surveyed on a monthly basis to monitor building settlement. The results of the surveys were that the recorded movements were consistent with those measured in the past, including the amount of change from prior surveys and the absolute elevations. For example, a comparison of the Reactor Building reading with that of February 1985, found that the two readings were identical. Thus, it is concluded that the earthquake had no impact on building settlement. (See Appendix E).

A walkdown of Unit 1 Cooling Tower was performed to determine whether any damage had resulted from the earthquake. The areas inspected included the basin walls, tower columns and footers, internal support columns, baffle system, discharge pipe, and veil. While all inspections were done from ground level, any significant cracks in

the veil would have been readily apparent since they would have been saturated by the previous day's rain. No structural damage was found in any area of the cooling tower. Water was observed seeping through the north and south vertical joints where the basin plume wall and pump house flume wall meet. Seepage at this joint has been noted in the past and stopped by the application of mastic material. (See Appendix E).

As part of the design program for the plant, seismic clearance criteria were established to assure that a seismic event would not cause any impact on a safety system either by causing swaying or by impact from a non-safety item. Instances of these criteria not being met are termed Seismic Clearance Violations (SCV's). SCV's are forwarded to engineering for evaluation to determine whether repair is required. At the time of the earthquake, there were 29 SCV's that had been dispositioned for repair, where the repair had not yet been completed. Following the earthquake, inspectors were directed to reinspect these SCV's to determine whether the seismic event affected the SCV condition. These inspections found neither damage nor dimensional change. (See Appendix E).

As previously noted, the plant systems, both safety related and non-safety related, operated properly during and following the seismic event. Recognizing the sensitivity of electrical components to high frequency response, a detailed engineering study was undertaken to identify the number and types of electrical equipment that was energized during the earthquake. The components included motors, transformers, relays, switchgear breakers, switches, batteries, contacts, valve operators, chargers/inverters, meters, recorders, and transmitters. A wide variety of suppliers was represented. More than 70 separate systems were involved. The study showed that over 47,000 electrical components were energized and experienced no adverse effects in terms of spurious system actuation (See Appendix E).

TABLE 3.1

SAFETY RELATED SYSTEMS
ENERGIZED DURING THE SEISMIC EVENT
OF JANUARY 31, 1986

<u>SYSTEM</u>	<u>DESCRIPTION</u>
C11	Control Rod Drive
C41	Standby Liquid Control
C71	Reactor Protection System
D17	Plant Radiation Monitors
E12	Residual Heat Removal
E21	Low Pressure Core Spray
E22	High Pressure Core Spray
G41	Fuel Pool Cooling and Cleanup
M15	Annulus Exhaust Gas Treatment
M23	MCC, Switchgear, & Misc. Area HVAC
M24	Battery Room Exhaust
M25	Control Room HVAC
M26	Control Room Emergency Recirculation
M32	ESW Pumphouse Ventilation
M40	Fuel Handling Building Ventilation
M43	Diesel Building Ventilation
P11	Condensate Transfer and Storage
P22	Mixed Bed Demineralizer
P41	Service Water
P42	Emergency Closed Cooling
P43	Nuclear Closed Cooling
P45	Emergency Service Water
P47	Control Complex Chill Water
P49	ESW Screen Wash
P52	Instrument Air
P54	Fire Protection
C95	Emergency Response Information System
P51	Service Air
R14	110 VAC Vital Inverters
R22	Metalclad Switchgear
R23	480 V Load Centers
R24	Motor Control Centers
R25	Distribution Panels - 120, 208 & 480 volts
R42	D. C. System
R43	Standby Diesel Generator (SDG)
R45	SDG Fuel Oil
R46	SDG Jacket Water Coolant
R47	SDG Lube Oil
R61	Main Control Room Annunciator

TABLE 3.2

NON-SAFETY RELATED SYSTEMS
ENERGIZED DURING THE SEISMIC EVENT
OF JANUARY 31, 1986

<u>SYSTEM</u>	<u>DESCRIPTION</u>
F42	Fuel Transfer Equipment
G33	Reactor Water Cleanup
M11	Containment Vessel Cooling
M13	Drywell Cooling
M21	Controlled Access HVAC
M27	Computer Room HVAC
M35	Turbine Building Cooling & Ventilation
M36	Off-Gas Building Exhaust
M41	Heater Bay Ventilation
M45	Circulating Water Pump House Ventilation
N21	Condensate
N23	Condensate Filtration
N24	Condensate Demineralizers
N32	Turbine Control (EHC)
N71	Circulating Water
P20	Water Treatment
P21	Two Bed Demineralizer
P44	Turbine Building Closed Cooling
P55	Building Heating
P61	Auxiliary Steam
P62	Auxiliary Boiler Fuel Oil
P72	Plant Underdrain
C91	Process Computer
C94	Health Physic Computer
P56	Security
R11	Station Transformers
R15	Technical Support Center UPS
R36	Heat Tracing & Anti Freeze Protection
R44	SDG Starting Air
R51	Intra Plant Communications
R52	Maintenance & Calibration
R53	Exclusion Area Paging System
R57	Radio & In-Plant Antenna System
R71	Lighting
S11	Power Transformers
S41	Step Up Station

4.0 EARTHQUAKE ANALYSIS AND SITE SEISMICITY

An earthquake of magnitude 4.96 M_{blg} occurred on January 31, 1986 at 11 hours, 46 minutes, and 42.3 seconds approximately 11 miles (17.7 kilometers) south of the plant. The depth of the earthquake is presently calculated to be 6 miles (10 kilometers) deep and is located at 41.640° W and 81.098° N by the National Earthquake Information Center of the United States Geological Survey (USGS). This location is near the intersection of Highways 86 and 166 in Thompson Township, Geauga County. The location of this earthquake is shown on Figure 4.1 of this report. Earthquakes which have occurred within 200 miles in historical times, and an update for those occurring within 50 miles of the plant site are shown in Figures 4.2. and 4.3.

4.1 BACKGROUND GEOLOGICAL & SEISMOLOGICAL STUDIES RELATED TO THE PERRY NUCLEAR POWER PLANT

As required by the regulations governing the siting of nuclear power plants, a thorough study of the geological and seismological characteristics of the Perry Nuclear Power Plant site and its regional surroundings was made as part of both the Preliminary Safety Analysis Report (PSAR) and Final Safety Analysis Report (FSAR). The purpose of these investigations was to assure that the site was geologically suitable for the construction of a nuclear power plant and to provide a basis for the determination of a Safe Shutdown Earthquake (SSE) and the site ground motion resulting from the occurrence of such an earthquake. The information contained herein is summarized from the detailed discussions contained in Chapter 2 of the PSAR and FSAR, as reviewed and accepted by the NRC in the Safety Evaluation Reports and Supplements.

These studies were extensive, consisting of a compilation and analyses of published and unpublished literature; field geological checking and mapping including wide scale and local geophysical studies to characterize geological conditions at depth; borings; laboratory analyses; and detailed engineering analysis of the site foundation materials.

Based on these studies and following Appendix A of 10 CFR Part 100, a correlation of earthquakes to a particular fault or series of faults which would be designated as "capable" could not be made. In addition, no "large scale dislocation or distortion" of the earth's crust designated as a tectonic structure could be identified to which earthquakes could be correlated. Consequently, earthquakes were identified with a "tectonic province", representative of a region within which there is a relative consistency of geologic structural features.

To select the SSE, a Modified Mercalli Intensity of VII was chosen as the maximum intensity earthquake at the Perry site. This intensity corresponds to an acceleration value of 0.15g, based upon a number of developed relationships which relate peak acceleration to earthquake intensity values; the principal relationship was developed by Trifunac and Brady. (Trifunac, M.D. and Brady, A.G., 1975, on the Correlation of Seismic Intensity Scales with the Peaks of Recorded Strong Ground Motion: Bulletin of the Seismological Society of America, v. 65, No. 1, pp. 139-162). The response spectra representing the SSE were then developed by adopting a NRC Regulatory Guide 1.60 response spectral shape. The design response spectra are shown on Figures 4.4 and 4.5.

During the review of the FSAR, the NRC staff requested that site-specific spectra be constructed for the Perry site. In response to this request, site-specific response spectra were constructed using a set of ground motion accelerograms from actual earthquakes of magnitude range $5.3 \pm .5$ recorded on rock (to simulate the foundation conditions at Perry) at epicentral distances of 0 to 25 kilometers; this represents the earthquake "at the site" as required by Appendix A and is shown on Figure 4.6.

Eleven (11) earthquakes representing 22 components of motion were chosen. A subset of records accepted by the staff as representative of an Anna, Ohio type earthquake had an average magnitude of $5.53 \pm .3$ at an average distance of 8.5 miles (13.66 ± 4.5 kilometers). A smoothed 84 percentile of this data set fell below the design

response spectra represented by a Regulatory Guide 1.60 spectra set at an acceleration of 0.15 g. These spectra are representative of free field data recorded at locations away from the influence of buildings and structures, and are shown on Figure 4.7.

4.2 REGIONAL GEOLOGY AND TECTONICS

The Perry site is located in the central part of Eastern Stable Platform Tectonic Province, characterized by an upper Precambrian crystalline basement and overlain unconformably by a sequence of Paleozoic sedimentary rocks. Basement rocks of this tectonic province comprise a complex sequence of high grade metamorphics and include: schists, gneisses, marbles, and granulites consolidated during the Grenville Orogeny (950 mya) onto the North American craton.

The basement rocks are overlain by a 5000' thick sequence of sedimentary rocks, Cambrian to Carboniferous in age, which dips less than 5° to the south. (Fig. 4.8). Sedimentary rocks within this sequence of Paleozoic sediments includes shales, salt, sandstone, dolomites, and limestones. In the epicentral region the sedimentary sequence is approximately 2 kilometers thick with the main shock focus well within the crystalline basement.

A thin veneer, generally less than 100' of variable thick Pleistocene deposits, lies unconformably on the sedimentary sequence. These deposits include a lower till, dense and compact (approximately 30' thick) overlain by less compact till, lacustrine deposits and beach deposits.

Post consolidation tectonic deformation in the province includes the following structural elements. Paleozoic structures include broad upwarps: Cincinnati arch, Findlay arch, Kankakee arch, Ozark uplift, Nashville dome, and intervening Michigan and Illinois basins. Uplift and subsidence produced localized faulting and folding. The north northeast-trending Waverly arch of west central Ohio is the nearest upwarp structure.

Faults in the site region include:

- o Chatham sag faults
- o Peck fault, Howell-Northville anticline faults
- o Bowling Green fault
- o Anna Ohio faults
- o Cincinnati arch faults
- o Eastern Ohio faults
- o Western New York faults
- o Appalachian Plateau and Northern Valley and Ridge faults

Within the region only the Clarendon-Linden fault system in western New York is considered active.

4.3 SITE GEOLOGY

In conjunction with the PSAR and FSAR preparation and reviews, intensive geological and geotechnical investigations were conducted at the Perry site including:

- o test borings (maximum depth 730')
- o 42" drilled exploratory shafts
- o in-site testing, plate load tests
- o permeability determinations
- o piezometer installations
- o seismic analyses
- o seismic refraction and seismic shear wave determinations
- o geologic mapping of excavations, tunnels and trenches

Two bedrock structural styles were observed by Gilbert Commonwealth, NRC staff, USGS, and the Corps of Engineers. Gentle northeast-trending folds with two to three foot wavelength and 6" amplitude were attributed to depositional processes. Two larger folds and several related faults were also examined. The folds terminated below foundation grade. Faults with characteristic north over south directed motion become bedding plane detachments at depth. One to

three inch thick gouge occurs in the fault zones. Absence of foreign materials, no recrystallization of country rock or crystallization within fault zone or adjacent fracture zones is interpreted to result from localized low temperature, relatively low stress deformation.

In summary, an approximately 45 foot thick layer, between excavation grade of the deepest onshore foundation excavations and the base of a boulder layer defining the bottom of structureless basal till, experienced deformation (folds, faults) including bedding detachment rotation and buckling, and slight upward thrusting. These features occur in glaciated terrain and are attributed to glacial loading, unloading and/or ice push mechanisms. Similar faulting was studied in the Warner Creek area with the same conclusions.

4.4 DEFORMATION - INTAKE AND DISCHARGE TUNNELS

Three minor low-angle north-northeast striking thrust faults occur in the intake and discharge tunnels to the north beneath Lake Erie. Displacements range between 0.5 and 2.5 feet, upward to the northeast.

Studies undertaken to define tunnel fault geometry included:

- o detailed mapping of tunnel walls
- o reconnaissance of lake bottom
- o lake shore reconnaissance
- o exploratory borings
- o borehole logging, offshore and onshore magnetic surveys
- o review of existing geophysical data
- o isotopic analyses of Lake Erie and fault seepage water

Studies to date fault included:

- o x-ray diffraction
- o clay mineralogic analysis
- o microcrack
- o consolidation of gouge

Miscellaneous studies included:

- o borehole stress
- o structure contour maps
- o interviews with knowledgeable Ohio geologists

Investigations of the vertical and lateral extent of faulting indicated that the faulting did not extend upward to the lake floor. Borings at the projected western shoreline intersection showed no faulting. Conclusions reached from detailed mapping of the tunnel faults, geophysical surveys, borings, and analysis of fault gouge and seepage included:

- o faults are genetically related; same fault or an echelon
- o faults confined in Chagrin shale; limited lateral and vertical extent
- o date of last motion is Pleistocene or older
- o motion sense indicates faults originated in northwest directed stress field, approximately 90° from present stress field
- o possible mechanisms of nontectonic glacial origin include ice sheet traction, differential downwarp, differential rebound, surficial stress relief ("pop up")
- o geologic processes responsible for initiation and latest motion are nontectonic and no longer operative; therefore faults are not capable according to Appendix A to 10 CFR 100

4.5 CURRENT SEISMOLOGICAL AND GEOLOGICAL STUDIES

Immediately after the occurrence of the earthquake, CEI undertook a number of geological and seismological investigations to provide a thorough understanding of the earthquake and assess any impact on previous studies performed for the siting and licensing of the Perry Nuclear Plant.

In addition to the investigations undertaken by CEI, USGS, as well as various universities and private groups, have deployed instruments to study earthquake aftershocks.

Portable Seismographic Network

At the request of CEI, Weston Geophysical Corporation installed six portable analog seismographs (Sprengnether Instrument Co. MEG-800) in the epicenter area of the January 31, 1986 earthquake during the period from approximately 10 hours to 30 hours after the event.

These seismograph stations are located at the Perry Nuclear Plant and in the communities of Chardon, Chesterland, Middlefield, Hartsgrove, and Thompson. A seventh station was installed on February 4, 1986 in the town of Concord. This spatial distribution of the stations is designed to form a symmetrical array around the preliminary epicentral area of the main shock, which was located in the basin of more distant stations. All instruments are operated continuously and all seismograms are recovered and analyzed daily. The purpose of this network is to obtain accurate locations of any recorded aftershocks, to refine the original location of the main shock, and to determine whether or not their occurrence reveals anything about the causative geologic structure.

Five other portable instruments integrated into this network are operated by Woodward-Clyde Consultants and deployed in a similar configuration to provide additional locationing capabilities.

Five small microearthquakes have been detected. The parameters of these earthquakes are located on the Table 4-1. Preliminary analyses indicate that the focal depths for these microearthquakes range from 2.3 to 8.9 kilometers. The largest of these microearthquakes, a magnitude 2.4 event on February 6, 1986, was the only event to be felt. These microearthquake locations are slightly to the west of the preliminary location of main shock provided by the National Earthquake Information Center.

Felt Intensity Investigation

A questionnaire survey is being conducted to evaluate the distribution of effects, including a general description of how people experienced the event and accounts of any damage that have been incurred. The questionnaires are being distributed using several parallel approaches to obtain broad coverage of the affected areas. Analysis and compilation of questionnaire results will be used to produce an "isoseismal map" or plot of intensity levels measured on the Modified Mercalli Scale. The purpose of such a map is to enable a comparison of effects of the present event with a well-known epicenter to the effects of some historical events located in the site area that have no well-determined instrumental epicenter.

Weston Geophysical personnel have been conducting personal interviews on perception and other effects of the earthquake in the epicenter region. Questionnaires have been distributed at establishments such as fire departments, grocery stores, schools, etc. with instructions to distribute these to persons near the earthquake epicenter. These reports will be used to recover information on the range of effects.

A preliminary evaluation of returned questionnaires indicates that most of the reports in the epicentral area are evaluated as representative of an Intensity VI on the Modified Mercalli Scale. Maximum observed or reported effects include a few instances of damaged chimneys above the roof line, cracks in concrete and cinder block walls, cracked or fallen plaster, and few broken windows. Some disturbances including silting of well-water have also been reported.

Geologic Studies

Weston Geophysical geologists have conducted preliminary reconnaissance of bedrock exposures in the epicentral area to determine whether or not any surface expression resulted from the earthquake. No significant expression of surface disturbance has been observed. Although several occurrences of minor rock slides and soil slumps have been documented and photographed, these are not considered unusual, since they occur in unstable, undercut stream banks where they could have been caused by ordinary weathering processes or induced vibratory ground motion from the earthquake.

Previously mapped fault locations on Paine Creek have been examined. No evidence of recent fault movement was observed. Also, no slumping or sliding of the steep slope was apparent. No evidence suggestive of a "capable fault" has been observed.

On-going work includes examination of other geological features, as well as an investigation of sites of unusual felt reports such as foundation damage and water-well disturbance. A field observation and evaluation of soil and rock conditions at such sites is being made to determine whether or not there is a correlation between the higher intensity values and geological conditions.

The earthquake, both as regards to magnitude and intensity, is below the maximum earthquake selected to represent the Safe Shutdown Earthquake. The intensity of the Safe Shutdown Earthquake was selected as intensity VII. It is estimated that the present earthquake is best represented by an intensity VI. The magnitude $4.96 M_{blg}$ of the January 1986 earthquake is below the magnitude of 5.3 ± 5 , used in establishing the site specific response spectra.

Based on the initial data evaluation, it appears that the free field design response spectra constructed to represent the SSE may have been exceeded. An accelerogram at the foundation level of Unit 1 showed a peak acceleration of 0.18 g at approximately 20 Hz on the north-south component. The duration of the motion on foundation above the smoothed ground response spectra (SSE) is less than 0.1 second. Since both the Regulatory Guide 1.60 ground motion and the site-specific spectra represent a smoothed spectra at the 84th percentile for a number of strong motion accelerograms, exceedances above the smoothed spectra are not unexpected.

At the high frequency end of the spectra, where the 20 Hz exceedance exists, it is important to look at the other parameters of ground motion. The particle velocity associated with the 0.18 g. is 0.55 inch per second and the displacement is 0.004 inch. This velocity value would be far less than the 1 inch per second generally accepted by the US Bureau of Mines as the threshold of damage at the 20 Hz frequency: cracking of plaster walls, etc. to ordinary structures. (Siskind, D.E. et al., 1980, Structure Response and Damage Produced by Ground Vibrations from Surface Mine Blasting, Bureau of Mines RI 8507). Structural damage therefore is not a problem.

The area and region in which the January 31, 1986 earthquake occurred is one of low seismicity. Prior to 1986, the largest earthquake to occur within 50 miles of the site occurred in 1943. The 1986 Ohio earthquake is slightly larger in magnitude (4.9 vs. 4.7) and intensity (VI vs. V) than the March 9, 1943 earthquake which occurred approximately 12 miles west-southwest of the 1986 earthquake. Although somewhat larger than historical earthquakes within 50 miles of the plant site, it is smaller than those within 200 miles of the site, as well as those on which the plant design is based. This earthquake is consistent with the seismicity of the area and the area and region are still of low seismicity.

Geological investigations to date have not uncovered any evidence suggestive of a "capable fault" as defined in 10 CFR Part 100, nor has the investigation revealed a cause for any geological concern. The 1986 earthquake does not change the conclusions in the FSAR on the geology and seismology of the Perry site.

Table 4.1

RECENT EARTHQUAKES
IN THE SITE VICINITY

<u>DATE</u>	<u>ORIGIN</u> (1) <u>TIME</u>	<u>LATITUDE</u>	<u>LONGITUDE</u>	<u>PRELIMINARY</u> <u>DEPTH</u> (KM)	<u>MAGNITUDE</u>
22-JANUARY-1983	07:46:57.9	41°51.24'	81°11.46'	5	2.7M _{bl.g} ⁽²⁾
31-JANUARY-1986	16:46:42.3	41°38.84'	81°05.30'	10	4.9 M _b ⁽³⁾
01-FEBRUARY-1986	18:54:49.7	41°38.39'	81°09.99'	3.1	--
02-FEBRUARY-1986	03:22:49.1	41°38.37'	81°09.81'	2.3	--
03-FEBRUARY-1986	19:47:19.6	41°39.19'	81°10.27'	9	--
05-FEBRUARY-1986	06:34:02.4	41°39.93'	81°09.11'	6	--
06-FEBRUARY-1986	18:36:22.6	41°38.66'	81°09.80'	5	2.4

(1) UNIVERSAL Time Unless Noted As Local Time

(2) SOURCE: University of Michigan

(3) SOURCE: National Earthquake Information Center (NEIC)



REGIONAL TECTONIC ELEMENTS

Greenland Basement - Ages around 950 million years
(Shaded: Exposed, Non-pottered Buried)

Keweenaw Basement - Ages around 1100 million years

Elston Basement - Ages around 1450 million years

Structure contours in feet drawn on the top of Precambrian basement surface

Thrust fault - teeth on upper plate

Normal fault - halchures on downthrown side

High angle fault

Anticlinal axis

Intensely disturbed "Cryptoexplosive" structure

(f) Primary basement structure sources: Rayley & Muehlberger, 1968, Stone et al., 1975, Owens, 1967



REGIONAL TECTONIC PROVINCES

PROVINCE BOUNDARY

EARTHQUAKES




Figure 4.2


Am. 10 (11-29-82)



PERRY NUCLEAR POWER
THE CLEVELAND ELECTRIC
ILLUMINATING COMPANY

Regional Tectonics -
Earthquake Tectonic Provi-

Figure 2.5-59






Figure 4.3




Figure 4.4



PERRY NUCLEAR POWER PLANT
THE CLEVELAND ELECTRIC
ILLUMINATING COMPANY

Safe Shutdown Earthquake
Design Response Spectra -
Vertical Motion

Figure 3.7-2





Figure 4.5

	<p>PERRY NUCLEAR POWER PLANT THE CLEVELAND ELECTRIC ILLUMINATING COMPANY</p>
	<p>Safe Shutdown Earthquake Design Response Spectra - Horizontal Motion</p>
	<p>Figure 3.7-1</p>



MEDIAN, MEAN AND 84TH PERCENTILE
RESPONSE SPECTRA FOR PERRY (ROCK) SITE.
(BASIC SUBSET, 5% DAMPING)


$$m_{BLG} = 5.3 \pm .5$$

Am. 10 (11-29-82)




PERRY NUCLEAR POWER PLANT
THE CLEVELAND ELECTRIC
ILLUMINATING COMPANY

Figure 230.6-2



MEDIAN, MEAN AND 84TH PERCENTILE
RESPONSE SPECTRA FOR PERRY (ROCK) SITE
(Basic Subset, Parkfield Included, 5% Damping)

$$m_{bLG} = 5.53 \pm .3$$

	PERRY NUCLEAR POWER PLANT THE CLEVELAND ELECTRIC ILLUMINATING COMPANY
	Figure 230.6-5




Figure 4.8

Three different types of seismic monitoring instrumentation were used to record the 1986 Ohio Earthquake. Table 5.1 and Figure A through H and J delineate the specific instrument number, type and location. One type of instrument used is the Kinemetrics Model SMA-3 strong motion triaxial time-history accelerograph. This system detects and records three mutually perpendicular components of acceleration over the entire duration of the earthquake onto cassette magnetic tape. Power to the unit is supplied by internal rechargeable batteries which are kept in a charged state by 120 VAC line power. Two instruments of this type were used and were located on the Reactor Building Foundation Mat at an elevation of approximately 575 feet. Their latest calibration was December 1, 1985. See Appendix A for further instrumentation details and data tabulation.

The second type of instrumentation used was the Engdahl PSR 1200-H/V response spectrum recorder. This totally mechanical system also records three mutually perpendicular components of acceleration. The instrument used twelve reeds fabricated of varying lengths and weights of spring steel, one for each frequency (ranging from approximately 2 Hz to 25 Hz). A diamond-tipped stylus is attached to the free end of each reed to inscribe a permanent record of its deflection on one of twelve record plates. The record plates are made of aluminum and plated with successive layers of nickel, tin and lead-tin. This system is totally self-contained and requires no outside power source.

Four instruments of this type were used - two on the Auxiliary Building Foundation Mat and an elevation of approximately 568 feet, one at the Reactor Building Foundation Mat at an elevation approximately 575 feet, and one at the Reactor Building Inside Drywell Platform at an elevation of approximately 630 feet. Except for the one instrument located on the Reactor Building platform which was calibrated on January 30, 1986, all instruments of this type were calibrated during January 1985. See Appendix B for further instrumentation details and data tabulation.

The third type of instrument was the Engdahl PAR 400 peak accelerograph. This totally mechanical system records three mutually perpendicular components of peak local acceleration (i.e., the zero period acceleration). A diamond tipped scribe at the end of an amplifier arm records a permanent mark on a record plate made of aluminum and successive layers of nickel, gold and burnt gold. Again, this system is totally self-contained and requires no outside power source. Two instruments of this type were used and were located on the Auxiliary Building Foundation Mat at an elevation of approximately 568 feet and on the Reactor Recirculation Pump at the elevation of approximately 605 feet. The latest calibration date for the Auxiliary Building instrument was January 30, 1986, while the calibration date for the Recirculation Pump instrument was December 4, 1985. A third instrument of this type was out of service at the time of the earthquake because it was being recalibrated. See Appendix B for further instrumentation details and data tabulation.

All recorded data from the in-plant seismic instruments have been used in the evaluation.

**PERRY NUCLEAR POWER PLANT UNIT NO. 1
SEISMIC MONITORING INSTRUMENTATION**

TABLE 5.1

Instrument Number	Type	Manufacturer / Model Number	Location	References
D51-N101	(1)	Kinematics / SMA-3	Reactor Building Foundation Mat Elevation 575'-10" Azimuth 175°	Figures A and B
D51-N111	(1)	Kinematics / SMA-3	Reactor Building Containment Vessel Elevation 686'-0" Azimuth 174°	Figures A and C
D51-R120	(2)	Engdahl / PAR-400	Reactor Recirculation Pump (Inside Drywell, Reactor Building) Elevation 605'-0" (Approximately) Azimuth 145°	Figures A and D
D51-R130	(2)	Engdahl / PAR-400	OUT OF SERVICE	
D51-R140	(2)	Engdahl / PAR-400	Auxiliary Building Foundation Mat (HPCS Pump Room) Elevation 568'-4"	Figures A and E

1. Triaxial Time-History Accelerograph
2. Triaxial Peak Accelerograph
3. Triaxial Response Spectrum Recorder


PERRY NUCLEAR POWER PLANT UNIT NO. 1
SEISMIC MONITORING INSTRUMENTATION

TABLE 5.1

Instrument Number	Type	Manufacturer / Model Number	Location	References
D51-R160	(3)	Engdahl / PSR-1200-H / V-12A	Reactor Building Foundation Mat Elevation 574'-10" Azimuth 225°	Figures A and F
D51-R170	(3)	Engdahl / PSR-1200-H / V	Reactor Building 630' Platform (Inside Drywell) Elevation 630'-1" Azimuth 238°	Figures A and G
D51-R180	(3)	Engdahl / PSR-1200-H / V	Auxiliary Building Foundation Mat (HPCS Pump Room) Elevation 568'-4"	Figures A and H
D51-R190	(3)	Engdahl / PSR-1200-H / V	Auxiliary Building Foundation Mat (RCIC Pump Room) Elevation 568'-4"	Figures A and J

1. Triaxial Time-History Accelerograph
2. Triaxial Peak Accelerograph
3. Triaxial Response Spectrum Recorder

FIGURE A
Sheet 1 of 2



KEY:

- ① Instrument #D51-N101
- ② Instrument #D51-N111
- ③ Instrument #D51-R120
- ④ Instrument #D51-R140
- ⑤ Instrument #D51-R160
- ⑥ Instrument #D51-R170
- ⑦ Instrument #D51-R180
- ⑧ Instrument #D51-R190






FIGURE A
Sheet 2 of 2



1. #D51-N101 R/B Foundation Mat, El. 575', Az. 175°
2. #D51-N111 R/B Containment Vessel, El. 686', Az. 174°
3. #D51-R120 Reactor Recirc Pump, El. 605', Az. 145°
4. #D51-R140 A/B Foundation Mat, El. 568'
5. #D51-R160 R/B Foundation Mat, El. 574' Az. 225°
6. #D51-R170 R/B Platform, El. 630' Az. 238°
7. #D51-R180 A/B Foundation Mat, El. 568'
8. #D51-R190 A/B Foundation Mat, El. 568'



[illegible]JOHNSON
CONTROLS.

Copyright © 2000 by John Wiley & Sons, Inc.

SEISMIC INSTRUMENTATION
INSTALLATION DETAIL FOR
Q051-N101

1011-1500	06	1011-1500
-----------	----	-----------


NAME		ADDRESS		CITY		STATE		ZIP		COUNTRY	
1	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
2	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
3	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
4	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
5	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
6	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
7	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
8	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
9	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					
10	Mr. J. H. Smith	123 Main St.	Springfield	Mass.	01103	U.S.A.					

1000

[illegible]

1000 900 800 700 600 500 400 300 200 100 0

100



CELESTIAL WOTTS

- | Model | Year | Make | Model | Year | Make |
|-------|------|------|-------|------|------|
| 1980 | 1980 | 1980 | 1980 | 1980 | 1980 |
| 1981 | 1981 | 1981 | 1981 | 1981 | 1981 |
| 1982 | 1982 | 1982 | 1982 | 1982 | 1982 |
| 1983 | 1983 | 1983 | 1983 | 1983 | 1983 |
| 1984 | 1984 | 1984 | 1984 | 1984 | 1984 |
| 1985 | 1985 | 1985 | 1985 | 1985 | 1985 |
| 1986 | 1986 | 1986 | 1986 | 1986 | 1986 |
| 1987 | 1987 | 1987 | 1987 | 1987 | 1987 |
| 1988 | 1988 | 1988 | 1988 | 1988 | 1988 |
| 1989 | 1989 | 1989 | 1989 | 1989 | 1989 |
| 1990 | 1990 | 1990 | 1990 | 1990 | 1990 |
| 1991 | 1991 | 1991 | 1991 | 1991 | 1991 |
| 1992 | 1992 | 1992 | 1992 | 1992 | 1992 |
| 1993 | 1993 | 1993 | 1993 | 1993 | 1993 |
| 1994 | 1994 | 1994 | 1994 | 1994 | 1994 |
| 1995 | 1995 | 1995 | 1995 | 1995 | 1995 |
| 1996 | 1996 | 1996 | 1996 | 1996 | 1996 |
| 1997 | 1997 | 1997 | 1997 | 1997 | 1997 |
| 1998 | 1998 | 1998 | 1998 | 1998 | 1998 |
| 1999 | 1999 | 1999 | 1999 | 1999 | 1999 |
| 2000 | 2000 | 2000 | 2000 | 2000 | 2000 |
| 2001 | 2001 | 2001 | 2001 | 2001 | 2001 |
| 2002 | 2002 | 2002 | 2002 | 2002 | 2002 |
| 2003 | 2003 | 2003 | 2003 | 2003 | 2003 |
| 2004 | 2004 | 2004 | 2004 | 2004 | 2004 |
| 2005 | 2005 | 2005 | 2005 | 2005 | 2005 |
| 2006 | 2006 | 2006 | 2006 | 2006 | 2006 |
| 2007 | 2007 | 2007 | 2007 | 2007 | 2007 |
| 2008 | 2008 | 2008 | 2008 | 2008 | 2008 |
| 2009 | 2009 | 2009 | 2009 | 2009 | 2009 |
| 2010 | 2010 | 2010 | 2010 | 2010 | 2010 |
| 2011 | 2011 | 2011 | 2011 | 2011 | 2011 |
| 2012 | 2012 | 2012 | 2012 | 2012 | 2012 |
| 2013 | 2013 | 2013 | 2013 | 2013 | 2013 |
| 2014 | 2014 | 2014 | 2014 | 2014 | 2014 |
| 2015 | 2015 | 2015 | 2015 | 2015 | 2015 |
| 2016 | 2016 | 2016 | 2016 | 2016 | 2016 |
| 2017 | 2017 | 2017 | 2017 | 2017 | 2017 |
| 2018 | 2018 | 2018 | 2018 | 2018 | 2018 |
| 2019 | 2019 | 2019 | 2019 | 2019 | 2019 |
| 2020 | 2020 | 2020 | 2020 | 2020 | 2020 |
| 2021 | 2021 | 2021 | 2021 | 2021 | 2021 |
| 2022 | 2022 | 2022 | 2022 | 2022 | 2022 |
| 2023 | 2023 | 2023 | 2023 | 2023 | 2023 |
| 2024 | 2024 | 2024 | 2024 | 2024 | 2024 |
| 2025 | 2025 | 2025 | 2025 | 2025 | 2025 |
| 2026 | 2026 | 2026 | 2026 | 2026 | 2026 |
| 2027 | 2027 | 2027 | 2027 | 2027 | 2027 |
| 2028 | 2028 | 2028 | 2028 | 2028 | 2028 |
| 2029 | 2029 | 2029 | 2029 | 2029 | 2029 |
| 2030 | 2030 | 2030 | 2030 | 2030 | 2030 |

DATE		TIME		LOCATION		REMARKS	
DAY	MONTH	YEAR	HOUR	MINUTE	PLACE	WIND	SEA
1	2	3	4	5	6	7	8
9	10	11	12	13	14	15	16
17	18	19	20	21	22	23	24
25	26	27	28	29	30	31	32

[illegible]

Table 1. *Continued*

1000

10

1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 26

CONTROLS

PHYSIC INSTRUMENTAL
INSTALLATION DETAIL
0051-1111

[illegible]

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific requirements of the task.

1.1	1.2	1.3	1.4	1.5	1.6	1.7	1.8	1.9	1.10	1.11	1.12	1.13	1.14	1.15	1.16	1.17	1.18	1.19	1.20	1.21	1.22	1.23	1.24	1.25	1.26	1.27	1.28	1.29	1.30	1.31	1.32	1.33	1.34	1.35	1.36	1.37	1.38	1.39	1.40	1.41	1.42	1.43	1.44	1.45	1.46	1.47	1.48	1.49	1.50	1.51	1.52	1.53	1.54	1.55	1.56	1.57	1.58	1.59	1.60	1.61	1.62	1.63	1.64	1.65	1.66	1.67	1.68	1.69	1.70	1.71	1.72	1.73	1.74	1.75	1.76	1.77	1.78	1.79	1.80	1.81	1.82	1.83	1.84	1.85	1.86	1.87	1.88	1.89	1.90	1.91	1.92	1.93	1.94	1.95	1.96	1.97	1.98	1.99	2.00	2.01	2.02	2.03	2.04	2.05	2.06	2.07	2.08	2.09	2.10	2.11	2.12	2.13	2.14	2.15	2.16	2.17	2.18	2.19	2.20	2.21	2.22	2.23	2.24	2.25	2.26	2.27	2.28	2.29	2.30	2.31	2.32	2.33	2.34	2.35	2.36	2.37	2.38	2.39	2.40	2.41	2.42	2.43	2.44	2.45	2.46	2.47	2.48	2.49	2.50	2.51	2.52	2.53	2.54	2.55	2.56	2.57	2.58	2.59	2.60	2.61	2.62	2.63	2.64	2.65	2.66	2.67	2.68	2.69	2.70	2.71	2.72	2.73	2.74	2.75	2.76	2.77	2.78	2.79	2.80	2.81	2.82	2.83	2.84	2.85	2.86	2.87	2.88	2.89	2.90	2.91	2.92	2.93	2.94	2.95	2.96	2.97	2.98	2.99	3.00	3.01	3.02	3.03	3.04	3.05	3.06	3.07	3.08	3.09	3.10	3.11	3.12	3.13	3.14	3.15	3.16	3.17	3.18	3.19	3.20	3.21	3.22	3.23	3.24	3.25	3.26	3.27	3.28	3.29	3.30	3.31	3.32	3.33	3.34	3.35	3.36	3.37	3.38	3.39	3.40	3.41	3.42	3.43	3.44	3.45	3.46	3.47	3.48	3.49	3.50	3.51	3.52	3.53	3.54	3.55	3.56	3.57	3.58	3.59	3.60	3.61	3.62	3.63	3.64	3.65	3.66	3.67	3.68	3.69	3.70	3.71	3.72	3.73	3.74	3.75	3.76	3.77	3.78	3.79	3.80	3.81	3.82	3.83	3.84	3.85	3.86	3.87	3.88	3.89	3.90	3.91	3.92	3.93	3.94	3.95	3.96	3.97	3.98	3.99	4.00	4.01	4.02	4.03	4.04	4.05	4.06	4.07	4.08	4.09	4.10	4.11	4.12	4.13	4.14	4.15	4.16	4.17	4.18	4.19	4.20	4.21	4.22	4.23	4.24	4.25	4.26	4.27	4.28	4.29	4.30	4.31	4.32	4.33	4.34	4.35	4.36	4.37	4.38	4.39	4.40	4.41	4.42	4.43	4.44	4.45	4.46	4.47	4.48	4.49	4.50	4.51	4.52	4.53	4.54	4.55	4.56	4.57	4.58	4.59	4.60	4.61	4.62	4.63	4.64	4.65	4.66	4.67	4.68	4.69	4.70	4.71	4.72	4.73	4.74	4.75	4.76	4.77	4.78	4.79	4.80	4.81	4.82	4.83	4.84	4.85	4.86	4.87	4.88	4.89	4.90	4.91	4.92	4.93	4.94	4.95	4.96	4.97	4.98	4.99	5.00	5.01	5.02	5.03	5.04	5.05	5.06	5.07	5.08	5.09	5.10
-----	-----	-----	-----	-----	-----	-----	-----	-----	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------	------

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

同治十一年


[illegible]

1. THE NATIONAL SERVICE AUTHORITY REPORTING ONLY.


1. The following information was obtained from the records of the Department of the Interior, Bureau of Land Management, Washington, D. C., and is being furnished to you for your information.

Year	Number of cases		Rate per 100,000
	Male	Female	
1970	1,000	1,000	1.0
1971	1,000	1,000	1.0
1972	1,000	1,000	1.0
1973	1,000	1,000	1.0
1974	1,000	1,000	1.0
1975	1,000	1,000	1.0
1976	1,000	1,000	1.0
1977	1,000	1,000	1.0
1978	1,000	1,000	1.0
1979	1,000	1,000	1.0
1980	1,000	1,000	1.0
1981	1,000	1,000	1.0
1982	1,000	1,000	1.0
1983	1,000	1,000	1.0
1984	1,000	1,000	1.0
1985	1,000	1,000	1.0
1986	1,000	1,000	1.0
1987	1,000	1,000	1.0
1988	1,000	1,000	1.0
1989	1,000	1,000	1.0
1990	1,000	1,000	1.0
1991	1,000	1,000	1.0
1992	1,000	1,000	1.0
1993	1,000	1,000	1.0
1994	1,000	1,000	1.0
1995	1,000	1,000	1.0
1996	1,000	1,000	1.0
1997	1,000	1,000	1.0
1998	1,000	1,000	1.0
1999	1,000	1,000	1.0
2000	1,000	1,000	1.0
2001	1,000	1,000	1.0
2002	1,000	1,000	1.0
2003	1,000	1,000	1.0
2004	1,000	1,000	1.0
2005	1,000	1,000	1.0
2006	1,000	1,000	1.0
2007	1,000	1,000	1.0
2008	1,000	1,000	1.0
2009	1,000	1,000	1.0
2010	1,000	1,000	1.0
2011	1,000	1,000	1.0
2012	1,000	1,000	1.0
2013	1,000	1,000	1.0
2014	1,000	1,000	1.0
2015	1,000	1,000	1.0
2016	1,000	1,000	1.0
2017	1,000	1,000	1.0
2018	1,000	1,000	1.0
2019	1,000	1,000	1.0
2020	1,000	1,000	1.0

100



L'EVELL, MARY ELLEN
SUMMERS (MAY 1891, S.A.-36) MAY 10 ± P?



RENT AND RAMP WORK
HITCHCOCK FOR A
COLUMBIA - 24
MAY 1917 - 1918
HITCHCOCK FOR A
COLUMBIA - 24
MAY 1917 - 1918

PLAN VIEW
SECTION

THE OFFICE OF THE ATTORNEY GENERAL

1. ☐ 2. ☐ 3. ☐ 4. ☐ 5. ☐ 6. ☐ 7. ☐ 8. ☐ 9. ☐ 10. ☐ 11. ☐ 12. ☐ 13. ☐ 14. ☐ 15. ☐ 16. ☐ 17. ☐ 18. ☐ 19. ☐ 20. ☐ 21. ☐ 22. ☐ 23. ☐ 24. ☐ 25. ☐ 26. ☐ 27. ☐ 28. ☐ 29. ☐ 30. ☐ 31. ☐ 32. ☐ 33. ☐ 34. ☐ 35. ☐ 36. ☐ 37. ☐ 38. ☐ 39. ☐ 40. ☐ 41. ☐ 42. ☐ 43. ☐ 44. ☐ 45. ☐ 46. ☐ 47. ☐ 48. ☐ 49. ☐ 50. ☐ 51. ☐ 52. ☐ 53. ☐ 54. ☐ 55. ☐ 56. ☐ 57. ☐ 58. ☐ 59. ☐ 60. ☐ 61. ☐ 62. ☐ 63. ☐ 64. ☐ 65. ☐ 66. ☐ 67. ☐ 68. ☐ 69. ☐ 70. ☐ 71. ☐ 72. ☐ 73. ☐ 74. ☐ 75. ☐ 76. ☐ 77. ☐ 78. ☐ 79. ☐ 80. ☐ 81. ☐ 82. ☐ 83. ☐ 84. ☐ 85. ☐ 86. ☐ 87. ☐ 88. ☐ 89. ☐ 90. ☐ 91. ☐ 92. ☐ 93. ☐ 94. ☐ 95. ☐ 96. ☐ 97. ☐ 98. ☐ 99. ☐ 100. ☐

JOHNSON
CONTROLS

1. The first step is to identify the problem or question that needs to be answered. This involves understanding the context and the specific information required.

SEISMIC INSTRUMENTATION
INSTALLATION DETAIL FOR
0051-R120

SP. 90 IF 0051-R120

--	--

10

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----

CHC 1	1
-------	---

1997

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1

1998




After 10 minutes, a group with 100% of the subjects showed a significant decrease in the number of subjects with a positive response to the stimulus.

© 2000 Blackwell Science Ltd

100

100

100

[illegible][illegible]

JOHNSON
CONTROLS.

1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 26

PERMIT NUCLEAR POWER PLANT UNIT 1 & 2

SEISMIC INSTRUMENTATION
INSTALLATION DETAIL FOR
OD51-R140

1000-0001	90 11# 0051-1140	1000-0001
-----------	------------------	-----------

[illegible]

01702600000
01702600000
01702600000


Journal of Interpersonal Violence

11 THE UNITED STATES DISTRICT COURT SOUTHERD DISTRICT OF NEW YORK


12
13
14
15
16
17
18
19
20
21
22
23
24
25

26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52


53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842



[PLAN VIEW](#)
[BOOKING DETAILS](#)



PLAN VIEW
MOUNTING STUD DETAIL



Next to the following
 address the name of the
 person to be notified
 by the letter

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838

ST. JOHN'S
GILSON

© 2000 Blackwell Science Ltd

COSMIC INSTRUMENTATION
INSTALLATION DETAIL FOR
OO 51-N160

0051-0160

[illegible]

1

NAME	ADDRESS	CITY OR ADDRESS
10-1		

[illegible]

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120	121	122	123	124	125	126	127	128	129	130	131	132	133	134	135	136	137	138	139	140	141	142	143	144	145	146	147	148	149	150	151	152	153	154	155	156	157	158	159	160	161	162	163	164	165	166	167	168	169	170	171	172	173	174	175	176	177	178	179	180	181	182	183	184	185	186	187	188	189	190	191	192	193	194	195	196	197	198	199	200	201	202	203	204	205	206	207	208	209	210	211	212	213	214	215	216	217	218	219	220	221	222	223	224	225	226	227	228	229	230	231	232	233	234	235	236	237	238	239	240	241	242	243	244	245	246	247	248	249	250	251	252	253	254	255	256	257	258	259	260	261	262	263	264	265	266	267	268	269	270	271	272	273	274	275	276	277	278	279	280	281	282	283	284	285	286	287	288	289	290	291	292	293	294	295	296	297	298	299	300	301	302	303	304	305	306	307	308	309	310	311	312	313	314	315	316	317	318	319	320	321	322	323	324	325	326	327	328	329	330	331	332	333	334	335	336	337	338	339	340	341	342	343	344	345	346	347	348	349	350	351	352	353	354	355	356	357	358	359	360	361	362	363	364	365	366	367	368	369	370	371	372	373	374	375	376	377	378	379	380	381	382	383	384	385	386	387	388	389	390	391	392	393	394	395	396	397	398	399	400	401	402	403	404	405	406	407	408	409	410	411	412	413	414	415	416	417	418	419	420	421	422	423	424	425	426	427	428	429	430	431	432	433	434	435	436	437	438	439	440	441	442	443	444	445	446	447	448	449	450	451	452	453	454	455	456	457	458	459	460	461	462	463	464	465	466	467	468	469	470	471	472	473	474	475	476	477	478	479	480	481	482	483	484	485	486	487	488	489	490	491	492	493	494	495	496	497	498	499	500	501	502	503	504	505	506	507	508	509	510	511	512	513	514	515	516	517	518	519	520	521	522	523</
--	---	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-----	-------

1

0.0000

1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173, 2174, 2175, 2176, 2177, 2178, 2179, 2180, 2181, 2182, 2183, 2184, 2185, 2186, 2187, 2188, 2189, 2190, 2191, 2192, 2193, 2194, 2195, 2196, 2197, 2198, 2199, 2200, 2201, 2202, 2203, 2204, 2205, 2206, 2207, 2208, 2209, 2210, 2211, 2212, 2213, 2214, 2215, 2216, 2217, 2218, 2219, 2220, 2221, 2222, 2223, 2224, 2225, 2226, 2227, 2228, 2229, 2230, 2231, 2232, 2233, 2234, 2235, 2236, 2237, 2238, 2239, 2240, 2241, 2242, 2243, 2244, 2245, 2246, 2247, 2248, 2249, 2250, 2251, 2252, 2253, 2254, 2255, 2256, 2257, 2258, 2259, 2260, 2261, 2262, 2263, 2264, 2265, 2266, 2267, 2268, 2269, 2270, 2271, 2272, 2273, 2274, 2275, 2276, 2277, 2278, 2279, 2280, 2281, 2282, 2283, 2284, 2285, 2286, 2287, 2288, 2289, 2290, 2291, 2292, 2293, 2294, 2295, 2296, 2297, 2298, 2299, 2300, 2301, 2302, 2303, 2304, 2305, 2306, 2307, 2308, 2309, 2310, 2311, 2312, 2313, 2314, 2315, 2316, 2317, 2318, 2319, 2320, 2321, 2322, 2323, 2324, 2325, 2326, 2327, 2328, 2329, 2330, 2331, 2332, 2333, 2334, 2335, 2336, 2337, 2338, 2339, 2340, 2341, 2342, 2343, 2344, 2345, 2346, 2347, 2348, 2349, 2350, 2351, 2352, 2353, 2354, 2355, 2356, 2357, 2358, 2359, 2360, 2361, 2362, 2363, 2364, 2365, 2366, 2367, 2368, 2369, 2370, 2371, 2372, 2373, 2374, 2375, 2376, 2377, 2378, 2379, 2380, 2381, 2382, 2383, 2384, 2385, 2386, 2387, 2388, 2389, 2390, 2391, 2392, 2393, 2394, 2395, 2396, 2397, 2398, 2399, 2400, 2401, 2402, 2403, 2404, 2405, 2406, 2407, 2408, 2409, 2410, 2411, 2412, 2413, 2414, 2415, 2416, 2417, 2418, 2419, 2420, 2421, 2422, 2423, 2424, 2425, 2426, 2427, 2428, 2429, 2430, 2431, 2432, 2433, 2434, 2435, 2436, 2437, 2438, 2439, 2440, 2441, 2442, 2443, 2444, 2445, 2446, 2447, 2448, 2449, 2450, 2451, 2452, 2453, 2454, 2455, 2456, 2457, 2458, 2459, 2460, 2461, 2462, 2463, 2464, 2465, 2466, 2467, 2468, 2469, 2470, 2471, 2472, 2473, 2474, 2475, 2476, 2477, 2478, 2479, 2480, 2481, 2482, 2483, 2484, 2485, 2486, 2487, 2488, 2489, 2490, 2491, 2492, 2493, 2494, 2495, 2496, 2497, 2498, 2499, 2500, 2501, 2502, 2503, 2504, 2505, 2506, 2507, 2508, 2509, 2510, 2511, 2512, 2513, 2514, 2515, 2516, 2517, 2518, 2519, 2520, 2521, 2522, 2523, 2524, 2525, 2526, 2527, 2528, 2529, 2530, 2531, 2532, 2533, 2534, 2535, 2536, 2537, 2538, 2539, 2540, 2541, 2542, 2543, 2544, 2545, 2546, 2547, 2548, 2549, 2550, 2551, 2552, 2553, 2554, 2555, 2556, 2557, 2558, 2559, 2560, 2561, 2562, 2563, 2564, 2565, 2566, 2567, 2568, 2569, 2570, 2571, 2572, 2573, 2574, 2575, 2576, 2577, 2578, 2579, 2580, 2581, 2582, 2583, 2584, 2585, 2586, 2587, 2588, 2589, 2590, 2591, 2592, 2593, 2594, 2595, 2596, 2597, 2598, 2599, 2600, 2601, 2602, 2603, 2604, 2605, 2606, 2607, 2608, 2609, 2610, 2611, 2612, 2613, 2614, 2615, 2616, 2617, 2618, 2619, 2620, 2621, 2622, 2623, 2624, 2625, 2626, 2627, 2628, 2629, 2630, 2631, 2632, 2633, 2634, 2635, 2636, 2637, 2638, 2639, 2640, 2641, 2642, 2643, 2644, 2645, 2646, 2647, 2648, 2649, 2650, 2651, 2652, 2653, 2654, 2655, 2656, 2657, 2658, 2659, 2660, 2661, 2662, 2663, 2664, 2665, 2666, 2667, 2668, 2669, 2670, 2671, 2672, 2673, 2674, 2675, 2676, 2677, 2678, 2679, 26

Figure 1

100

年份	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100																																																																																																																																																													
人口	115.8	116.5	117.2	117.9	118.6	119.3	120.0	120.7	121.4	122.1	122.8	123.5	124.2	124.9	125.6	126.3	127.0	127.7	128.4	129.1	129.8	130.5	131.2	131.9	132.6	133.3	134.0	134.7	135.4	136.1	136.8	137.5	138.2	138.9	139.6	140.3	141.0	141.7	142.4	143.1	143.8	144.5	145.2	145.9	146.6	147.3	148.0	148.7	149.4	150.1	150.8	151.5	152.2	152.9	153.6	154.3	155.0	155.7	156.4	157.1	157.8	158.5	159.2	159.9	160.6	161.3	162.0	162.7	163.4	164.1	164.8	165.5	166.2	166.9	167.6	168.3	169.0	169.7	170.4	171.1	171.8	172.5	173.2	173.9	174.6	175.3	176.0	176.7	177.4	178.1	178.8	179.5	180.2	180.9	181.6	182.3	183.0	183.7	184.4	185.1	185.8	186.5	187.2	187.9	188.6	189.3	190.0	190.7	191.4	192.1	192.8	193.5	194.2	194.9	195.6	196.3	197.0	197.7	198.4	199.1	199.8	200.5	201.2	201.9	202.6	203.3	204.0	204.7	205.4	206.1	206.8	207.5	208.2	208.9	209.6	210.3	211.0	211.7	212.4	213.1	213.8	214.5	215.2	215.9	216.6	217.3	218.0	218.7	219.4	220.1	220.8	221.5	222.2	222.9	223.6	224.3	225.0	225.7	226.4	227.1	227.8	228.5	229.2	229.9	230.6	231.3	232.0	232.7	233.4	234.1	234.8	235.5	236.2	236.9	237.6	238.3	239.0	239.7	240.4	241.1	241.8	242.5	243.2	243.9	244.6	245.3	246.0	246.7	247.4	248.1	248.8	249.5	250.2	250.9	251.6	252.3	253.0	253.7	254.4	255.1	255.8	256.5	257.2	257.9	258.6	259.3	260.0	260.7	261.4	262.1	262.8	263.5	264.2	264.9	265.6	266.3	267.0	267.7	268.4	269.1	269.8	270.5	271.2	271.9	272.6	273.3	274.0	274.7	275.4	276.1	276.8	277.5	278.2	278.9	279.6	280.3	281.0	281.7	282.4	283.1	283.8	284.5	285.2	285.9	286.6	287.3	288.0	288.7	289.4	290.1	290.8	291.5	292.2	292.9	293.6	294.3	295.0	295.7	296.4	297.1	297.8	298.5	299.2	299.9	300.6	301.3	302.0	302.7



THE UNIVERSITY OF CHICAGO

[illegible][illegible]

Year	1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100
1900	1901	1902	1903	1904	1905	1906	1907	1908	1909	1910	1911	1912	1913	1914	1915	1916	1917	1918	1919	1920	1921	1922	1923	1924	1925	1926	1927	1928	1929	1930	1931	1932	1933	1934	1935	1936	1937	1938	1939	1940	1941	1942	1943	1944	1945	1946	1947	1948	1949	1950	1951	1952	1953	1954	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	

[illegible][illegible]

...the ... of ...

PLAN VIEW
W/0.000 TO 0.000 PL. ELEV.[illegible]

JOHNSON
CONTROLS

SEISMIC INSTRUMENTATION
INSTALLATION DETAIL FOR
DPSI-0190

8-90 0051-R190

[illegible]

DATE	PRODUCTION	OR SET AND ONLY
RELEASED FOR		
THE FOLLOWING LISTING REMAINS IN THE		
STREET NUMBER AND NAME		
CITY		

04/10/2017 17:05
 2017-05-17
 2017-05-17
 2017-05-17

44-38861-10000

The seismic design basis for the Perry Nuclear Power Plant is established by requirements in 10 CFR Part 100, Appendix A and NRC Regulatory Guide 1.60. These regulations require nuclear plant structures and safety class systems and components to be designed to withstand loads induced by a "Safe Shutdown Earthquake" (SSE) for the particular site. The SSE is the strongest earthquake in terms of magnitude of vibratory ground motion that is ever expected to occur at a particular site. The SSE is the design basis earthquake considered for plant licensing. A second seismic event also considered in designing nuclear plants is the "Operating Basis Earthquake" (OBE). The OBE is the strongest earthquake considered likely to occur at a particular site and is at least one-half of the SSE. Operations may resume following an earthquake which exceeds the OBE after demonstrating that no functional damage has occurred to safety-related plant features. (10 CFR Part 100, Appendix A, III(c), V(a)).

The SSE can be described by means of a "response spectrum," which depicts the maximum acceleration, velocity or displacement response to an input excitation (here the SSE) at a specified damping value for single degree-of-freedom oscillators of varying natural frequencies. The high frequency end of a response spectrum indicates the "zero period acceleration" (ZPA) associated with the event. The ZPA is equal to the maximum ground acceleration of the SSE itself.

In the design of any plant, it is difficult to predict the exact shape of postulated earthquake acceleration time-histories and associated ground response spectra. Appendix A of 10 CFR Part 100 therefore requires an expected SSE to be developed by statistically combining the response spectra from multiple historical earthquakes. Following this guideline, the NRC has provided in Reg. Guide 1.60 standardized response spectra that can be used in lieu of spectra developed for each site (see Fig. 6.1). These standardized spectra were derived by normalizing and combining spectra calculated from

numerous sets of historically recorded acceleration time-histories. From these sets of spectra, smoothed response curves (acceleration, velocity and displacement) were generated at a level equal to one standard deviation greater than the mean of the responses. This method provides an 84% level of statistical confidence that responses at any particular frequency will not be exceeded by any future event.

Thus, in lieu of having to develop site-specific SSE ground response spectra, the standardized response spectra of Reg. Guide 1.60 can be used. The standardized spectra need only be scaled up or down to reflect the effective maximum ground accelerations (i.e., ZPA's) expected for the SSE at that site. The SSE design response spectra are used to dynamically analyze a lumped-mass model of the power plant structures.

6.1 DESIGN OF THE PERRY PLANT

The Perry design response spectra were derived by using the standard response spectra of Reg. Guide 1.60 scaled to a ZPA of 0.15 g determined for the Perry site. These spectra served as the design response spectra at the foundation elevations for use in designing the plant buildings.

From these spectra, a simulated SSE time-history of ground accelerations was developed for each directional component (N-S, E-W, and vertical). The conservatism of these simulated time-histories was checked and confirmed by assuring that the response spectra generated from the simulated time-histories envelop the Reg. Guide 1.60 design response spectra (see Fig. 6.2).

Seismic Category I structures were analyzed by applying the simulated time-histories to a lumped-mass model of the entire structure, as shown in Figure 6.3. From this analysis, time-history accelerations at each floor elevation were also derived. These time-histories were then used to derive response spectra for each floor of each main building. The floor response spectra were used in designing the safety class equipment, components, and systems.

In addition to the conservatism included in the derivation of response spectra, there were numerous other conservatisms included in the overall structural design of the Perry structures, systems and components. Examples of some of the more significant conservatisms are as follows:

1. Broadening the Envelope of Floor Response Spectra

Frequency bands of floor responses spectra were artificially broadened (typically by 15%) to account for possible frequency variations. Responses used for design were thus overestimated for systems having more than one dominant frequency falling into the broadened frequency bands of the floor response spectra.

2. Equipment Qualification by Test

Equipment qualified by shake table testing used time-histories simulated from the floor response spectra. The simulated time-histories were generated in such a way that their calculated response spectra envelop the broadened floor response spectra, which in turn already envelop the original design response spectra. The conservatism of the time-histories is increased by this "envelope on top of an envelope" process. Moreover, this process results in simulated time-histories with maximum accelerations much higher than the ZPA's of the floor response spectra.

3. Strain Hardening Not Accounted For and Static Allowables Used for Dynamic Load

In equipment design, material is assumed to behave linearly up to the yield point, then to deform continuously to collapse when the

external load is maintained. All material used in equipment design exhibits characteristics of strain hardening. This means that resistance to deformation increases after the deformation exceeds the yield point. Furthermore, even if no strain hardening is assumed, the material can resist dynamic loads having peak values higher than the yield strength through the absorption of energy in the plastic region.

4. Loading Combinations

The plant was designed to withstand loading combinations with a very low probability of simultaneous occurrence. For example, some load combinations included seismic loads, hydrodynamic loads, and loads due to a hypothetical loss of coolant accident. This results in design capability well above the loads associated with seismic alone.

5. Allowable Stresses

Computed seismic stresses used in design were considered to be primary, non-self-limiting stresses instead of secondary stresses with a self-limiting nature. The actual behavior of seismic stresses is somewhere between a primary and secondary nature. Consideration of seismic stresses as primary stresses results in overestimated values used for design.

6. Damping Values

Conservative damping values were employed at Perry pursuant to NRC Regulatory Guide 1.61. The recent ASME code case N-411 allows increased damping values to be used in the design of nuclear power plant piping systems.

One example of just how significant these types of design conservatisms are is the response of the El Centro Steam Plant (in California) to the 1979 Imperial Valley earthquake. The El Centro Steam Plant was designed to withstand a 0.2 g static lateral load. The recorded peak horizontal load at the site was 0.5 g. The station tripped when station power was lost. One unit was restored to service in 15 minutes and another one in 2 hours. According to calculations performed by Lawrence Livermore Laboratories, the actual loads experienced by the plant were 2 to 9 times higher than the design values. The plant, however, suffered essentially no damage. The El Centro case shows that an engineered structure can indeed resist seismic loads many times higher than their design values.

6.2 EVALUATION OF THE JANUARY 31 EARTHQUAKE

The USGS determined the magnitude of the January 31, 1986 earthquake to be $M_b = 4.9$ with an epicenter at about 11 miles (17.6 Km.) south of the Perry Power Plant site. This is of much less magnitude than the earthquake for which the plant was designed (the SSE) and contained substantially lower total energy than the Perry SSE. Evidence of the low energy content of the January 31 earthquake is shown by a comparison of the acceleration time-histories it induced at various elevations with the corresponding design acceleration time-histories. (See Figs. 6.4 through 6.9). The time-histories used for design are 22 seconds long and of sustained high magnitude (strong motion). By contrast, the January 31 time-histories are about 5 seconds long and contain strong motion in only less than a one-second interval (total) of the event.

A comparison of Figures 6.1 and 6.10 gives a further indication of the low energy content of the January 31 earthquake. These figures show that the Reg. Guide 1.60 spectra used for design have much broader frequency contents than those of the recorded earthquake, which contain strong motion only at high frequencies. The design earthquake therefore contains much greater total energy.

The maximum relative displacements from the recorded time-histories of the recorded earthquake are shown in Table 6.1. A comparison of the total square-root-of-the-sum-of-the-squares (SRSS) recorded relative displacements with the SSE and OBE values shows that the recorded displacements were all far below those values. For example, the overall relative displacement shown in the Table is 0.36 cm for the SSE and 0.10 cm for the actual event. Since stresses in the structures are proportional to relative displacements, and the recorded relative displacements were far less than the SSE design values, the stresses induced by the 1986 earthquake were all well within design capabilities.

Table 6.2 compares the structural response ZPA's of the recorded data with those of the SSE and OBE. The SRSS comparison indicates that the recorded values of the 1986 earthquake vary from significantly below OBE values to 74% of SSE values, except at elevation 686 feet of the Reactor Building Containment Vessel. At that location, the N-S and Vertical acceleration components exceed SSE values, while the E-W acceleration component is less than the SSE value. However, the recorded relative displacements are far less than their design values, as shown in Table 6-1. In addition, recorded response spectra accelerations show that the design response spectra accelerations in certain instances were exceeded at the high frequency end of the spectra. At lower frequencies (at or below approximately 14 Hz) the recorded accelerations are all well under the design values (see response spectra comparisons in Appendix D).

The measurement of accelerations outside the predicted responses at the high frequency ends of certain response spectra has no engineering significance. This is explained by the interrelationships among the frequencies, accelerations, velocities, and displacements associated with a seismic event. In general, high frequency acceleration responses have correspondingly low velocity and displacement responses. The 1986 earthquake accelerations occurred at very high frequencies. Therefore, despite some recorded maximum

acceleration responses which exceeded SSE values at higher frequencies, corresponding velocities and displacements (and resulting stresses) were nevertheless acceptably low.

As discussed, the significant indicators of structural stresses are the relative displacements, and Table 6.1 indicates that relative displacements (and thus stresses) caused by the 1986 earthquake were very small. This is consistent with the high frequency nature of the disturbance. The high frequencies combined with the short duration resulted in an earthquake that contained very low total energy compared to the SSE.

The maximum recorded velocity at the top of the Reactor Building foundation mat during the 1986 earthquake was 0.87 inches/sec (2.21 cm/sec). This can be compared with the Bureau of Mines (BOM) velocity threshold for no damage to non-engineered buildings, which is 1 inch/sec (2.54 cm/sec). This shows that the BOM considers it acceptable for blasting work to induce velocity waves in nearby residential housing foundations that are greater than the maximum velocities induced by the 1986 earthquake at the Perry Plant. This example helps provide perspective on just how low the velocities and energy content of the 1986 event were.

As discussed earlier in this report, extensive plant inspections have indicated that no structural damage resulted from the 1986 earthquake. This is as expected based upon the low energy, short duration, and low velocity and displacement of the event. Although some hairline cracks in the structural concrete were documented during plant walkdowns, this does not constitute damage. Reinforced concrete structures are expected to show hairline cracks. Regardless of their cause, such cracks have no effect on the strength and integrity of the structures. Moreover, such cracking is judged not to be attributable to the 1986 earthquake because of the low magnitude of the event.

Section 7.5 of IEEE 344 "Recommended Practices for Seismic Qualification of Class 1E Equipment for Nuclear Power Generating Stations," was employed at Perry. This standard recognizes that short duration/high frequency/low energy input motions will not cause significant structural stresses. Instead, it requires qualification by long duration/broad band frequency/high energy testing to provide conservatism.

As discussed earlier in this report, all energized plant equipment functioned during this event as designed. To confirm the lack of impact of the high frequency accelerations on plant equipment, CEI is comparing the qualification data for equipment listed in Table 6.3 against recorded response spectra. Although still ongoing, the evaluation to date shows that the original conservatism in the equipment qualification was more than adequate to accommodate the recorded event.

6.3 EVALUATION OF SPECIFIC DATA

In light of the above discussion, recorded responses at particular locations can be evaluated. At all four instrument locations recording response spectra, SSE design spectra are all well above the recorded spectra in the frequency range of 1 Hz to 14 Hz (see Figs. D1 through D12). These figures compare recorded data with the appropriate design spectra at adjacent elevations. These figures also compare the data from different types of seismic instrumentation at the same elevation.

At higher frequencies, the design spectra are exceeded by recorded values in certain cases. However, the corresponding displacements based on recorded data are all extremely small (on the order of several one-hundredths of an inch) at 20 Hz. These extremely low displacements conform to the above analysis demonstrating that the stresses at higher frequencies are insignificant despite acceleration exceedences.

In evaluating all the spectra data recorded at the various locations, it was noted that the acceleration responses at the Reactor Building Platform outside the Biological Shield Wall varied from the general pattern of responses recorded at the other three locations. The recorded N-S and E-W acceleration components for this location are all well-enveloped by the entire range of the SSE spectra while the recorded vertical acceleration component exceeds the SSE spectra at the high frequency end (see Figure D-9). This response may be due to the fact that this particular Engdahl PSR-1200 instrument is located near multiple supports and piping system snubbers and components. Actuation of snubbers or local loads induced by nearby components may thus have influenced the recorded vertical response. Such impacts would be of a local, secondary nature. Regardless, the low energy, short duration, high frequency nature of the event indicates that these accelerations had no structural significance. Indeed, the recorded displacement spectrum value is only 0.023 inches (0.06 cm) at 25 Hz at this location.

In general, the high frequency acceleration content of ground motion will be filtered out by buildings and thus will not appear at higher elevations. This is due in part to the low participation factor generally associated with modes at the higher frequencies. This phenomenon is exhibited by the responses recorded at the Reactor Building mat and elevation 686 feet of the Reactor Building Containment Vessel. A very high frequency p-wave was recorded at the Reactor Building foundation mat. The time-histories shown in Figures 6.4 through 6.9 indicate that this p-wave (appearing during the first second or so of the time-histories) was filtered out by the building and did not appear at elevation 686 feet.

There was a response in the range of 20 Hz that was transmitted to the higher elevations. The explanation for this involves the structural characteristics of the buildings on the Reactor Building foundation mat. The Reactor Building consists of multiple structures sitting on

a common foundation mat--a concrete shield building, steel containment vessel, concrete drywell wall, and biological shield wall. The structural response of each building influences the responses of the others. The frequencies, mode shapes and participation factors of the two most dominant vibration modes are at roughly 4 Hz and 18.4 Hz, as shown in Figures 6.11 through 6.13. These two dominant frequencies correspond to the peaks at 4 Hz and 20 Hz on the recorded spectra for the Reactor Building at the mat and elevation 686 feet. The input motion at 20 Hz (corresponding to the s-wave) was amplified by this latter mode with some rigid body motion. The 20 Hz input was thus not filtered out but did appear at the higher elevation. As discussed, the acceleration peaks at 20 Hz at this location correspond to very small relative displacements and thus are not significant in an engineering sense.

6.4 CONCLUSION

The 1986 Ohio earthquake was a low energy, high frequency, short duration, low velocity, and small displacement event. As a result of these characteristics and the above discussions, the 1986 earthquake had no adverse effects on the Perry structures, systems, or components, and no changes to the Perry seismic design basis are required.

TABLE 6.1

Comparison of Design Displacements¹ VS Recorded Displacements¹

(Expressed in centimeters / one inch = 2.54 cm)

		COLUMN 1	COLUMN 2	COLUMN 2 minus COLUMN 1
		Reactor Building Foundation Mat Elevation 574'-10" SMA-3 (Kinometrics) D51-N101	Reactor Building Containment Vessel Elevation 686' SMA-3 (kinometrics) D51-N111	Relative Displacements for the Containment Vessel
NS	Recorded	0.09	0.17	0.08
	SSE	0.044	0.28	0.24
	OBE	0.023	0.17	0.15
EW	Recorded	0.16	0.21	0.05
	SSE	0.044	0.28	0.24
	OBE	0.023	0.17	0.15
VERT.	Recorded	0.05	0.07	0.02
	SSE	0.02	0.37	0.017
	OBE	0.013	0.022	0.009
SRSS ²	Recorded	—	—	0.1
	SSE	—	—	0.34
	OBE	—	—	0.21

1. Displacements based on same time-step to determine relative displacements

2. Square-root-of-the-sum of the squares

TABLE 6.2
Comparison of Design ZPA's¹ VS Recorded ZPA's
(Expressed in g values)

		Auxiliary Building Foundation Mat Elevation 568' PAR 400 (Engdahl) D51-R140	Reactor Building Foundation Mat Elevation 574'-10" SMA-3 (Kinematics) D51-N101	Reactor Building Recirculation Pump Elevation 605' PAR 400 (Engdahl) D51-R120	Reactor Building Platform Elevation 630' Inside Drywell PSR 1200 (Engdahl) D51-R170	Reactor Building Containment Vessel Elevation 686' SMA-3 (Kinematics) D51-N111
NS	Recorded	.17	.18	.32	.09	.55
	SSE	.17	.18	1.06	.48	.40
	OBE	.10	.10	.86	.40	.24
EW	Recorded	.06	.10	.11	.16	.18
	SSE	.20	.18	1.06	.48	.40
	OBE	.10	.10	.86	.40	.24
VERT.	Recorded	.03	.11	.05	Note 2	.30
	SSE	.20	.18	.47	.28	.24
	OBE	.10	.10	.38	.16	.15
SRSS ³	Recorded	.18	.23	.34	Note 2	.65
	SSE ⁴	.33	.31	1.57	.73	.62
	OBE	.17	.17	1.27	.59	.37

- 1 Zero period acceleration of structural response
- 2 ZPA indeterminable from available data
- 3 Square-root-of-the-sum of the squares
- 4 Licensing basis is SSE

TABLE 63
EQUIPMENT LIST AT AUXILIARY BUILDING ELEVATION 568'

1H22P0001	LPCS	Instrument Rack	
1H22P0017	RCIC	Instrument Rack	
1H22P0018	RHR	Instrument Rack	A
1H22P0021	RHR	Instrument Rack	B
1H22P0055	RHR	Instrument Rack	C
1C61N0001		Differential Press Transmitter	
1E12N0007A,B		Differential Press Transmitter	
1E12N0015A,B,C		Differential Press Transmitter	
1E12N0026A,B		Pressure Transmitter	
1E12N0028		Pressure Transmitter	
1E12N0050A,B		Pressure Transmitter	
1E12N0051A,B		Pressure Transmitter	
1E12N0052A,B,C		Differential Press Transmitter	
1E12N0055A,B,C		Pressure Transmitter	
1E12N0056A,B,C		Pressure Transmitter	
1E12N0058 C		Pressure Transmitter	
1E21N0003		Pressure Transmitter	
1E21N0050		Pressure Transmitter	
1E21N0051		Flow Transmitter	
1E21N0052		Pressure Transmitter	
1E21N0053		Pressure Transmitter	
1E21N0054		Pressure Transmitter	
1E31N0075A		Pressure Transmitter	
1E31N0077A		Pressure Transmitter	
1E31N0083A,B		Pressure Transmitter	
1E51N0003		Differential Press Transmitter	
1E51N0050		Pressure Transmitter	
1E51N0051		Differential Press Transmitter	
1E51N0053		Pressure Transmitter	
1E51N0055A,B,E,F		Pressure Transmitter	
1E51N0056A, E		Pressure Transmitter	
1E12C002A	RHR	Pump & Motor	
1E12C002B	RHR	Pump & Motor	
1E12C002C	RHR	Pump & Motor	
1E21C001	LPCS	Pump & Motor	
1E22C001	HPCS	Pump & Motor	






FIGURE 1. HORIZONTAL DESIGN RESPONSE SPECTRA — SCALED TO 1g HORIZONTAL GROUND ACCELERATION

Figure 6.1




 PERRY NUCLEAR POWER PLANT
 THE CLEVELAND ELECTRIC
 ILLUMINATING COMPANY

Response Spectra -
 Horizontal Motion H1
 (2% and 5% Damping)

Figure 3.7-5

Figure 6.2




Figure 6.3





Figure 6.4





Figure 6.5





Figure 6.6





Figure 6.7





Figure 6.8





Figure 6.9

ML 5.0 EARTHQUAKE JANUARY 31, 1980


11A8001

PERRY NUCLEAR POWER PLANT



COMP WEST

SMA35/N 165-11

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ




Gilbert/Commonwealth, Inc.
Reading, PA.




CEI PERRY NPP
Reactor Building Seismic Mode
Mode Shape Plot

Figure 6.11

2/9/86



Gilbert/Commonwealth, Inc.
Reading, PA.



CEI PERRY NPP
Reactor Building Seismic Model
Mode Shape Plot
Figure 6.13
2/7/86

7.0 CONFIRMATORY PROGRAMS

Within hours of the earthquake, CEI's geophysical consultant had set up seismographs in the area of the epicenter to monitor any aftershocks. These remain in place at this time and the monitoring will continue until it is determined that no further aftershocks are anticipated. In addition, CEI is cooperating with the U.S. Geological Survey and others who are studying the earthquake.

CEI has instituted a specific procedure (OM19A: GTI-003) to ensure proper documentation, review, and reporting of all potentially earthquake related conditions in the plant. Under the procedure, all of the items identified within 24 hours following the seismic event have been documented as Earthquake Inspection Team Items ("EITI's"). Engineering has evaluated each EITI to determine whether the item was a direct result of the earthquake. The results of the evaluation are shown in Appendix E. The two EITI's determined to have been caused by the earthquake, and those with an "indeterminate" cause (i.e., where it cannot be definitively established that the condition existed prior to the earthquake), were identified and documented as discussed above. None of these items is associated with any plant structural damage. It is anticipated that minor rework or repair will be done on some of the items in accordance with CEI's normal program to correct nonconforming conditions. CEI's procedure provides that all potentially earthquake related EITI's will be maintained in the "as found" condition until reviewed by CEI and released by the NRC.

New Work Requests (WR's) (for conditions other than those already covered by EITI's), are also being reviewed in accordance with CEI's new procedure for earthquake related items.

Engineering evaluation results for these items are being documented and tracked. As with the EITI's, any potentially earthquake related conditions associated with new WR's are being maintained in the as-found condition until reviewed by CEI and released by the NRC. CEI has not identified any plant structural damage associated with potentially earthquake related items identified on new WR's.

On a longer term basis, CEI is participating in several industry efforts to study the effects of seismic events on nuclear plants. The organizations performing these studies include the Seismic Owners Group (SOG), the Seismic Qualification Utilities Group (SQUG), and Electric Power Research Institute (EPRI).

These industry groups are examining various generic seismic issues which have been under consideration by the NRC. For example, SOG has been focusing on eastern seismicity hazard analysis, with EPRI managing the program effort. SOG will review the Perry earthquake as part of this work. SQUG has focused its effort on the seismic qualification of electrical equipment. SQUG intends to review the Perry data presented in this report, and will integrate this information into their studies. EPRI has been supporting SQUG by sponsoring projects to resolve issues associated with equipment qualification, focusing on test data, adequacy of equipment anchorages, and post earthquake investigation programs.

These industry groups all visited the site shortly after the seismic event. A SOG/EPRI team installed in-plant and field instruments within a day of the seismic event to collect aftershock data. An SQUG team conducted a plant walkdown. The team informed CEI that the seismic event at Perry was much smaller than others they have evaluated (Coalingo, Chile, Mexico City, Morgan Hill), and that the SQUG data base generated from these previous earthquakes would predict no damage from the January 31, 1986 earthquake. This prediction was confirmed by the group's plant walkdown. The EPRI equipment qualification program manager concluded that Perry's response to the seismic event was properly handled. The Perry experience will be used in EPRI's development of generic post-earthquake investigation methods.

The seismic event which occurred on January 31, 1986 has been thoroughly studied and its effects on the Perry Nuclear Power Plant analyzed in detail. The earthquake itself was of smaller magnitude and intensity than the postulated earthquake which was used as the basis for the plant seismic design. The occurrence of the 1986 earthquake does not change any of the conclusions previously reached as to the geology and seismology of the site. Consideration of this event does not result in any change in the Safe Shutdown Earthquake licensing basis for the Perry plant.

The earthquake confirmed the adequacy of the plant's seismic design. The plant structures and equipment were essentially unaffected by the earthquake. The large number of safety and non-safety related systems which were operating or energized at the time of the earthquake responded in accordance with their design. Extensive plant walkdowns and inspections revealed no structural or equipment damage.

The seismic characteristics of the earthquake have been reviewed and compared the plant's seismic design. The high frequencies which typified the 1986 earthquake are of no significance with regard to the adequacy of the plant's design. In contrast to the seismic design basis, the earthquake was of short duration, with low energy, low velocities and small displacements. Although certain of the recorded response spectra exceeded the design response spectra in the high frequency range, such exceedances are consistent with the analytical methods of Regulatory Guide 1.60 and are of no engineering significance. In the frequency range of significance for plant structural design (below 14 Hz), recorded spectra are far below the design response spectra for Perry.

The January 31, 1986 earthquake, in effect, constituted a proof test of Perry's seismic design. By any standard the Perry Nuclear Power Plant passed that test. The earthquake presents no new information which would change the previously accepted licensing basis for the plant.

APPENDIX A


STRONG-MOTION DATA FROM THE PERRY NUCLEAR POWER PLANT
SEISMIC INSTRUMENTATION
KINEMATICS

ML 5.0 EARTHQUAKE



JANUARY 31, 1986

STRONG-MOTION DATA
from the
PERRY NUCLEAR POWER PLANT
SEISMIC INSTRUMENTATION

February 3, 1986



CompuSels



STRONG-MOTION DATA REPORT

for the

M_L 5.0 EARTHQUAKE

of

1147 EST, JANUARY 31, 1986

PERRY, OHIO

RECORDED ON THE

PERRY NUCLEAR POWER PLANT

STRONG MOTION ACCELEROGRAPHS

for

Cleveland Electric Illuminating Company

Requisition No. NED-E-860006

by

Kinematics/Systems
222 Vista Ave.
Pasadena, CA 91107

Sales Order C-K6028

February 4, 1986

TABLE OF CONTENTS

	page
1.0 INTRODUCTION.....	1
2.0 INSTRUMENTATION.....	1
2.1 Model SMA-3 Accelerograph.....	1
2.2 Calibration Data.....	1
3.0 DATA PROCESSING.....	2
3.1 Digitization.....	2
3.2 VOL1 Processing.....	2
3.3 VOL2 Processing.....	3
3.4 VOL3 Processing.....	3

DATA PLOTS

Uncorrected Acceleration
Corrected Acceleration, and Integrated Velocity
and Displacement
Velocity Response Spectrum with Fourier
Spectra
Tripartite Presentation of PSV, PSA and SD

for triaxial response at each of:
Reactor Building Foundation, El 575',
Containment Vessel Annulus, El 682'

APPENDICES

"Conditioning and Correction of Strong Motion Data on
on Analog Magnetic Tapes"
SMA-3 Data Sheet

1.0 INTRODUCTION

On January 31, 1986, a (M_L 5.0) local earthquake was recorded by the strong-motion instrumentation at Perry Nuclear Power Plant, Perry, Ohio. The FM analog magnetic tape cassette records from two Kinemetrics Model SMA-3 accelerographs were retrieved from the instruments and provided to Kinemetrics for analysis.

This report describes the processing of these strong-motion records and presents the results. Included are the uncorrected accelerograms, corrected acceleration, velocity and displacement time series, and response spectra.

2.0 INSTRUMENTATION

2.1 Model SMA-3 Accelerograph

The SMA-3 is a multi-channel, centralized recording, FM analog magnetic tape accelerograph system designed to detect and record strong local earthquakes and record the three orthogonal acceleration signals on cassette tape. The SMA-3 remains in a standby mode until its vertical trigger detects an earthquake. The trigger then actuates recording in less than .10 seconds.

The force balance accelerometers in the SMA-3 have a nominal natural frequency of 50 Hz and damping of 65% critical, providing flat (-3dB) response from DC to 50 Hz. The nominal sensitivity of each of the three channels is 2.5 volts/g with a full scale response of 1.0g. The dynamic range of the accelerograph is nominally 40 dB, giving it a resolution of approximately .01g.

The trigger in the SMA-3 has a flat (-3dB) response from 1 to 10 Hz and a nominal trigger level of 0.01g.

Power is supplied to the SMA-3 by internal rechargeable batteries. These batteries are kept in a charged state by 120 VAC line power.

2.2 Calibration Data

The three Model SMA-3 accelerographs which recorded the event were factory calibrated in January, 1985, and the sensors were recalibrated for sensitivity by the Perry NPP personnel in December of 1985. These most current calibration data are given in Table 1 below.

<u>Ser. No.</u>	<u>Channel</u>	<u>Sens., v/g</u>	<u>Nat. Freq., Hz</u>	<u>Damping % critical</u>
165-1	long	2.48	52.3	65
	tran	2.49	53.7	65
	vert	2.47	50.6	64
165-2	long	2.48	52.6	67
	tran	2.48	52.2	72
	vert	2.65	50.5	66

TABLE 1: Calibration Data

3.0 DATA PROCESSING

Data from the Model SMA-3 accelerographs were played back using a Kinematics Model SMP-1 Playback System through a Data Compensator, digitized using a Kinematics Model DDS-1105 Digital Data System and processed as described in Kinematics' Application Note No. 7 "Conditioning and Correction of Strong Motion Data on Analog Magnetic Tapes", appended to this report.

3.1 Digitization

The magnetic tapes were digitized using the DDS-1105. The 1024 Hertz FM time reference recorded on channel 4 of the cassette is output from the SMP-1 and divided down by four (256 Hz \pm deviation) and used as the timing signal for the digital conversion time interval. The multiplexed uncorrected time series are written on 9-track computer-compatible tape.

3.2 VOL1 Processing

The digitized data were demultiplexed and scaled to acceleration units using the Table 1 calibration data. The mean was then subtracted from each acceleration time history. The new time histories were then written in a Kinematics' VOL1-format disk file.

The three uncorrected acceleration time histories from each SMA-3 record were then plotted; these plots are included in the data section of this report.

3.3 VOL2 Processing

The recorded accelerograms were then instrument and baseline corrected using Kinematics' VOL2 program. This program is based upon the VOL2 program developed at Caltech (Trifunac and Lee, 1973). No major modifications to the original VOL2 algorithms have been made.

The data were bandpass filtered using Ormsby filters. The low-pass filter had a cut-off frequency of 35 Hz and a termination frequency of 40 Hz. The high-pass filter had a cutoff frequency of 0.625 Hz and a termination frequency of 0.4 Hz.

Output of this program consists of a plot of corrected acceleration, velocity and displacement for each component of recorded data. These plots are presented in the data section of this report.

3.4 VOL3 Processing

Linear response spectra were calculated from the corrected acceleration time histories using the algorithms developed by Trifunac and Lee. Response spectra were calculated for damping ratios of 0, 1, 2, 4, and 7 percent. The period range of these spectra was 1.68 to 0.0283 seconds (0.59 to 35.4 Hz) with oscillator response calculated at 1/24 th octave intervals.

Two types of plots were produced and are included in the data section of this report. The first type is the traditional tripartite log-log plot of pseudo-velocity vs. period. The second is a linear plot of velocity response and Fourier spectrum vs. frequency.

Reactor Building Foundation, Elevation 575 Ft.

SMA-3 Serial Number 165-1

Tag Number D51-N101


Longitudinal Channel - South Orientation

Transverse Channel - West Orientation

Vertical Channel - Up Orientation

UNCORRECTED
ACCELERATION, g

TIME IN SECONDS




ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA3S/N 165-1L





UNCORRECTED
ACCELERATION, g

TIME IN SECONDS



ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA3S/N 165-11






ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA3S/N 165-1V



11A8001
 ML 5.0 EARTHQUAKE JANUARY 31, 1986
 PERRY NUCLEAR POWER PLANT COMP SOUTH SMA3S/N 165-1L
 ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ
 PEAK VALUES: ACCEL = 177.21 CM/SEC/SEC VEL = 1.74 CM/SEC DISPL = 0.09 CM



ML 5.0 EARTHQUAKE JANUARY 31, 1986

11A8001


PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-11

ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ

□ PEAK VALUES: ACCEL = -101.12 CM/SEC/SEC VEL = -2.21 CM/SEC DISPL = +.16 CM



ML 5.0 EARTHQUAKE JANUARY 31, 1986

11A8001



PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-1V

ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ

PEAK VALUES: ACCEL = +103.46 CM/SEC/SEC VEL = -1.71 CM/SEC DISPL = +.07 CM



RELATIVE VELOCITY RESPONSE SPECTRUM


ML 5.0 EARTHQUAKE JANUARY 31, 1986

PERRY NUCLEAR POWER PLANT

COMP SOUTH SMA3S/N 165-1L

11A8001

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL



RELATIVE VELOCITY RESPONSE SPECTRUM

ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-11

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL



RELATIVE VELOCITY RESPONSE SPECTRUM

ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-1V

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA3S/N 165-1L

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-11

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-1V

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA3S/N 165-1L

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11AB001

PERRY NUCLEAR POWER PLANT

COMP WEST


SMA3S/N 165-1T

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



SMA3S/N 165-1V

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11AB001

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA3S/N 165-1L

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-1T

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8001

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-1V

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ



Containment Vessel Annulus, Elevation 682 Ft.


SMA-3 Serial Number 165-2

Tag Number D51-N111

Longitudinal Channel - South Orientation

Transverse Channel - West Orientation

Vertical Channel - Up Orientation



ML 5.0 EARTHQUAKE

JANUARY 31, 1986

SMA3S/N 165-2L



1.00 0.80 0.60 0.40 0.20 -0.20 -0.40 -0.60 -0.80 -1.00


UNCORRECTED
ACCELERATION, g

TIME IN SECONDS



ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA3S/N 165-21







ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA3S/N 165-2V



ML 5.0 EARTHQUAKE JANUARY 31, 1986
 PERRY NUCLEAR POWER PLANT COMP SOUTH SMA3S/N 165-2L
 ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ
 PEAK VALUES: ACCEL = +535.17 CM/SEC/SEC VEL = +5.13 CM/SEC DISPL = 0.17 CM



11A8002
 ML 5.0 EARTHQUAKE JANUARY 31, 1986
 PERRY NUCLEAR POWER PLANT COMP WEST
 SMA3S/N 165-2T
 ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ
 PEAK VALUES: ACCEL = +178.35 CM/SEC/SEC VEL = -3.77 CM/SEC DISPL = +.21 CM



ML 5.0 EARTHQUAKE JANUARY 31, 1986

11A8002


PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-2V

ACCELEROGRAM IS BAND-PASS FILTERED BETWEEN 0.400- 0.625 AND 35.00- 40.00 HERTZ

□ PEAK VALUES: ACCEL = +297.21 CM/SEC/SEC VEL = +3.09 CM/SEC DISPL = 0.07 CM



RELATIVE VELOCITY RESPONSE SPECTRUM

ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA3S/N 165-2L

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL



RELATIVE VELOCITY RESPONSE SPECTRUM

ML 5.0 EARTHQUAKE JANUARY 31, 1986


PERRY NUCLEAR POWER PLANT

SMA3S/N 165-21

COMP WEST

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL

11A8002



RELATIVE VELOCITY RESPONSE SPECTRUM

ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-2V

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA3S/N 165-2L

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP WEST

SMAJS/N 16S-2T

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


22AB002

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-2V

DAMPING VALUES ARE 0. 1. 2. 4. 7 PERCENT OF CRITICAL
FREQUENCY - HZ



KINEMATICS

ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA35/N 165-2L

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-21

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-2V

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11A8002

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SMA35/N 165-2L

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ



KINETICS

ML 5.0 EARTHQUAKE JANUARY 31, 1980


11A8002

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 165-27

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986


11AB002

PERRY NUCLEAR POWER PLANT

COMP UP

SMA3S/N 165-2V

DAMPING VALUES ARE 4 PERCENT OF CRITICAL
FREQUENCY - HZ





APPLICATION NOTE

Conditioning and Correction of Strong Motion Data on Analog Magnetic Tapes

No. 7

Kinometrics has developed programs for routine computer processing of data recorded on the analog magnetic tape accelerographs, Models SMA-2 and SMA-3. The software from published research for film recording accelerographs (Trifunac & Lee, 1973) has been adapted to the analog magnetic tape recording instruments.

Magnetic tape is used where rapid playback and analysis of data are required. These accelerographs are normally located at large engineered facilities, such as nuclear power plants. Figure 1, "Kinometrics Earthquake Data Reduction System Flow Diagram," illustrates the specialized services needed to prepare data immediately after an earthquake.

The purpose of this Note is to describe the standard data conditioning and correction used to prepare accelerograms for subsequent response spectrum or time-series analysis. On Figure 1 are references to the following paragraphs: 1.0--Data Playback, 2.0--Analog-to-Digital Conversion, 3.0--Data Conditioning, and 4.0--Data Correction.

There are two "tape speed" errors in all FM analog recording/playback systems. One "error" is a change in apparent amplitude due to unwanted tape speed changes. Correction of this error is called "amplitude compensation". This is shown in Figure 2 and described in Sections 1.0 and 3.0. The second "error" is a change in apparent length of the earthquake due to different tape speeds during recording and playback. Correction of this error is called "time base compensation". This is shown in Figure 3 and described in Section 2.0.

1.0 Data Playback

1.1 The playback system is a Model SMP-1 (Figure 4). If the SMP-1 is used to play out the SMA-2 or SMA-3 tapes, the signals




FIGURE 1 Flow Diagram for Kinometrics E.D.R.S.
(Earthquake Data Reduction Sequence)

Channel 1
(see Figure 4)




Uncompensated Earthquake Record

Channel 4
(see Figure 4)



1024 Hz Time Compensation Channel

Channel 4
subtracted from
Channel 1



Final Record Following Amplitude Compensation

FIGURE 2 Amplitude Compensation





FIGURE 3 Time Base Compensation



SMP-1

Magnetic Tape Playback System

FIGURE 4



The SMP-1 is a versatile magnetic tape playback system designed for use with the Kinematics SMA-2 and SMA-3 Magnetic Tape Acceleration Systems. The combination of the SMA-2 or SMA-3 Acceleration Systems with the SMP-1 Magnetic Tape Playback System meets the applicable requirements of US NRC Regulatory Guide 1.12, and

provides immediate visual playback capability of recorded acceleration data.

The SMP-1 is portable and may be operated either from 110 Vac or internal rechargeable batteries. Optionally the unit may be mounted in a standard 19-inch cabinet. An internal battery charger is included with the unit.

which appear on the chart recorder are amplitude compensated.

1.2 The electrical outputs taken from the DEMODULATED OUTPUT jacks (Channels 1, 2, or 3 of Figure 4) are not amplitude compensated. However, Kinometrics has an electronic Data Compensator which plugs into an SMP-1.

If this Data Compensator is used, the electrical signals are amplitude compensated by electronic subtraction of Channel 4 from Channels 1, 2, and 3. The Data Compensator should be used if the signals are to be recorded on a three-channel strip-chart recorder for display. The signals are not time base compensated.

1.3 If the signals are to be processed on a computer, there are two options:

1.3.1 Use the Data Compensator for amplitude compensation.

1.3.2 Without a Data Compensator, have software perform amplitude compensation.

2.0 Analog-to-Digital Conversion

The following steps are taken at Kinometrics using the SMP-1 connected to the Analog-to-Digital Converter, Model DDS-1105 or DataSeis[®].

2.1 Three (3) analog outputs of the SMP-1 with Data Compensator are digitized simultaneously: longitudinal, transverse, and vertical (Channels 1, 2, 3 of Figure 4). A 12-bit analog-to-digital converter is used with normal full scale of ± 5 volts.

2.2 The FM Time reference output (Channel 5 of Figure 4) is 1,024 Hz plus or minus tape speed error. This signal is divided down by four (256 Hz \pm deviation) and used as the timing signal for the digital conversion time interval. Thus, the accelerogram time base is corrected for tape speed error and the voltage values are equally spaced at 1/256 second. This is "time base compensation" and can be done on analog-to-digital converters other than DDS-1105 or DataSeis[®].

2.3 The final uncorrected accelerograms are written on 9-track computer-compatible tape. The three channels are

multiplexed (i.e., 1, 2, 3, 1, 2, 3, 1, 2,...), and are in a 16-bit, offset binary format.

3.0 Data Conditioning

Figure 5 illustrates the flow of the "Data Conditioning" software. Tape speed variations during recording and during playback of FM analog tape change the apparent time base and affect the analog amplitude. The time base has been compensated in the previous section by using the FM time reference output (Channel 5 of Figure 4) as the timing signal for the analog-to-digital converter. The amplitude has been compensated using the Data Compensator module.

The output accelerograms are uncorrected in the sense that no modifications have been introduced which involve any hypothesis of the ground motion character or of the instrument involved.

4.0 Data Correction

Figure 6 illustrates the flow of the "Data Correction" software. The purpose is to present corrected acceleration data and integrated ground velocity and displacement curves in as accurate a form and over as wide a frequency range as is compatible with the original data. The modified data is believed to be the most accurate form of input data feasible to produce from the original record for structural response calculations and for response spectrum determinations.

Instrument correction is introduced to compensate for the accelerometers' frequency response. The Caltech publication EERL 71-05 discusses the approach used. The baseline correction uses an Ormsby high-pass filter. The technique is explained in Caltech publication EERL 70-07.

Figure 7 contains a sample output plot of corrected data for one component of the Santa Barbara earthquake of 13 August 1978, recorded on a SMA-2 accelerograph.




FIGURE 5

Data Conditioning, E.D.R.S.




FIGURE 6

Data Correction, E.D.R.S.


FIGURE 7

SANTA BARBARA EARTHQUAKE AUGUST 13, 1978 - 1555 PDT

GOLETA SUBSTATION SCE, $34^{\circ}28.0'N$, $119^{\circ}53.1'W$ COMP UP



PEAK VALUES : ACCEL = 105.9 CM/SEC/SEC VELOCITY = -5.6 CM/SEC DISPL = 1.0 CM

BANDWIDTH 0.03, 4.0 SEC




REFERENCES

- Trifunac, M. D. (1970). Low Frequency Digitization Errors and a New Method for Zero Baseline Correction of Strong-Motion Accelerograms, Earthquake Engineering Research Laboratory, EERL 70-07, pgs. 32-52, California Institute of Technology, Pasadena
- Trifunac, M. D., P. E. Udvardi and A. G. Brady (1971). High Frequency Errors and Instrument Corrections of Strong-Motion Accelerograms, Earthquake Engineering Research Laboratory, EERL 71-05, pgs. 33-47, California Institute of Technology, Pasadena
- Trifunac, M. D. and V. Lee (1973). Routine Computer Processing of Strong-Motion Accelerograms, Earthquake Engineering Research Laboratory, EERL 73-03, California Institute of Technology, Pasadena



SMA-3

Strong Motion Acceleration System



The SMA-3 is a multi-channel, centralized recording, magnetic tape accelerograph system designed to detect and record strong local earthquakes. Typical structural applications include nuclear power plants, tall buildings, dams, offshore platforms and bridges. The SMA-3, used with the companion SMP-1 Playback System, meets the requirements of U.S. NRC Regulatory Guide 1.12 and is being used at over 90 nuclear power plants around the world.

An SMA-3 can accommodate up to 27 channels of acceleration data, usually from triaxial force balance accelerometers, Model FBA-3. Downhole triaxial sensors (FBA-13DH) can be installed, and uniaxial and biaxial accelerometers may also be used. The sensors may be located up to 1500 feet from the central recorder. The TS-3 triaxial seismic trigger is standard with any SMA-3 system. The SMA-3 comes supplied with two cassettes per recording section, and all mounting hardware and mating connectors for the specified number of triggers and accelerometers.



GENERAL DESCRIPTION

The SMA-3 is a versatile multi-channel acceleration recording system. It is self-actuating when a local earthquake exceeds a predetermined level of ground acceleration. When acceleration falls below the preset value, the SMA-3 automatically returns to the standby condition.

The standard FBA-3 triaxial accelerometer package is approximately a 20 centimeter cube. It contains three force-balance acceleration sensors. The accelerometer package accepts calibration commands for damping and natural frequency.

Each accelerometer signal is buffered, frequency modulated, and recorded on an assigned track of a four-track magnetic tape cassette. Three tracks are used for acceleration data and the fourth for a timing signal, which is common for all recording tape transports in the system.

TECHNICAL SPECIFICATIONS

SEISMIC TRIGGERS (Model TS-3)

Type: Triaxial acceleration trigger
Housing: Cast aluminum, waterproof
Set Point: 0.01g standard, field adjustable, 0.005g to 0.05g
Option: Adjustment range of 0.025g to 0.25g
Current Drain: 0.45 mA in standby; 60 mA operating

TRANSDUCERS (Model FBA-3)

Type: Force balance accelerometers
Housing: Cast aluminum, waterproof
Bandwidth: 0 to 50 Hz
Range: $\pm 1g$ full scale
Output: $\pm 2.5 V$ full scale
Damping: 70% of critical
Natural Frequency: 50 Hz
Calibration: Damping and natural frequency recorded by command
Temperature Range: -20° to $70^{\circ} C$ (0° to $160^{\circ} F$)
Temperature Effects: $\pm 1.5\%$ of full scale over operating range

RECORDING SYSTEM


Type: Frequency modulation
Tape: Four track magnetic tape cassette
Tape Speed: 1-7/8" per second
Recording Time: 30 minutes
Bandwidth: 0 to 50 Hz
Dynamic Range: 40 dB from 15° to $35^{\circ} C$ (with SMP-1)
Modulation Frequency: 1000 Hz $\pm 50\%$ modulation
Timing Frequency: 1024 Hz $\pm 0.2\%$
System Accuracy (with SMP-1): $\pm 5\%$ at full scale, changing linearly to 1.5% of full scale at 0.01g
Start-up Time: Less than 0.1 seconds
Event Alarm: Normally open contacts, rated 1 amp @ 12 Vdc
Event Indicator: Electromagnetic visual display

POWER SUPPLY

Two 12 V internal, rechargeable batteries. An internal battery charger, operating from 110 Vac, is supplied.

OPERATING ENVIRONMENT

Temperature: 0° to $55^{\circ} C$ (32° to $130^{\circ} F$)
Humidity: Remote packages, 100% R.H.
Cabinet mounted panels, 80% R.H. non-condensing



ORDERING INFORMATION, SMA-3

Kinemetrics Part Number: 101100
Strong Motion Acceleration System, including:

- One triaxial seismic trigger, Model TS-3
Specify triggering threshold (0.01g standard)
Specify number of additional triggers if desired
- Up to nine triaxial acceleration sensors, Model FBA-3, 1.0g full scale
Cost Option—Model FBA-11 uniaxial sensor
Cost Option—Model FBA-13DH downhole triaxial sensor
Option—Range 0.25g, 0.5g, 2.0g full scale
Specify number and type of sensors, up to 27 channels

- Up to nine triaxial tape recording modules, with cassettes
Cost Option—Flame resistant wiring
Specify number of channels, up to twenty-seven

- Control/Power Panel
Cost Option—Conversion to 220 Vac

Accessories:

- Interconnecting Cables for seismic trigger(s)
Cost Option—Flame retardant cable
Specify lengths required, up to 1500' to each trigger
- Interconnecting Cables for remote accelerometers
Cost Option—Flame retardant cable
Specify lengths required, up to 1500' to each sensor

- 19-Inch Rack Mounting Cabinet
Cost Option—Seismically braced cabinet

- Tape Playback, Model SMP-1 (see SMP-1 data sheet)

- Spares and Supplies
Magnetic Tape Cassettes, Part #700030
Desiccant Envelopes, Part #700049
12 V Batteries (pair), Part #103413

APPENDIX B

REPORT ON THE PEAK SHOCK RECORDERS AND PEAK
ACCELERATION RECORDERS INSTALLED AT THE
PERRY NUCLEAR POWER PLANT DURING THE SEISMIC EVENT
ON JANUARY 31, 1986 ENGBAHL ENTERPRISES

ENGDAHL ENTERPRISES

2850 Monterey Avenue, Costa Mesa, California 92626, (714) 540-0398

Document Number 120910
Revision Number N/C
Page 1 of 14

REPORT ON THE
PEAK SHOCK RECORDERS AND
PEAK ACCELERATION RECORDERS
INSTALLED AT THE
PERRY NUCLEAR POWER PLANT
DURING THE SEISMIC EVENT ON
JANUARY 31, 1986

Copy Number 04

Engdahl Enterprises
Costa Mesa, CA 92626

February 7, 1986

CONTENTS

1.	Introduction	3
2.	Instrument Descriptions	3
3.	Designations, Locations and Calibration Status of Instruments	4
4.	Data Reduction	5
5.	Data Evaluation	5
6.	Current Status	7
7.	Conclusions	7

APPENDICES:

A. Bulletins (3)

1. INTRODUCTION

On January 31, 1986, the effects of a seismic event were recorded by the Engdahl PSR1200, Peak Shock Recorders and PAR400, Peak Acceleration Recorders at the Perry Nuclear Power Plant located at Perry, Ohio. The record plates were removed from the recorders within hours and new plates were installed by Perry Plant and Engdahl personnel. A preliminary data reduction was completed the same day. A second independent data reduction was made on February 2, 1986. Photographs of all of the scribed records were made on February 2-3, 1986.

This report reviews the status of the instruments at the time of the event, contains the recorded data, and evaluates the data. The report also reviews the present status of the recorders and work to be done in the near future.

2. INSTRUMENT DESCRIPTIONS

2.1 PEAK SHOCK RECORDER (Response Spectrum Recorder and Response Spectrum Switch)

The Model PSR1200-H/V, Peak Shock Recorder, is designed to meet the characteristics of the Response Spectrum Recorder and the Response Spectrum Switch as described in the American Nuclear Society Standard ANSI/ANS-2.2-1978, "Earthquake Instrumentation Criteria for Nuclear Power Plants", and NRC Regulatory Guide 1.12 (Rev. 1), "Instrumentation for Earthquakes". It is a completely passive device covering the range of 2-25 HZ in 1/3 octave increments. Damping of each accelerometer is nominally 2%. It is completely self contained. Three recorders are arranged triaxially.

Twelve reeds of different lengths and weights, one for each frequency, are fabricated from spring steel. A diamond-tipped stylus is attached to the free end of each reed to inscribe a permanent record of its deflection on one of twelve record plates. The record plates are aluminum, plated with successive layers of nickel, tin, and lead-tin.

The Model PSR1200-H/V-12A comprises the standard PSR1200-H/V plus the capability of providing instantaneous warning signals when preset accelerations at selected frequencies have been exceeded. This is achieved by adding dual contacts which are closed by the reed when it is deflected through a predetermined distance.

2.2 PEAK ACCELERATION RECORDER (Peak Accelerograph)

The Model PAR400, Peak Acceleration Recorder, is designed to meet the characteristics of the Peak Accelerograph described in ANSI/ANS-2.2-1978 and NRC Regulatory Guide 1.12. It senses and records peak accelerations triaxially. It is a self-contained passive device requiring no external power or control connections and has a minimum band width of 0 to 26 Hertz with a sensitivity as low as .01 g. The recorder is nominally 60% damped. A diamond tipped scribe at the end of an amplifier arm traces a very fine visible permanent record on an aluminum record plate with successive layers of nickel, gold, and burnt gold.

3. DESIGNATIONS, LOCATIONS, AND CALIBRATION STATUS OF INSTRUMENTS

3.1 D51-R160 - REACTOR BUILDING FOUNDATION

Triaxial Response Spectrum Recorder (PSR1200-H/V-12A)
Location - 574' Reactor Building foundation mat, azimuth
210° (see drawing D-811-801 and D-814-663-909)
Active scratch recorder, which alarms on control room panel
1H13-P969, annunciator panel D51-R215
Most recent calibration on 1-14-85. *

3.2 D51-R170 - REACTOR BUILDING I.D.W. 630' PLATFORM

Triaxial Response Spectrum Recorder (PSR1200-H/V)
Location - inside Drywell platform - 630', azimuth, 240°
(see drawing D-811-605 and D-814-665-910)
Most recent calibration completed on 1-30-86. *

3.3 D51-R180 - HPCS PUMP BASE MAT

Triaxial Response Spectrum Recorder (PSR1200-H/V)
Location - HPCS Pump Room - Auxiliary Building foundation mat
574' (see drawing D-811-701 and D-814-663-911)
Equipment being calibrated on 1-31-86 during earthquake. (North-
South and East-West recorders operable).
Previous calibration on 1-14-85. *

* Calibration interval is established at 18 months by ANSI/ANS - 2.2-1978, "Earthquake Instrumentation Criteria for Nuclear Power Plants."

3.4 D51-R190 - RCIC PUMP BASE MAT

Triaxial Response Spectrum Recorder (PSR1200-H/V)

Location - RCIC Pump Room - Auxiliary Building foundation mat
574' (see drawing D-811-702 and D-814-663-912)

Equipment being calibrated on 1-31-86 during earthquake
(all recorders operable).

Previous calibration on 1-14-85.*

3.5 D51-R120 - REACTOR RECIRCULATION PUMP

Peak Acceleration Recorder (PAR400)

Location - inside Drywell - 574' elevation. (see drawing D-811-602
and D-814-663-906). Located on recirculation pump B33-C001A.

Most recent calibration 12-4-85.*

3.6 D51-R140 - HPCS PUMP BASE MAT

Peak Acceleration Recorder (PAR400)

Location - Auxiliary Building - 574'

HPCS Pump Room - Auxiliary Building foundation mat 574'
(see drawing D-814-633-908 and D-811-701)

Most recent calibration on 1-30-86. *

4. DATA REDUCTION

The following tabulations on Pages 8 through 13, show the initial data reduction made on January 31, 1986 by Perry Plant personnel and a field representative of Engdahl Enterprises. An independent data reduction made by Engdahl Enterprises on February 2, 1986 is listed alongside the initial reduction.

A total of 129 data point readings were tabulated. A comparison of the two independent data reductions indicates a very close correspondence. Most indicate no significant differences. For those cases where differences exist, the greatest differences (with one exception) are on the order of 0.03g. The largest acceleration difference between the two data reductions was 9% (MPL Number D51-R170, reed number 12, vertical). Even in this case, the difference is within tolerances allowed by industry standards.

5. DATA EVALUATION

The record plates from three of the four triaxial PSR1200 recorders had many scratches and some had multiple zero lines which made them difficult to read. This condition was due to construction work in progress since the recorders had been calibrated and installed in January 1985. Although initial review of these plates indicated that data reduction might be questionable, further review (including comparison with data from the Kinometrics Time-History recorders**) has established the validity of the data reduction.

**Kinometrics/Systems, "Strong-Motion Data Report for the ML 5.0 Earthquake of 1147 EST, January 31, 1986" (February 4, 1986)

5.1 D51-R120, Reactor Recirculation Pump and
D51-R140, HPCS Pump Base Mat

The records from these PAR400 recorders were good. D51-R120 had the best records. D51-R140 had poorer zero lines but the results were nonetheless in close agreement with Reactor Building foundation mat data from Kinematics Time-History recorder data.

5.2 D51-R160, Reactor Building Foundation

A reading was made for each reed in the horizontal directions. The North/South accelerations were in very close agreement with the response spectrum generated from the Time-History recorder (D51-N101). The East/West did not agree as well but was similar. Only six of twelve vertical data points were readable. All of these values were quite low indicating a low vertical component of acceleration.

5.3 D51-R170, Reactor Building I.D.W. 630' Platform

The most readable of the PSR1200 records were on the Reactor Building I.D.W. 630' Platform. The North/South was especially good with very good zero lines. The East/West and the vertical recorders each had two of twelve records that were difficult to read.

5.4 D51-R180, HPCS Pump Base Mat and
D51-R190, RCIC Pump Base Mat

These two installations are both on the Auxiliary Building foundation mat but separated by approximately 80 feet. The resulting North/South response spectra are almost identical. The East/West response spectra were similar. The vertical D51-R180 recorder was not in service due to recalibration activities, so no comparison can be made. The vertical D51-190 recorder is questionable since the zero lines were offset by large amounts in most cases.

5.5 Dual records were noted on some of the record plates. The clearest of these are on D51-R160, East/West. A separate tabulation is made of the six best records (see page 14). A dual record is normally made when the record plate moves a very slight amount (.001 to .002 inches) after one record is made and then a second record is made. It is possible that all six plates moved at low levels and that the second record is just a continuation of the same event. It is also possible that the low level event was recorded and then the plates moved before the second event.


6. CURRENT STATUS

6.1 At present, the instruments are in operation with new record plates except the vertical recorder, D51-R180, which has been removed for recalibration.

6.2 Plans have been made to start the recalibration of all of the instruments on February 10, 1986. This recalibration is in preparation of fuel loading, and not as a result of the seismic event.

7. CONCLUSIONS

Although the records were not always easy to read because of activity at the plant during the construction phase, the records were clear enough in most cases to give very good overall results. Recalibration of the instruments was not required by the seismic event. Recalibration will be performed starting February 10, 1985 in preparation for fuel loading.


Paul D. Engdahl

cjw

MPL NUMBER: D51-R120
LOCATION: REACTOR RECIRCULATION PUMP

SENSOR LOCATION	ACCELERATION (g)	
	1-31-86	2-2-86
NORTH/SOUTH (L)	.32	.318
EAST/WEST (T)	.10	.106 *
VERTICAL	.07	.048 *

* Zero lines not clear, best estimate

MPL NUMBER: D51-R140
LOCATION: HPCS PUMP BASE MAT - 574'

SENSOR LOCATION	ACCELERATION (g)	
	1-31-86	2-2-86
NORTH/SOUTH (L)	.15	.167
EAST/WEST (T)	.06	.058
VERTICAL	.04	.029

MPL NUMBER: D51-R160
 LOCATION: REACTOR BUILDING FOUNDATION - 574'

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION (g)					
		North/South		East/West		Vertical	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	.027	.027	.029	.030	.007	**
2	2.52	.038	.038	.046	.046	.013	.011
3	3.17	.062	.060	.039	.040	**	**
4	4.00	.032	.035	.022	.026	**	**
5	5.04	.067	.069	.056	.054	**	.018
6	6.35	.065	.075	.054	.054	**	.016
7	8.00	.143	.133	.056	.051	.010	**
8	10.1	.136	.091	.176	.160	.061*	.053*
9	12.7	.196	.227	.236	.230	.032	.038
10	16.0	.286	.305	.284	.284	.101	.111
11	20.2	1.04	1.02	.605	.586	.224	**
12	25.4	.7657	.766	.540	.513	.329	**

* "C" surface

** Unreadable

MPL NUMBER: D51-R170

LOCATION: REACTOR BUILDING I.D.W. 630' PLATFORM - DW 630', 240°

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION (g)					
		North/South		East/West		Vertical	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	.047	.048	.049	.051	.007	.007
2	2.52	.082	.082	.086	.084	*	.013
3	3.17	.184	.184	.144	.140	.015	.014
4	4.00	.226	.223	.128	.127	.023	.023
5	5.04	.132	.134	.158	.158	.035	.033
6	6.35	.131	.134	.058	.055	.033	.030
7	8.00	.104	.104	.109	.090	*	.019 (2)
8	10.1	.093	.093	*	.052 (1)	.093	.085 (2)
9	12.7	.188	.182	.166	.080 (2)	.198	.199
10	16.0	.194	.204/ .167	.348	.312	.490	.500
11	20.2	.152	.152	.191	.175	.973	.973
12	25.4	.114	.091	.155	.158	1.7	1.54

* Unreadable

(1) Unusual appearance

(2) Very difficult to read - best estimate

MPL NUMBER: D51-R180
 LOCATION: HPCS PUMP BASE MAT - 574'

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION (g)					
		North/South		East/West		Vertical*	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	.0198	.020	.022	.021	-	-
2	2.52	.0358	.036	.033	.031	-	-
3	3.17	.0677	.068	.045	.048	-	-
4	4.00	.0474	.047	.022	.020	-	-
5	5.04	.0637	.064	.033	.029	-	-
6	6.35	.0735	.068	.054	.050	-	-
7	8.00	.0473	.052	.046	.046	-	-
8	10.1	.0744	.074	.566	**	-	-
9	12.7	.125	.149	.182	.176	-	-
10	16.0	.4582	.449	.253	.214	-	-
11	20.2	.9130	.896/ .432	.413	.429	-	-
12	25.4	.6100	.610/ .293	.191	**	-	-

* Not in service

** Unreadable

MPL NUMBER: D51-R190
 LOCATION: RCIC PUMP BASE MAT - 574'

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION (g)					
		North/South		East/West		Vertical	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	.021	.018	.026	.022	**	**
2	2.52	.039 (1)	.030	.031	.021	**	.013
3	3.17	*	*	.024	.017	**	**
4	4.00	.0367	.031	.028	.023	.029	**
5	5.04	.0305	.045	.037	.038	**	**
6	6.35	.0896	.065	.057	.048	**	**
7	8.00	.0750	.040	.068	.034	.019	.014
8	10.1	*	*	.097	.044	**	**
9	12.7	.130	.124	.142	.136	.053	.024
10	16.0	.409	.400	.162	.162	.082	.055
11	20.2	.810	.794	.237	**	**	.099
12	25.4	.556	.557	**	.156	.256	.256

(1) Mathematical error corrected. Originally reported acceleration 0.198.

* Unable to read due to corrosion


** Unreadable

MPL NUMBER: D51-R160
 LOCATION: REACTOR BUILDING FOUNDATION - 574'
 DUAL RECORDS

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION (g)					
		North/South		East/West		Vertical	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	-	-	-	.006	-	-
2	2.52	-	-	-	.009	-	-
3	3.17	-	-	-	.010	-	-
4	4.00	-	-	-	.026	-	-
5	5.04	-	-	-	.054	-	-
6	6.35	-	-	-	.035	-	-
7	8.00	-	-	-	-	-	-
8	10.1	-	-	-	-	-	-
9	12.7	-	-	-	-	-	-
10	16.0	-	-	-	-	-	-
11	20.2	-	-	-	-	-	-
12	25.4	-	-	-	-	-	-

APPENDICES

MODEL
PSR1200-H/V-4A
and
PSR1200-H/V-12A



MODEL PSR1200-V
PEAK SHOCK RECORDER™

SENSES AND PERMANENTLY RECORDS THE SPECTRAL ACCELERATION AT SPECIFIED FREQUENCIES

PROVIDES SIGNALS FOR IMMEDIATE REMOTE INDICATION THAT
SPECIFIED PRESET SPECTRAL ACCELERATIONS HAVE BEEN EXCEEDED

- EARTHQUAKES
- STORMS
- EXPLOSIONS

RELIABLE and ECONOMICAL

ENGDAHL ENTERPRISES



2850 Monterey Avenue • Costa Mesa, California 92626 • (714) 540-0398

Introduction

Traditionally, measurement of acceleration has implied measurement with the aid of a device whose resonant frequency was far removed from the frequency range of interest. A typical accelerometer for aerospace applications might have a mass of 10 grams and a resonant frequency of 10 kHz or higher. Such devices were designed primarily for attachment to a structural member to measure its response to shock or vibration. Their low mass was necessary to avoid modifying the characteristics of the device under test, while the resonant frequency had to be at least five times that of the highest frequency of interest. At the other end of the spectrum, earthquakes and other low frequency phenomena are conventionally detected and recorded using instruments whose resonant frequencies are much lower than the frequency range of interest.

A structure such as a large office building, a missile silo or an electrical generating station has many members and subassemblies with a wide range of resonant frequencies, and many of these are lightly damped, i.e., a shock will cause them to "ring" for a relatively long time. To measure the effects of an earthquake or other shock on such a structure in the traditional way, would require a very large number of transducers and a complex data acquisition system followed by computer analysis to digest the raw

data and decide whether or not structural damage had been sustained.

To simplify the design of shock resistant structures, dynamicists frequently define shocks and earthquakes in terms of response shock spectra. Basically, a response shock spectrum is a plot of acceleration vs. frequency in which each point represents the peak acceleration experienced by an accelerometer tuned to that specific frequency. The range of frequencies covered by the peak shock accelerometers corresponds to those found in most structures, systems, and components. Since all structural elements possess some low inherent damping, the Peak Shock Recorder™ has been designed with 2% of critical damping. The output obtained is thus directly applicable to structural design and analysis.

A response spectrum may be derived from the conventional acceleration vs. time record of a suitable recording accelerometer, but this involves either digitizing the records followed by computer manipulation of the data or the use of a large amount of auxiliary equipment. The first method is time consuming, while the second is expensive. The Model PSR1200-H/V is an inexpensive instrument requiring no source of power, and virtually no maintenance. It provides a permanent record of data from which the response spectrum may be plotted by a very simple reduction process.

Description

The Model PSR1200-H/V, Peak Shock Recorder™, is a completely passive device covering the range of 2-25 Hz in 1/3 octave increments. Damping of each accelerometer is nominally 2%. It is completely self contained.

Twelve reeds of different lengths and weights, one for each frequency, are fabricated from spring steel. A diamond-tipped stylus is attached to the free end of each reed to inscribe a permanent record of its deflection on one of twelve record plates. A calibration sheet for each

recorder lists the resonant frequency and g-sensitivity of each reed.

—V designates a recorder designed for vertical shock recording (compensated for earth's gravitational force). —H designates a recorder designed for horizontal shock recording.

The Model PSR1200-H/V-4A/12A comprises the standard PSR1200-H/V plus the capability of providing instantaneous warning signals when preset accelerations at selected frequencies have been exceeded. This is achieved by adding dual contacts which are closed by the reed when it is deflected through a predetermined distance. Model —4A monitors four selected reeds, while —12A monitors all of the reeds.

Uses

The PSR1200, Peak Shock Recorder™, is useful whenever acceleration measurements are desired at low frequencies. These accelerations may be due to earthquakes, storms, or explosions. The plot of the recorder's twelve individual measurements is the response spectrum of the acceleration to which the recorder was subjected.

The response spectrum switch (-A) version of the PSR1200 is useful whenever remote indications are desired that acceleration limits have

been exceeded. The remote indication that four or twelve dual acceleration limits have or have not been exceeded provides immediate information on which to act.

The Peak Shock Recorder™ can be used in connection with:

1. Nuclear power plants
2. Steel mills
3. Refineries
4. Bridges and dams
5. High-rise structures
6. Oil explorations
7. Mines
8. Ships
9. Earth studies
10. Towers

Features

Dzus, quarter-turn fasteners, are used to secure the cover, making it easily removable. The cover is clamped tight enough against the gasket bonded to the watertight housing to provide protection of the unit to 50 PSI (3.6 kg/Cm²) of water pressure.

The record plates are serialized so only one set of twelve have the same number. In addition, the plates have two types of slots to allow keying. The narrow key slot allows the plate to slide into only one slot in the housing to its full depth. That is, the plates all have to be in their correct locations in the housing to attach the cover.

The record plates can be inserted four different ways into the housing, allowing four records to be made before using a second set of plates. To prevent mixing the records, all plates must be inserted for the record to appear at A, B, C, or D or, again, the cover cannot be attached. A viewing window is provided, and the appropriate letter A through D will show so the cover need not be removed to know how the plates are inserted. During shipping, a red dot is seen. This means that the plates have been removed and the reed support structure is in place.

Additional keying is provided between the covers and housings in the form of dowel pins. These pins prevent the cover from being put on upside down. They also prevent a cover from a horizontal recorder (-H) being put on a vertical recorder (-V) or a -V on a -H.

Since a lower atmospheric pressure could be created inside the recorder than outside during shipment by air, a jackscrew is provided in the cover to lift a corner of the cover and break the partial vacuum. It will also be of assistance when the unit has been closed for a long period of time as the neoprene gasket may adhere slightly to the cover.

The recorder is reliable because of its simplicity. It does not contain any of the more complex and less reliable components, i.e., batteries, connectors, motors, and bearings. Its rugged structure is fabricated from aluminum alloy. Only a few parts are used. The recorder is self-contained, and requires no start-up time.

The recorder is economical in that no external connections or power are required. The record plates are reusable by replating after four records have been obtained. Maintenance is very low since the unit can be unattended for long periods of time. Data reduction is very simple, requiring only one measurement and one multiplication for each record plate to plot its point on the response spectrum.

The response spectrum switch (—A) version of the recorder has all of the features of the PSR1200.


To retain the basic reliability of the PSR1200, no batteries, motors, or bearings have been added. Electrical power is provided from the Peak Shock Annunciator™.

Every effort has been made to achieve the utmost reliability in the switching circuitry so as to match the reliability of the basic Peak Shock Recorder™. Closure of a switch contact sets an electronic latching switch which energizes the appropriate circuit in the annunciator and holds it energized until reset by the key-switch.

High impedance circuitry permits normal operation even if switch contact resistance exceeds several hundred thousand ohms. Ceramic encapsulated integrated circuits offer maximum resistance to the effects of temperature and humidity.

Finally, the heavy cast aluminum housing of the recorder offers protection against radiated interference or spurious mechanical operation caused by striking the recorder.

The recorder can be used singly, biaxially, or triaxially.



TRIAXIAL INSTALLATION OF THREE
MODEL PSR 1200-H/V-12A
PEAK SHOCK RECORDERS™
ON TRIAXIAL MOUNT

Switch Settings (—A version only)

The switch settings are permanently set to positions required by the customer's application. The —4A allows four dual settings, that is, the customer selects four frequencies to be monitored between 2 and 25 Hertz. Two acceleration



levels can be selected for switch contacts for each reed frequency, e.g., .47 g and .70 g at 3.2 Hertz. The —12A has twelve dual settings between 2 and 25 Hertz. See the tabulation of "Frequency and Switch Setting Limits" for selection available.

Data Reduction

Data reduction is done by measuring the maximum distance of the scratched record from the zero line. Normally just the maximum is recorded regardless of the direction. List this distance under "Displacement" on the calibration sheet. Multiply the "Displacement" times the

"Acceleration sensitivity" and record in the "Equivalent static acceleration" column. Plot the response spectrum graph.

Large displacement measurements can be made with a six-inch (152 mm) scale with graduations in hundredths (.01) of an inch (.25 mm). Small displacements can be made using a microscope with a reticle having graduations in thousandths (.001) of an inch (.025 mm).




CALIBRATION SHEET AND TEST DATA

Reed Number	Frequency (Hertz)	Acceleration Sensitivity (g/inch)	Displacement (inches)	Equivalent Static Acceleration (g)
1	2.02	.359	2.51	.90
2	2.54	.55	2.00	1.1
3	3.20	.85	1.41	1.2
4	4.02	1.32	.98	1.3
5	4.92	2.34	.55	1.3
6	6.02	3.62	.33	1.2
7	8.08	5.5	.15	.83
8	10.2	7.6	.079	.6
9	12.7	6.6	.078	.5
10	16.2	10.5	.046	.5
11	20.6	17.5	.022	.4
12	26.1	26.8	.015	.4

CALIBRATION

DATA REDUCTION

RESPONSE SPECTRUM



PEAK SHOCK RECORDERTM

MODELS PSR1200-H/V-4A and PSR1200-H/V-12A

QUALIFIED TO: GUIDE FOR SEISMIC QUALIFICATION OF CLASS I ELECTRICAL EQUIPMENT FOR
NUCLEAR POWER GENERATING STATIONS — IEEE GUIDE 344

Designed to meet the characteristics of the Response Spectrum Recorder and the Response Spectrum Switch described in the American Nuclear Society's Standard, ANSI/ANS-2.2-1978, Earthquake Instrumentation Criteria for Nuclear Power Plants and the U.S. Nuclear Regulatory Commission's Regulatory Guide 1.12, Nuclear Power Plant Instrumentation for Earthquakes, Revision 1. NOTE: Frequency range from 2.00 to 25.4, instead of 1.00 to 30.0.

PHYSICAL

Length	12-27/32 inches (32,6 cm)
Width	11-1/2 inches (29,2 cm)
Thickness	10 inches (25,4 cm)
Weight	34 pounds (15,4 kg) 36 pounds (-A) (16,3 kg)

ENVIRONMENTAL

Temperature	-40°C to +85°C
Altitude	To 50,000 feet (15,240 meters)
Humidity	To 100% RH
RFI	No adverse radiated or conducted RFI
Water-Tight	To 50 PSI (3,6 kg/cm ²) To 10 PSI (-A) (.7 kg/cm ²)
Nuclear Radiation	No effect on performance of permanent recorder. Switch electronics are not radiation hardened, unless requested at extra cost.

SENSORS

Number of Sensing Elements	12
Damping	2% (Q of 25)
Arrangement of Sensing Elements	Coplanar
Number of Switch Contacts	
-4A	4 Dual Contacts
-12A	12 Dual Contacts

ACCURACY

Frequency	±1%
Acceleration	±3% at 1g
Dynamic Range	See Table
Switch Settings	±3% at 1g

MOUNTING

4 through holes for 1/2 inch bolts

FREQUENCY, RANGE, and SWITCH SETTING LIMITS OF SENSING ELEMENTS


Reed Number	Nominal* Resonant Frequency (Hertz)	Full Scale Acceleration (g)	Dynamic Range		Switch Setting Limits** (g)	
			(db)	Ratio	Minimum*** (Accuracy ±100%)	Maximum (Physical Stops)
1	2.00	1.6	54.5	530:1	.003	1.6
2	2.52	2.5	55.8	620:1	.004	2.5
3	3.17	4	58.1	800:1	.005	4
4	4.00	6	58.7	860:1	.007	6
5	5.04	10	60.9	1110:1	.009	10
6	6.35	16	61.8	1230:1	.013	16
7	8.00	24	63.0	1410:1	.017	24
8	10.1	34	64.6	1700:1	.020	34
9	12.7	8	54.5	530:1	.015	8
10	16.0	12	55.6	600:1	.020	12
11	20.2	4	46.0	200:1	.020	4
12	25.4	6	49.5	300:1	.020	6

- * — 4A Allows choice of 4 frequencies to be monitored from 2 to 25 Hertz
— 12A Allows all 12 frequencies to be monitored from 2 to 25 Hertz
** — Two switch settings for each frequency to be monitored

- *** — Do not use PSR1200-H/V-A for settings under 0.10g.
For lower settings use RSR1600-H/V-A.

REPRESENTED BY:

MODEL
PAR400



3-3/16 inches
(8.1 cm)

MODEL PAR400
PEAK ACCELERATION RECORDER™

SENSES AND PERMANENTLY RECORDS PEAK ACCELERATIONS

- EARTHQUAKES
- STORMS
- EXPLOSIONS

RELIABLE and ECONOMICAL

ENGDAHL ENTERPRISES

2850 Monterey Avenue • Costa Mesa, California 92626 • (714) 540-0398

Introduction

Seismic events are random events, and may occur in remote and inaccessible locations or in built-up areas. Scientists and engineers frequently need to know the acceleration levels associated with these events, and for this reason, have developed instruments requiring no source of power, which can provide permanent records of peak acceleration.

Instruments of this type have been used for many years, but with the advent of the nuclear power plant, higher sensitivity and increased bandwidth are required to measure the accelerations induced in piping and other equipment. Since the older types of peak accelerometers

had been pushed to their design limits, an entirely new instrument was required.

This requirement has been met with the Model PAR400, Peak Acceleration Recorder™. It is an inexpensive triaxial unit which requires no power supply, and is virtually maintenance free. Peak accelerations as low as .01 g can be recorded, and the minimum bandwidth extends from 0 to 26 Hertz. Permanent records are scribed by diamond styli on replaceable metal plates. The peak acceleration is computed by multiplying the maximum excursion of the trace by the acceleration sensitivity of the recorder.

Description

The Model PAR400, Peak Acceleration Recorder™, senses and records peak accelerations triaxially. It is a self-contained passive device requiring no external power or control connections and has a minimum band width of 0 to 26 Hertz with a sensitivity as low as .01 g.

Each sensor of the PAR400 incorporates a new method of mechanical amplification which makes it more than five times as sensitive as previous devices. With the aid of optical magnification, its permanent record can be read to .001 of an inch (.025 mm) or less. With a full scale deflection of .200 inches (5 mm), the -1 version (2 g full scale) has a dynamic range of 200:1 (46 db).

Air damping is used since it is very efficient for its size and weight. Minor adjustments of damping can be made in the field, if required.

Sensors are available in three natural frequencies: 32, 51 and 64 Hertz. The assemblies are mechanically identical and completely interchangeable, so any combination may be included in a triaxial recorder.

The record is scratched permanently on a metal plate which is both serialized and keyed to the recorder to assure that the records are not confused among the three axes. Since the record is scratched, it can be measured without further processing. The record plates are inserted through side holes in the casting without taking off the cover. This minimizes the possibility of damaging the recorder or inadvertently recording on the record plate during insertion or removal by touching the mechanism.

Applications

The PAR400 is useful whenever low frequency peak acceleration measurements are needed. These accelerations may be due to earthquake, storms, or explosions. The three records give the acceleration levels along three mutually perpendicular axes.

The Peak Acceleration Recorder™ can be used in connection with:

1. Nuclear power plants
2. Steel mills

3. Refineries
4. Bridges and dams
5. High-rise structures
6. Mines
7. Ships
8. Off-shore oil rigs
9. Transportation shock

Features

The PAR400 is a very sensitive, wide band, low frequency acceleration recording instrument. The high sensitivity is obtained by using a heavy mass to detect the acceleration, and then mechanically amplifying its

motion. A diamond tip scribe at the end of the amplifier arm traces a very fine visible permanent record of the arm's excursions. The scribe line widths are on the order of .0004 inches (.01 mm).

Three plates, stamped L, T, and V, respectively, are used to record the excursions in the three axes. Slotted keyways on the plates match up with pins in the housing so that only the correctly stamped plate can be inserted full depth into the corresponding sensor. Each set of three plates also carries a unique serial number. This permanent identification system eliminates the possibility of confusing the records.

The rugged cast aluminum housing has three pads to contact the mating surface when mounted. A single screw is used for attachment. Shims can be slid under the appropriate pad to level the unit. The screw is then tightened. A clearance hole is provided in the cover for the screw head so the cover need not be removed during mounting of the recorder.

To install the record plates, three plugs are removed from the side walls of the casting and the plates are slipped into the appropriate holders. The plugs are of such a size as to preclude damage to the mechanism during insertion or removal of the record plates. Since the cover does not have to be removed to replace record plates, the mechanism is not exposed to inadvertent damage.

When a record plate is inserted, a spring-loaded pin forces the plate to one side of the track to eliminate any side play which would introduce an error in the recorded acceleration. The insertion produces a zero line on the plate. On removal, a zero line is also scratched. These zero lines should coincide if there is no mechanical

shifting between insertion and removal. If there is a shift, the user is made aware that a problem exists.

To obtain wide band response, the instrument is damped to 60% of critical. A preadjusted air damper is used for damping to keep the size and weight of the total package as small as possible.

The recorder is reliable because of its simplicity. It does not contain any of the more complex and less reliable components, i.e., batteries, connectors, motors, and bearings. The recorder is self-contained, and requires no start-up time.

The recorder is economical in that no external connections or power are required. The record plates are reusable by replating. Maintenance is very low since the unit can be unattended for long periods of time.

Materials have been selected for long life even when exposed to nuclear radiation. The cast housing, along with the cover and three plugs, is chemically filmed (alodine) and painted with epoxy paint. The gaskets are made of EPDM to increase resistance to radiation. All hardware is stainless steel. An indicating silica gel desiccant is also provided to decrease the humidity inside the recorder.


Data reduction is very simple requiring only one measurement and one multiplication for each of the three record plates to obtain its maximum acceleration.

Data Reduction

Data reduction is accomplished by measuring the maximum displacement of the scratched record from the zero line. Normally just the maximum is recorded regardless of the direction. List this distance under "Displacement" on the calibration sheet.

Multiply the "Displacement" times the "Acceleration Sensitivity" and record in the "Acceleration" column.

MAGNIFIED RECORD
USING A RETICLE



SAMPLE OF A
CALIBRATION AND TEST DATA SHEET

Sensor	Natural Frequency (Hertz)	Acceleration Sensitivity (g/inch) (g/mm)	Displacement (inches) (mm)	Acceleration (g)
L	32.3	14.0 (.551)	.023 (.58)	.32
T	30.9	13.5 (.532)	.010 (.26)	.14
V	33.3	14.2 (.559)	.005 (.13)	.07

CALIBRATION

DATA REDUCTION

PEAK ACCELERATION RECORDER™

MODEL PAR400

QUALIFIED TO IEEE RECOMMENDED PRACTICES FOR SEISMIC QUALIFICATION OF CLASS 1E
EQUIPMENT FOR NUCLEAR POWER GENERATING STATIONS, STD. 344-1975

Designed to meet the characteristics of the Peak Accelerograph described in the American National Standard ANSI/ANS-2.2-1978, Earthquake Instrumentation Criteria for Nuclear Power Plants and the U.S. Nuclear Regulatory Commission's Regulatory Guide 1.12, Nuclear Power Plant Instrumentation for Earthquakes, Revision 1.

SENSORS

Number of Sensing Elements	3
Arrangement of Elements	Triaxial
Full Scale Acceleration	-1 2 g -2 5 g -3 10 g
Dynamic Range	-1 200:1 (46 db) -2 385:1 (52 db) -3 500:1 (54 db)
Natural Frequency ($\pm 5\%$)	-1 32 Hz -2 51 Hz -3 64 Hz
Damping	55 to 70% of Critical ¹
Bandwidth	-1 0 to 26 Hz -2 0 to 41 Hz -3 0 to 52 Hz
Overall Accuracy	Within $\pm 5\%$ at full scale, changing linearly to $\pm 1.5\%$ of full scale at 0.01 g
Detail Acceleration Accuracy	-1 .01 to .50 g $\pm .01$ g .50 to 1 1/4 g $\pm 2\%$ 1 1/4 to 2 g $\pm 3\%$ -2 .013 to .65 g $\pm .013$ g .65 to 2 g $\pm 2\%$ 2 to 5 g $\pm 3\%$ -3 .02 to 1 g $\pm .02$ g 1 to 3 g $\pm 2\%$ 3 to 10 g $\pm 3\%$

Spurious Resonances: None within frequency range of interest

Cross Axis Sensitivity: Less than .03 g/g

PHYSICAL DIMENSIONS

Length	5-1/4 inches (13.34 cm)
Width	3-5/8 inches (9.21 cm)
Height	3-11/32 inches (8.49 cm)
Weight	2-3/4 pounds (1.3 kg)

¹Damping adjusted at nominal atmospheric pressure expected at time of operation.

MOUNTING

One (1) #10-24 Screw.

Level Recorder to $\pm 1^\circ$ (1/16 inch in 3 1/2 inches) (1.6 mm in 90 mm) by adding shims under the appropriate mounting pad.

"V" will measure the vertical accelerations.

Align long side of recorder within 3° (1/4 inch in 5-1/8 inches) (6.4 mm in 130 mm) of designated North/South line. "L"

(longitudinal) will measure N/S accelerations. "T" (transverse) will measure E/W.

ENVIRONMENTAL

Temperature -40°C to +85°C

Humidity To 100% RH

RFI Does not radiate or conduct RFI. Not affected by external RFI.

Water Water-Tight to 70 PSI (5 kg/cm²)

Nuclear Radiation

The following materials are used in the construction of the PAR400.

1. Metals: Aluminum, Brass, Stainless Steel, Beryllium Copper, Gold, Nickel
2. Non-Metallic Materials


Description	Material	Stress Level	Approx. Stability ² (RAD)
Paint	Epoxy	Low	1×10^8
Adhesive	Epoxy	Low	1×10^8
Adhesive	Anaerobic	Low	2×10^8
Adhesive	Cyanocrylate	Low	2×10^8
Gaskets	EPDM	Low	1×10^8
Piston	Graphite	Low	2×10^8
Cylinder	Pyrex	Low	2×10^8
Scriber	Diamond	Low	2×10^8

POWER REQUIREMENTS - None

²Source: Dow Corning Corporation, Loctite Corporation, Corning Glass Works, E.I. Du Pont de Nemours & Company, Parker Seal Company, Raychem Corporation, General Electric

REPRESENTED BY:

MODEL
PSA875
and
PSA1575



17 1/4 inches
(43.8 cm)

MODEL PSA1575
PEAK SHOCK ANNUNCIATOR™

INDICATES THAT SPECIFIED PRESET SPECTRAL ACCELERATIONS HAVE BEEN EXCEEDED
PROVIDES CONTACT CLOSURES FOR REMOTE INDICATORS OR ALARMS

- EARTHQUAKES
- STORMS
- EXPLOSIONS

RELIABLE and ECONOMICAL

ENGDAHL ENTERPRISES



2850 Monterey Avenue • Costa Mesa, California 92626 • (714) 540-0398

Description

The Models PSA875 and PSA1575, Peak Shock Annunciators™, give visual warning that pre-determined acceleration limits, making up a response spectrum, have been exceeded at certain frequencies. They are designed to operate in conjunction with tuned Peak Shock Recorders™, PSR1200-H/V-4A/12A. Both models have three banks of indicator lamps, one bank for each of

three mutually perpendicular axes. Amber lights indicate accelerations approaching design limits (normally 70%) while red lights indicate that design limits have been exceeded. Model PSA875 monitors four frequencies per axis while Model 1575 monitors twelve. Both models may be equipped with relays to operate remote indicators or alarms. (See "Options and Accessories".)

Applications

The annunciators may be used whenever it is desired to indicate instantaneously the reaction of a structure to a complex shock such as an earthquake or an explosion. The information provided permits an immediate decision as to whether or not the operation can continue or must be shut down.

The Peak Shock Annunciator™ can be used in connection with:

1. Nuclear power plants
2. Steel mills
3. Refineries
4. Bridges and dams
5. High-rise structures
6. Mines
7. Ships
8. Off-shore oil rigs
9. Transportation shock

Features

The "AC Power" indicator lamp is fed from the DC power on the printed circuit boards and shows that the incoming power line and the regulated DC supply are both operating normally.


A key-operated test/reset switch is provided. It controls two functions. In the "test" position, all of the indicator lamps should be illuminated and

all relays (if provided) should be energized. This permits an immediate check that the annunciator is functioning correctly. When the key is returned to the "reset" position and removed from the switch, all indicators will be de-energized, the latches will be reset, and the annunciator is ready to receive signals from the Response Spectrum Recorder™. Once a signal has been received, the

appropriate lamp and relay, if any, will remain energized until the annunciator is reset with the key.

Where relays are provided for remote indicators or alarms, separate electronic driving circuitry is provided. Dual redundancy is thereby achieved for additional reliability.

Uninterruptible power supplies incorporating batteries for emergency operation can also be provided. If power failure is anticipated, battery operation is strongly recommended since power failure will reset any annunciated signal at the time of failure. Two additional indicators are mounted on the panel. One monitors the AC power at the transformer of the battery charger. The second monitors the charging circuit.



MODEL PSA875
PEAK SHOCK ANNUNCIATOR™

TRIAxIAL INSTALLATION OF THREE
MODEL PSR-1200-H/V-4A,
PEAK SHOCK RECORDERS™
ON TRIAXIAL MOUNT

PEAK SHOCK ANNUNCIATORTM

Models PSA875 and PSA1575

QUALIFIED TO: GUIDE FOR SEISMIC QUALIFICATION OF CLASS I ELECTRICAL EQUIPMENT FOR
NUCLEAR POWER GENERATING STATIONS - IEEE GUIDE 344

Designed to meet the characteristics of the Control Room Indicator for Response Spectrum Switch described in the American Nuclear Society's Standard ANSI/ANS-2.2-1978, Earthquake Instrumentation Criteria for Nuclear Power Plants and the U.S. Nuclear Regulatory Commission's Regulatory Guide 1.12, Nuclear Power Plant Instrumentation for Earthquakes, Revision 1.

PHYSICAL			ENVIRONMENTAL	
Length	PSA875 19 inches (48,3 cm)	PSA1575 19 inches (48,3 cm)	Temperature	0 to +70°C
Width	20 1/2 inches (52,4 cm)	20 1/2 inches (52,4 cm)	Humidity	To 100% RH
Thickness	10 1/4 inches (26,0 cm)	17 1/4 inches (43,8 cm)	RFI	No adverse radiated or conducted RFI
Weight	33 pounds (15 kg)	45 pounds (20,5 kg)	POWER REQUIREMENTS	
INDICATORS			Voltage	115 VAC
Number of Axes Monitored	3	3	Current	2 1/2 amperes maximum
Number of Frequencies Monitored	12	36	MOUNTING	
Number of Indicators	24	72	Bench or Standard 19" (48,3 cm) Relay Rack	
			8 3/4" (22,2 cm) high or	
			15 3/4" (40,0 cm) high	
			27 lbs. (12,3 kg)	

Options and Accessories (available at extra cost)

1. Relay closures for remote indication and alarm.
One relay with Form C contacts can be provided for each output indicator. A connector on the back of the chassis facilitates system implementation. The connector is wired for normally open or normally closed operation.

To date, most customers have selected a two-relay system. One relay indicates that the lower level (amber) has been exceeded. The second relay indicates the upper level (red) has been exceeded at least once.

Relays are rated at: 1/10 Hp, 3 amps @ 120 VAC
or 3 amps @ 28 VDC resistive.

2. Uninterruptible power supplies incorporating batteries for emergency operation can be furnished within the confines of the annunciator. If power failure is anticipated, battery operation is strongly recommended since power failure will reset any annunciated signals at the time of the failure.

REPRESENTED BY:

APPENDIX C

A PRELIMINARY EVALUATION OF THE SIGNIFICANCE
OF THE SEISMIC EVENT ON JANUARY 31, 1986
AT THE PERRY NUCLEAR POWER PLANT

STEVENSON



STEVENSON & ASSOCIATES

a structural-mechanical consulting engineering firm

9217 Midwest Avenue • Cleveland, Ohio 44125 • (216) 587-3805 • Telex: 980101

Document Number 861401-1
Revision 0 -- 2/10/86

A PRELIMINARY EVALUATION
OF THE SIGNIFICANCE
OF THE SEISMIC EVENT ON
JANUARY 31, 1986 ON
THE PERRY NUCLEAR POWER PLANT

February 10, 1986

Perry Nuclear Power Plant
Cleveland Electric Illuminating Co.
10 Center Road
Perry, Ohio 44080

PREPARED BY:

Stevenson and Associates
9217 Midwest Avenue
Cleveland, Ohio 44125
(216) 587-3805

Document Number 861401-1
Revision 0 -- 2/10/86

A PRELIMINARY EVALUATION
OF THE SIGNIFICANCE
OF THE SEISMIC EVENT ON
JANUARY 31, 1986 ON
THE PERRY NUCLEAR POWER PLANT

February 10, 1986

Perry Nuclear Power Plant
Cleveland Electric Illuminating Co.
10 Center Road
Perry, Ohio 44080

PREPARED BY:

Stevenson and Associates
9217 Midwest Avenue
Cleveland, Ohio 44125
(216) 587-3805



1.0 INTRODUCTION

On January 31, 1986, at 11:47 a.m. EST, a brief (approximately 0.75 second strong motion duration) and shallow (10 km focal depth) earthquake with a 4.9 m_b magnitude occurred. Its epicenter was south of Lake Erie, at a distance of approximately eleven (11) miles from the Perry Nuclear Power Plant site at Perry, Ohio.

Stevenson and Associates was retained to analyze the data provided by seismic recorders installed at various locations in the Perry plant, and determine: (1) how the earthquake parameters, as recorded by the instrumentation at the site, compare to those for the Safe Shutdown Earthquake (SSE) and Operating Basis Earthquake (OBE) postulated in the design of the Perry plant's buildings, systems and components; (2) the structural significance of the readings by the seismic recorders at the Perry site during the January 31, 1986 earthquake; and (3) the anticipated impact of the earthquake on the plant's buildings, systems and components.

This report contains Stevenson and Associates' preliminary evaluation of the above-described matters. It is based on a physical walkdown of the site, analysis of data recorded by the seismic instrumentation, and discussions with plant technical and operating personnel. Since some of the evaluations of the earthquake are still underway, this report may be supplemented and/or revised at a later date if new information developed during these ongoing activities so warrants.



A resume of the qualifications and experience of Stevenson and Associates is included as Attachment 1 to this report.

2.0 SEISMIC INSTRUMENTATION AT THE PERRY PLANT

The earthquake motion at the Perry site was recorded by three different types of instrumentation. One type of recorder is the Kinometrics Model SMA-3 strong motion time history recording accelerograph; this system detects and records the three orthogonal components of acceleration signals over the duration of an earthquake. Another type of instrumentation is the Engdahl PSR 1200-H/V response spectrum recorder, which provides the response at selected frequencies in three orthogonal directions. The third type of instrumentation is the Engdahl PAR 400 peak accelerograph, which records the three orthogonal components of peak local accelerations produced by the earthquake. The locations and readings taken by these systems will be discussed separately below.

2.1 Locations and Readings by the Kinometrics SMA-3 Accelerographs

Two Kinometrics SMA-3 strong motion time history recording accelerographs installed at the Perry plant provided time history data on the earthquake. One system is located on the Unit 1 reactor containment concrete wall at the basemat at Elevation 575', as shown in Figure 1. The second system is attached to the steel containment vessel wall at Elevation 686', 111 feet

above the first system and offset by less than one degree in Azimuth. The longitudinal axes of both instruments are in the N-S direction.

The time history motions recorded by these two systems are shown in Figures 2 through 8. A detailed interpretation of the readings from these recorders is contained in Reference 1.^{1/}

The lower instrument (Elevation 575') gave a peak acceleration of 0.18g in the N-S direction, 0.10g in the E-W direction, and 0.11g in the vertical direction. The upper instrument (Elevation 686') gave a peak acceleration of 0.55g in the N-S direction, 0.18g in the E-W direction, and 0.30g in the vertical direction. It should be noted that both instruments are installed on cantilever brackets off the wall. While the brackets are quite heavy and relatively rigid, they are attached by four 3/8" diameter bolts, approximately 5 inches on center vertically and 8 inches horizontally. This arrangement may result in amplified bracket motion.

2.2 Locations and Readings of the Engdahl Response Spectra Recorders

There are four Engdahl PSR 1200-H/V triaxial response spectra recorders at the Perry plant. This type of recorder includes twelve reeds of different lengths and weights, one for each

^{1/} References are listed at the end of this report.

frequency, fabricated from spring steel. A diamond-tipped stylus is attached to the free end of each reed to inscribe a permanent record of its deflection on one of twelve record plates. The record plates are aluminum, plated with successive layers of nickel, tin, and lead-tin.

The four PSR 1200-H/V recorders at the Perry plant are located as follows (all locations are for Unit 1):

1. Reactor Building Foundation: Elevation 574', Reactor Building foundation mat, Azimuth 210°. This recorder was most recently calibrated on January 14, 1985.
2. Reactor Building Drywell Platform: Inside the drywell platform at Elevation 630', Azimuth 240°, mounted as shown in Figure 9. This recorder was most recently calibrated on January 30, 1986.
3. HPCS Pump Base Mat: In the HPCS Pump Room, in the Auxiliary Building foundation mat, Elevation 574'. The equipment was being calibrated at the time of the earthquake. Previous calibration occurred on January 14, 1985.
4. RCIC Pump Base Mat: In the RCIC Pump Room in the Auxiliary Building foundation mat at Elevation 574'. The equipment was being calibrated at the time of the earthquake. Previous calibration was on January 14, 1985.

The readings taken by these four instruments are discussed in detail in Reference 2. Briefly stated, three of the four instruments provided response spectra which were consistent with each other and which were reasonable in light of the time history readings of the Kinematics instruments. The fourth spectra recorder, mounted inside the drywell on the Elevation 630' platform (see Figure 9), indicated vertical acceleration response components of .973g and 1.54g at frequencies of 20.2 and 25.4 Hz, respectively. These readings were 8 to 10 times higher than the corresponding horizontal accelerations at the same frequencies measured by the instrument. See Table 1.^{2/}

2.3 Location and Readings of the Engdahl Peak Acceleration Recorders

The Engdahl Model PAR 400 peak acceleration recorder senses and records peak accelerations triaxially. A diamond tipped scribe at the end of an amplifier arm traces a very fine visible permanent record on an aluminum record plate with successive layers of nickel, gold, and burnt gold.

2/ Figure 9 shows the mounting of the Engdahl PSR 1200-H/V instrument on the Elevation 630' platform. The instrument is located approximately 6 feet from the face of the reactor vessel shield wall on an outer beam which provides supports for the platform, recirculation and safety injection piping, and a monorail. Given the highly complex nature of the steel platform and support structure on which the instrument is mounted, it is quite possible the instrument may have measured the acceleration caused by a secondary impact resulting from the earthquake.

The two peak acceleration recorders are located as follows:

1. Reactor Recirculation Pump: Inside the drywell at Elevation 574', on recirculation pump B33-C001A. This instrument was most recently calibrated on December 4, 1985.
2. HPCS Pump Base Mat: In the HPCS Pump Room, in the Auxiliary Building foundation mat at Elevation 574', mounted as shown in Figure 10. This instrument was most recently calibrated on January 30, 1986.

The readings by the Engdahl PAR 400 recorders are discussed in detail in Reference 2.

3.0 COMPARISON AND EVALUATION OF RECORDED ACCELERATIONS AGAINST THOSE ASSUMED FOR THE PERRY SSE AND OBE

Table 2 shows a comparison of the zero period accelerations ("ZPAs"), as recorded by the various instruments, with the corresponding SSE and OBE design accelerations. According to the recorded accelerations, the design basis values of ZPA for the OBE, and in a few instances the SSE, were exceeded during the January 31, 1986 earthquake. As will be discussed below, given the short duration and low energy of the earthquake, the exceedences were not significant from an engineering point of view. This is supported by the apparent lack of damage to plant structures and mechanical and electrical components detected as a result of the earthquake. Moreover, inspection of

engineered facilities located near the epicenter and not designed to withstand any earthquake force did not reveal any damage from the earthquake (Reference 3). In order to correlate the short duration, high frequency acceleration that was recorded with the lack of impact on structures and equipment, it is necessary to understand how measured ground acceleration can and should be correlated with design basis accelerations.

In postulating the limiting earthquake conditions for designing nuclear power plant facilities, a key parameter has been the zero period acceleration or Instrumental Peak Acceleration (A_{ip}), which represents the peak acceleration recorded during the entire earthquake motion. As concluded in many studies (References 4 through 11), A_{ip} is a poor indicator of the damage potential of earthquake ground motions. It has been observed that structures performed much better than would have been predicted based on the measured A_{ip} to which the structures were subjected; this phenomenon has been particularly noticeable in connection with short duration, high energy ground motions due to low to moderate magnitude earthquakes, such as the January 31, 1986 earthquake near Perry.^{3/} The differences

^{3/} Examples of this behavior may be found in the records of the 1966 Parkfield earthquake, the 1971 Pacoima Dam earthquake, the 1972 Ancona earthquake, and the 1972 Melendy Ranch Barn earthquake. These earthquakes showed recorded instrumental peak ground accelerations of between 0.5g and 1.2g, yet only minor damage occurred in the vicinity of the recording sites.

between measured ground motion, assumed design levels, and observed physical behavior is so significant that it cannot be attributed to the safety factors which are utilized in the design and in elastic seismic analyses.

Kennedy (Reference 12), based on the work of others (References 13 through 16) has suggested that it is not appropriate to use just measured A_{ip} to define the characteristics of the SSE and OBE. It is necessary to take also into account, in addition to A_{ip} , the dominant frequency of the strong motion excitation and the duration of the strong motion.^{4/} He has proposed the following relationship to develop an equivalent design acceleration for the anchoring elastic spectra:

$$A_D = (K_p) (rms),$$

where A_D is the equivalent design acceleration and the other parameters are defined as follows:

$$K_p = \sqrt{2 \ln (2T_D/T_o)} \geq 2.0$$

$$T_D = \text{Duration of strong motion (sec.)}$$

^{4/} Thus, for a high dominant frequency and/or short duration earthquake, the equivalent peak acceleration would be significantly less than that predicted on the basis of A_{ip} measurements alone.

T_0 = Predominant period of motion (sec.)

$$r_{ms} = \sqrt{P}$$

P = $E(T)/T_D$ = earthquake power (average rate of energy input)

$$E_T = \int_{t_0}^{t_0 + T_D} a^2(t) dt = \text{total energy}$$

fed into the structure between times t_0 and $t_0 + T_D$, and

$a(t)$ = instrument acceleration at time t .

Efforts are underway to compute A_D for the January 31, 1986 earthquake. In the meantime and by way of comparison, four earthquakes similar in magnitude and duration to the Perry earthquake have been selected from Tables 1 and 2 of Reference 12. The characteristics of those earthquakes, and those of the one at Perry, are summarized in Table 3. For the four earthquakes listed, an average ZPA of 0.434g is required to cause the same level of response for elastic structures as that postulated by the NRC Reg. Guide 1.60 (Reference 17) spectra for a .20g ground acceleration. This result suggests that a correction factor of $0.20/0.434 = 0.46$ should be applied to the accelerations measured during low to moderate magnitude earthquakes (such as the one near Perry) to obtain elastic responses

that can be compared to those from the limiting Reg. Guide 1.60 earthquake.

If, in fact, a 0.46 correction factor is applied to the accelerations recorded at Perry and shown in Table 2, accelerations well below the SSE and OBE levels are obtained for all locations except for the readings at the Reactor Building Containment Vessel (Elevation 686'), where the corrected N-S and vertical ZPA are approximately equal to the OBE design value. This is shown in Table 4, where the recorded values of Table 2 have been adjusted by a .46 factor.

4. STRUCTURAL SIGNIFICANCE OF THE PERRY EARTHQUAKE AND ANTICIPATED IMPACT OF EVENT ON THE ADEQUACY OF THE PLANT STRUCTURES, SYSTEMS AND COMPONENTS.

Table 4 indicates that if the recorded accelerations from the Perry earthquake are corrected to take into account the short duration and low energy of the event, the average elastic response ZPAs are in all but one instance equal to or less than one-third of the OBE design values, and are approximately equal to the OBE values in the remaining case. In light of these results and the design limits placed on the strength of materials for safety applications (i.e., not to exceed a 0.6 to 0.8 factor of yield during an OBE), all safety-related plant structures, systems and equipment should have remained essentially elastic during an earthquake such as the one experienced on

January 31, 1986, and thus should have emerged undamaged from it. This expectation has been corroborated by physical observation of plant conditions following the earthquake.

Some auxiliary or secondary structural systems, such as suspended ceilings and plaster ceilings and walls, might be expected to sustain some displacement or cracking. One might also expect actuation of instrumentation measuring or sensing changes in liquid levels or the presence of vibration. In addition, one might expect some activation of inertia-sensing relays or switches (fluid or spring loaded), if such controls or instrumentation have not been qualified for seismic operability. If any of these circumstances are determined to have taken place at Perry, their occurrence would only be indicative of the anticipated response of non-seismically qualified structures to moderate earthquake conditions.

TABLE 1 (From Reference 2)

READINGS FROM RESPONSE SPECTRA RECORDER

MPL NUMBER: D51-R170

LOCATION: REACTOR RECIRCULATION

PIPING SUPPORT - DW 630', 240°

REED NUMBER	NOMINAL FREQUENCY (HERTZ)	ACCELERATION(g)					
		North/South		East/West		Vertical	
		1-31-86	2-2-86	1-31-86	2-2-86	1-31-86	2-2-86
1	2.00	.047	.048	.049	.051	.007	.007
2	2.52	.082	.082	.086	.084	(*)	.013
3	3.17	.184	.184	.144	.140	.015	.014
4	4.00	.226	.223	.128	.127	.023	.023
5	5.04	.132	.134	.158	.158	.035	.033
6	6.35	.131	.134	.058	.055	.033	.030
7	8.00	.104	.104	.109	.090	(*)	.019
8	10.1	.093	.093	(*)	.052	.093	.085
9	12.7	.188	.182	.166	.080	.198	.199
10	16.0	.194	.204/.167	.348	.312	.490	.500
11	20.2	.152	.152	.191	.175	.973	.373
12	25.4	.114	.091	.155	.158	1.7	1.54

(*) Unreadable

TABLE 2

COMPARISON OF DESIGN ZPAs (1)
VS RECORDED ZPAs
(Expressed in g values)

		Auxiliary Building Founda- tion Mat Eleva- tion 568' PAR 400 (Engdahl) D51-R140	Reactor Building Founda- tion Mat Elevation 574'-10" SMA -3 (Kine- metrics) D51-N101	Reactor Building Recircu- lation Pump Eleva- tion 605' PAR 400 (Engdahl) D51-R120	Reactor Building Con- tainment Vessel Elevation 686' SMA-3 (Kine- metrics) D51-N111	Reactor Building Platform Ele- vation 630'-1" Inside Drywell PSR 1200 (Engdahl) D51-R170
NS	Recorded	.17	.18	.32	.55	.09
	SSE	.17	.18	1.06	.40	.48
	OBE	.10	.10	.86	.24	.40
EW	Recorded	.06	.10	.11	.18	.16
	SSE	.20	.18	1.06	.40	.48
	OBE	.10	.10	.86	.24	.40
VERT	Recorded	.03	.11	.05	.30	Note 2
	SSE	.20	.18	.47	.24	.28
	OBE	.10	.10	.38	.15	.16
SRSS(3)	Recorded	.18	.23	.34	.65	Note 2
	SSE	.33	.31	1.57	.62	.73
	OBE	.17	.17	1.27	.37	.59

- (1) Zero period acceleration
(2) ZPA indeterminable from available data
(3) Square-root-of-the-sum of the squares

TABLE 3

CHARACTERISTICS AND GROUND ACCELERATION LEVELS
REQUIRED TO ACHIEVE EQUAL STRUCTURAL ELASTIC
RESPONSE BETWEEN R.G. 1.60 AND SELECTED EARTHQUAKES

Earthquake	Magni- tude M_v	Recording Station Epicen- tral Dis- tance(km)	Peak Inst. Ground Accelera- tion, g	Strong Motion Dura- tion, sec.	Equiv. ZPGA to the 0.20g R.G. 1.60 Spectra
Parkfield - 1966	5.6	1	0.49	1.4	.3275
Hollister - 1974	5.2	13	0.138	1.1	.4825
Santa Barbara - 1978	5.1	4	0.347	3.0	.2825
Bear Valley-1972	4.7	6	0.520	0.8	<u>.6450</u>
Ohio - 1986	4.9	17	(*)	0.75	<u>.434(Average)</u> --

(*) 0.18g in N-S direction, 0.10g in E-W direction, measured
at the foundations.

TABLE 4

COMPARISON OF DESIGN ZPAs (1)
VS CORRECTED RECORDED ZPAs
(Expressed in g values)

		Auxiliary Building Founda- tion Mat Eleva- tion 568' PAR 400 (Engdahl) D51-R140	Reactor Building Founda- tion Mat Elevation 574'-10" SMA -3 (Kine- metrics) D51-N101	Reactor Building Recircu- lation Pump Eleva- tion 605' PAR 400 (Engdahl) D51-R120	Reactor Building Con- tainment Vessel Elevation 686' SMA-3 (Kine- metrics) D51-N111	Reactor Building Platform Ele- vation 630'-1" Inside Drywell PSR 1200 (Engdahl) D51-R170
NS	Recorded	.08	.08	.15	.25	.04
	SSE	.17	.18	1.06	.40	.48
	OBE	.10	.10	.86	.24	.40
EW	Recorded	.03	.05	.06	.08	.07
	SSE	.20	.18	1.06	.40	.48
	OBE	.10	.10	.86	.24	.40
VERT	Recorded	.02	.06	.02	.14	Note 2
	SSE	.20	.18	.47	.24	.28
	OBE	.10	.10	.38	.15	.16
SRSS(3)	Recorded	.08	.11	.16	.30	Note 2
	SSE	.33	.31	1.57	.62	.73
	OBE	.17	.17	1.27	.37	.59

- (1) Zero period acceleration
(2) ZPA indeterminable from available data
(3) Square-root-of-the-sum of the squares




FIGURE 1 - KINEMETRICH SMA-3
ACCELERATION TIME HISTORY RECORDER
SERIAL NO. 165-1, TAG NO. 351-411
LOCATED AT BASE OF C MOUNTAIN
ELEVATION 575.




FIGURE 2 - KINEFLEX AFA-3
ACCELERATION TIME HISTORY RECORDING
SERIAL NO. 165-2, TAG NO. 151-111
LOCATED ON THE STEEL CONTROL
SHELL AT BL. 492.




FIGURE 3-EL. 575.0 BASE MAT CONT.
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-1L (N-S)






FIGURE 4-EL. 575.0 BASE MAT. CONT.
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-IT (E-W)




FIGURE 5-EL. 575.0 BASE MAT. CONT.
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-1V (VERT.)




FIGURE 6-EL. 682.0 CONT. WALL
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-2L






FIGURE 7-EL. 682.0 CONT. WALL
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-2T




FIGURE 8-EL. 682.0 CONT. WALL
ML 5.0 EARTHQUAKE
JANUARY 31, 1986
SMA 3S/N 165-2V




FIGURE 9 - MOUNTING OF
ENGDAHL PSR 1200-H/V
RECORDER ON THE LL-430
BOATWELL PLATFORM.




FIGURE 10 - MOUNTING OF
ENCODER TYPE PAF 40
RECORDED ON SURFACE
BUILDING SURVEILLANCE
BL. 500.

REFERENCES

- (1) Kinemetrics/Systems, "Strong-Motion Data report for the M_L 5.0 Earthquake of 1147 EST, January 31, 1986 Perry, Ohio", 4 February 1986.
- (2) ENGDAHL Enterprises, "Report on the Peak Shock Recorder and Peak Acceleration Recorder Installed at the Perry Nuclear Power Plant During the Seismic Event on January 31, 1986," Document No. 120910, 7 February 1986.
- (3) Stevenson and Associates, "Reconnaissance Report Prepared for EERI for the Ohio-1986 Earthquake" (In Preparation).
- (4) Blume, J.A., "On Instrumental versus Effective Acceleration and Design Coefficients", Proceedings of the 2d U.S. National Conference on Earthquake Engineering, Stanford University, California, August 1979.
- (5) Schnabel, P.B., and Seed, H.B., "Accelerations in Rock for Earthquakes in the Western United States", Seismol. Soc. America Bull., Vol. 62, April 1973.
- (6) Ploessel, M.R., and Slosson, J.E., "Repeatable High Ground Accelerations from Earthquakes", California Geology, Vol. 27, No. 9, pp. 195-199, September 1974.
- (7) Newmark, N.M., "A Rationale for Development of Design Spectra for Diablo Canyon Reactor Facility", N.M. Newmark Consulting Engineering Services, Urbana, Illinois, September 1976.
- (8) Nuttli, O.W., "State-of-the-Art for Assessing Earthquake Hazards in the United States; The Relation of Sustained Maximum Ground Acceleration and Velocity to Earthquake Intensity and Magnitude", Miscellaneous Paper S-73-1, Report 16, November 1979, U.S. Army Engineers Waterways Experiment Station, Vicksburg, Miss.
- (9) Whitman, R.V., "Effective Peak Acceleration", Proceedings of the Second International Conference on Microzonation, San Francisco, California, November 26 - December 1, 1978, Vol. III, pp. 1247-1255.
- (10) Fage, R.A., Boore, D.M., Joyner, W.B., and Coulter, H.W., "Ground Motion Values for Use in the Seismic Design of the Trans-Alaska Pipeline System", USGS Circular No. 672, Washington (1972).

- (11) Kennedy, R.P., Tong, W.H., and Short, S.A., "Earthquake Design Ground Acceleration Versus Instrumental Peak Ground Acceleration", SMA 12501.01, Structural Mechanics Associates, Newport Beach, California, October 1980.
- (12) Kennedy, R.P., "Peak Acceleration as a Measure of Damage", Presented at 4th International Seminar on Extreme-Load Design of Nuclear Power Plants", Paris, France, August 1981.
- (13) Arias, A., "A Measure of Earthquake Intensity", Seismic Design for Nuclear Power Plants, MIT Press, Cambridge, Mass. (1970).
- (14) Housner, G.W., "Measures of Severity of Earthquake Ground Shaking", Proceedings of the U.S. National Conference on Earthquake Engineering, EERI, Ann Arbor, Michigan, June 1975, pp. 25-33.
- (15) Mortgat, C.P., "A Probabilistic Definition of Effective Acceleration", Proceedings of the 2nd U.S. National Conference on Earthquake Engineering, Stanford University, August 22-24, 1979, pp. 743-752.
- (16) McCann, M.W., Jr. and Shah, H.C., "RMS Acceleration for Seismic Risk Analysis: An Overview", Proceedings of the 2nd U.S. National Conference on Earthquake Engineering, Stanford University, August 22-24, 1979, pp. 883-897.
- (17) U.S. Nuclear Regulatory Commission, Regulatory Guide 1.60, "Design Response Spectra for Seismic Design of Nuclear Power Plants" (Rev. 1, December 1973).

JOHN D. STEVENSON

EXPERIENCE:

PRESIDENT - MANAGING
PARTNER

Since November 1981, Dr. Stevenson has managed and has served as President and Senior Consultant to Stevenson & Associates. The firm specializes in high technology consulting and forensic engineering associated with failure analysis of structural and mechanical systems; extreme loads; and nonlinear, dynamic, and probabilistic high temperature analyses.

VICE-PRESIDENT -
GENERAL MANAGER
1976 - 1981

As Vice-President, Dr. Stevenson managed and served as Senior Engineering Consultant to the Cleveland Offices of Woodward-Clyde Consultants and Structural Mechanics Associates specializing in areas of high technology applicable to the structural-mechanical design and analysis of systems and components. Prior to this time, the consulting group he headed provided similar services as a Division of Davy-McKee Co. Dr. Stevenson also served as Corporate Manager of Engineering Quality Assurance for Davy-McKee Co.

ASSOCIATE PROFESSOR
AND PRINCIPAL
MANAGER OF EASTERN
OPERATIONS
1974 - 1976

Case Western Reserve University, CWRU, and EDAC, Inc., Cleveland, Ohio.

As an Associate Professor at CWRU, Dr. Stevenson served as Director of a program in Design for the Extreme Load Environment and held a joint appointment in the Departments of Civil Engineering and Mechanical Design. He also conducted a number of seminars on Seismic Quality Assurance Scheduling and Manpower Requirements and Mechanical and Electrical Equipment Pipe and Duct Design of Industrial Facilities. Dr. Stevenson was a Principal and managed one of three consulting offices for Engineering Decision Analysis Corp., Palo Alto, California. He was active in marketing and providing consulting services in the area of extreme load, seismic, tornado, high energy systems rupture, and component failure analysis.

CONSULTANT
1973 - 1974

Westinghouse Nuclear Energy Systems,
Pittsburgh, Pennsylvania.

As a Consulting Engineer for Westinghouse Nuclear Energy Systems, Dr. Stevenson acted as an advisor to the Technical Director on the Executive Vice-President for Nuclear Power Staff. He performed evaluations of balance of plant requirements associated with nuclear power plant design and constructed and represented Westinghouse on a number of Industry Committees associated with nuclear power.

CONSULTANT
1972 - 1973

Westinghouse Water Reactor Divisions,
Pittsburgh, Pennsylvania.

As an Advisory Engineer for the Westinghouse Standard Plant Project, Dr. Stevenson acted as a consultant to the Manager of the Westinghouse Standard Plant Project. In this capacity he had responsibility for determining interface requirements with site-related design parameters and set envelope requirements for the standard plant design. He was responsible for nuclear island PSAR text developments and AEC licensing requirements associated with the standard plant layout development.

ADJUNCT PROFESSOR
AND PRESIDENT
1970 - 1972

University of Pittsburgh and NSSA Inc.,
Pittsburgh, Pennsylvania.

As a member of the Civil Engineering Faculty of the University of Pittsburgh, Dr. Stevenson was particularly active in the areas of structural dynamic response to earthquake, tornado, missile and fluid jet effects as well as reliability and risk analysis and optimum design of structural systems. Dr. Stevenson was responsible for the development of a graduate study program for the study of structural design and analysis for the extreme load environment.

Dr. Stevenson founded and served as President and Managing Director of Nuclear Structural Systems Associates, Inc. During this period, the firm served as consultants to the nuclear power industry, particularly in the areas of structural and mechanical design and licensing of nuclear plant facilities. Dr. Stevenson was active in developing Standard Plant design concepts and also conducted engineering design seminars for the nuclear industry throughout the U.S., Europe and Japan for over 500 representatives of over 150 companies.

MANAGER STRUCTURAL
SYSTEM ENGINEERING
1968 - 1970

Westinghouse PWR Systems Division,
Pittsburgh, Pennsylvania.

Dr. Stevenson had overall responsibility within Westinghouse for the development and approval of structural design criteria and layout used in the design of the six nuclear power stations for which Westinghouse had prime design and construction responsibility for product line management of design and development of support structures for major nuclear components.

LEAD ENGINEER
1966 - 1968

Westinghouse PWR Systems Division,
Pittsburgh, Pennsylvania.

As Lead Engineer, Dr. Stevenson was responsible for liaison with the various architect-engineer-constructor firms which performed the detailed structural design and construction of turnkey plants, and as such he was responsible for design review and approval. Dr. Stevenson was active in representing Westinghouse structural design policy before the Atomic Energy Commission and Advisory Committee on Reactor Safeguards.

GRADUATE STUDENT
1963 - 1966

Case Institute of Technology, Cleveland, Ohio.

Work toward a Ph.D. in Structures with emphasis on computer applications and risk analysis applied to structural design.

RESEARCH ENGINEER
1962 - 1963

I.I.T. Research Institute, Chicago, Illinois.

Responsibilities included integrated radiation, structural and operational analysis and minimum cost design of nuclear blast resistant underground structures.

ASSISTANT PROFESSOR
1957 - 1962

Virginia Military Institute, Lexington, Virginia.

Courses in structural design of concrete and steel structures were taught to Civil Engineering undergraduates.

John Hopkins University, Baltimore, Maryland
(Part-Time) Research Assistant.

Responsibilities included report editing and research in the location, type quantity and packaging of low level solid atomic wastes.

FIELD ENGINEER
1956 - 1957

McDowell Construction Co., Cleveland, Ohio

Field Engineer responsible for Technical Supervision and engineering field modifications to construction of a Sintering Plant for U.S. Steel Corp. Youngstown Works.

Dr. Stevenson has been particularly active in the review and evaluation of design adequacy of structures and equipment in nuclear power plants and other industrial facilities. Particular projects where he personally performed such evaluations include the following:

Nuclear Power Plants:

Indian Point Units 2 & 3
H.B. Robinson
R.E. Ginna
Point Beach
Dresden 2
Monticello
D. C. Cook
Palisades
Oyster Creek
Millstone
South Texas Project
Fessenheim - France
Cordoba - Argentina
Mihama - Japan
Conn. Yankee
Maine Yankee
Midland

Other Industrial Facilities:

Tokamac Fusion Test Facility
Purex Facility Hanford
Rocky Flats Processing Facility
Centrifuge Plant
Granger Soda Ash Plant
LMFBR
Hercules Polypropylene Plant
Shuichang Steel Complex
Touss Oil Fired Power Station
Hanford Coal Fired Power Station
Addy Ferro Silicate Plant
Killen Coal Fired Power Station
LNG Storage Facilities - U.S.

EDUCATION:

B.S. - Civil Engineering -
Virginia Military Institute, 1954

AEC Institute on Nuclear Engineering -
Purdue University, Summer 1960

M.S. - Civil Engineering -
Case Institute of Technology, 1962

Ph.D. - Civil Engineering -
Case Institute of Technology, 1968

PROFESSIONAL:

1. Member: American Society of Civil Engineers
Chairman: Executive Committee Technical Council Codes
And Standards
Chairman: Nuclear Standards Committee
Member: Structural Division Committee on Nuclear
Safety
Member: Structural Division Committee on Nuclear
Structures and Materials
2. Member: American Concrete Institute
Member: Joint ACI-ASME Subgroup on Design of
Concrete Components in Nuclear Service, ASME
BPVC-Section III-Div. 2, Corresponding
Consultant ACI 349 Safety Class Concrete
Structures
3. Member: American Society of Mechanical Engineers
Member: Subgroup on Design of ASME BPVC-Section
III-Div. 1 Nuclear Components
Member: Subcommittee on Qualification of Mechanical
Components in Nuclear Service
4. Member: Nuclear Standards Management Board of ANSI
representing ASCE
5. Member: U.S. Representative International Standards
Committee SC 85/3/7 on Seismic Criteria for
Nuclear Plants
6. Member: U.S. Representative International Atomic
Energy Agency Working Group on the
Development of Seismic Design Standards
7. Vice Chairman: ANS-2, American Nuclear Society Committee on
Site Evaluation
Member: NUPPSCO, American Nuclear Society Committee
on Nuclear Power Plant Codes and Standards
8. Member: AISC, American Institute of Steel
Construction Committee on Specifications for
Structural Steel in Safety Class Nuclear
Structures
9. Member: Earthquake Engineering Research Institute
10. Register Professional Engineer: Virginia, Pennsylvania,
and Ohio
11. Winner: Moiseiff Award - ASCE, 1971

PUBLICATIONS:

1. Stevenson, J.D., and Haga, P.G., "Pressurized Water Reactor Containment Structures Design Experience," Journal of the Power Division, ASCE, Vol. 96, No. PO 1, Proc. Paper 7037, January 1970.
2. Moses, F., and Stevenson, J.D. "Reliability Based Structural Design," Journal of the Structural Division, ASCE, Vol. 96, No. ST 2, Proc. Paper 7072, February 1970.
3. Stevenson, J.D., and Moses, F. "Reliability Analysis of Frame Structures," Journal of the Structural Division, ASCE, Vol. 96, No. ST 11, Proc. Paper 7692, November 1970.
4. Stevenson, J.D., "Criteria and Design of Pressurized Water Reactor Coolant System Support Structures - State-of-the-Art," First International Conference on Structural Mechanics in Reactor Technology, Berlin, Germany, September 1971.
5. Stevenson, J.D., and Abrams, J.I., (Editors) "Proceedings of Symposium on Structural Design of Nuclear Power Plant Facilities," University of Pittsburgh, 1972.
6. Stevenson, J.D., "Seismic Design of Small Diameter Pipe and Tubing for Nuclear Power Plants," Proc. 5th World Conference on Earthquake Engineering, Rome, June 1973.
7. Stevenson, J.D., "Containment Structures for Pressurized Water Reactor Systems: Past, Present, and Future State-of-the Art," Proc. 2nd International Conference on Structural Mechanics in Reactor Technology, North Holland Publishing Company, 1973.
8. Stevenson, J.D. (Editor), "Proceedings of Symposium on Structural Design of Nuclear Power Plant Facilities," ASCE Speciality Conference, Chicago, December 1973.
9. Stevenson, J.D. and LaPay, W.S. "Amplification Factors to be Used in Simplified Seismic Dynamic Analysis of Piping Systems," Proc. Pressure Vessel and Piping Conference, ASME, June 1974.
10. Stevenson, J.D. (Editor), "Proceedings of Second ASCE Speciality Conference on Structural Design of Nuclear Power Plant Facilities," New Orleans, December 1975.
11. Stevenson, J.D., "Rational Determination of Operational Basis Earthquake and its Impact on Overall Safety and Cost of Nuclear Facilities," Nuclear Engineering and Design, Vol. 135, North Holland Publishing Company, 1975.
12. Stevenson, J.D. "Survey of Extreme Load Design Regulatory Agency Licensing Requirements for Nuclear Power Plants," Nuclear Engineering and Design, Vol. 36, North Holland Publishing Company, 1976.

13. Stevenson, J.D., "External Hazards in Reliability and Risk Assessment of Nuclear Power Plants," Proceeding 2nd International Conference on Structural Safety and Reliability, Munich, Sept. 1977.
14. Stevenson, J.D., "Preliminary Design of a Containment to Withstand Core Melt for a 1300 MWe LWR System," Nuclear Engineering and Design, Vol. 48, North Holland Publishing Company, June 1978.
15. Stevenson, J.D., "The Economic Effect of Increased Seismic Load on Nuclear Power Plant Design and Construction Costs," Nuclear Engineering and Design, Vol. 48, North Holland Publishing Company, June 1978.
16. Stevenson, J.D., "Research Needs Associated with Seismic Load on Nuclear Power Plants," Nuclear Engineering and Design, Vol. 50, North Holland Publishing Co., October 1978.
17. Stevenson, J.D. (Editor), "International Seminar on Probabilistic and Extreme Load Design of Nuclear Plant Facilities," Presented August 22-24, 1977 by SMIRT 4 and ASCE, March 1979.
18. Stevenson, J.D., "Standards - Status and Development in the Nuclear Industry," Proceedings of ASCE Speciality Conference on Design of Nuclear Plant Facilities, Boston, April 1979.
19. Stevenson, J.D., "Probabilistic Analysis of Nuclear Containment Structures to Resist Seismic Loads," Proceedings of ASCE Speciality Conference on Design of Nuclear Plant Facilities, Boston, April 1979.
20. Bergman, L.A. and Stevenson, J.D., "The Effects of Support Stiffness Upon the Response of Piping Systems," Presented at ASME National Congress on Pressure Vessels and Piping, June 1979.
21. Gorman, M. and Stevenson, J.D., "Probability of Failure of Piping Designed to Seismically Induced Emergency and Faulted Condition Limits," to be Presented 5th SMIRT Conference, Berlin, Germany, August 1979.
22. Stevenson, J.D. Chairman, Editing Board, Structural Analysis and Design of Nuclear Plant Facilities, ASCE Manuals and Reports on Engineering Practice - No. 58, American Society of Civil Engineers, August 1980.
23. Stevenson, J.D., "Structural Damping Values as a Function of Dynamic Response Stress and Deformation Levels," Nuclear Engineering and Design, Vol. 60 No. 2, September 1980.
24. Stevenson, J.D., "Nuclear Standards Applicable to the Civil-Structural Design of Nuclear Power Plants," Proceedings of Speciality Conference on Experience with the Implementation of Construction Practices, Codes Standards, and Regulations in Construction of Power Generating Facilities, Pennsylvania State University, September 1981.

25. Stevenson, J.D. and Thomas, F.A., "Selected Review of Foreign Licensing Practices for Nuclear Power Plants," NUREG/CR-2664, U.S. Nuclear Regulatory Commission, April 1982.
26. Stevenson, J.D. and Thomas, F.A., "Selected Review of Regulatory Standards and Licensing Issues for Nuclear Power Plants," NUREG/CR-3020, U.S. Nuclear Regulatory Commission, November 1982.
27. Stevenson, J.D. and Thomas, F.A., "Selected Review of Foreign Safety Research for Nuclear Power Plants," NUREG/CR-3040, U.S. Nuclear Regulatory Commission, November 1982.
28. Stevenson, J.D., "Use of the Delphi Approach in Seismic Qualification of Existing Electrical and Mechanical Equipment and Distribution Systems in Industrial Facilities," Proceedings of the 6th Japan Earthquake Engineering Symposium - 1982, Tokyo, Japan, December 1982.
29. Stevenson, J.D. and Thomas, F.A., "Selected Review and Evaluation of U.S. Safety Research Vis-a-Vis Foreign Safety Research for Nuclear Power Plants," NUREG/CR-3212, U.S. Nuclear Regulatory Commission, March 1983.
30. Stevenson, J.D., "Seismic Design of Nuclear Plant Facilities at Low Seismicity Sites," Lawrence Livermore Laboratories Sponsored Conference on Seismic Design of Industrial Facilities, San Francisco, May 1983.
31. Hall, W.J., Kennedy, R.P. and Stevenson, J.D., "Nuclear Power Plant Seismic Design - A Review of Selected Topics," Paper K 14/1 Presented at the 7th International Conference on Structural Mechanics in Reactor Technology, Chicago, Ill., August 1983. (Submitted for Publication in Nuclear Engineering and Design)
32. Stevenson, J.D., "Designing for Extreme Loads - The Impact on Cost and Schedule", Nuclear Engineering International, July 1984
33. Stevenson, J.D., "A Review of Procedures Available to Seismically Requalify Operating Nuclear Plant Structures, Equipment and Distribution Systems", Paper K 936 To be Presented at 8th SMIRT, August 1985
34. Stevenson, J.D. "A Summary of Snubber Failure Experience in Nuclear Power Plant Facilities", Paper F1 935, To be Presented at 8th SMIRT, August, 1985
35. Stevenson, J.D., "Rational Seismic Design of Nuclear Power Plant Piping at Low and Moderate Seismicity Sites", Paper K937, To Be Presented at 8th SMIRT, August 1985

APPENDIX D

PERRY SPECIFIC
RESPONSE SPECTRA PLOTS

FLOOR RESPONSE SPECTRA DESIGN VERSUS RECORDED

TABLE OF CONTENTS

<u>Instrument Number</u>	<u>Location</u>	<u>Direction</u>	<u>OBE/SSE</u>	<u>Damping Percentage</u>	<u>Figure</u>
D51-R180 and D51-R190	Auxiliary Building Foundation Mat	N-S	SSE	2	D-1
D51-R180 and D51-R190	Auxiliary Building Foundation Mat	E-W	SSE	2	D-2
D51-R190	Auxiliary Building Foundation Mat	VERT	SSE	2	D-3
D51-N101 and D51-R160	Reactor Building Foundation Mat	N-S	SSE	2	D-4
D51-N101 and D51-R160	Reactor Building Foundation Mat	E-W	SSE	2	D-5
D51-N101 and D51-R160	Reactor Building Foundation Mat	VERT	SSE	2	D-6

<u>Instrument Number</u>	<u>Location</u>	<u>Direction</u>	<u>OBE/SSE</u>	<u>Damping Percentage</u>	<u>Figure</u>
D51-R170	Inside Drywell Reactor Building Platform-630'	N-S	SSE	2	D-7
D51-R170	Inside Drywell Reactor Building Platform-630'	E-W	SSE	2	D-8
D51-R170	Inside Drywell Reactor Building Platform-630'	VERT	SSE	2	D-9
D51-N111	Reactor Building Containment Vessel-686'	N-S	SSE	2	D-10
D51-N111	Reactor Building Containment Vessel-686'	E-W	SSE	2	D-11
D51-N111	Reactor Building Containment Vessel-686'	VERT	SSE	2	D-12

PNPP UNIT NO.1
 AUXILIARY BUILDING
 RESPONSE SPECTRA (SSE)
 N/S DIRECTION
 ELEVATION 568'-4"




FIGURE D-1

PNPP UNIT NO.1
 AUXILIARY BUILDING
 RESPONSE SPECTRA (SSE)
 E/W DIRECTION
 ELEVATION 568'-4"





FIGURE D-2

PNPP UNIT NO. 1
 AUXILIARY BUILDING
 RESPONSE SPECTRA (SSE)
 VERTICAL
 ELEVATION 568'-4"



NOTE: D51-R190

(Vertical) Out of phase
 Due to calibration

FIGURE D-3

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ




FIGURE D-4



11A8001

PERRY NUCLEAR POWER PLANT

COMP WEST

SHASS/N 165-17

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ





FIGURE D-5



DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ





FIGURE D-6

PNPP UNIT NO. 1
 REACTOR BUILDING
 RESPONSE SPECTRA (SS)
 NORTH-SOUTH
 EL 431' PLATFORM



NOTE: DESIGN SPECTRA IS
 ENVELOPE OF DRYMULLI 11
 AND ALIQUOTED RALLI 11
 SPECTRA

FIGURE D-7

PNPP UNIT NO. 1
 REACTOR BUILDING
 RESPONSE SPECTRA (E-W)
 EAST-WEST
 EL 631' PLATFORM




FIGURE 2-8

RAPP UNIT NO. 1
 REACTOR BUILDING
 RESPONSE SPECTRA (SSS)
 VERTICAL
 PL 631' PLATFORM




FIGURE D-9

ML 5.0 EARTHQUAKE JANUARY 31, 1966


11A8002

PERRY NUCLEAR POWER PLANT

COMP SOUTH

SHAS/N 165-2

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ



ML 5.0 EARTHQUAKE JANUARY 31, 1986

11A8002

PERRY NUCLEAR POWER PLANT

COMP WEST

SMA3S/N 16S-21

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ





FIGURE D-11



ML 5.0 EARTHQUAKE JANUARY 31, 1966

11A8002

PERRY NUCLEAR POWER PLANT

COMP UP

SMA35/N 165-2V

DAMPING VALUES ARE 2 PERCENT OF CRITICAL
FREQUENCY - HZ





FIGURE D-12



APPENDIX E

RESULTS OF SPECIFIC INSPECTIONS

EVALUATION OF WALKDOWN ITEMS
PLANT SETTLEMENT READINGS
SEISMIC CLEARANCE WALKDOWN
COOLING TOWER WALKDOWN
REVIEW OF ENERGIZED CIRCUITS

MEMORANDUM

☐ I no longer wish to receive this material.

TO F. R. Stead

ROOM E270

FROM

K. R. Pech

DATE 11-Feb-86

PHONE

5246

ROOM W220

SUBJECT

Evaluation of Walkdown
Items

As a result of the plant walkdowns conducted the evening of 1/31/86, Perry Plant Technical Department prepared a list of the observations of the inspection teams. These observations were given the title Earthquake Inspection Team Items or EITI's. The list of EITI's was then forwarded to Engineering for determination of whether the item was a result of the earthquake and whether or not the item needed to be repaired. The assessment of the need for repair and the documentation of that decision whether on a Non-Conformance Report or a Work Request was done in accordance with POP-1501.

The evaluation of all 473 items was completed this afternoon, and the final summary of determinations is presented in the attached table. Each item was placed in one of three categories with respect to its relationship to the earthquake.

1. Caused by the earthquake
2. Indeterminate
3. Not caused by the earthquake

As shown in the summary, 375 items were determined not to be caused by the earthquake, 96 to be indeterminate, and 2 to be caused by the earthquake. With respect to the latter two items, one was the trip of the main transformer, noted in the walkdown of electrical bus L10. The second was a non-safety heater exchanger drain valve that was found dripping water during the walkdown and was reported to be closed and not dripping prior to the earthquake.

In addition each item was categorized as to its final disposition using the procedures contained in POP-1501. Through this process, 330 items were determined to require no repair, 119 to be repaired via a Work Request and 24 items were determined to require dispositioning via a Non-Conformance Report. Of the 24 NR's, 20 are anticipated to be use-as-is and the remainder constitute cosmetic repairs to concrete and drywall walls.

Page 2
Evaluation of Walkdown Items

By copy of this memo, the Engineering evaluation of the EITI's is being issued to the Perry Plant Technical Department for preparation of appropriate documentation and inclusion in their Condition Report.

KRP:jg

EITI LIST EVALUATION SUMMARY

13:15 2/11/86

DISCIPLINE	TOTAL	C	I	N	NR	WR	NA
ELECTRICAL	35	1	22	12	0	25	10
I & C	18	0	10	8	0	15	3
MECHANICAL	83	1	29	53	2	53	28
PIPING	23	0	18	5	2	10	11
STRUCTURAL	314	0	17	297	20	16	278
TOTAL	473	2	96	375	24	119	330

C = Caused by Earthquake
I = Indeterminate
N = Not Caused by Earthquake
N/A = No Action Required

MEMORANDUM

☐ I no longer wish to
receive this material.

K. Pech

ROOM W210

FROM M.R. Kritzer

DATE 2-6-86

PHONE 6460

ROOM TQ6

SUBJECT PLANT SETTLEMENT READINGS

Per our discussion, plant settlement readings were taken on February 5, 1986 (Attached). No significant difference in the building elevation before and after the seismic event was observed. The maximum change occurred in the Reactor Building #1. This change was only a minus (-)0.006 of a foot or 1/16 of an inch. The maximum growth was +0.003 of a foot or 1/32 of an inch, which occurred in the Radwaste Building.

A review of settlement readings taken last February 15, 1985, revealed that the Reactor Building #1 was at the same elevation as it is today.

The minute changes in plant elevation can be expected due to structural growth as a result of weather.

cc: E. Riley
J. Eppich
C. Angstadt
T. Keaveney
S. Dodeja
302.MRK

KRETT & ASSOC. REG. ENGINEERS & SURVEYORS

PERRY NUCLEAR POWER PLANT
PERRY, OHIO

SKETCH OF: PLANT SETTLEMENTS

DATE: (M)

SCALE:

FIELD BOOK:

see Table

DISC	DATE	1/18/86	2/5/86				
1-F		625.406	625.402				
2-D		624.339	624.333				
3-D		624.363	624.359				
4-F		626.391	626.386				
5-D		624.540	624.538				
6-D		622.105	622.108				
7-C		621.300	621.298				
SP-8		624.458	624.459				
SP-9		624.924	624.921				
SP-10		624.450	624.453				
SP-11		624.491	624.487				

Initial

CONDENSER
Total 4 1/2 in. water 1/2 in.

DISC	DATE						
1-F							
2-D							
3-D							
4-F							
5-D							
6-D							
7-C							
SP-8							
SP-9							
SP-10							
SP-11							

GARRETT & ASSOC. REG. ENGINEERS & SURVEYORS PERRY NUCLEAR POWER PLANT PERRY, OHIO.

PLANT SETTLEMENTS

SCALE:

FIELD BOOK:

[illegible]

SKETCH OF: PLANT SETTLEMENTS

DATE: (M)

SCALE:

PT.	SEPT 27, 83	OCT 27, 1983	NOV. 22, 83	DEC 21, 83	JAN. 5, 1984	FEB 10, 84	MAR. 24, 84	
1-F	625.396	625.395	625.402	625.407	625.405	625.406	625.401	
2-D	624.332	624.329	624.335	624.338	624.334	BLOCKED	624.331	
3-D	624.372	624.365	624.365	624.363	624.361	624.362	624.361	
4-F	626.389	626.384	626.388	626.388	626.385	626.391	626.381	
5-D	624.543	624.517	624.547	624.549	624.550	624.546	624.542	
6-D	622.101	622.098	622.096	622.101	622.093	622.101	622.099	
7-C	621.295	621.295	621.294	621.303	621.295	621.290	621.281	
PT.	APRIL 28, 84	MAY 29, 84	JUNE 20, 1984	JULY 10, 84	AUG. 21, 84	SEPT 14, 84	OCT 10, 84	NOV. 23, 84
1-F	625.397	625.401	625.400	625.402	625.405	625.403	625.406	625.402
2-D	624.335	624.334	624.337	624.336	624.338	624.341	624.339	624.333
3-D	624.365	624.365	624.369	624.368	624.369	624.370	624.366	624.363
4-F	626.385	626.383	626.394	626.390	626.389	626.393	626.391	626.391
5-D	624.537	624.544	624.545	624.546	624.552	624.553	624.550	624.535
6-D	622.102	622.102	622.105	622.108	622.106	622.106	622.103	622.094
7-C	621.287	621.291	621.300	621.298	621.298	621.301	621.300	621.297
PT.	11/10/85	2/15/85	3/22/85	4/12/85	5/15/85	6/25/85	7/9/85	
1-F	625.405	625.403	625.406	625.401	625.403	625.396	625.398	625.398
2-D	624.335	624.334	624.333	624.341	624.343	624.336	624.333	624.330
3-D	624.362	624.358	624.361	624.359	624.360	624.360	624.357	624.364
4-F	626.387	626.384	626.389	626.380	626.382	626.384	626.381	626.384
5-D	624.546	624.542	624.544	624.547	624.543	624.542	624.546	624.543
6-D	622.096	622.094	622.105	622.103	622.106	622.100	622.101	622.108
7-C	621.297	621.296	621.292	621.297	621.297	621.297	621.306	621.299

MARK NO	DEC 18, 78	JAN 2, 79	FEB 2, 79	MARCH 20, 1979	FOUNDATION SET	PERY TOWER	PLANT	SEPT 10, 79	OCT 5, 79	DEC 15, 1981
1-E	625.286 NEW DISC	625.270 →	625.270 →	625.270	COVERED	625.270	625.270	625.270	625.270	625.270
1-F	624.351	624.336	624.331	624.336	COVERED	624.336	624.336	624.336	624.336	624.336
2-D	624.423	624.403	624.388	624.401	COVERED	624.401	624.401	624.401	624.401	624.401
3-D	596.003 REMOVED	604.626	604.626	604.626	COVERED	604.626	604.626	604.626	604.626	604.626
4-C	603.615	603.607	603.607	603.607	COVERED	603.607	603.607	603.607	603.607	603.607
4-D	619.025	619.025	619.025	619.025	COVERED	619.025	619.025	619.025	619.025	619.025
4-E	622.086	622.086	622.086	622.086	COVERED	622.086	622.086	622.086	622.086	622.086
4-F	616.733	616.733	616.733	616.733	COVERED	616.733	616.733	616.733	616.733	616.733
5-E	620.462	620.462	620.462	620.462	COVERED	620.462	620.462	620.462	620.462	620.462
5-F	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
6-A	624.548	624.548	624.548	624.548	COVERED	624.548	624.548	624.548	624.548	624.548
6-B	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
6-C	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
6-D	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
6-E	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
6-F	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-A	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-B	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-C	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-D	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-E	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-F	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091
7-G	622.091	622.091	622.091	622.091	COVERED	622.091	622.091	622.091	622.091	622.091

DATE	1-F	2-D	3-D	4-F	5-D	6-D	7-C	DATE	1-F	2-D	3-D	4-F	5-D	6-D	7-C	DATE	1-F	2-D	3-D	4-F	5-D	6-D	7-C	DATE	1-F	2-D	3-D	4-F	5-D	6-D	7-C	
PER 9 1981	625.395	624.332	624.325	624.366	624.390	624.347	622.096	621.312	JAN 5 1982	625.393	624.328	624.365	624.385	624.545	622.092	621.281	NOV 30 82	625.395	624.334	624.350	624.387	624.559	622.097	621.288	NOV 30 82	625.395	624.334	624.350	624.387	624.559	622.097	621.288
9/15/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	9/15/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	9/15/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	9/15/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
9/22/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	9/22/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	9/22/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	9/22/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
9/29/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	9/29/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	9/29/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	9/29/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
10/6/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	10/6/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	10/6/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	10/6/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
10/13/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	10/13/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	10/13/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	10/13/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
10/20/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	10/20/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	10/20/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	10/20/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
10/27/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	10/27/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	10/27/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	10/27/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
11/3/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	11/3/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	11/3/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	11/3/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
11/10/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	11/10/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	11/10/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	11/10/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
11/17/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	11/17/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	11/17/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	11/17/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
11/24/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	11/24/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	11/24/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	11/24/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
11/31/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	11/31/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	11/31/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	11/31/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
12/7/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	12/7/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	12/7/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	12/7/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
12/14/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	12/14/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	12/14/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	12/14/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
12/21/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	12/21/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	12/21/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	12/21/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
12/28/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	12/28/81	625.394	624.322	624.352	624.384	624.540	622.096	621.276	12/28/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311	12/28/81	625.395	624.325	624.365	624.388	624.541	622.099	621.311
1/4/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	1/4/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	1/4/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	1/4/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
1/11/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	1/11/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	1/11/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	1/11/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
1/18/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	1/18/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	1/18/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	1/18/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
1/25/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	1/25/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	1/25/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	1/25/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
2/1/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	2/1/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	2/1/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	2/1/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
2/8/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	2/8/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	2/8/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	2/8/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
2/15/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	2/15/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	2/15/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	2/15/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
2/22/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	2/22/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	2/22/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	2/22/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
2/29/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	2/29/82	625.394	624.322	624.352	624.384	624.540	622.096	621.276	2/29/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	2/29/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311
3/6/82	625.395	624.325	624.365	624.388	624.541	622.099	621.311	621.310	3/6/82	625.394	624.322	624.352	6																			

PERRY NUCLEAR DWEI PLANT
FOUNDATION SETTLEMENT CHART CONTINUED BY GARRETT
SHEET NO. 3-C

MARK NO.	FEB. 16, 78	MARCH 13, 78	APRIL 7, 1978 WILL BE CLEAR NEXT MONTH	MAY 9, 1978 NOT CLEAR	MAY 25, 78	JUNE 15, 78	JULY 20, 78 NOT CLEAR	JULY 31, 78	AUG. 17, 78	AUG 28, 78	SEPT 21, 78	
1-B	COVERED	COVERED	COVERED	COVERED	575.625	COVERED	COVERED	COVERED	COVERED			
2-D	624.362	NOT ABLE TO READ	624.360	624.355	624.360	624.360	624.348	624.358	624.357		624.360	624.35
3-B	599.046	599.041	599.040	579.041	579.052	RAISED 5' TO 604.046	604.047	604.033	604.041			
4-B	596.940	596.938	596.939	576.940	COVERED	COVERED	COVERED	COVERED	COVERED			
5	COVERED	COVERED	COVERED	COVERED	COVERED	COVERED	COVERED	"	"			
6-B	602.188	602.170	602.191	602.195	602.188	602.118	602.200	602.197	602.210			
7	NOT ABLE TO READ	NOT ABLE TO READ	NOT ABLE TO READ	NOT ABLE TO READ	COVERED UNDER LUG	COVERED	COVERED	COVERED	COVERED			
5-A		NEW POINT SET ON WALL	591.524	COVERED	COVERED	COVERED	COVERED	"	"			
2-C		600.144			600.146	COVERED	COVERED	"	"			
1-C			NEW	593.517	593.514	593.517	COVERED	"	"			
B				578.805	578.794	COVERED	COVERED	"	"			
1-D					NEW 614.287	COVERED	COVERED	"	"		614.291	614.295
3-C					623.514	623.507	623.506	"	"			
4-C					576.018	COVERED	COVERED	595.997	595.999			596.007
7-A		MARK ON WALL	13' W. OF SE COR.		NEW 563.143	562.122	562.112	COVERED				563.180
3-D					PERMANENT DISC. SET	REACTOR N92 (270°)			INITIAL 624.425	624.422	624.411	
4-D											NEW →	604.625
1-E											NEW →	625.292
6-C											NEW →	619.028
5-C											NEW →	603.600

COVERED OR CANNOT READ

COVERED END IN COVER IN NOV.



FOUNDATION SETTLEMENT CHART CONTINUED BY GARRETT & ASSOCIATES INCORPORATED
SHEET NO 2

NR	JULY 8, 77	JULY 15, 77	JULY 22, 77	JULY 29	8/5/77	AUG 11, 77	AUG 18, 77	SEPT 14, 77	SEPT 26, 77	OCT 12, 77
1A	582.090	582.093	582.092	582.095	582.095	582.087	582.092	COVERED	575.619	595.622
1B	585.619	595.617	585.622	585.625	595.627	595.615	595.624	595.620	595.620	595.622
2	572.484	572.983	COVERED	COVERED	COVERED	572.779	572.984	COVERED	COVERED	COVERED
2A	576.984	578.333	578.335	COVERED	COVERED	COVERED	COVERED	COVERED	COVERED	COVERED
2B	582.980	COVERED	589.981	589.984	589.984	589.978	589.978	589.981	COVERED	COVERED
3	572.982	572.982	572.984	572.987	COVERED	572.986	572.986	572.987	COVERED	COVERED
	585.493	585.493	585.494	585.493	585.493	585.493	585.493	585.495	585.494	585.498
A	572.904	572.904	572.906	572.905	572.904	572.904	572.906	572.903	572.898	572.891
3A	587.475	587.476	587.478	587.481	587.496	587.477	587.478	587.474	587.477	587.474
2-C	NEW MARK					590.267	590.267	590.266	590.262	590.270
2-D = BRADO DISC								600.146	600.144	600.144
								624.361	624.360	624.365
1-B	NOV 17, 77	DEC 2, 77	DEC 19, 77	DEC 29, 77	JAN 25, 78	FEB 16, 78				
2-D	COVERED	COVERED	COVERED	COVERED	COVERED					
3-A	624.358	624.358	624.361	624.362	624.358	624.362				
4-A	COVERED	COVERED	COVERED	COVERED	COVERED					
5	COVERED	COVERED	COVERED	COVERED	COVERED					
6-A	587.470		589.490	589.490	589.496	587.496				
7-B	596.943		596.942	596.940	596.940	596.940				
2-C	600.142		600.142	600.155	600.155	600.155				
1-B	602.183		602.180	602.194	602.194	602.188				
3-B	599.045		599.048	599.044	599.047	599.046				

NOTES. 1) USE IN CONJUNCTION WITH GILBERT PRINT RDB 121416.
2) ELEVATIONS ARE IN FEET AND DECIMALS.
3) REF. GARRETT BOOK NO 28
SHEET NO 1

MARK N°	JAN 18, 77	JAN 24, 77	FEB 1, 77	FEB 2, 77	FEB 13, 77	FEB 21, 77	FEB 26, 77	MARCH 8, 77	MARCH 17, 77	MARCH 25, 77	MARCH 30, 77	APRIL 6, 77
1	568.334	568.346	568.339	568.333	568.334	568.334	568.333	568.333	568.333	568.318	568.333	568.333
2	572.992	572.993	572.990	572.991	572.990	572.988	572.987	572.988	572.988	572.987	572.986	572.982
3	572.998	572.996	572.996	572.996	572.995	572.994	572.992	572.993	572.989	572.986	572.984	572.987
4								SET MARCH 14, 77	568.295	568.291	568.287	568.287
5												
6					SET FEB 18, 77	573.934	573.931	573.936	573.938	573.931	573.930	573.937

MARK N°	APRIL 11, 77	APRIL 20, 77	APRIL 22, 77	MAY 6, 77	MAY 12, 77	MAY 19, 77	MAY 27, 77	JUNE 3, 1977	JUNE 10, 77	JUNE 15, 77	JUNE 22, 77	JULY 1, 77
1	568.333	568.330	568.331	568.330	568.334	1-A-582.092 568.335	1-A-582.097	582.094	582.095	582.094	582.091	1-A-582.097
2	572.986	572.986	572.986	572.986	2-A-572.986 572.986	2-A-572.986 572.984	2-A-572.985	572.989	572.980	572.980	572.980	1-A-572.984
3	572.987	572.984	572.987	572.988	572.990	572.986	572.985	572.989	572.988	572.990	572.989	1-A-572.986
4	568.287	568.284	568.285	568.289	568.288	568.287	568.291	568.290	568.286	4A-585.493	585.493	4A-585.493
5		SET MAY 27, 77	572.905	572.905	572.906	572.905	572.904	572.897	572.896	572.905	572.895	572.904
6	573.938	573.936	573.939	573.935	573.935	573.932	573.932	6-A-587.478 587.478	587.478	587.475	587.473	587.479



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

MEMORANDUM

G-2
REV. 1-82

☐ I no longer wish to
receive this material.

TO K. Pech

ROOM W210

FROM *M. C. Kritzer* J. Messenger *com*

DATE 2-5-86

PHONE 6460

ROOM TQ6

SUBJECT SCV WALKDOWN AFTER SEISMIC EVENT

Ref. documents NIR's C-23642,

C-23661 thru and including C-23666

also C-23677

Due to the seismic event which occurred on 1/31/86, the Seismic Clearance Group has conducted a walkdown of all open "Repair" dispositioned Seismic Clearance Violations.

The scope of the walkdown was to evaluate if any dimensional changes from the original SCV, and to note any structural or system damage in these particular areas that could have been attributed to the earthquake.

The results of the evaluation, as shown on the above referenced inspection reports, indicates that there were no dimensional changes from the document SCV's. There was also no plant damage associated with the unrepaired SCV's.

It should be noted that 7 of the ^{29 MRK files} ~~28~~ SCV's have at minimum, partial work complete.

Any questions, please feel free to contact us.

attachments: 8

cc: E. Riley
S. Dodeja
302.MRK
302. JWM
J. Eppich
C. Angstadt

PNPP No. 5978

<u>N/A</u>	<u>N/A</u>	<u>C-23642</u>
CONTRACTOR	SPEC. NO.	INSPECTION REPORT NUMBER
<u>SCV INSPECTION WALKDOWN AFTER</u>		<u>SEE Below N/A</u>
SYSTEM/COMPONENT/ACTIVITY	<u>SEISMIC EVENT</u>	M.P.L. NUMBER
<u>AX-1 599' EL</u>		<u>21 2-3-86</u>
LOCATION	INSP. TYPE	DATE

DUE TO THE SEISMIC EVENT WHICH OCCURED ON 1-31-86 THE FOLLOWING OPEN SCVs HAVE BEEN FIELD VERIFIED TO DETERMINE IF ANY DIMENSIONAL CHANGES HAVE OCCURED.

SCV 6215
 SCV 6292
 SCV 6550

CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): N/A
 MEASURING/INSPECTION TOOLS I.D.: MISC INSPECTION TOOLS

REMARKS NO DIMENSIONAL CHANGES DIRECTLY ATTRIBUTED TO THE SEISMIC EVENT WERE FOUND AND NO DAMAGE ENCOUNTERED.

cc: S. DODERA - E180 Phil Hagel 2-3-86
 _____ INSPECTOR DATE
 _____ John W. Messinger 2-4-86
 _____ REVIEWED - LEAD INSPECTOR DATE

PNPP No. 5978

CONTRACTOR	SPEC. NO.	INSPECTION REPORT NUMBER
WALKDOWN of open S.C.U.s after the seismic event of 1-31-86	N/A	C-23661
SYSTEM/COMPONENT/ACTIVITY	H.P.L. NUMBER	
Control Complex, 679'-6" Floor elev.	21	2-3-86
LOCATION	INSP. TYPE	DATE

Due to the seismic event which occurred on 1-31-86, the following open S.C.U.s have been field verified to determine if any dimensional changes had occurred: S.C.U. # 5978

S.C.U. # 6060 rev. ①

S.C.U. # 6061 rev. ①

NO dimensional changes or damage, directly attributed to the seismic event, were found.

CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): N/A.

MEASURING/INSPECTION TOOLS I.D.: Miscellaneous Inspection Tools.

REMARKS N/A

cc: S. Dodega E-180

FLManner
INSPECTOR

2-4-86
DATE

REVIEWED - LEAD INSPECTOR

DATE

PNPP No. 3978

<p>CONTRACTOR <u>N/A</u></p> <p>SYSTEM/COMPONENT/ACTIVITY <u>Walkdown of open S.C.U.s after the seismic event of 1-31-86</u></p> <p>LOCATION <u>Intermediate Bldg., All elevations</u></p>	<p>SPEC. NO. <u>N/A</u></p>	<p>INSPECTION REPORT NUMBER <u>C-23662</u></p> <p>M.P.L. NUMBER <u>N/A</u></p> <p>INSP. TYPE <u>21</u></p> <p>DATE <u>2-3-86</u></p>								
<p>Due to the seismic event which occurred on 1-31-86, the following open S.C.U.s have been field verified to determine if any dimensional changes had occurred:</p> <table style="margin-left: 40px;"> <tr> <td>S.C.U. # 6500</td> <td rowspan="2">} 620'-6" Floor elev.</td> </tr> <tr> <td>S.C.U. # 6536</td> </tr> <tr> <td>S.C.U. # 6639</td> <td rowspan="2">} 599' Floor elev.</td> </tr> <tr> <td>S.C.U. # 6688</td> </tr> <tr> <td>S.C.U. # 5968</td> <td>574'-^{10"} Floor elev.</td> </tr> </table>			S.C.U. # 6500	} 620'-6" Floor elev.	S.C.U. # 6536	S.C.U. # 6639	} 599' Floor elev.	S.C.U. # 6688	S.C.U. # 5968	574'- ^{10"} Floor elev.
S.C.U. # 6500	} 620'-6" Floor elev.									
S.C.U. # 6536										
S.C.U. # 6639	} 599' Floor elev.									
S.C.U. # 6688										
S.C.U. # 5968	574'- ^{10"} Floor elev.									
<p>NO dimensional changes or damage, directly attributed to the seismic event, were found.</p>										
<p>CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): <u>N/A</u></p> <p>MEASURING/INSPECTION TOOLS I.D.: <u>Miscellaneous Inspection Tools</u></p>										
<p>REMARKS <u>S.C.U. # 5968 has 3 of the 4 repair supports added.</u></p>										
<p>cc: <u>S. Dodeja E-180</u> <u>H. Manno</u> <u>2-4-86</u></p> <p style="text-align: center;">INSPECTOR DATE</p> <p style="text-align: center;"><u>James Messinger</u> <u>2-4-86</u></p> <p style="text-align: center;">REVIEWED - LEAD INSPECTOR DATE</p>										



PNPP No. 5978

CONTRACTOR Walden of open S.C.U.s after the seismic event of 1-31-86		SPEC. NO. N/A		INSPECTION REPORT NUMBER C-23663	
SYSTEM/COMPONENT/ACTIVITY Auxiliary Bldg #1, All elevations		H.P.L. NUMBER 21		N/A	
LOCATION		INSP. TYPE		DATE 2-3-86	
<p>Due to the seismic event which occurred on 1-31-86, the following open S.C.U.s have been field verified to determine if any dimensional changes had occurred: S.C.U.# 6563 - 620'-6" Floor elev.</p> <p>S.C.U.# 6136 } 599' Floor elev.</p> <p>S.C.U.# 6262 }</p>					
<p>NO dimensional changes or damage, directly attributed to the seismic event, were found.</p>					
<p>CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): N/A.</p>					
<p>MEASURING/INSPECTION TOOLS I.D.: Miscellaneous Inspection Tools.</p>					
<p>REMARKS S.C.U.# 6262 has repair work in-progress.</p>					
cc: S. Dadeja E-180		H. Manno		2-4-86	
		INSPECTOR		DATE	
		J. Messenger		2-4-86	
		REVIEWED - LEAD INSPECTOR		DATE	

PNPP No. 5978

N/A	N/A	C-23664																
CONTRACTOR	SPEC. NO.	INSPECTION REPORT NUMBER																
WALKDOWN OF OPEN SCV'S AFTER SEISMIC EVENT OF 1/31/86		N/A																
SYSTEM/COMPONENT/ACTIVITY	M.P.L. NUMBER																	
IB @ FLOOR EL. 599' & 682'	21	2-3-86																
LOCATION	INSP. TYPE	DATE																
<p>DUE TO THE SEISMIC EVENT WHICH OCCURED ON 1-31-86 THE FOLLOWING OPEN SCV'S HAVE BEEN FIELD VERIFIED TO DETERMINE IF ANY DIMENSIONAL CHANGES HAD OCCURED :</p> <table style="margin-left: 40px; border: none;"> <tr> <td style="text-align: center;">SCV #</td> <td style="text-align: center;">596 *</td> <td rowspan="4" style="font-size: 3em; vertical-align: middle;">}</td> <td rowspan="4" style="vertical-align: middle;">EL. 599'</td> </tr> <tr> <td style="text-align: center;">↓</td> <td style="text-align: center;">597 *</td> </tr> <tr> <td></td> <td style="text-align: center;">5518 *</td> </tr> <tr> <td></td> <td style="text-align: center;">6633 *</td> </tr> <tr> <td></td> <td style="text-align: center;">4727 *</td> <td rowspan="2" style="font-size: 3em; vertical-align: middle;">}</td> <td rowspan="2" style="vertical-align: middle;">EL. 682'</td> </tr> <tr> <td></td> <td style="text-align: center;">4729 *</td> </tr> </table>			SCV #	596 *	}	EL. 599'	↓	597 *		5518 *		6633 *		4727 *	}	EL. 682'		4729 *
SCV #	596 *	}	EL. 599'															
↓	597 *																	
	5518 *																	
	6633 *																	
	4727 *	}	EL. 682'															
	4729 *																	
<p>NO DIMENSIONAL CHANGES OR DAMAGE, DIRECTLY ATTRIBUTED TO THE SEISMIC EVENT, WERE FOUND.</p>																		
<p>CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): N/A</p>																		
<p>MEASURING/INSPECTION TOOLS I.D.: MISC. INSPECTION TOOLS</p>																		
<p>REMARKS * ALL REPAIR WORK WAS COMPLETE AT TIME OF WALKDOWN.</p>																		
<p>cc: S. DODEJA : E-180</p>																		
<p><i>H.P. Shari, Jr.</i></p> <p>INSPECTOR</p>		<p>2/4/86</p> <p>DATE</p>																
<p><i>John W. Messinger</i></p> <p>REVIEWED - LEAD INSPECTOR</p>		<p>2-4-86</p> <p>DATE</p>																

PNPP No. 5978

N/A	N/A	C-23665
CONTRACTOR	SPEC. NO.	INSPECTION REPORT NUMBER
WALKDOWN OF OPEN SCV'S AFTER SEISMIC EVENT OF 1/31/86		N/A
SYSTEM/COMPONENT/ACTIVITY	H.P.L. NUMBER	
AX-1 @ FLOOR EL. 599'	21	2-3-86
LOCATION	INSP. TYPE	DATE
<p>DUE TO THE SEISMIC EVENT WHICH OCCURED ON 1-31-86 THE FOLLOWING OPEN SCV'S HAVE BEEN FIELD VERIFIED TO DETERMINE IF ANY DIMENSIONAL CHANGES HAD OCCURED: SCV * 6833 (NR * CQCN-0126)</p> <p>NO DIMENSIONAL CHANGES OR DAMAGE, DIRECTLY ATTRIBUTED TO THE SEISMIC EVENT, WERE FOUND.</p> <p>CORRECTIVE ACTION DOCUMENTATION - (D.R.'s): N/A</p> <p>MEASURING/INSPECTION TOOLS I.D.: MISC. INSPECTION TOOLS</p> <p>REMARKS N/A</p>		
cc: S DODEJA : E-180	 INSPECTOR	2/4/86 DATE
	 REVIEWED - LEAD INSPECTOR	2-4-86 DATE

PNPP No: 5978

N/A	N/A	C-23666
CONTRACTOR	SPEC. NO.	INSPECTION REPORT NUMBER
WALKDOWN OF OPEN SCV'S AFTER SEISMIC EVENT OF 1/31/86		N/A
SYSTEM/COMPONENT/ACTIVITY	M.P.L. NUMBER	
CC @ FLOOR EL. 679'	21	2-4-86
LOCATION	INSP. TYPE	DATE
<p>DUE TO THE SEISMIC EVENT WHICH OCCURED ON 1-31-86 THE FOLLOWING OPEN SCV'S HAVE BEEN FIELD VERIFIED TO DETERMINE IF ANY DIMENSIONAL CHANGES HAD OCCURED : SCV # 6014</p> <p>NO DIMENSIONAL CHANGES OR DAMAGE, DIRECTLY ATTRIBUTED TO THE SEISMIC EVENT, WERE FOUND.</p>		
CORRECTIVE ACTION DOCUMENTATION - (D.R.'s):		N/A
MEASURING/INSPECTION TOOLS I.D.:		MISC. INSPECTION TOOLS
REMARKS N/A		
cc: S. DODEJA : E-180	B.P. Shaner, Jr.	2/4/86
	INSPECTOR	DATE
	John W. Messinger	2-4-86
	REVIEWED - LEAD INSPECTOR	DATE

PNPP No. 5978

N/A		N/A	C-23677
CONTRACTOR		SPEC. NO.	INSPECTION REPORT NUMBER
WALKDOWN OF OPEN SCV'S AFTER SEISMIC EVENT OF 1/31/86			N/A
SYSTEM/COMPONENT/ACTIVITY		M.P.L. NUMBER	
CC & IB @ VARIOUS ELEVS.		21	2-5-86
LOCATION	INSP. TYPE		DATE
<p>THE ATTACHED MEMO DATED 2-5-86 CONCERNING THE WALKDOWN PERFORMED BY ENGINEERING TO EVALUATE CERTAIN OPEN REPAIR DISPOSITIONED SCV'S (EIR'S) FOR POTENTIAL DIMENSIONAL CHANGES CAUSED BY THE EARTHQUAKE OCCURING ON 1-31-86.</p> <p>RESULTS INDICATED - NO NOTICABLE CHANGES.</p>			
CORRECTIVE ACTION DOCUMENTATION - (D.R.'s):		N/A	
MEASURING/INSPECTION TOOLS I.D.:		N/A	
REMARKS	N/A		
cc: S DODEJA - E180			
		G.P. Shaney, Jr. INSPECTOR	2/5/86 DATE
		John W. Messinger REVIEWED - LEAD INSPECTOR	2/5/86 DATE

memorandum



Gilbert/Commonwealth

February 5, 1986

to J. W. Messenger/M. R. Kritzer
from H. Dharja/S. C. Dodeja
subject Walkdown of Open EIR's for
Potential Earthquake Effect

The following EIR's were walked down to see if the previously reported condition had changed due to the earthquake event.

<u>EIR #</u>	<u>SCV #</u>
CC-620-3	6712
CC-679-7	6720
IB-654-4	6797
CC-574-1	6708
CC-679-17	6730
CC-679-13	6726
Cc-679-1	6714

The conclusion of the walkdown was that there had been no noticeable change due to the earthquake.

H. Dharja

S. C. Dodeja

CC: C. R. Angststadt
K. R. Pech

THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

G-2
REV. 1-82

MEMORANDUM "E"SO/-2712

☐ I no longer wish to receive this material.

E. M. Mead	ROOM E280	FROM	I. B. Babiak	DATE	February 3, 1986
T. M. Jameson	E260	PHONE	6699	ROOM E260	
T. P. Keaveney	E230	SUBJECT	N71, Circulating Water System Walkdown to Assess the Intensity of the January 31, 1986 Earthquake		

On February 1, 1986, a system walkdown was performed on the N71 Circulating Water System and the following was observed:

No yard flooding was observed above the buried 12' diameter FRP on both supply to the condensers, and return line to cooling tower. No water was present in the Oil Storage Tank Dyke or beneath the temporary (trailers) lunch room building or in the Sodium Hypochlorite Storage Tank Dyke.

A walkdown was also performed inside the Turbine Building basement to assess if any damage was present to the system, and none was observed.

A walkdown of the cooling tower basin wall was performed and two vertical (minor) leaks were observed. One located on the south cooling tower forebay flume wall and other near the cooling tower raiser manifold (entry into the basin).

The severity of the vertical seam leak in the forebay flume wall exhibits approximately 1 to 2 gpm flow rate out into the yard and with approximately (less than) 1 gpm flow rate through the second vertical seam leak.

The Civil/Structural element is to advise on the severity of the leak with a repair solution.

clm

cc: R. A. Newkirk - E280
E. B. Ortalan - E260
N71 System File - E280
PO/DC - R290

MEMORANDUM

"C"SO-2773

☐ I no longer wish to receive this material.S-2
REV. 1-62

K. R. Pech

ROOM W220 FROM
PHONE
SUBJECTE. C. Christiansen DATE February 7, 1986
5467 ROOM W245
Review of Energized Circuits
During 1/31/85 Seismic Event

Per your request, NCES - Electrical has reviewed the circuits that were energized during the January 31, 1986 seismic event. The intent of the review was to determine the number of active electrical components in the energized circuits. Active components were categorized in seven subgroups for this study. The groups were motors, power sources, switches, instruments, relays, transformers, and miscellaneous. The later category included lamps, fuses, resistors, diodes, etc. Attachment I lists major suppliers of equipment in each subgroup. Passive devices such as cables, lugs, terminal boards, conduits, and trays were not considered in this study.

A listing of systems that were operating during the seismic event was obtained from Perry Plant Operating Department. This list is included as Attachment II of this memorandum. Upon an engineering review of this list it was determined that it was incomplete. Power sources, communication, security, and computer systems were added by Engineering. Attachment II also reflects these additions.

The total number of active components in the energized circuits was 47,460. Attachment III contains Electrical Device Lists used by each engineer in their review of each energized system. A breakdown of the total active components by subgroup follows:

Motors	775
Power Sources	6493
Switches	6962
Instruments	4721
Relays	6968
Transformers	1885
Miscellaneous	19656

Total Devices 47,460

ECC/mcw

Attachment I

Vendors

Motors

General Electric

Siemens-Allis

Westinghouse

Reliance

U.S. Electrical

Transformers

Westinghouse

General Electric

Brown Boveri

Relays

General Electric

Westinghouse

Brown Boveri

Cutler-Hammer

Agastat

Potter Braumfield

Switchgear Breakers

Brown Boveri

General Electric

Cutler-Hammer

Switches

Allen Bradley

General Electric

States

Electroswitch

Batteries

C & D

Exide

Contractors

Cutler-Hammer

Allen Bradley

General Electric

Attachment I

MOV Operators

Limitorque

Rotorque

EIM

ITT

Chargers/Inverters

C & D

Power Conversion

Topaz

CYBREX

Fuse Disconnects

Cutler-Hammer

General Electric

Cutler-Hammer

Limit Switches

Limitorque

Instrument Switches

Magnetrol

Rosemount

ITT Barton

Mercoïd

Meriam

MSW Instruments

Meters

General Electric

Brown Boveri

Westinghouse

Weksler

Instruments (T/C, RTD's)

Weed

Recorders

Leeds & Northrup

Transmitters

Rosemount

Gould

Foxboro

Magnetrol

Weed

Molded Case Breakers

General Electric

Westinghouse

Cutler-Hammer

Gould (Brown Boveri)

Attachment II

Systems Energized During Seismic Event of January 31, 1986

System Supplied of PPOD

System	Description
C11	Control Rod Drive
C41	Standby Liquid Control
C71	Reactor Protection System
D17	Plant Radiation Monitors
E12	Residual Heat Removal
E21	Low Pressure Core Spray
E22	High Pressure Core Spay
F42	Fuel Transfer Equipment
G33	Reactor Water Cleanup
G41	Fuel Pool Cooling and Cleanup
M11	Containment Vessel Cooling
M13	Drywell Cooling
M15	Annulus Exhaust Gas Treatment
M21	Controlled Access HVAC
M23	MCC, Switchgear, & Misc. Area HVAC
M24	Battery Room Exhaust
M25	Control Room HVAC
M26	Control Room Emergency Recirculation
M27	Computer Room HVAC
M32	ESW Pumphouse Ventilation
M35	Turbine Building Cooling & Ventilation
M36	Off-Gas Building Exhaust
M40	Fuel Handling Building Ventilation
M41	Heater Bay Ventilation
M43	Diesel Building Ventilation
M45	Circulating Water Pump House Ventilation
N21	Condensate
N23	Condensate Filtration
N24	Condensate Demineralizers
N32	Turbine Control (EHC)
N71	Circulating Water
P11	Condensate Transfer and Storage
P20	Water Treatment
P21	Two Bed Demineralizer
P22	Mixed Bed Demineralizer
P41	Service Water
P42	Emergency Closed Cooling
P43	Nuclear Closed Cooling
P44	Turbine Building Closed Cooling
P45	Emergency Service Water
P47	Control Complex Chill Water
P49	ESW Screen Wash
P52	Instrument Air
P54	Fire Protection
P55	Building Heating
P61	Auxiliary Steam
P62	Auxiliary Boiler Fuel Oil
P72	Plant Underdrain

Attachment II

Systems Added by Engineering

System	Description
C91	Process Computer
C95	Emergency Response Information System
P51	Service Air
P56	Security
R11	Station Transformers
R14	110 VAC Vital Inverters
R15	Technical Support Center UPS
R22	Metalclad Switchgear
R23	480 V Load Centers
R25	Distribution Panels - 120, 208 & 480 volts
R36	Heat Tracing & Anti Freeze Protection
R41	Instrumentation
R42	D.C. System
R43	Standby Diesel Generator (SDG)
R44	SDG Starting Air
R45	SDG Fuel Oil
R46	SDG Jacket Water Coolant
R47	SDG Lube Oil
R51	Intra Plant Communications
R52	Maintenance & Calibration
R53	Exclusion Area Paging System
R57	Radio & In-Plant Antenna System
R61	Main Control Room Annunciator
R71	Lighting
S11	Power Transformers