

NO. PMA 84-06

DRF No. E22-00070

PLANT MATERIALS APPLICATION ENGINEERING

TITLE: FAILURE ANALYSIS, F010 AND F011 VALVES, CLINTON PROJECT

Date: December 3, 1985

Prepared By:

G. R. Hansen  
G. R. Hansen

Approved By:

J. Jacobson 12/3/85  
J. Jacobson, Manager  
Equipment Design Engineering

Approved By:

E. D. Sayre for E. D. Sayre  
E. D. Sayre, Manager  
Plant Materials Application

NOTICE

Neither the General Electric Company nor any of the contributors to this document makes any warranty or representation (express or implied) with respect to the accuracy, completeness, or usefulness of the information contained in this document, or that the use of such information may not infringe privately owned rights; nor do they assume any responsibility for liability or damage of any kind which may result from the use of any of the information contained in this document.

DISTRIBUTION

GRH43

C.T. Nieh	G.M. Gordon
H. Ehsan	B.M. Gordon
J. Jacobson	F.F. Smith
E.D. Sayre	J.T. Cochran
E. Kiss	R.T. Reich

8603140317 860312  
PDR ADOCK 05000461  
E PDR

Failure Analysis Report of F010 and F011  
Valves From The Clinton Reactor

1. INTRODUCTION

1.1 Discovery of Cracked Valve Stem and Loose Parts in HPCS System

While the Clinton Site was operating the High Pressure Core Spray (HPCS) pump in system test (October-November, 1985) with suction from the condensate storage tank a noise was heard in the return line to the condensate storage tank. The noise sounded as if loose parts were rolling down the return line followed by a "thunk". Subsequently the flow rate dropped substantially. Disassembly of F010 and F011 valves revealed the following damage in the valves:

F010 Valve

- a. Broken valve stem
- b. Disc and stub of stem were jammed at an angle into the seat and guides resulting in the valve being locked open
- c. Extruded back seat on stem. The valve stem at the back seat location was mushroomed indicating the stem had been pulled into the backseat with the motor
- d. Bent Stem Clamp The stem clamp was bent.

F011 Valve

- a. The disc and disc nut were unscrewed leaving the stem free to travel out of the disc. One retainer ring segment was found downstream of the valve just beyond the flow restricting orifice. The other ring segment was found in the condensate storage tank.
- b. The stem was heavily galled and the back seat in the bonnet was badly cracked as a result of pulling the stem through the back seat with the motor operator.

## 1.2 Objectives of This Failure Analysis Report are to Document Findings and to Make Recommendations

The objectives of this report are to document the findings regarding F010 and F011 valves at the Clinton site, subsequent failure analysis work, to determine cause of failure and to make recommendations for further action.

## 1.3 Cause of Failure

### 1.3.1 E22F010 Valve Stem Failure

Metallographic studies showed that the crack started intergranularly (probably Intergranular Stress Corrosion Cracking) (IGSCC) and progressed to approximately 30° around the circumference to approximately  $\frac{1}{2}$  inch deep. The balance of the cross section shows a brittle cleavage failure indicting the shaft broke suddenly with a single application of overload. It is entirely possible that the intergranular cracking (IGC) started due to high tensile stresses resulting from backseating the stem with the motor actuator coupled with the residual stresses from heat treatment and high hardness of the stem (RC 40-42 in the failure area). When the IGC had grown to sufficient size, a loading of the stem from the motor operator could have been sufficient to cause a single brittle fracture to occur in the balance of the stem cross section.

### 1.3.2 E22F010 Valve Disc Jammed Open

Sometime after fracture of the stem the disc became cocked in the valve such that one edge was striking the seat and the opposite side was wedged in the guides, Figure 8. This effectively jammed the valve open with no possibility of closing. The broken top part of the stem was striking the lower part of the stem such that it wedged the disc tighter in the open position with each stroke. The cocking of the disc was most likely due either to use of the valve for throttling or from closing the valve while the pump was operating. It is not likely that the stem could have cocked with no flow in the valve.

1.3.3 E22F010 Valve Stem Back Seat Mushrooming and E22F011 Back Seat Damage

The damage to both valves in the back seat area was caused by pulling the stems into the back seat with the motor operator probably at full thrust. In the case of F010 valve the shaft seat was extruded; while in the case of the F011 valve the back seat was cracked and expanded and the shaft badly galled. It appears that the limit switches were inoperative and the motor operators pulled until the torque switch turned the motor off. This type of damage is typical where the limit switch is not set properly or where it is bypassed.

1.3.4 E22F011 Valve Disc and Nut Separation

The disc nut unscrewed from the disc and completely separated the stem and disc due to vibration.

It is not clear when the loosening of the nut occurred. The fact that there was no fretting on the shaft and no damage to the threads would suggest that the loosening and separation occurred very closely together. On the other hand the loosening of the stem clamp and other problems with the valve would suggest that the nut loosening took place over a longer period of time.

1.4 Recommended Corrective Action

1.4.1 Damaged Items

All damaged items should be replaced or repaired. The stems should be replaced with properly heat treated Type 410 stainless steel. General Electric's current standards require hardness of Type 410 not to exceed RC28 (See paragraph 2.4 for basis). 17-4 Ph stems may also be used providing the aging temperature is 1075°F or greater (material temperature).

1.4.2 Packing

As a product improvement GE recommends use of valve packing with high purity packing meeting the limits of GE SIL No 399 to control the pitting that can occur with high chloride packing material. A copy of SIL No 399 is attached.



#### 1.4.3 Back Seating of Valve

Measures should be taken to assure that the valve stems do not remain backseated for long periods of time. This traps water in the back seat pocket which acts as a crevice and corrodes the shaft. The corrosion and pitting can be a nucleus for IGC as a nucleation site for IGSCC.

#### 1.4.4 Proper Setting of Limit Switch

The cause for switches being inoperative should be determined. Corrections in both equipment and procedure to assure proper operation in the future should be made. The need for adjustment of position may be indicative of problems in the valve such as a broken stem or unscrewed disc nut.

#### 1.4.5 Use of Valves for Throttling

These valves are not designed for intensive throttling service. They can be used to throttle for a limited amount of flow (down to 30% flow) for short periods of time. If it is desired that these valves be used for more throttling than this other alternatives can be developed.

#### 1.4.6 Other Valves

##### Hardness

The hardness of other valve stems in the HPCS system was determined near the mid length of the stem as shown in Table 1. It is obvious that the F023 valve stem is too hard and it should either be retempered or replaced. For the other valves it is not as obvious since F010 shows RC35 at mid-length but RC40 at the hard end and RC30-31 at the soft end. For these other valves it is recommended that hardness be taken at midstem and at the top end. These two measurements will allow an estimate of the hardness at the lower end of the valve stem.

Other Valves should be disassembled and inspected unless there is evidence to show that the stems were not pulled into the back seat with the motor. The stems should be inspected visually and with liquid penetrant to assure freedom from damage. In addition for valves with stems harder than RC28 and which were backseated for an extended period of time (in excess of 500 hours), the stems should be inspected visually and with liquid penetrant to assure freedom from cracking. Alternately the stems may be examined with ultrasonics using a procedure qualified to detect such intergranular cracking.

Table 1  
Hardness of Valve Stems in HPCS System

<u>Valve</u>	<u>Hardness in Mid Stem Location (above the stem clamp)</u>
F001	RC 29.4
F004	RC 32.7
F010	RC 35.0
F011	RC 37.3
F012	RC 32.4
F015	RC 28.6
F023	RC 40.5

## 2.0 DISCUSSION

### 2.1 Contributors to Damage

The main contributors to the damage found in the valves (see Section 3.0) are:

- (1) Limit switch problems resulting in overtravel of stem into back seat.
- (2) Vibrations (a) due to original positioning of the D004 orifice too close to the F011 valve and (b) due to extensive use of the valves for throttling.
- (3) High stem hardness with resultant high residual stress caused by tempering at too low a temperature. (RC41 in region of failure)

### 2.2 Why Vibration Loosened Parts in F011 Valve and Not F010 Valve

For the F011 valve vibration caused the separation of stem, disc and stem nut and allowed the split rings to cascade down the pipe. Only the F011 valve had evidence of loosening of parts due to vibration. There are two possible explanations explain this as follows:

- a) It is possible that the vibration resulting from the D004 orifice being too close caused the loosening of the stem nut on F011 and later throttling served to complete the separation. The F010 valve would not have experienced as severe a vibration from the orifice.
- b) It is possible that the F010 valve stem fractured before it had experienced significant throttling and before the vibration from the D004 orifice.

If item (a) is correct it appears that the valves can withstand the amount of throttling use applied at Clinton. However if item (b) is correct and if such an amount of throttling is applied again of the disc nut and disc may again become disassembled. Further review of the test records or discussions with test personnel may shed more light on this. In any event throttling should be minimized.

### 2.3 Cracks and Fractures in Stem, F010 Valve

The main fracture severing the valve stem was initiated intergranularly (IG) and then rapidly propagated by brittle fracture, Figure 12 through 14. Longitudinal cracks were also found emanating from the main fracture which were intergranular. There were also other cracks in the stem located at the bottom radius of the groove housing the split ring retainer, Figure 16 and 17. There are several notable attributes of this stem fracture and these cracks as follows:

- a. It is unusual to see intergranular cracks this deep with so little apparent time exposed to water considering the low temperatures involved (ambient temperature)
- b. There is corrosion on the stem just above the back seat suggesting that the valve was backseated with water present for a long period of time. F011 valve does not show this corrosion.
- c. The valve stem shows a considerable gradient in hardness from one end to another. In the area of the fracture the hardness is RC40-41 while at the other end it is RC30-31. This suggests a tempering temperature of less than 950°F at the lower end and approximately 1050°F at the upper end.
- d. The fracture exclusive of the IGC area is almost entirely a brittle cleavage failure. This would correspond to a notched tensile fracture of material heat treated in the 800-1000°F range, Figure 2.1

Considering the above items it appears likely that the IGC in the stem fracture occurred or at least initiated during the period of time when the stem was back seated. Other failures similar to this have started in the packing area and this break would be located in the packing only if the stem were back seated. The stem was probably under significant load from the motor operator which if not actually causing the crack to initiate would have accelerated, the initiation and the propagation of the cracks. The cracks in the retainer ring area show that cracking can start in Type 410 at this hardness level in an area which is creviced and which has a high stress concentration but has essentially no applied stress.

#### 2.4 Basis for Current GE Hardness Limits on Type 410 S.S.

There are numerous accounts of failure of Type 410 and 416 stainless steels in the literature with hardness of 38-42 RC. On two occasions GE has found cracking of Type 410 stainless steel in the 31-32RC hardness range. There were several factors in common with these failures as follows:

<u>Component</u>	<u>Operating Temperature</u>	<u>Material</u>	<u>Metallographic Stress</u>		<u>Other</u>
			<u>Structure</u>	<u>Level</u>	
(a) $\frac{1}{2}$ inch Cap Screws	Estimated at 125-150°F	416(?)	Banded with heavy sulf- ide inclus- ions	Probably high since it was a fastener	
(b) 1 3/8" Dia studs	~200°F	410	Banded with heavy sulfide inclusions	~46,000 psi	IGSC started in area of intermit- tent wet- ting and drying

As a precautionary measure GE has since imposed a limit of RC28 for newly purchased Type 410SS stainless steel.



### 3.0 DESCRIPTION OF DAMAGED VALVE PARTS

#### 3.1 The following damage was found for the F010 Valve:

- a. Broken Valve Stem - As shown in Figures 1 and 2, the stem was broken above the back seat, 1 7/8 to 2 1/2 inches beyond the newly formed back seat area on the shaft.
- b. Stem Upset in Area of Backseat. The upset was caused by the motor pulling the stem into the backseat, (Figure 3 and 4).
- c. Gouged Area on Stem - See Figure 5. The heavily abraded area on both the upper and lower part of the stem, were due to the bottom shaft (attached to disc) becoming cocked in the valve and the upper shaft scraping against the lower shaft when the valve was closed. See Figures 5, 6, and 8.
- d. Bent Stem Clamp The stem clamp fastens to the stem by a key and set screw and its purpose is to prevent stem rotation. The stem clamp was bent approximately 1 1/2 inches as shown in Figure 6. In addition the clamp had been shifted on the shaft approximately 1/2 inch. The clamp was bent when the shaft broke and cocked in the valve thus allowing the shaft to over travel approximately two inches. Figure 8 illustrates this travel.
- e. Back Seat in Bonnet Deformed - While the back seat did not appear to be deformed from visual inspection, it was later found that the angle of the seat was not correct. This deformation most likely occurred when the motor pulled the stem into the back seat.
- f. Disc and Stub Shaft Wedged in Valve at an Angle, Figure 7 and 8. The lower part of the stem and the disc were found tightly wedged in the valve at an angle. The disc had a circular shaped indentation on the lower edge where the disc was pressed into the stellite seat and the upper flanged part of the disc had two

impressions matching the guide ribs in the valve body. The disc was not seriously damaged but maintenance was unable to separate the nut from the disc and subsequently cut the lower part of the disc from the upper part (to avoid cutting the stellite and then saw cut the upper part of the disc to allow disassembly of the disc from the stem.

- g. Seat Chipped - There was some deformation of the seat due to the pressure of the disc on the seat at a local area also resulting in a small chip of stellite flaking away. The chip was not in the seating plane and lapping should correct the small amount of deformation.

3.2 The following damage was found for the F011 Valve:

- a. The disc nut was unscrewed from the disc and separated from the stem. There was no apparent damage to the threads or shaft.
- b. The split ring retainer was separated from the assembly. One-half of the retainer was found just downstream of the D004 pressure reducing orifice and the other half was found in the condensate storage tank. The orifice was heavily marked by impact and bowed concave toward the downstream side.
- c. The stem was badly galled due to the motor pulling the stem into the backseat, Figure 9.
- d. The back seat in bonnet is badly cracked as a result of the stem being pulled into the back seat, Figure 10.

#### 4.0 METALLURGICAL EVALUATIONS

The following metallurgical evaluations were performed on the F010 valve stem to aid in determining cause of failure:

- 4.1 Chemistry A chemical analysis yielded the following results and confirmed that the stem material was 410 stainless steel meeting requirements of ASTM A276.

<u>Element</u>	<u>Weight %</u>
Carbon	0.09
Chrome	12.35
Manganese	0.40
Silicon	0.35
Phosphorus	0.017
Sulfur	0.007
Nickel	0.37

#### 4.2 Hardness

Hardness traverses are shown in Figure 11. There was a hardness gradient along the length of the shaft from RC41 at the disc side of the shaft to RC30 at the threaded end of the shaft. There was also a gradient through the thickness of the shaft and this varied from RC38.5 at the surface to a maximum of RC42.7 near the center.

#### 4.3 Metallography

A metallographic section was taken near the failure point and it was found to be typical for Type 410 stainless steel microstructure.

#### 4.4 SEM Examination of Fracture Face

Both fracture faces from the lower stub piece as well as the upper shaft were examined by scanning electron microscope (SEM). Both pieces were quite badly hammered but the upper one was in better shape and the origin of the crack was identified, Figure 12. A band of intergranular fracture was found approximately 30° in length and 1/2 inch in depth in from the circumference of the shaft. The balance of the fracture was cleavage indicating a rapid fracture, Figures 13 and 14.

#### 4.5 Longitudinal Cracks Transverse to Main Fracture

There were several short longitudinal cracks extending from the main fracture the longest of which was approximately 3/8 inch long. This crack was broken open and examined by SEM and it was found to be completely intergranular. Figure 15 shows metallography of one of the longitudinal cracks.

#### 4.6 PT Examination of Shaft Reveals Additional Cracking

When penetrant examination was performed on the shaft several other cracks were found in the groove where the stem retainer rings are located. The largest of these cracks were broken open and a crack approximately 1 1/2 inches long with a maximum depth of 1/8 inch was found. See figure 16. Examinations of the fracture surface with SEM showed it to be intergranular. This section was fractured at room temperature and less than 1% ductile shear was identified on the fracture surface.




FIGURE 1. FO10 VALVE DISASSEMBLED. BODY IS BLANKED OFF WITH A COVER PLATE




FIGURE 2. FO10 VALVE DISASSEMBLED SHOWING  
BROKEN VALVE STEM

# Effect of Tempering Temperature on Tensile Properties

## Type 410




FIGURE 2.1 TYPICAL MECHANICAL PROPERTIES FOR TYPE 410 STAINLESS STEEL TEMPERED AT VARYING TEMPERATURES

SOURCE: Source Book on Industrial Alloy and Engineering Data, American Society for Metals, Metals Park Ohio, 1978, p229



- LUG WELDED TO FACE BY  
MAINTENANCE TO REMOVE  
SHAFT FROM VALVE

- EDGE OF FRACTURE

- RINGS OF CORROSION

- UPSET AREA ON SHAFT,  
360°, VERY UNIFORM

- FRETTING 360° AROUND,  
HEAVIEST AREA SHOWN

AREA OF GENERAL  
CORROSION




FIGURE 3. LOWER END OF BROKEN VALVE STEM (F010)



FIGURE 4. CLOSEUP VIEW OF UPSET AREA ON STEM  
(IN REGION OF THE BACK SEAT) (F010)




FIGURE 5. GOUGED AREAS IN UPPER PART OF STEM (ABOVE) AND LOWER PART OF STEM (BELOW). GOUGES CAUSED BY UPPER SHAFT MOVING AGAINST LOWER SHAFT WHEN LOWER SHAFT WAS COCKED IN VALVE. SEE ALSO FIGURE 8. (F010)





FIGURE 7. UPPER AND LOWER PARTS OF THE DISC (SAW CUT TO ASSIST IN DISASSEMBLY) SHOWING DEFORMATION WHERE THE DISC WAS PRESSED AGAINST THE GUIDE RIBS (UPPER PHOTO) AND THE SEAT (LOWER PHOTO) (F010)




FIGURE 8. VIEW SHOWING FO10 VALVE WITH CRACKED  
SHAFT AND APPROXIMATE ANGLE OF WEDGING  
FOR DISC, FO10 VALVE







FIGURE 9. BADLY CALLED AREA ON STEM OF F011 VALVE.  
CALLING DUE TO PULLING STEM INTO BACKSEAT  
IN BONNET







FIGURE 10. UPPER PHOTO SHOWS STEM PARTIALLY PULLED INTO BACK SEAT. LOWER PHOTO SHOWS CRACKED STELLITE RESULTING FROM PULLING STEM INTO BACK SEAT (FOIL VALVE)




FIGURE 11. HARDNESS MEASUREMENTS ON F010 SHAFT SHOWING HARDNESS GRADIENTS. ALL HARDNESS MEASUREMENTS TAKEN WITH EQUOTIP TESTER AND CONVERTED TO RC




FIGURE 12. MACRO PHOTO OF CRACK FACE SHOWING POINT OF ORIGIN OF INTERGRANULAR CRACKING




FIGURE 13. SEM PHOTO SHOWING CLEAVAGE FRACTURE TYPICAL OF AREA OUTSIDE IG AREA




FIGURE 14. SEM PHOTO SHOWING TYPICAL FRACTURE IN IG AREA




FIGURE 15. METALLOGRAPHY OF LONGITUDINAL CRACK COMING FROM MAIN FRACTURE. 100X, ETCHANT VILELLA'S REAGENT






FIGURE 16. LOWER PORTION OF VALVE STEM WITH SECTION  
BROKEN AWAY SHOWING IG CRACK




FIGURE 17. MACRO OF IG CRACK IN LOWER PORTION OF VALVE STEM, 3.4X



Appendix A  
DESCRIPTION OF HPCS SYSTEM

A.1.0 High Pressure Core Spray System (HPCS)

The purpose of the high pressure core spray system (Figure A-1) is to depressurize the nuclear boiler system and to provide makeup water in the event of a loss of reactor coolant. In addition, the high pressure core spray system prevents fuel cladding damage in the event the core becomes uncovered due to loss of coolant by directing water down into the area of the fuel assemblies. The makeup water is jetted as a spray over the area of the fuel assemblies from nozzles mounted in a sparger ring located inside the reactor vessel above the fuel assemblies. The high pressure core spray system is an integral part of the total design for Emergency Core Cooling (ECC) which provides for adequate core cooling and depressurization for all rates of coolant loss from the nuclear boiler.

Cooling water for the operation and testing of the high pressure core spray system comes from the condensate storage tank. Upon depletion of this supply, the system automatically transfers to the water in the containment suppression pool. Water inventory lost from the nuclear boiler system drains to the drywell and then into the suppression pool thereby providing an inexhaustible supply of cooling water allowing continued operation of the high pressure core spray system until it is manually stopped by the operator from the control room. System piping and equipment are maintained full of condensate water to avoid time delays in filling the lines and to avoid hydraulic hammer.

Operation of the system is automatically initiated from independent redundant signals indicating low reactor vessel water level or high pressure in the primary containment. The system also provides for remote-manual startup, operating, and shutdown. A testable check valve in the discharge line prevents back flow from the reactor pressure vessel when the reactor vessel pressure exceeds the high pressure core spray system pressure as can occur during initial activation of the system. A low flow bypass system is placed into operation until pump head exceeds the nuclear system pressure and permits flow into the reactor vessel.

The high pressure core spray system can be tested during normal plant operation or when the plant is shut down. During normal plant operation, pump suction is from the condensate storage tank with a full flow return line to the condensate storage tank. During plant shutdown, pump suction is from the primary containment pressure suppression pool with a full flow return line to the suppression pool. The control system provides for the automatic transfer to the service mode upon the presence of ECC demand signal.

#### A.2 E22-F010 and E22-F011 Valves

Note in Figure A-1 that the F010 and F011 valves are located in the test return line running to the condensate storage tank. These valves only operate during the test mode; otherwise they are in the closed condition.




Figure A-1 High Pressure Core Spray System

Appendix B  
DESCRIPTION OF F010 AND F011 VALVES

B1.0 Valves

The F010 and F011 valves are ten-inch 900 lb globe stop, bolted bonnet, rising stem, butt welded ends, cast carbon steel, stellite trim motor operated valves manufactured by the Anchor Darling Company, Figure B-1.

These valves are primarily designed for tight shut-off and limited throttling. All sections of the body are designed to provide absolute tightness ensuring minimum pressure drop. Their use, however, is limited to those systems where head losses are not critical as the internal flow passage creates a pressure drop across the valve. With the disc in the full open or any intermediate position, the fluid is allowed to flow through the seat area at a rate determined by the position of the disc. With the disc in the closed position, the force of the stem provides a mechanical seal between the disc and seat and effects a shut-off at the valve.

B2.0 Motor Operators

B2.1 The motor operators are Philadelphia Gear Corporation (Limitorque) SMB4 units, Figure B-3.

Each operator is provided with a high starting torque motor, reduction gear, handwheel for manual operation, a handwheel de-clutching device, a double torque switch, 4-train geared limit switches and a hammer blow device.

The handwheel on each operator is automatically declutched whenever the drive motor is energized. A lever is provided to engage the clutch when manual operation is required. A hammer-blow device is furnished to permit motor to reach full speed before load is applied. The design is such that the operator can be removed from the valve for maintenance without dismantling the valve.

## B2.2 Torque Limit Switches and Position Limit Switches

Adjustable torque switches assure power cut-off in the event motor is overloaded when valve disc or shaft movement is restricted. The switches operate in both opening and closing directions of travel and are separately adjustable for torque in either direction. See figure B-4.

Rotary geared type, 4-train limit switches are provided. Each motor operated valve actuator is provided with four mechanically independent position switch contacts that are indexed to monitor positions of valve travel during both motor and hand operations. Each switch has four electrically independent contacts.

There is a position indicator for remote indication of valve position.

## B2.3 Motor Control Circuits

- a. Valve Closure F010 and F011 valve motor control circuits, whose safety direction is close are designed such that either LS7 or TS17 will allow the valve to go fully closed. See figure B-2. Since full closure is imperative for all nuclear boiler isolation valves, TS17 is used to mechanically torque the valve tightly closed. In the event TS17 fails, LS7 will complete the closing cycle. LS7 must be set such that it opens just before TS17, thereby allowing TS17 to break the seal-in. This design feature prevents cycling of the valve in the event of torque switch relaxation. During testing, the valve motion being sealed-in through the torque switch provides valve protection from an overtorqued condition.
- b. Valve Opening For opening the valve the limit switch must be set to shut off the motor before the stem enters the back seat. The torque switch should be set to as low a setting as is commensurate with proper opening of the valve and yet provide some protection against damage to the back seat in event the limit switch malfunctions.



1. DESIGN & MANUFACTURE IN CONJUNCTION WITH ASME BOILER AND PRESSURE VESSEL CODE COMMITTEE, CLASS 2, WINTER 1973 AGREEMENT WITH CODE CASE 1637.
2. HYDROSTATIC TESTS:  
(A) SHELL TEST PRESSURE 32.00 MPa  
(B) SEAT TEST PRESSURE 18.75 MPa  
ESTIMATED VALUE WITH 21,000 PSI SEAT WARE WITH W/1000 OPERATIONS 5.20%  
MAXIMUM TORQUE VALUE RECOMMENDED FOR 3.410

QTY REQD	MANUF. DWG. NO.	INSTR.	DESCRIPTION	MATERIAL	HAFL SPEC. A101, 50, 40, 30, 20, 10
1	5107-2-5	31	BODY -	CAST STL	A216 WCB
1	5107-2-5	32	PONNET	CAST STL	A216 WCB
1	5107-2-5	33	25C (WELL FACE)	CAST STL	A216 WCB
1	5107-2-2	34	STEM (10' 8" MIN. MAX. 10')	STN. 5"	A479 F410
1	7-312-1	35	6-AND (END A)	STN. 5"	A479 F410
1	5107-2-3	36	YOLK	CAST STL	A216 WCB
2	7306-3P	37	SEAT RING (SPRUE)	ST. PIPE	A101 50
7		38	16 PACKING (LOWER)	ASBESTOS	3/4" 2" 10"
5		39	16 PACKING (UPPER)	ASBESTOS	3/4" 2" 10"
1		40	17 CAT WREN (SPRUE)	ALLOY STL	A51 4140
1		41	18 SCKET	5-5-1/2"	RENTALIC
12	5107-2-3	42	6-9 STUD (BONN)	ALLOY STL	A193 B7
12	5107-2-3	43	25 NUT (BONN)	STEEL	A194 2H
2		44	31 BOLT	ALLOY STL	A193 B7
2	5107-2-2	45	22 NUT (GLAND RLT)	STEEL	A194 2H
1	5107-2-2	46	25 STEM CLAMP	STL R	A36
1	5107-2-3	47	27 YOLK CLAMP	STL R	A36
4		48	29 STUD (YOLK CLIP)	ALLOY STL	A193 B7
8	5107-2-3	49	27 NUT (YOLK CLIP)	STEEL	A194 2H
1	30-750-2	50	GLAND FLG	STN. F2	SAFIGN 70
1		51	32 MOTOR OPERATOR	STN. F2	SAFIGN 70
1		52	25 PACKS (W/ST. OF)	STN. F2	SAFIGN 70
1	5107-2-5	53	24 BACKSTAY (NUT 2H)	ALLOY STL	A51 4140
2	5107-2-2	54	25 KEY (GAND CLIP)	STEEL	A101 50
1	5107-2-2	55	65 STEEL RING (STEM)	STEEL	A101 50
1	5107-2-2	56	64 DYC NUT	STN. 5"	A216 WCB
1		57	65 NUT	STN. 5"	A216 WCB
1	71-312-2	58	52 FLG (2H 5-5-1/2")	CAST STL	A101 50
1		59	71 LAUNCHER (2H 5-5-1/2")	STN. 5"	A216 WCB
1	5107-2-1	60	PIPE FLG	RENTALIC	A101 50

(1) CHEM. RANGE C Co A

Received by Chet  
 Date 8-7-75  
10-21-75

GENERAL ELECTRIC CO.

**ANCHOR/DARLING VALVE COMPANY**  
HAYWARD, CALIFORNIA

0200° GLOES (STOP) DB., R.S.,  
W. ENDS, CAIT CAREB. ST., STALL  
TRIM, SM3-4 MOTOR OPER

2999-3





FIGURE B-1



BLT WELD END DETAIL  
SCHED. 130 (71BW) PER IN-  
SPECTION WITH SUFFICIENT  
ELECTRIC DMS. BIC 6062  
P. 3

[illegible]





# LIMITORQUE® TYPE SMB INSTRUCTION AND MAINTENANCE MANUAL




FIGURE B-3

A PRODUCT OF LIMITORQUE CORPORATION

# SMB-00 THRU SMB-5 DOUBLE TORQUE SWITCH\*

## Procedure for Setting:

1. Torque settings must be made with switch mounted in Limitorque.
2. Make sure all electric power is off.

3. For the open direction torque switch or close direction torque switch loosen screw, pc. #35 and set pointer, pc. #7, at desired torque setting. The higher the number, the higher the torque output of the unit.

4. Tighten pc. #35.

5. Operate valve electrically to seat valve insuring tight shut-off.

6. A maximum stop setting plate is furnished on all units. Do not exceed this setting without consulting factory.

\* Available in assembled form only

PC. NO.	NO. REQ.	DESCRIPTION
1	1	TERMINAL BLOCK
2	2	CONTACT BLOCK
4	2	ARM
5	1	DIAL
6	1	ACTUATING LINK
7	1	POINTER
8	1	SHAFT
9	1	SPACER
10	2	CONTACT SUPPORT
11	1	TORQUE LIMITER
12	1	BUSHING
13	1	SW. PINION
14	1	BEARING
15	2	CONTACT FINGER
16	4	TERMINAL STUD
17	1	COMPR. SPRING
18	1	TORSION SPRING
19	1	INSULATOR
20	1	FLAT WASHER
21	1	O-RING
22	2	SCREW-ROUND HD SLOTTED $\frac{1}{4}$ -18 x $\frac{1}{2}$ LG.
23	1	ROLL-PIN $\frac{3}{32}$ DIA x $\frac{5}{8}$ LG.
24	1	LOCKWASHER- $\frac{1}{4}$
25	3	THRUST WASHER
26	2	$\frac{5}{16}$ LOCKWASHER
27	12	LOCKWASHER #10
28	1	ROLL PIN $\frac{3}{32}$ DIA x $\frac{3}{4}$ LG.
29	8	HEX NUT #10-32
30	2	HEX NUT #6-32
31	1	COTTER PIN $\frac{1}{8}$ DIA x $\frac{1}{2}$ LG.
32	1	SCREW-SOC. HD. CAP $\frac{1}{4}$ -20 x $\frac{1}{2}$ LG.
33	2	SCREW-PAN HD. SELF-TAPPING #4-40 x $\frac{1}{2}$ LG.
34	2	SCREW-HEX. SOC SET #6-32 x $\frac{5}{8}$ LG.
35	6	SCREW-MACH. RD. HD. #10-32 x $\frac{3}{8}$ LG.
36	1	SCREW-MACH. RD. HD. #5-40 x $\frac{3}{16}$ LG.
37	1	WAX AS REQUIRED
39	2	LOCKWASHER
45	1	O-RING
46	1	MOUNTING BRACKET









FIGURE B-4

NOTE: APPLY GREASE AT ASSEMBLY

Appendix C  
HISTORY OF F010 AND F011 VALVES

Following is a brief outline of the history of the F010 and F011 valves.

- 8/74 Valves were ordered from Anchor Darling, Hayward California by General Electric
- 8/77 Valves fabrication completed by Anchor Darling. Stems were heat treated by Oakland Heat Treating (Lindberg).
- 9/77 Valves shipped to Clinton Site and placed in storage
- 5/80 Valves installed at Clinton Site.

Dec 84 - Jan 85 System operated for Integrated FLush

C&IO Phase

- 4/29/85 F011 valve stem guide is found disconnected and wedged against base of bonnet. Valve fixed on 6/20/85 but breaker keeps tripping.
- 5/21/85 MUR-17593 written to fix breaker trips on F011. Cause - tripping due to residual MOV rotor/stator motion/field development. Breaker overload increased from position 4 to 5
- 6/5/85 FPR written to address F011 breaker trips
- 7/885 FPR #5489 written for all valve breakers

Preoperational Phase

- 8/23/85 Performed vibration measurement of RST line per XTP-VI-01. See attached sheets for actual data. FPR #6065 written to request relocation of orifice



8/28/85 Received engineering evaluation to relocate orifice temporarily.  
CWR 16712 performed the relocation.

9/13/85 Performed RST to RST flow test per PTP-HP-01.  
Run time: 2 hours 18 min  
Flow Regime: minimum flow (315 gpm) to 5600 gpm  
Engineer noted apparent piping/valve resonance at = 3300 gpm

9/19/85 FECN's 22,103 and 60,336 were issued which approved the relocation  
of the orifice. CWR 17403 submitted to manufacture new orifice.

10/11/85 Found F010 stem clamp collar bound on the stem and bent. CR  
1-85-10-040 written, noted that similar problem occurred on F011  
4/29/85 (MWR B9425). Addressing possible damage to stem, NCMR  
1-1918 says "damage due to improperly staked set screw. This  
generic condition to be addressed by 10CFR 21-85-02/21-85-05.

11/02/85 During testing, it is reported that a loud noise like something  
moving down the inside of the pipe and coming to a resounding stop.


11/03/85 Reported that I.P.Co. found 1/2 retainer ring downstream of orifice  
D004 and disassemble F010 and F011.

11/04/85 Received JK575 requesting help

11/05/85 FDDR LHI-5466 R/O Issued

11/06/85 George Hanson at site

11/08/85 FDDR LHI-5466 R/1 issued



November, 1983  
File Tab A

SIL No. 399  
Category 3

# NONMETALLIC MATERIALS FOR NUCLEAR STEAM SUPPLY SYSTEMS

The following recommendations are for nonmetallic materials such as gaskets, valve stem packing and lubricants which are used in nuclear steam supply systems (NSSS) and which will remain in service as part of the operating system exposed to NSSS coolant. This information is the result of continual development, changing over the past several years to reflect latest available technology and operating experience. Therefore, all of these criteria might not have been applied in their present form to any one material in the past, but it would be prudent to follow these recommendations in the future.

## DISCUSSION

Selection of nonmetallic materials such as gaskets, valve stem packing and lubricants is an important area of plant maintenance. The following recommendations may help in extending the life of metallic materials associated with them. General Electric does not endorse any particular nonmetallic materials or manufacturers, but the following limitations should be considered by BWR owner/operators who select and use such materials.

## RECOMMENDATIONS

General Electric recommends that the following be considered by utilities when selecting nonmetallic material such as gaskets, valve stem packing and lubricants for the NSSS:

1. Vendor certification or alternate testing should be obtained to assure that contaminants do not exceed the following:

<u>Total</u> *	
Fluorine	300ppm
Chlorine	500ppm
Sulfur **	700ppm
Heavy Metals	500ppm ***

- \* - Quantities are based on total element contents, not leachables.
- \*\* - As active sulfur. Active sulfur is "low valent" sulfur or "reactive" sulfur with chemical valence less than +6 (i.e. sulfite, sulfide, etc.). If active sulfur analysis is not done, then all of the sulfur is assumed to be active sulfur.
- \*\*\* - No single one of the heavy (low melting point) metals should constitute more than 200ppm. The eleven heavy metals of concern are zinc, cadmium, mercury, lead, tin, silver, arsenic, antimony, bismuth, gallium and indium. Analysis of all or some of the heavy metals may be waived if the vendor certifies that there are no deliberate additions or reasons to expect significant

**GENERAL  ELECTRIC**



quantities of these metals to be present.

2. There should be no added constituents of nitrates or nitrites used in the manufacture or packaging of the product.

For additional information contact your local General Electric service representative.

Prepared by: G.R. Hanson/D.R. Heising

Approved by: *D.L. Allred*  
D.L. Allred, Manager  
Customer Service Information

Issued by: *R.E. Bates*  
R.E. Bates, Specialist  
Service Communications

Product Reference:  
A71 - Plant Recommendations

#### ACKNOWLEDGEMENT

Appreciation is expressed to the following individuals for their significant contributions to the preparation of this document: Clyde Nieh for his technical input regarding valve and system details, John Cochran for his technical input from the Clinton site, Barry Gordon for his careful review of the document and to Alicia Ordonez for her patient retyping of the many corrections.

GENERAL ELECTRIC	:	DATE OF ISSUE	ISSUED	:	FDDR NO.	LH1-5504
	:		NOV 22 1985	:	REVISION	0
FIELD DEVIATION DISPOSITION REQUEST	:		PSE & SI	:	SHEET	1 OF 4
PROJECT	:	Clinton	UNIT	:	FDDR ORIGINATOR	DATE
EQUIPMENT (MPL OR DESCRIPTION OR BOTH)	:	E22-F010	I	:	J.T. Cochran	11-21-85
	:			:	J. Bruden for	
DOCUMENT NO. : SH NO.: REV : TITLE						
VPF3238-682-2 : Fig.4: : Instruction Manual Motor Operated Carbon Steel Valves						
DEVIATION DESCRIPTION NCMR 01-1960						
Valve E22-F010 has been damaged during test:						
a) The valve stem is fractured approximately 1 3/4" above the back seat level.						
b) The disk was cut apart during disassembly.						
c) The disk nut was cut apart during disassembly.						
d) There is a chip out of the hard face seat ring. 11/22/85						
e) There are several gouges in the valve body disk guide ribs. W. Radford for						
SITE QC CONCURRENCE		11/22/85	FIELD CONCURRENCE		J. C. Logan	DATE 11-22-85
X SUGGESTED DISPOSITION			EXPEDITED DISPOSITION			
For part numbers refer to the Reference (Anchor Darling Dwg. 2999-3 Rev.D) Sheet 3 of this FDDR. The following steps may be performed out of order to effect repairs.						
a) Penetrant test the bonnet back seat hard face part 34. If free of indications the bonnet is suitable for reuse.						
(CONTINUED ON SHEET 2 OF THIS FDDR)						
Cost: 8Y275		Material: 408-20122-910				
DISPOSITION NEED DATE 11-21-85		EXPEDITED DISPOSITION APPROVAL BY			DATE	
FINAL DISPOSITION						
Same as Suggested Disposition.						
QC - Verify the requirements of this FDDR are met. 11/22/85						
ECA/ECN N/R			FDI NO. N/R			
JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)						
Damage to valve parts have required substantial repairs. Replacing broken parts and performing repair of pressure boundary parts in accordance with the Code Section XI will restore the valve to design conditions resulting in safe reliable operation.						
DESIGN VERIFICATION STATEMENT						
The disposition will restore the valve E22-F010 to an acceptable configuration based on an independent review and engineering judgment.						
APPROVALS		DATE	VERIFIED BY		DATE 11-22-85	
J. Bruden for L. Patterson	11/22/85	Clyde Nieh				
QUALITY		DRF NO. IF APPLICABLE	THIS EQUIPMENT IS SAFETY RELATED			
N/R		N/R	YES X NO			
MATL APPL ENGR		APPROVALS	DATE	SAFETY FUNCTION IS AFFECTED		
N/R				YES NO X		
LEAD SYSTEM ENGR				COMPLETION RECORD : SUPPLIER ACTION		
J. Bruden for L. Patterson	11-22-85			REQUIRED BY R.E. : REQUIRED		
ENGRG MANAGER		DISTRIBUTION CODE		YES NO X : YES NO X		
J.T. Cochran	11-22-85	INTERNAL EXTERNAL		FIELD WORK ORDER NO.		
RESPONSIBLE ENGR				DISPOSITION COMPLETE DATE		
W. Radford for	11-22-85			SITE QUALITY CONTROL		
PROJECT MANAGER				FIELD MANAGER		

## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5504 Rev.0 SHEET 2 OF 4  
PROJECT Clinton I DATE 11-21-85

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F010

## SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 1)

Under the direction of an Anchor Darling field representative, perform the following work: Steps (b) through (l).

- b) Inspect the bonnet back seat (Part 34) and dress as required to meet design requirements.
- c) Break sharp corners and blend the chipped area in the valve seat so as to preserve the maximum valve seat width.
- d) Blend the gouge marks in the valve body disk guide ribs. The work must be performed under Code Section XI since this is a pressure retaining part.
- e) IPC is to supply the following replacement parts:
  - 1) Stem part (5) Anchor Darling Drawing 5287-2-2.
  - 2) Disk nut part (64) Anchor Darling Drawing 5287-2-2.
  - 3) Stem clamp, part (25) or straighten the bent stem clamp.
  - 4) Valve disk part (4) Anchor Darling Drawing 5287-2-5 or equivalent. A possible source is to remove a disk from the Black Fox valve without operator.
  - 5) Valve stem packings (parts 16 and 16A).
  - 6) Replacement gasket part (18)
- f) Since the disk is a pressure retaining part, the use of a substitute disk must be resolved with the authorized code inspector.
- g) Check shaft dimensions and bonnet back seat dimensions to assure that a proper back seat can be achieved.
- h) Using the procedure on Sheets 4-2 and 4-3 of VPF 3238-682-2 (Anchor Darling Valve IOM Manual) lap the seat to the point where a seal line is established.
  - 1) Reassemble the valve per VPF 3238-682-2 Sheets 5-4 and 5-5.
- j) Reset limit and torque switches and manually operate the valve to assure that they are properly set. CAUTION: Operation of the valve by means of the motor, without having the switches properly set can lead to destruction of the back seat. Under close surveillance, operate the valve by means of the motor operator to assure that the limit stops are working properly.
- k) Check bonnet and stem leakage, correct any observed leaks.
- l) Assemble code data package to substantiate acceptable valve repairs.

QTY	MANUF.	REV	DESCRIPTION	MATERIAL	MATL SPEC.
PER	DWG. NO.				ASME, EN, ASTM
1	5207-2-5	01	BODY -	CAST STL	A216 WPL
1	5207-2-5	02	FLANGE	CAST STL	A216 WPL
1	5207-2-5	04	DISC (MILL MACH)	CAST STL	A216 WPL
1	5207-2-2	5	STEM (MILL MACH)	STAIN. ST.	A216 WPL
1	7-312-2	7	GLAND	STAIN. ST.	A216 WPL
1	5207-2-3	11	YOKER	CAST STL	A216 WPL
2	13-700-3P	13	SEAT RING (MILL)	STAIN. ST.	A216 WPL
7	5207-2-5	16	PACKING (MILL)	PACKING	SAFETY
6	5207-2-5	16	PACKING (MILL)	PACKING	SAFETY
1	5207-2-5	17	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	18	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	19	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	20	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	21	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	22	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	23	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	24	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	25	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	26	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	27	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	28	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	29	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	30	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	31	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	32	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	33	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	34	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	35	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	36	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	37	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	38	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	39	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	40	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	41	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	42	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	43	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	44	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	45	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	46	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	47	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	48	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	49	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	50	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	51	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	52	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	53	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	54	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	55	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	56	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	57	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	58	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	59	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	60	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	61	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	62	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	63	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	64	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	65	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	66	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	67	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	68	CLAMP (MILL)	CLAMP	SAFETY
1	5207-2-5	69	CLAMP (MILL)	CLAMP	SAFETY

PRESSURE CONTAINING PARTS

[illegible]

GENERAL ELECTRIC CO.



**ANCHOR/DARLING VALVE COMPANY**  
HAYWARD, CALIFORNIA

10" 500° GLOBS (5700) B.B., R.  
B.W. ENOS. CAST CARB. STEEL  
TRIM, SMD-4 MOTOR OPER.


299-3	299-3	299-3
-------	-------	-------

1. DESIGN & MANUFACTURE IN ACCORDANCE WITH ASME  
BOLLER AND PRESSURE VESSEL CODE, SECTION III,  
CLASS 2, WINTER 1975 ACCORDING WITH CODE CASE  
1622.
2. ISOSTATIC TESTS:  
(A) SMALL TEST PRESSURE 35.00 MPa.  
(B) SEAT TEST PRESSURE 1875 PSIG.
3. ESTIMATED VALVE WT: 2100 LBS. 1 INCH VAST W/TT  
NATION OPERATOR: 8724 5410
4. MAXIMUM TOXIC VALUE RECOMMENDED FOR  
STDS 19 & 20: 1250 PSIA

00	Andal/Parling	Value Company
SIZE	10	BODY
RATING	1410	STEM
TEMPF	700	DISC
SERIAL		SEAT
HYDRO	1220	PSIG DWG
VALUE ID		REFL NO 622-1910 (IN TOLL)



BUTT WELD END DETAIL  
SIZED 135 (710W) TEE IN  
AGREEMENT WITH OTHER  
ELECTRIC DIVISIONS, 11-1-62



75.9







GENERAL ELECTRIC

DATE OF ISSUE ISSUED

NOV 27 1985

FDDR NO. LHI-5504  
REVISION 1  
SHEET 1 OF 5FIELD DEVIATION DISPOSITION  
REQUEST

PROJECT Clinton

UNIT PSE-GT SI

EQUIPMENT (MPL OR DESCRIPTION OR BOTH) E22-F010

FDDR ORIGINATOR DAT  
J.T. Cochran 11-21-

DOCUMENT NO. : SH NO. : REV : TITLE

VPF3238-682-2 : Fig. 4 :

Instruction Manual Motor Operated Carbon Steel Valves

DEVIATION DESCRIPTION

NCMR 01-1960

This FDDR LHI-5504 Rev.1 completely supersedes FDDR LHI-5504 Rev.0.

Valve E22-F010 has been damaged during test:

- The valve stem is fractured approximately 1 3/4" above the back seat level.
- The disk was cut apart during disassembly.
- The disk nut was cut apart during disassembly.
- There is a chip out of the hard face seat ring.
- There are several gouges in the valve body dish guide ribs.

SITE QC CONCURRENCE *William E. Fuchs* DATEFIELD CONCURRENCE *J. T. Cochran* DATE 11/27/85

X SUGGESTED DISPOSITION

EXPEDITED DISPOSITION

For part numbers refer to the Reference (Anchor Darling Dwg. 2999-3 Rev.D) Sheet 3 of this FDDR. The following steps may be performed out of order to effect repairs.

- Penetrant test the bonnet back seat hard face part 34. If free of indications the bonnet is suitable for reuse.

(CONTINUED ON SHEET 2 OF THIS FDDR)

Cost: 8Y275

Material: 408-20122-910

DISPOSITION NEED DATE 11-21-85 EXPEDITED DISPOSITION APPROVAL BY

DATE

FINAL DISPOSITION

Same as Suggested Disposition.

QC TO VERIFY (M) OF REVISION *11/27/85* ECA/ECN N/R

FDI NO. N/R

JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)

Damage to valve parts have required substantial repairs. Replacing broken parts and performing repair of pressure boundary parts in accordance with the Code Section XI will restore the valve to design conditions resulting in safe reliable operation.

## DESIGN VERIFICATION STATEMENT

Review of current design practice reveals that tack weld of disc to disc nut is the preferred method of locking disc to disc nut.

APPROVALS	DATE	VERIFIED BY	DATE
<i>William E. Fuchs</i>	11/27/85	<i>J. E. Smith Jr.</i>	11/27/85
QUALITY		DRF NO. IF APPLICABLE	
N/R		N/R	
MATL APPL ENGR		APPROVALS	DATE
N/R			
LEAD SYSTEM ENGR			
<i>J. T. Cochran</i>	11/27/85		
ENGRG. MANAGER		DISTRIBUTION CODE	
J.T. Cochran	11-27-85	INTERNAL	EXTERNAL
RESPONSIBLE ENGR			
<i>J. T. Cochran</i>	11-27-85		
PROJECT MANAGER			

THIS EQUIPMENT IS SAFETY RELATED	YES	X	NO
SAFETY FUNCTION IS AFFECTED	YES		NO X
COMPLETION RECORD : SUPPLIER ACTION REQUIRED BY R.E. :	REQUIRED		
YES	NO X	YES	NO X
FIELD WORK ORDER NO.			
DISPOSITION COMPLETE		DATE	
SITE QUALITY CONTROL			
FIELD MANAGER			

## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5504 Rev.1

PROJECT Clinton I

SHEET 2 OF 5

DATE 11-21-85

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F010

## SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 1)

(Rev.0)

Under the direction of an Anchor Darling field representative, perform the following work: Steps (b) through (l).

- b) Inspect the bonnet back seat (Part 34) and dress as required to meet design requirements.
- c) Break sharp corners and blend the chipped area in the valve seat so as to preserve the maximum valve seat width.
- d) Blend the gouge marks in the valve body disk guide ribs. The work must be performed under Code Section XI since this is a pressure retaining part.
- e) IPC is to supply the following replacement parts:
  - 1) Stem part (5) Anchor Darling Drawing 5287-2-2.
  - 2) Disk nut part (64) Anchor Darling Drawing 5287-2-2.
  - 3) Stem clamp, part (25) or straighten the bent stem clamp.
  - 4) Valve disk part (4) Anchor Darling Drawing 5287-2-5 or equivalent. A possible source is to remove a disk from the Black Fox valve without operator.
  - 5) Valve stem packings (parts 16 and 16A).
  - 6) Replacement gasket part (18)
- f) Since the disk is a pressure retaining part, the use of a substitute disk must be resolved with the authorized code inspector.
- g) Check shaft dimensions and bonnet back seat dimensions to assure that a proper back seat can be achieved.
- h) Using the procedure on Sheets 4-2 and 4-3 of VPF 3238-682-2 (Anchor Darling Valve IOM Manual) lap the seat to the point where a seal line is established.
- i) Reassemble the valve per VPF 3238-682-2 Sheets 5-4 and 5-5.
- j) Reset limit and torque switches and manually operate the valve to assure that they are properly set. CAUTION: Operation of the valve by means of the motor, without having the switches properly set can lead to destruction of the back seat. Under close surveillance, operate the valve by means of the motor operator to assure that the limit stops are working properly.
- k) Check bonnet and stem leakage, correct any observed leaks.
- l) Assemble code data package to substantiate acceptable valve repairs.

(Rev.1)

- (M) In reassembly of the disk to the stem, the disk nut threads Part 117 are to be tack welded to the disk, Part 11 with three one inch long tack welds at 120° to each other. Per Anchor Darling Drawing 93-14884 Rev.F (Sheet 4 of this FDDR) the nut material is A108 and the disk material is SA352. Use site approved welding procedure for the welds and visually inspect for the absence of cracking in the welds. The Anchor Darling field Representative is required for Steps (b) through (h) only.

[illegible]

1. INSTRUMENTS - IN ACCORDANCE WITH THE  
BULLETIN AND PRESSURE TESTS CODE, SECTION 111,  
CLASS 2, WINTER 1973 ADDENDUM WITH CODE CASE  
1835.
2. INSTRUMENTS TESTS:  
(a) 3611 TEST PRESSURE ST. AND P.W.D.  
(b) 3611 TEST PRESSURE / P.W.D. AND
3. TESTED VALUE WITH 20% TEST VER. W/  
MAXIMUM OPERATOR, 2700. 5410-
4. MAXIMUM TESTED VALUE WITH 20% TEST VER.  
1100 19 & 201200 88

**E. UNIVERSALITY OF THE RESULTS**



TABLE 1  
TEST RESULTS

TEST	TEST RESULTS
(1) SPLIT TENSILE	32,000 PSI
(2) SPLIT TENSILE	1,875 PSI

3. Estimated value wt. 2.80<sup>g</sup>, post mortem.

4. SAVINGS THROUGH VALUE RECOGNITION FOR  
STOCKS AS A 20-17-00 PROJECT

00 And/or Darling Value Company	0
DATE: 12-2-88	
SIZE 10	BODY WGT 25
RATING 1810	STEM 11.1-CPA
TEMP F 700	DSC 10.0-CPA
SERIAL	SEAT 10.0-CPA
H/DRO 13.0	PSG DMG 12.0-3
VALVE ID	VAL NO 232-130 134 7011



(1) CHEM. RANGE CO CO A

[illegible]

LH1-5504 Rev. 81  
3 OF 4587C  
11-27-8

PLATT VELD AIR DETAIL  
SHEET 100 (THIS) FROM  
AIRPORT PROJECT W/4. EXHIBIT  
ELECTRIC DRAWING 6062

GENERAL ELECTRIC CO.

ANCHOR/DARLING VALVE COMPANY

10°-500° GLOUS (-100°) DO, E;  
DW. ENOS. CAT CARO. ST, SML  
TRIM 500-4 MOTA; ORC

	90-68	E-6667
--	-------	--------

FIG. 9





: FDDR No. IHL-5504 :

: Revision 1 :

: Sheet 5 of 5 :

: Job No. 8Y275 :

: WPSS ACTIVITY TYPE R            :

\* = Documents Transferred to S&L FOR PRINTING

```

:      :      : UPDATE WITH :
: RESP : RESP : FDDR ISSUE :
: COMP : ENG'R : YES : NO :

```

DOCUMENT ID NO. : DOCUMENT TITLE/TYPE : MPL ITEM NO.  
NO DOCUMENTS ARE AFFECTED.

Ek 11/24/95

FOR REFERENCE ONLY

Quality Control is to verify that field work is in compliance with this SOP

ECA/ECN	EIS	FDI NO.	N/R
---------	-----	---------	-----

ECR/ECN	EIS	FDI NO.	N/R
JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)			
Damage to the valve back seat prevents continued operation without repair. Actions required by this FDDR will return the valve to full code compliance condition which will assure safe reliable operation.			

DESIGN VERIFICATION STATEMENT  
This disposition will restore valve E22-F011 to an acceptable configuration based on an independent review and engineering judgement.

VERIFIED BY F. E. Smith, Jr. DATE 11/24/65

APPROVALS	DATE	DRF NO. IF APPLICABLE	THIS EQUIPMENT IS SAFETY RELATED
<i>William E. Galt</i>	11/24/85	N/R	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
QUALITY		APPROVALS	DATE
N/R			
MATL APPL ENGR			
N/R			
LEAD SYSTEM ENGR			
<i>DRIVEN FOR L. PATTERSON</i>	11/24/85	DISTRIBUTION CODE	COMPLETION RECORD : SUPPLIER ACTION
ENGRG MANAGER BY		INTERNAL	REQUIRED BY R.E. : REQUIRED
J. T. Cochran	11/24/85	EXTERNAL	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> : YES <input type="checkbox"/> NO <input type="checkbox"/>
RESPONSIBLE ENGR			FIELD WORK ORDER NO.
<i>Colman</i>	11-24-85		DISPOSITION COMPLETE <i>HP</i> DATE

II



## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5503 Rev. 0 SHEET 2 OF 4  
PROJECT Clinton I DATE 11-21-85

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F011

## DEVIATION DESCRIPTION: (CONTINUED FROM SHEET 1)

- b.) The stem is galled for a length of approximately 1 1/2 inches below the back seat bevel surface.
- c.) Field stem hardness measurements of RC 372, Brinell 333 exceed the desired maximum value of Brinell 300.
- d.) The disc separated from the stem and the stem retaining rings are lost.
- e.) There are scratch marks on the body disc guide surfaces.

## SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 1)

- of the back seat. Replacement by use of a seal welded insert is acceptable if Code requirements are maintained.
- c) Replace the valve stem (part 5) with a stem having a Brinell hardness less than 300. (IP Co. to supply)
- d) Provide replacement Retaining Ring stem (part 63) (IP Co. to supply)
- e) Provide replacement valve stem packings parts 16 and 16A (IP Co. to supply)
- f) Provide replacement gasket (part 18). (IP Co. to supply)
- g) Anchor-Darling to provide a Code Package update for the repairs which will maintain the code status of the of the repaired valve.  
Under the direction of an Anchor Darling field representative perform steps h, i and j.
- h) Refurbish the valve body disc guides to blend scratch marks.
- i) Check the disc seat mating surface and refinish if required.
- j) Reassemble the valve using the existing disc (Part 4) disc nut (Part 64), and parts from item b, c, d, e and f above.
- k) Reset limit switches and manually operate the valve to assure that they are properly set. CAUTION: Operation of the valve by means of the motor, without having the switches properly set can lead to destruction of the back seat.  
Under close surveillance, operate the valve by means of the motor operator to assure that the switches are working properly.
- l) Check bonnet and seat leakage, correct any observed leaks.
- m) Assemble code data package to substantiate acceptability of valve repairs.

HP

II

I-34

[illegible]

(1) OILM. PARKER C. CO. A

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840. 84

GENERAL ELECTRIC CO.

**ANCHOR/DAHLING VALVE COMPANY**  
HAYWARD, CALIFORNIA

102500 GLOVE (-10-) DO, L.S.  
DW. ENOS. CAR. CARO. SM, SHIL.  
TRIM. 5710-4 NOTAL OF L.

2999.3

441-5503 Rev. 0  
3 of 4




PLATE WELD END DETAIL  
SECTION 12 (TYPICAL) PER N  
A.C. WELDED WITH DET. 12-1  
FINISHING TYPICAL DET. 12-1  
END

Fig. 2. SECTION 8. CONSTRUCTION IN ACCORDANCE WITH ADME  
BORDER AND PARTIAL WITHIN COR. SECTION III.  
CLASS B. WITHIN 1000 ACCORDA WITH COR. CASE  
1000.

[illegible]

3. ESTIMATED VALUE: \$215.00  
 ANALYSIS OF VARIATION: 226.00  
 100% VARY WITH 2410-

10-10 02107 1 11 1011  
1304 10 1 201120 10-10

© Arthur D. Dantley Vols Company

|         |     |      |         |
|---------|-----|------|---------|
| SIZE    | 10  | BOOK | 3000    |
| PARTING | 100 | SIEM | 10-100  |
| TEMP    | 100 | DESC | 10-100  |
| SERIAL  | 100 | CFM  | 10-100  |
| INDROB  | 100 | PSIC | 100-100 |
| NAME    | 100 | DWG  | 100-100 |

1-011

| CAPACITE | VALUE |
|----------|-------|
| 500      |       |
| 1000     |       |
| 2000     |       |
| 3000     |       |
| 4000     |       |
| 5000     |       |
| 6000     |       |
| 7000     |       |
| 8000     |       |
| 9000     |       |
| 10000    |       |
| 11000    |       |
| 12000    |       |
| 13000    |       |
| 14000    |       |
| 15000    |       |
| 16000    |       |
| 17000    |       |
| 18000    |       |
| 19000    |       |
| 20000    |       |
| 21000    |       |
| 22000    |       |
| 23000    |       |
| 24000    |       |
| 25000    |       |
| 26000    |       |
| 27000    |       |
| 28000    |       |
| 29000    |       |
| 30000    |       |
| 31000    |       |
| 32000    |       |
| 33000    |       |
| 34000    |       |
| 35000    |       |
| 36000    |       |
| 37000    |       |
| 38000    |       |
| 39000    |       |
| 40000    |       |
| 41000    |       |
| 42000    |       |
| 43000    |       |
| 44000    |       |
| 45000    |       |
| 46000    |       |
| 47000    |       |
| 48000    |       |
| 49000    |       |
| 50000    |       |
| 51000    |       |
| 52000    |       |
| 53000    |       |
| 54000    |       |
| 55000    |       |
| 56000    |       |
| 57000    |       |
| 58000    |       |
| 59000    |       |
| 60000    |       |
| 61000    |       |
| 62000    |       |
| 63000    |       |
| 64000    |       |
| 65000    |       |
| 66000    |       |
| 67000    |       |
| 68000    |       |
| 69000    |       |
| 70000    |       |
| 71000    |       |
| 72000    |       |
| 73000    |       |
| 74000    |       |
| 75000    |       |
| 76000    |       |
| 77000    |       |
| 78000    |       |
| 79000    |       |
| 80000    |       |
| 81000    |       |
| 82000    |       |
| 83000    |       |
| 84000    |       |
| 85000    |       |
| 86000    |       |
| 87000    |       |
| 88000    |       |
| 89000    |       |
| 90000    |       |
| 91000    |       |
| 92000    |       |
| 93000    |       |
| 94000    |       |
| 95000    |       |
| 96000    |       |
| 97000    |       |
| 98000    |       |
| 99000    |       |
| 100000   |       |

卷一百一十五

10

4.4233/526

10

—

[illegible]

1. *Phragmites*

**PLATE 1**

[illegible]

I-26

|  |                    |                 |               |
|--|--------------------|-----------------|---------------|
| GENERAL ELECTRIC                       | DATE OF ISSUE      | FDDR NO.        | LH1-5503      |
| FIELD DEVIATION DISPOSITION REQUEST    | DEC 19 1985        | REVISION        | 1             |
| PROJECT Clinton                        | PSE & SI           | SHEET           | 1 OF 5        |
| EQUIPMENT (MPL OR DESCRIPTION OR BOTH) | UNIT I<br>E22-F011 | FDDR ORIGINATOR | J. T. Cochran |
| DOCUMENT NO. : SH NO. : REV : TITLE    |                    | DATE            | 12-18-85      |

VPF 3238-682-2:Fig.4 : Instruction Manual Motor Operated Carbon Steel Valve  
 DEVIATION DESCRIPTION NCMR 02-0563 DTF JK684  
 This FDDR completely supersedes LH1-5503 Rev.0.  
 (Rev.0)

Valve E22-F011 has been damaged during test:  
 a) The integral Stellite back seat in the bonnet is cracked radially and circumferentially, there is evidence of separation from the substrate.  
 (CONTINUED ON SHEET 2 OF THIS FDDR)

SITE QC CONCURRENCE *K. F. Hannan* DATE 12/19/85 FIELD CONCURRENCE *J. T. Cochran* DATE 12-19-85  
 X SUGGESTED DISPOSITION EXPEDITED DISPOSITION

There is no technical change to (Rev.0) therefore only this revision requires justification and verification.  
 (Rev.0)

For part numbers refer to the reference, (Anchor Darling Dwg. 2999-3 Rev. D), Sheet 3 of this FDDR. The following steps may be performed out of order to effect repairs.

- a) IPC to confirm with Anchor Darling that the Bonnet can be repaired in conformance with Code requirements within site scheduling needs.
- b) IPC to ship the valve Bonnet (part 2) to Anchor Darling for replacement of the back seat.

(CONTINUED ON SHEET 2 OF THIS FDDR.)  
 Cost: 8Y275 Material: 408-20122-910  
 DISPOSITION NEED DATE 11-21-85 EXPEDITED DISPOSITION APPROVAL BY DATE

FINAL DISPOSITION  
 Same as Suggested Disposition.  
 Quality Control is to verify that field work is in compliance with this FDDR.

JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)  
 Anchor/Darling has designed a recessed drop-in brackseat which will be seal welded to the bonnet replacing the damaged integral backseat. The bonnet to insert weld is recessed and will be finished to permit either MT or PT acceptance inspection. Safety and reliability are not affected.

DESIGN VERIFICATION STATEMENT  
 Verified by an independent review of the submitted data and based on engineering judgement.

|                      |          |                                  |          |
|----------------------|----------|----------------------------------|----------|
| APPROVALS            | DATE     | VERIFIED BY                      | DATE     |
| <i>K. F. Hannan</i>  | 12/19/85 | <i>J. T. Cochran for C. Nigh</i> | 12-19-85 |
| QUALITY              |          | DRF NO. IF APPLICABLE            |          |
| N/R                  |          | N/R                              |          |
| MATL APPL ENGR       |          | APPROVALS                        | DATE     |
| N/R                  |          |                                  |          |
| LEAD SYSTEM ENGR     |          |                                  |          |
| <i>J. T. Cochran</i> | 12/19/85 | DISTRIBUTION CODE                |          |
| ENGRG MANAGER        |          | INTERNAL                         | EXTERNAL |
| <i>J. T. Cochran</i> | 12-19-85 |                                  |          |
| RESPONSIBLE ENGR     |          |                                  |          |
| <i>J. T. Cochran</i> | 12-19-85 |                                  |          |
| PROJECT MANAGER      |          |                                  |          |

|   |   |
|---|---|
| THIS EQUIPMENT IS SAFETY RELATED                                    | YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>   |
| SAFETY FUNCTION IS AFFECTED   | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>   |
| COMPLETION RECORD : SUPPLIER ACTION                                 | REQUIRED BY R.E. : REQUIRED   |
| YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> | : YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> |
| FIELD WORK ORDER NO.  |   |
| DISPOSITION COMPLETE  | DATE  |
| SITE QUALITY CONTROL  |   |
| FIELD MANAGER   |   |



## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5503 Rev. 1 SHEET 2 OF 5  
PROJECT Clinton I DATE 12-18-85

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F011

## DEVIATION DESCRIPTION: (CONTINUED FROM SHEET 1)

- b.) The stem is galled for a length of approximately 1 1/2 inches below the back seat bevel surface.
- c.) Field stem hardness measurements of RC 372, Brinell 333 exceed the desired maximum value of Brinell 300.
- d.) The disc separated from the stem and the stem retaining rings are lost.
- e.) There are scratch marks on the body disc guide surfaces.

(Rev.1)

Review and approval is requested of Anchor/Darling Drawing 2999-3 Rev.(J) for application to Clinton valve E22-F011.

## SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 1)

- Replacement by use of a seal welded insert is acceptable if Code requirements are maintained.
- c) Replace the valve stem (part 5) with a stem having a Brinell hardness less than 300. (IP Co. to supply)
- d) Provide replacement Retaining Ring stem (part 63) (IP CO. to supply)
- e) Provide replacement valve stem packings parts 16 and 16A (IP Co. to supply)
- f) Provide replacement gasket (part 18). (IP Co. to supply)
- g) Anchor-Darling to provide a Code Package update for the repairs which will maintain the code status of the of the repaired valve.  
Under the direction of an Anchor Darling field representative perform steps h, i and j.
- h) Refurbish the valve body disc guides to blend scratch marks.
- i) Check the disc seat mating surface and refinish if required.
- j) Reassemble the valve using the existing disc (Part 4) disc nut (Part 64), and parts from item b, c, d, e and f above.
- k) Reset limit switches and manually operate the valve to assure that they are properly set. CAUTION: Operation of the valve by means of the motor, without having the switches properly set can lead to destruction of the back seat.  
Under close surveillance, operate the valve by means of the motor operator to assure that the switches are working properly.
- l) Check bonnet and seat leakage, correct any observed leaks.
- m) Assemble code data package to substantiate acceptability of valve repairs.

(Rev.1)

Anchor/Darling Drawing 2999-3 Rev. (J) depicting a modified bonnet to accept a drop in backseat is approved for valve E22-F011 at Clinton Station, Sheet 4 of this FDDR.

General Electric to incorporate Anchor/Darling Drawing 2999-3 Rev. (J) into the vendor print file for valve E22-F011 at Clinton Station.



[illegible]

(1) CHEM. RANGE C-CuA

From:

[illegible]

GENERAL ELECTRIC CO.

**ANCHOR/DARLING VALVE COMPANY**  
MAYNARD, CALIFORNIA

107° 50' GLORIA (-100) DB, L<sup>2</sup>,  
NW. ENCL. CALIF. CO. B. 5N, 5ME  
TRIM. 5MO-4 NOTED ORC

E-6662

[illegible]

2000

\* DESIGN & MANUFACTURE IN ACCORDANCE WITH AMERICAN BOILER AND PRESSURE VESSEL CODE, SECTION III, CLASS 3, WINTER 1975 ACCORDA WITH CODE CASE 1637.


[illegible]

ESTIMATED VALUE WT: 2.80<sup>g</sup> | POST WEIGHT WITH  
W/1010 ORGANAL: 0.77<sup>g</sup> | POST WEIGHT WITH  
W/1010 ORGANAL: 0.10<sup>g</sup>


MAXIMUM VOLUME VALUE ALLOWED FOR  
STOCK 10 & 20x1200 FT-4.87

10

Andrew Darling Valve Company  
 ADDRESS: 25-0000  
 SIZE  20 BODY  W/C/F  
 RATING  150 STEM  11-1/2" HGT  
 TEMP  700 DEG  10-8PSI  
 SERIAL  SEAT  15-8PSI  
 HNDRL  22-70, PSIG DWG.  22-92-3  
 VALVE ID  1/2" NO 22-75-0 15 7010



PLATT WELD AIR DETAIL  
SHEET 133 (THIS) THE N  
ACCORDING TO THE  
ELECTRIC ENGINEER,  
1922




175.5

1. DESIGN & MANUFACTURE IN ACCORDANCE WITH USC TITLE 10, SECTION 111, CLASS 2, WITH A DESIGN WITH 100% CMA 100%.
2. INSPECTION TESTS:  
ALL WELD TESTS PERFORMED BY 100% NDT  
ALL SAE 100% TESTS BY 100% NDT
3. ESTIMATED WEIGHT: 2100# (100% NDT W/ 100% NDT)  
WORKING WEIGHT: 2200# (100% NDT W/ 100% NDT)
4. MAXIMUM TORQUE VALUE: 10000 FT-LBS
5. REPLACEMENT MOTORS ARE CLASS 1E WITH RH-INSULATION FURNISHED VIA A/DV SO. E2214-300 (CLINTON SHV).
6. ROCKET (ITEM 95) MODIFIED TO ACCEPT BROWN BACKSEAT (ITEM 94) ONLY ON VALVE NO. E22-501 (CLINTON STATION) VIA A/DV SO. E2214-300 (REF DETAIL A).

**Anchor/Darling Valve Company**

SIZE: 10" BODY: WCB  
 RATING: 1500 PSI DEC: 10-20-20  
 TEMP: 700°F SEAT: 10-20-20  
 SERIAL: 10-20-20  
 HYDRO: 10-20-20  
 VALVE: 10-20-20



DDR No. L11-5503 Rev. 1  
 SHEET 4 OF 5

| ITEM | DESCRIPTION           | QTY | UNIT | PRICE | TOTAL |
|------|-----------------------|-----|------|-------|-------|
| 1    | 5207-2-5 (1) BODY     | 1   | EA   | 51.00 | 51.00 |
| 2    | 5207-2-5 (1) STEM     | 1   | EA   | 51.00 | 51.00 |
| 3    | 5207-2-5 (1) SEAT     | 1   | EA   | 51.00 | 51.00 |
| 4    | 5207-2-5 (1) HYDRO    | 1   | EA   | 51.00 | 51.00 |
| 5    | 5207-2-5 (1) VALVE    | 1   | EA   | 51.00 | 51.00 |
| 6    | 5207-2-5 (1) BACKSEAT | 1   | EA   | 51.00 | 51.00 |
| 7    | 5207-2-5 (1) ROCKET   | 1   | EA   | 51.00 | 51.00 |
| 8    | 5207-2-5 (1) MOTOR    | 1   | EA   | 51.00 | 51.00 |
| 9    | 5207-2-5 (1) CLAMP    | 1   | EA   | 51.00 | 51.00 |
| 10   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 11   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 12   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 13   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 14   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 15   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 16   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 17   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 18   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 19   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 20   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 21   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 22   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 23   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 24   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 25   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 26   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 27   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 28   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 29   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 30   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 31   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 32   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 33   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 34   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 35   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 36   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 37   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 38   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 39   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 40   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 41   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 42   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 43   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 44   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 45   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 46   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 47   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 48   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 49   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 50   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 51   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 52   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 53   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 54   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 55   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 56   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 57   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 58   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 59   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 60   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 61   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 62   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 63   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 64   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 65   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 66   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 67   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 68   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 69   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 70   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 71   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 72   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 73   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 74   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 75   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 76   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 77   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 78   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 79   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 80   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 81   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 82   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 83   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 84   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 85   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 86   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 87   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 88   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 89   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 90   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 91   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 92   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 93   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 94   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 95   | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |
| 96   | 5207-2-5 (1) WASH     | 1   | EA   | 51.00 | 51.00 |
| 97   | 5207-2-5 (1) O-RING   | 1   | EA   | 51.00 | 51.00 |
| 98   | 5207-2-5 (1) GASKET   | 1   | EA   | 51.00 | 51.00 |
| 99   | 5207-2-5 (1) BOLT     | 1   | EA   | 51.00 | 51.00 |
| 100  | 5207-2-5 (1) NUT      | 1   | EA   | 51.00 | 51.00 |

**ATTACHMENT 5C**  
**PAGE 17 OF 27**

**DETAIL A**  
 SEE NOTE G

**DETAIL B**  
 SEE NOTE H

**DETAIL C**  
 SEE NOTE I

**DETAIL D**  
 SEE NOTE J

**DETAIL E**  
 SEE NOTE K

**DETAIL F**  
 SEE NOTE L

**DETAIL G**  
 SEE NOTE M

**DETAIL H**  
 SEE NOTE N

**DETAIL I**  
 SEE NOTE O

**DETAIL J**  
 SEE NOTE P

**DETAIL K**  
 SEE NOTE Q

**DETAIL L**  
 SEE NOTE R

**DETAIL M**  
 SEE NOTE S

**DETAIL N**  
 SEE NOTE T

**DETAIL O**  
 SEE NOTE U

**DETAIL P**  
 SEE NOTE V

**DETAIL Q**  
 SEE NOTE W

**DETAIL R**  
 SEE NOTE X

**DETAIL S**  
 SEE NOTE Y

**DETAIL T**  
 SEE NOTE Z

**DETAIL U**  
 SEE NOTE AA

**DETAIL V**  
 SEE NOTE AB

**DETAIL W**  
 SEE NOTE AC

**DETAIL X**  
 SEE NOTE AD

**DETAIL Y**  
 SEE NOTE AE

**DETAIL Z**  
 SEE NOTE AF

**DETAIL AA**  
 SEE NOTE AG

**DETAIL AB**  
 SEE NOTE AH

**DETAIL AC**  
 SEE NOTE AI

**DETAIL AD**  
 SEE NOTE AJ

**DETAIL AE**  
 SEE NOTE AK

**DETAIL AF**  
 SEE NOTE AL

**DETAIL AG**  
 SEE NOTE AM

**DETAIL AH**  
 SEE NOTE AN

**DETAIL AI**  
 SEE NOTE AO

**DETAIL AJ**  
 SEE NOTE AP

**DETAIL AK**  
 SEE NOTE AQ

**DETAIL AL**  
 SEE NOTE AR

**DETAIL AM**  
 SEE NOTE AS

**DETAIL AN**  
 SEE NOTE AT

**DETAIL AO**  
 SEE NOTE AU

**DETAIL AP**  
 SEE NOTE AV

**DETAIL AQ**  
 SEE NOTE AW

**DETAIL AR**  
 SEE NOTE AX

**DETAIL AS**  
 SEE NOTE AY

**DETAIL AT**  
 SEE NOTE AZ

**DETAIL AU**  
 SEE NOTE BA

**DETAIL AV**  
 SEE NOTE BB

**DETAIL AW**  
 SEE NOTE BC

**DETAIL AX**  
 SEE NOTE BD

**DETAIL AY**  
 SEE NOTE BE

**DETAIL AZ**  
 SEE NOTE BF

**DETAIL BA**  
 SEE NOTE BG

**DETAIL BB**  
 SEE NOTE BH

**DETAIL BC**  
 SEE NOTE BI

**DETAIL BD**  
 SEE NOTE BJ

**DETAIL BE**  
 SEE NOTE BK

**DETAIL BF**  
 SEE NOTE BL

**DETAIL BG**  
 SEE NOTE BM

**DETAIL BH**  
 SEE NOTE BN

**DETAIL BI**  
 SEE NOTE BO

**DETAIL BJ**  
 SEE NOTE BP

**DETAIL BK**  
 SEE NOTE BQ

**DETAIL BL**  
 SEE NOTE BR

**DETAIL BM**  
 SEE NOTE BS

**DETAIL BN**  
 SEE NOTE BT

**DETAIL BO**  
 SEE NOTE BU

**DETAIL BP**  
 SEE NOTE BV

**DETAIL BQ**  
 SEE NOTE BW

**DETAIL BR**  
 SEE NOTE BX

**DETAIL BS**  
 SEE NOTE BY

**DETAIL BT**  
 SEE NOTE BZ

**DETAIL BU**  
 SEE NOTE CA

**DETAIL BV**  
 SEE NOTE CB

**DETAIL BW**  
 SEE NOTE CC

**DETAIL BX**  
 SEE NOTE CD

**DETAIL BY**  
 SEE NOTE CE

**DETAIL BZ**  
 SEE NOTE CF

**DETAIL CA**  
 SEE NOTE CG

**DETAIL CB**  
 SEE NOTE CH

**DETAIL CC**  
 SEE NOTE CI

**DETAIL CD**  
 SEE NOTE CJ

**DETAIL CE**  
 SEE NOTE CK

**DETAIL CF**  
 SEE NOTE CL

**DETAIL CG**  
 SEE NOTE CM

**DETAIL CH**  
 SEE NOTE CN

**DETAIL CI**  
 SEE NOTE CO

**DETAIL CJ**  
 SEE NOTE CP

**DETAIL CK**  
 SEE NOTE CQ

**DETAIL CL**  
 SEE NOTE CR

**DETAIL CM**  
 SEE NOTE CS

**DETAIL CN**  
 SEE NOTE CT

**DETAIL CO**  
 SEE NOTE CU

**DETAIL CP**  
 SEE NOTE CV

**DETAIL CQ**  
 SEE NOTE CW

**DETAIL CR**  
 SEE NOTE CX

**DETAIL CS**  
 SEE NOTE CY

**DETAIL CT**  
 SEE NOTE CZ

**DETAIL CU**  
 SEE NOTE DA

**DETAIL CV**  
 SEE NOTE DB

**DETAIL CW**  
 SEE NOTE DC

**DETAIL CX**  
 SEE NOTE DD

**DETAIL CY**  
 SEE NOTE DE

**DETAIL CZ**  
 SEE NOTE DF

**DETAIL DA**  
 SEE NOTE DG

**DETAIL DB**  
 SEE NOTE DH

**DETAIL DC**  
 SEE NOTE DI

**DETAIL DD**  
 SEE NOTE DJ

**DETAIL DE**  
 SEE NOTE DK

**DETAIL DF**  
 SEE NOTE DL

**DETAIL DG**  
 SEE NOTE DM

**DETAIL DH**  
 SEE NOTE DN

**DETAIL DI**  
 SEE NOTE DO

**DETAIL DJ**  
 SEE NOTE DP

**DETAIL DK**  
 SEE NOTE DQ

**DETAIL DL**  
 SEE NOTE DR

**DETAIL DM**  
 SEE NOTE DS

**DETAIL DN**  
 SEE NOTE DT

**DETAIL DO**  
 SEE NOTE DU

**DETAIL DP**  
 SEE NOTE DV

**DETAIL DQ**  
 SEE NOTE DW

**DETAIL DR**  
 SEE NOTE DX

**DETAIL DS**  
 SEE NOTE DY

**DETAIL DT**  
 SEE NOTE DZ

**DETAIL DU**  
 SEE NOTE EA

**DETAIL DV**  
 SEE NOTE EB

**DETAIL DW**  
 SEE NOTE EC

**DETAIL DX**  
 SEE NOTE ED

**DETAIL DY**  
 SEE NOTE EE

**DETAIL DZ**  
 SEE NOTE EF

**DETAIL EA**  
 SEE NOTE EG

**DETAIL EB**  
 SEE NOTE EH

**DETAIL EC**  
 SEE NOTE EI

**DETAIL ED**  
 SEE NOTE EJ

**DETAIL EE**  
 SEE NOTE EK

**DETAIL EF**  
 SEE NOTE EL

**DETAIL EG**  
 SEE NOTE EM

**DETAIL EH**  
 SEE NOTE EN

**DETAIL EI**  
 SEE NOTE EO

**DETAIL EJ**  
 SEE NOTE EP

**DETAIL EK**  
 SEE NOTE EQ

**DETAIL EL**  
 SEE NOTE ER

**DETAIL EM**  
 SEE NOTE ES

**DETAIL EN**  
 SEE NOTE ET

**DETAIL EO**  
 SEE NOTE EU

**DETAIL EP**  
 SEE NOTE EV

**DETAIL EQ**  
 SEE NOTE EW

**DETAIL ER**  
 SEE NOTE EX

**DETAIL ES**  
 SEE NOTE EY

**DETAIL ET**  
 SEE NOTE EZ

**DETAIL EU**  
 SEE NOTE FA

**DETAIL EV**  
 SEE NOTE FB

**DETAIL EW**  
 SEE NOTE FC

**DETAIL EX**  
 SEE NOTE FD

**DETAIL EY**  
 SEE NOTE FE

**DETAIL EZ**  
 SEE NOTE FF

**DETAIL FA**  
 SEE NOTE FG

**DETAIL FB**  
 SEE NOTE FH

**DETAIL FC**  
 SEE NOTE FI

**DETAIL FD**  
 SEE NOTE FJ

**DETAIL FE**  
 SEE NOTE FK

**DETAIL FF**  
 SEE NOTE FL

**DETAIL FG**  
 SEE NOTE FM

**DETAIL FH**  
 SEE NOTE FN

**DETAIL FI**  
 SEE NOTE FO

**DETAIL FJ**  
 SEE NOTE FP

**DETAIL FK**  
 SEE NOTE FQ

**DETAIL FL**  
 SEE NOTE FR

**DETAIL FM**  
 SEE NOTE FS

**DETAIL FN**  
 SEE NOTE FT

**DETAIL FO**  
 SEE NOTE FU

**DETAIL FP**  
 SEE NOTE FV

**DETAIL FQ**  
 SEE NOTE FW

**DETAIL FR**  
 SEE NOTE FX

**DETAIL FS**  
 SEE NOTE FY

**DETAIL FT**  
 SEE NOTE FZ

**DETAIL FU**  
 SEE NOTE GA

**DETAIL FV**  
 SEE NOTE GB

**DETAIL FW**  
 SEE NOTE GC

**DETAIL FX**  
 SEE NOTE GD

**DETAIL FY**  
 SEE NOTE GE

**DETAIL FZ**  
 SEE NOTE GF

**DETAIL GA**  
 SEE NOTE GH

**DETAIL GB**  
 SEE NOTE GI

**DETAIL GC**  
 SEE NOTE GJ

**DETAIL GD**  
 SEE NOTE GK

**DETAIL GE**  
 SEE NOTE GL

**DETAIL GF**  
 SEE NOTE GM

**DETAIL GH**  
 SEE NOTE GN

**DETAIL GI**  
 SEE NOTE GO

**DETAIL GJ**  
 SEE NOTE GP

**DETAIL GK**  
 SEE NOTE GQ

**DETAIL GL**  
 SEE NOTE GR

**DETAIL GM**  
 SEE NOTE GS

**DETAIL GN**  
 SEE NOTE GT

**DETAIL GO**  
 SEE NOTE GU

**DETAIL GP**  
 SEE NOTE GV

**DETAIL GQ**  
 SEE NOTE GW

**DETAIL GR**  
 SEE NOTE GX

**DETAIL GS**  
 SEE NOTE GY

**DETAIL GT**  
 SEE NOTE GZ

**DETAIL GU**  
 SEE NOTE HA

**DETAIL GV**  
 SEE NOTE HB

**DETAIL GW**  
 SEE NOTE HC

**DETAIL GX**  
 SEE NOTE HD

**DETAIL GY**  
 SEE NOTE HE

**DETAIL GZ**  
 SEE NOTE HF

**DETAIL HA**  
 SEE NOTE HG

**DETAIL HB**  
 SEE NOTE HH

**DETAIL HC**  
 SEE NOTE HI

**DETAIL HD**  
 SEE NOTE HJ

**DETAIL HE**  
 SEE NOTE HK

**DETAIL HF**  
 SEE NOTE HL

**DETAIL HG**  
 SEE NOTE HM

**DETAIL HH**  
 SEE NOTE HN

**DETAIL HI**  
 SEE NOTE HO

**DETAIL HJ**  
 SEE NOTE HP

**DETAIL HK**  
 SEE NOTE HQ

**DETAIL HL**  
 SEE NOTE HR

**DETAIL HM**  
 SEE NOTE HS

**DETAIL HN**  
 SEE NOTE HT

**DETAIL HO**  
 SEE NOTE HU

**DETAIL HP**  
 SEE NOTE HV

**DETAIL HQ**  
 SEE NOTE HW

**DETAIL HR**  
 SEE NOTE HX

**DETAIL HS**  
 SEE NOTE HY

**DETAIL HT**  
 SEE NOTE HZ

**DETAIL HU**  
 SEE NOTE IA

**DETAIL HV**  
 SEE NOTE IB

**DETAIL HW**  
 SEE NOTE IC

**DETAIL HX**  
 SEE NOTE ID

**DETAIL HY**  
 SEE NOTE IE

**DETAIL HZ**  
 SEE NOTE IF

**DETAIL IA**  
 SEE NOTE IG

**DETAIL IB**  
 SEE NOTE IH

**DETAIL IC**  
 SEE NOTE II

**DETAIL ID**  
 SEE NOTE IJ

**DETAIL IE**  
 SEE NOTE IK

**DETAIL IF**  
 SEE NOTE IL

**DETAIL IG**  
 SEE NOTE IM

**DETAIL IH**  
 SEE NOTE IN

**DETAIL II**  
 SEE NOTE IO

**DETAIL IJ**  
 SEE NOTE IP

**DETAIL IK**  
 SEE NOTE IQ

**DETAIL IL**  
 SEE NOTE IR

**DETAIL IM**  
 SEE NOTE IS

**DETAIL IN**  
 SEE NOTE IT

**DETAIL IO**  
 SEE NOTE IU

**DETAIL IP**  
 SEE NOTE IV

**DETAIL IQ**  
 SEE NOTE IW

**DETAIL IR**  
 SEE NOTE IX

**DETAIL IS**  
 SEE NOTE IY

**DETAIL IT**  
 SEE NOTE IZ

**DETAIL IU**  
 SEE NOTE JA

**DETAIL IV**  
 SEE NOTE JB

**DETAIL IW**  
 SEE NOTE JC

<

GENERAL ELECTRIC  
FIELD DEVIATION DISPOSITION  
AFFECTED DOCUMENTS LIST

: FDDR No. LH1-5503  
: Revision 0  
: Sheet 5 of 5  
: Job No. 8Y275 :  
: WPSS ACTIVITY TYPE R

: @ = Documents Transmitted to Document Control Center  
: \* = Documents Transferred to S&L for Maintenance  
: SCHEDULE COMMITMENTS TO MEET ESTABLISHED SOP CYCLE DATES

[illegible]

ISSUED

|   |                    |                                   |   |                                     |                                  |
|---|--------------------|-----------------------------------|---|-------------------------------------|----------------------------------|
| GENERAL ELECTRIC  | :                  | DATE OF ISSUE                     | :   | FDDR NO.                            | LH1-5503                         |
|   | :                  | FEB 06 1986                       | :   | REVISION                            | 2                                |
| FIELD DEVIATION DISPOSITION REQUEST   | :                  | PSE & SI                          | :   | SHEET                               | 1 OF 2                           |
| PROJECT   | Clinton            | UNIT                              | I   | FDDR ORIGINATOR                     | DATE                             |
| EQUIPMENT (MPL OR DESCRIPTION OR BOTH)  | E22-F011           |                                   |   | G. L. Moore                         | 2/6/86                           |
|   |                    |                                   |   | <i>G. L. Moore</i>                  | 2/6/86                           |
| DOCUMENT NO.  | :SH NO.:           | REV :                             | TITLE   |                                     |                                  |
| VPF 3238-682-2: Fig.4:  | :                  |                                   | Instruction Manual, Motor Operated Carbon Steel Valve |                                     |                                  |
| DEVIATION DESCRIPTION   | JK-793             |                                   |   |                                     |                                  |
| This FDDR supplements LH1-5503 Rev. 1.  |                    |                                   |   |                                     |                                  |
| I.P. Co. has requested that the Anchor Darling Valve Company representative presence be made non-mandatory.   |                    |                                   |   |                                     |                                  |
| SITE QC CONCURRENCE   | <i>K.F. Hammer</i> | DATE                              | 2/6/86  | FIELD CONCURRENCE                   | <i>W. Radford for J.R. Logan</i> |
|   |                    |                                   |   |                                     | DATE                             |
| X SUGGESTED DISPOSITION   |                    | EXPEDITED DISPOSITION             |   |                                     |                                  |
| Change "Under the direction of an Anchor Darling Field representative perform steps h, i, and j" to "when performing steps h, i, and j, seek the guidance of the Anchor Darling Field representative as his availability permits" |                    |                                   |   |                                     |                                  |
| Cost: 8Y275   | Material: None     |                                   |   |                                     |                                  |
| DISPOSITION NEED DATE   | 2/7/86             | EXPEDITED DISPOSITION APPROVAL BY |   | DATE                                |                                  |
| FINAL DISPOSITION   | Same as suggested. |                                   |   |                                     |                                  |
| <i>QC - None. HAH 2/6/86</i>  |                    |                                   |   |                                     |                                  |
|   | ECA/ECN            | N/R                               |   | FDI NO.                             | N/R                              |
| JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)   |                    |                                   |   |                                     |                                  |
| I.P. Co. has accomplished this same task previously and nothing to be done is irreversible.   |                    |                                   |   |                                     |                                  |
| DESIGN VERIFICATION STATEMENT   |                    |                                   |   |                                     |                                  |
| The disposition is verified to be adequate by reviewing LH1-5503 Rev. 1, VPF 3238-682-2, and by engineering judgment.   |                    |                                   |   |                                     |                                  |
| APPROVALS   | DATE               | VERIFIED BY                       | J. R. Glazier   | DATE                                | 2/6/86                           |
| <i>K.F. Hammer</i>  | 2/6/86             | DRF NO. 1. APPLICABLE             | :   | THIS EQUIPMENT IS SAFETY RELATED    |                                  |
| QUALITY   |                    | N/R                               | :   | YES X NO                            |                                  |
| N/R   |                    | APPROVALS                         | DATE  | SAFETY FUNCTION IS AFFECTED         |                                  |
| MATL APPL ENGR  |                    |                                   |   | YES NO X                            |                                  |
| N/R   |                    |                                   |   | COMPLETION RECORD : SUPPLIER ACTION |                                  |
| LEAD SYSTEM ENGR  |                    |                                   |   | REQUIRED BY R.E. : REQUIRED         |                                  |
| <i>Bob Fisher for F.F. Smith</i>  | 2/6/86             | DISTRIBUTION CODE                 | :   | YES NO X : YES NO X                 |                                  |
| ENGRG MANAGER   |                    | INTERNAL                          | EXTERNAL  | FIELD WORK ORDER NO.                |                                  |
| G. L. Moore   | 2/6/86             |                                   |   | DISPOSITION COMPLETE                | DATE                             |
| RESPONSIBLE ENGR  |                    |                                   |   | SITE QUALITY CONTROL                |                                  |
| <i>W. Radford</i>   | 2-6-86             |                                   |   | FIELD MANAGER                       |                                  |
| PROJECT MANAGER   |                    |                                   |   |                                     |                                  |



: FDDR No. LHI-5503 :  
: Revision 5/12/4/96 2 :  
: Sheet 2 of 2 :  
: Job No. 8Y275 :  
: WPSS ACTIVITY TYPE R :

```

: Job No.      8Y275      :
: WPSS ACTIVITY TYPE R    :

```

: WPSS ACTIVITY TYPE R \_\_\_\_\_:

[illegible]



|   |               |                       |                                     |                        |
|---|---------------|-----------------------|-------------------------------------|------------------------|
| GENERAL ELECTRIC  | DATE OF ISSUE | ISSUED                | FDDR NO.                            | LH1-5503               |
| FIELD DEVIATION DISPOSITION REQUEST   | FEB 07 1986   | PSE & SI              | REVISION                            | 3                      |
| PROJECT Clinton   | UNIT E22-F011 |                       | SHEET                               | 1 OF 7                 |
| EQUIPMENT (MPL OR DESCRIPTION OR BOTH)  |               |                       | FDDR ORIGINATOR                     | DATE                   |
|   |               |                       | J. T. Cochran                       | 2/7/86                 |
| DOCUMENT NO. : SH NO. : REV : TITLE   |               |                       |                                     |                        |
| VPF 3238-682-2: Fig. 4:   |               |                       |                                     |                        |
| DEVIATION DESCRIPTION   | DTFJK-797     | NCMR 02-0563          | DTF JK684                           | DTF CR 322 NCMR 2-0673 |
| This FDDR supplements LH1-5503 Rev. 0 Rev. 1 and Rev. 2.  |               |                       |                                     |                        |
| (Rev. 0)  |               |                       |                                     |                        |
| Valve E22-F011 has been damaged during test:  |               |                       |                                     |                        |
| a) The integral Stellite back seat in the bonnet is cracked radially and circumferentially, there is evidence of separation from the substrate.   |               |                       |                                     |                        |
| (CONTINUED ON SHEET 2)  |               |                       |                                     |                        |
| SITE QC CONCURRENCE   | DATE 2/7/86   | FIELD CONCURRENCE     | DATE 2-7-86                         |                        |
| X SUGGESTED DISPOSITION   |               | EXPEDITED DISPOSITION |                                     | 5 JRG 2-7-86           |
| For part numbers refer to the reference, (Anchor Darling Dwg. 2999-3 Rev. D), Sheet 4 of this FDDR. The following steps may be performed out of order to effect repairs.  |               |                       |                                     |                        |
| a) IPC to confirm with Anchor Darling that the Bonnet can be repaired in conformance with Code requirements within site scheduling needs.   |               |                       |                                     |                        |
| b) IPC to ship the valve Bonnet (part 2) to Anchor Darling for replacement of the back seat.  |               |                       |                                     |                        |
| Cost: 8Y274 Material: IP Co. to supply (CONTINUED ON SHEET 2)   |               |                       |                                     |                        |
| DISPOSITION NEED DATE 2/7/86 EXPEDITED DISPOSITION APPROVAL BY DATE   |               |                       |                                     |                        |
| FINAL DISPOSITION   |               |                       |                                     |                        |
| Same as suggested disposition.  |               |                       |                                     |                        |
| Quality control is to verify that field work is in compliance with this FDDR.   |               |                       |                                     |                        |
| ECA/ECN EIS FDI NO. N/R   |               |                       |                                     |                        |
| JUSTIFICATION OF DISPOSITION DECISION (SAFETY, RELIABILITY)   |               |                       |                                     |                        |
| Anchor/Darling has designed a recessed drop-in back seat which will be seal welded to the bonnet replacing the damaged integral backseat. The bonnet to insert weld is recessed and will be finished to permit either MT or PT acceptance inspection. Safety and reliability are not affected. The presence of an Anchor Darling representative is non-mandatory, since I.P. has accomplished this same task previously and nothing to be done is irreversible. Use of equivalent parts from the spare Black Fox valve is justified because the valves were made to equivalent purchase specification. (CONTINUED ON SHEET 3) |               |                       |                                     |                        |
| DESIGN VERIFICATION STATEMENT   |               |                       |                                     |                        |
| Rev. 1 Verified based on submitted data as reviewed by C. T. Nieh.  |               |                       |                                     |                        |
| Rev. 2 Verified based on independent review of the disposition described in Rev. 1.   |               |                       |                                     |                        |
| (CONTINUED ON SHEET 3)  |               |                       |                                     |                        |
| VERIFIED BY H. L. Moore DATE 2-7-86   |               |                       |                                     |                        |
| APPROVALS   | DATE          | DRF NO. IF APPLICABLE | THIS EQUIPMENT IS SAFETY RELATED    |                        |
| L. F. Hanner  | 2/7/86        | N/R                   | YES X NO                            |                        |
| QUALITY   |               | APPROVALS             | DATE                                |                        |
| N/R   |               |                       | YES NO X                            |                        |
| MATL APPL ENGR  |               |                       | COMPLETION RECORD : SUPPLIER ACTION |                        |
| N/R   |               |                       | REQUIRED BY R.E. : REQUIRED         |                        |
| LEAD SYSTEM ENGR  |               |                       | YES NO X : YES NO X                 |                        |
| ENGRG MANAGER   | DATE 2/7/86   | DISTRIBUTION CODE     |                                     |                        |
| G. L. Moore   |               | INTERNAL              | EXTERNAL                            |                        |
| RESPONSIBLE ENGR  |               |                       | FIELD WORK ORDER NO.                |                        |
| W. R. Hanner  | 2-7-86        |                       | DISPOSITION COMPLETE DATE           |                        |
| PROJECT MANAGER   |               |                       | SIT QUALITY CONTROL                 |                        |
|   |               |                       | FIELD MANAGER                       |                        |

## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5503 Rev. 3 SHEET 2 OF 7  
PROJECT Clinton I DATE 2/7/86

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F011

## DEVIATION DESCRIPTION: (CONTINUED FROM SHEET 1)

- b) The stem is galled for a length of approximately 1 1/2 inches below the back seat bevel surface.
- c) Field stem hardness measurements of RC 372, Brinell 333 exceed the desired maximum value of Brinell 300.
- d) The disc separated from the stem and the stem retaining rings are lost.
- e) There are scratch marks on the body disc guide surfaces.

(Rev. 1)

Review and approval is requested of Anchor/Darling Drawing 2999-3 Rev. (J) for application to Clinton valve E22-F011.

(Rev. 2)

I.P. Co. has requested that the Anchor Darling Valve Company representative presence be made non-mandatory.

(Rev. 3)

- a) I.P. Co. has requested approval to use packing gland parts and stem clamp parts from the spare "Black Fox" valve, and to install new disc and disc nut.
- b) Actual hardness test data of the new valve stem supplied by I.P. Co. is documented on sheet 4 of this FDDR. Hardness exceeds Brinell 300 in some places.

## SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 1)

- Replacement by use of a seal welded insert is acceptable if Code requirements are maintained.
- c) Replace the valve stem (part 5) with a stem having a Brinell hardness less than 300. (IP Co. to supply)
  - d) Provide replacement Retaining Ring stem (part 63) (IP Co. to supply)
  - e) Provide replacement valve stem packings parts 16 and 16A (IP Co. to supply)
  - f) Provide replacement gasket (part 18). (IP Co. to supply)
  - g) The following items from the spare "Black Fox:" valve are approved for incorporation in the reassembly of E22-F011; stem clamp (Part 25), as modified by FDDR LHI-5570 Rev. 0, gland flange (Part 30), gland (Part 7), gland nuts (part 22), gland bolts (part 21), two keys (stem clamp) (part 25a), and set screws (part 17)
  - h) Anchor-Darling to provide a Code Package update for the repairs which will maintain the code status of the repaired valve. When performing steps h, i, and j seek the guidance of the Anchor Darling Field representative as his availability permits.
  - i) Refurbish the valve body disc guides to blend scratch marks.
  - j) Check the disc seat mating surface and refinish if required in accordance with sheets 4-2 and 4-3 of VPF 3238-682-2.
  - k) Accept the IP Co. - supplied stem as-is. Reassemble the valve using IP Co. supplied disc (Part 4), disc nut (Part 64), and parts from item b, c, d, e, f and g above. Perform reassembly per VPF 3238-682-2 sheets 5-4 and 5-5.

## GENERAL ELECTRIC FIELD DEVIATION DISPOSITION REQUEST

FDDR NO. LHI-5503 Rev. 3 SHEET 3 OF 7  
PROJECT Clinton I DATE 2/7/86

EXPEDITED APPROVAL

EQUIPMENT (DESCRIPTION AND/OR MPL) E22-F011

SUGGESTED DISPOSITION: (CONTINUED FROM SHEET 2)

- 1) Reset limit switches and manually operate the valve to assure that they are properly set. CAUTION: Operation of the valve by means of the motor, without having the switches properly set, can lead to destruction of the back seat. Under close surveillance, operate the valve of the motor operator to assure that the switches are working properly.
- m) Check bonnet and seat leakage, correct any observed leaks.
- n) Assembly code data package to substantiate acceptability of valve repairs.

Anchor/Darling Drawing 2999-3 Rev. (J) depicting a modified bonnet to accept a drop in back seat is approved for valve E22-F011 at Clinton Station, Sheet 6 of this FDDR.

General Electric to incorporate Anchor/Darling Drawing 2999-3 Rev. (J) into the vendor print file for valve E22-F011 at Clinton Station.

JUSTIFICATION: (CONTINUED FROM SHEET 1)

The water-wetted surfaces of the IP Co. - supplied valve stem have hardness less than or just slightly above Brinell 300; this indicates an acceptable condition of heat treat of the stem in the area of concern.



DESIGN VERIFICATION STATEMENT (CONTINUED FROM SHEET 1)

Rev. 3 Verified by review of data submitted by IP Co. (Sheet 4) and by comparison of parts descriptions of VPF 3238-682-2, Fig. 4, with the descriptions of the replacement parts from the Black Fox valve drawing. *o J.L.M. (2-7-86)*

The disposition restores the valve to the condition intended by the original design.

VERIFIED BY *J.I. Moore* Date 2/7/86  
*G.L. Moore*

STEM C-19868 P.O.# X-27375-



FDOR NO. L41-5503 Rev. 3  
SHEET 4 OF 7

| LD VALUE | RC VALUE | BRINELL VALUE |
|----------|----------|---------------|
| 58.2     | 31.6     | 305           |
| 58.0     | 31.3     | 302           |
| 58.6     | 32.1     | 309           |
| 58.8     | 32.4     | 312           |
| 56.8     | 29.7     | 289           |
| 60.4     | 34.8     | 331           |
| 60.0     | 34.2     | 326           |
| 62.5     | 37.7     | 357           |
| 62.2     | 37.3     | 353           |









GENERAL ELECTRIC  
FIELD DEVIATION DISPOSITION  
AFFECTED DOCUMENTS LIST

@ = Documents Transmitted to Document Control Center  
\* = Documents Transferred to S&L for Maintenance

SCHEDULE COMMITMENTS TO MEET ESTABLISHED SOP CYCLE DATES

```

: FDDR No.      LH1-5503      :
: Revision      3              :
: Sheet         7 of 7         :
: Job No.       8Y275-4 JRL   :
: WPSS ACTIVITY TYPE R 2-7-84:

```

[illegible]