

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) St. Lucie Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 3 3 1 5										PAGE 1 1 OF 0 1			
TITLE (4) ISI Snubber Inspection Failures												OTHER FACILITIES INVOLVED (8) FACILITY NAMES NA										DOCKET NUMBER(S) 0 5 0 0 0 0 0 0	
EVENT DATE (5) MONTH DAY YEAR 1 2 1 9 8 5			LER NUMBER (6) YEAR SEQUENTIAL NUMBER REVISION NUMBER 5 0 1 2 0 0 0 1			REPORT DATE (7) MONTH DAY YEAR 2 0 8 6																	
OPERATING MODE (9) 6			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5. (Check one or more of the following) (11)										73.71(b) 73.71(c) OTHER (Specify in Abstract, below and in Text, NRC Form 300A)										
POWER LEVEL (10) 0 0 0 0			20.402(b) 20.405(a)(1)(i) 20.405(a)(1)(ii) 20.405(a)(1)(iii) 20.405(a)(1)(iv) 20.405(a)(1)(v)			20.405(a) 20.36(a)(1) 20.36(a)(2) 20.73(a)(2)(i) 20.73(a)(2)(ii) 20.73(a)(2)(iii) 20.73(a)(2)(iv)			20.73(a)(2)(iv) 20.73(a)(2)(v) 20.73(a)(2)(vi) 20.73(a)(2)(vii)(A) 20.73(a)(2)(vii)(B) 20.73(a)(2)(viii)														
LICENSEE CONTACT FOR THIS LER (12) NAME S.E. Mohn - Technical Staff												TELEPHONE NUMBER AREA CODE 3 0 5 4 6 5 - 3 5 5 0											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE TRIBED IN THIS REPORT (13)																							
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC														
A	X	X	S N B	X X X X	Yes																		
B	X	X	S N B	X X X X	Yes																		
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)		MONTH DAY YEAR 0 2 1 4 8 6											
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input type="checkbox"/> NO													

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

DESCRIPTION OF EVENT:

While the plant was shutdown for a scheduled refueling outage from 10/20/85 to 12/24/85, visual examination and functional testing of snubbers was performed per Tech. Spec. 4.7.10. One hundred percent of the snubbers were tested. Because of the large sample size, a detailed report is being drafted to summarize failures, root causes, and corrective actions. The supplemental report will be submitted by February 14, 1986. See LER 389-34-10 for previous snubber problems.

CAUSE OF EVENT:

The causes of the various snubber failures included design and personnel errors.

ANALYSIS OF EVENT:

This event is considered reportable under several categories due to the various systems affected. Engineering evaluation has indicated that no piping or components have been adversely affected by these failures.

CORRECTIVE ACTIONS:

All defective snubbers were repaired or replaced. Corrective actions for the failure mode root causes will be specified in the supplemental report.

8601230441 860120
PDR ADOCK 05000335
S PDR

IE22
111



JAN 20 1986

L-86-24

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Gentlemen:

Re: Reportable Event 85-12
St. Lucie Unit 1
Date of Event: December 19, 1985
ISI Snubber Inspection Failures

The attached Licensee Event Report is being submitted pursuant to the requirements of 10 CFR to provide notification of the subject event.

Very truly yours,

A handwritten signature in dark ink, appearing to read "C.O. Woody".

C.O. Woody
Group Vice President
Nuclear Energy

COW/PLP/mg
Attachment

cc: Dr. J. Nelson Grace, Region II, USNRC
Harold F. Reis, Esquire
File 933.1

1622
11