

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Brunswick Steam Electric Plant Unit 1														DOCKET NUMBER (2) 0 5 0 0 0 3 2 5										PAGE (3) 1 OF 0 2									
TITLE (4) Inadequate Response Time Testing of Main Steam Line Tunnel Temperature Containment Isolation Instrumentation Logic Circuitry																																	
EVENT DATE (5)				LER NUMBER (6)				REPORT DATE (7)				OTHER FACILITIES INVOLVED (8)																					
MONTH		DAY		YEAR		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER		MONTH		DAY		YEAR		FACILITY NAMES						DOCKET NUMBER(S)									
																		Brunswick Unit 2						0 5 0 0 0 3 2 4									
0 9		0 5		8 5		8 5		0 4		9 0		1 0		0 3		8 5								0 5 0 0 0 3 2 4									
OPERATING MODE (9)				THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																													
5				20.402(b)				20.406(e)				50.73(a)(2)(iv)				73.71(b)																	
POWER LEVEL (10)				20.406(a)(1)(i)				50.38(e)(1)				50.73(a)(2)(v)				73.71(c)																	
0 0 0				20.406(a)(1)(ii)				50.38(e)(2)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)																	
				20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(viii)(A)																					
				20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(ix)																					
				20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)																					
LICENSEE CONTACT FOR THIS LER (12)																																	
NAME																		TELEPHONE NUMBER															
M. J. Pastva, Jr., Regulatory Technician																		AREA CODE		9 1 9						4 5 7 - 2 3 1 5							
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																																	
CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NPDOS				CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO NPDOS													
SUPPLEMENTAL REPORT EXPECTED (14)																		EXPECTED SUBMISSION DATE (15)				MONTH				DAY				YEAR			
YES (If yes, complete EXPECTED SUBMISSION DATE)																		X				NO											

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (18)

On 9-5-85, it was identified plant procedures did not adequately response time test certain relays of the primary containment isolation instrumentation logic. The testing requirement is reflected by Technical Specifications Table 3.3.2-3, Item 1.D. The subject response time tests are for the main steam line tunnel temperature switches (Periodic Test PT-45.2.1) and primary containment isolation (PCI) valves circuit (PT-45.2.6). The untimed logic supports the PCI System exclusively.

The procedural problems apply to Units 1 and 2 and were discovered during a review and rewriting of plant maintenance surveillance procedures. Unit 1 was in a refuel maintenance outage and preparations were underway for startup of Unit 2. The procedural problems are attributed to insufficient technical review during original procedural development.

On 9-7-85, the subject logic circuitry was satisfactorily tested using a plant special procedure. As previously reported in LERs 1-85-020 and 1-85-046, system test descriptions will be developed and implemented by 12-31-85 for response time tests to provide enhanced definition and control of procedural overlap points.

8510090018 851003
PDR ADOCK 05000325
S PDR

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/85


FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Brunswick Steam Electric Plant Unit 1	0 5 0 0 0 3 2 5 8 5	—	0 4 9	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On September 5, 1985, it was identified that plant procedures, to response time test primary containment isolation instrumentation, did not adequately test certain relays in the logic. The main steam line tunnel temperature switch response time test (Periodic Test PT-45.2.1) and the primary containment isolation valves circuitry response time test, PT-45.2.6, did not test steam leak detection relays TR/3A-3D. This testing requirement is reflected by Technical Specification Table 3.3.2-3, Item 1.D. The procedural problems apply to Units 1 and 2 and were discovered during review and rewriting of plant maintenance surveillance procedures. Unit 1 was in a refueling/maintenance outage and preparations were underway for startup of Unit 2.

The subject procedural problems result from insufficient technical review during the original procedure development. On September 7, 1985, the subject logic circuitry was tested via plant Special Procedure SP-85-088 and found to be functioning within technical specification response time requirements on both units. Surveillance tests will be revised and/or generated by October 31, 1985, to require periodic response time testing of the primary containment isolation associated with the main steam line tunnel temperature high trip isolation function on a periodic basis.

The ongoing review and rewriting of plant maintenance surveillance procedures also identified prior similar procedural problems which were reported in LERs 1-85-003, 1-85-020, and 1-85-046. The corrective action to these events is embodied within the Maintenance Surveillance Test (MST) procedure rewrite program, scheduled for completion in 1985. By December 31, 1985, system test descriptions relative to the MST program will also be developed and implemented for plant surveillance test procedures to provide enhanced definition and control of procedural overlap points.



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
October 3, 1985

FILE: B09-13510C
SERIAL: BSEP/85-1746

NRC Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
LICENSEE EVENT REPORT 1-85-049

Gentlemen:

In accordance with Title 10 to the Code of Federal Regulations, the enclosed Licensee Event Report is submitted. This report fulfills the requirement for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-1022, September 1983.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

MJP/mbh

Enclosure

cc: Dr. J. N. Grace

IE22
1/1