



Carolina Power & Light Company
P.O. Box 10429
Southport, NC 28461-0429

MAY 02 1997

SERIAL: BSEP 97-0205

10 CFR 50.73

U. S. Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLANT, UNIT NO. 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
VOLUNTARY LICENSEE EVENT REPORT 1-97-005

Gentlemen:

In accordance with the Code of Federal Regulations, Title 10, Part 50.73, Carolina Power & Light Company submits the enclosed Voluntary Licensee Event Report.

Please refer any questions regarding this submittal to Mr. Keith Jury, Manager - Regulatory Affairs, at (910) 457-2783.

Sincerely,

William Levis
Director — Site Operations
Brunswick Steam Electric Plant

SFT/sft

Enclosure

1. Voluntary Licensee Event Report

IE221

9705090019 970502
PDR ADOCK 05000325
S PDR

080056



pc (with enclosures):

U. S. Nuclear Regulatory Commission
ATTN.: Mr. Luis A. Reyes, Regional Administrator
Atlanta Federal Center
61 Forsyth Street, SW, Suite 23T85
Atlanta, GA 30303

U. S. Nuclear Regulatory Commission
ATTN: Mr. C. A. Patterson, NRC Senior Resident Inspector
8470 River Road
Southport, NC 28461

U. S. Nuclear Regulatory Commission
ATTN.: Mr. David C. Trimble, Jr. (Mail Stop OWFN 14H22)
11555 Rockville Pike
Rockville, MD 20852-2738

The Honorable J. A. Sanford
Chairman - North Carolina Utilities Commission
P.O. Box 29510
Raleigh, NC 27626-0510

NRC FORM 366 (4-95)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB NO. 3150-0104 EXPIRES 04/30/98	
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)					
FACILITY NAME (1) Brunswick Steam Electric Plant, Unit 1				DOCKET NUMBER (2) 05000325	PAGE (3) 1 OF 1
TITLE (4) Feedwater Flow Indication Discrepancy - Voluntary Report					
EVENT DATE (5)			LER NUMBER (6)		REPORT DATE (7)
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER
04	02	97	97	-- 005 --	00
					05 02 97
					OTHER FACILITIES INVOLVED (8)
					FACILITY NAME
					DOCKET NUMBER
					05000
					FACILITY NAME
					DOCKET NUMBER
					05000
OPERATING MODE (9) 1			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)		
			20.2201(b)		20.2203(a)(2)(v)
					50.73(a)(2)(i)
					50.73(a)(2)(viii)
POWER LEVEL (10) 95			20.2203(a)(1)		20.2203(a)(3)(i)
			20.2203(a)(2)(i)		20.2203(a)(3)(ii)
					50.73(a)(2)(ii)
					50.73(a)(2)(iii)
			20.2203(a)(2)(ii)		20.2203(a)(4)
			20.2203(a)(2)(iii)		50.73(a)(2)(iv)
			20.2203(a)(2)(iv)		50.73(a)(2)(v)
					50.73(a)(2)(vi)
					50.73(a)(2)(vii)
					X OTHER
					Specify in Abstract below or in NRC Form 366A
LICENSEE CONTACT FOR THIS LER (12)					
NAME Steve Tabor, Senior Analyst - Licensing				TELEPHONE NUMBER (Include Area Code) (910) 457-2178	
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	
SUPPLEMENTAL REPORT EXPECTED (14)					EXPECTED SUBMISSION DATE (15)
X YES (If yes, complete EXPECTED SUBMISSION DATE).					NO
					MONTH DAY YEAR 07 30 97
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)					
<p>On April 2, 1997, with Unit 1 operating at 95% reactor power, while awaiting implementation of power uprate to 100% reactor power, the results of an ultrasonic flow test (UT) conducted on the Unit 1 Feedwater (FW) system flow venturi indicated that the Unit 1 FW system flow indication was potentially non-conservative by approximately 1.6%. The Unit 1 FW flow instruments were last calibrated in 1994; based upon rubidium tracer testing. The current UT results are inconsistent with the rubidium tracer test results. Based upon the UT results, there is the potential that Unit 1 has operated in excess of rated thermal power limits during past operation.</p> <p>Following validation of the UT report, Unit 1 reactor power was reduced to 93%. Administrative controls were implemented to ensure core thermal power would not exceed 93% until the FW system flow instrumentation could be re-calibrated. On April 7, 1997, the Unit 1 FW flow instrumentation was re-calibrated based on the most conservative feedwater flow test results; the affected nuclear instrumentation was adjusted accordingly.</p> <p>Research into the cause for the discrepancy between the rubidium tracer and UT test results is ongoing. An evaluation is in progress to establish the proper FW flow instrumentation calibration limits based on the most accurate test data. As a result of the discrepancy between the UT and rubidium tracer test results, this issue is being voluntarily reported due to the potential of Unit 1 having operated in excess of rated thermal power limits. A supplement to this LER will be submitted containing the results of the evaluations, including the resultant safety analyses.</p>					