

UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION 1  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 50-29

Yankee Atomic Electric Company  
Attention: Mr. L. E. Minnick  
Vice President  
20 Turnpike Road  
Westboro, Massachusetts 01581

Gentlemen:

The enclosed Directorate of Regulatory Operations Bulletin No. 73-6, "Inadvertent Criticality in a Boiling Water Reactor" has been sent for completion of the requested action to utilities that are presently licensed (or that will be licensed in the near future) to operate boiling water reactors. This bulletin is being sent to you to provide you with information that was reported\* to the AEC by the Vermont Yankee Nuclear Power Corporation, concerning an inadvertent criticality incident that was experienced at their Vermont Yankee facility. This bulletin is provided only for your general information.

Sincerely,

James P. O'Reilly  
Director

Enclosure:  
RO Bulletin No. 73-6

\* Letter dated November 14, 1973, to the Directorate of Licensing, USAEC, Washington, D.C.

cc: Mr. H. A. Autio, Plant Superintendent

bcc: CO Files

— DR Central Files

PDR

Local PDR

NSIC

DTIE

State of Massachusetts

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

OFFICE ▶	CRESS					
SURNAME ▶	O'Reilly/jmr	<i>gmc</i>				
DATE ▶	11/27/73					

November 26, 1973

INADVERTENT CRITICALITY IN A BOILING WATER REACTOR

We recently received an abnormal occurrence report from the Vermont Yankee Nuclear Power Corporation relating to an inadvertent criticality incident that was experienced at their Vermont Yankee facility. A copy of the abnormal occurrence report is attached to this Bulletin to provide you with pertinent details of this event.

At the time of the inadvertent criticality incident, the reactor vessel and primary containment heads were removed, the refueling cavity above the reactor vessel was flooded, control rod friction tests were in progress, the rod worth minimizer was bypassed, and core verification had been in progress. As a result of the incident, no measurable radioactivity was released, no fuel damage resulted and no personnel exposures were experienced. The incident is currently under review and evaluation by the Regulatory Staff.

Action requested by this bulletin is contained in Section A.

A. Action Requested by Licensees

In light of this occurrence, you are requested to take the following actions. Upon completion of these actions you are requested to inform this office in writing, within 45 days of the date of this letter, of the status of each item identified in each paragraph and subparagraph listed below:

1. Procedural Review

a. Control Rod Drive Operating and Testing Procedures

- (1) Conduct a review of your control rod drive operating and testing procedures to determine that approved procedures exist for all operations and tests.
- (2) Verify that appropriate prerequisites are included in the procedures to require testing of associated interlock and protective features before control rod testing is permitted.
- (3) Assure that prerequisites and detailed instructions are provided that demonstrate compliance with technical specification requirements and design bases.

Super H

7911130550



b. Bypass Installation Procedures (Jumpers or Lifting of Leads)

Assure that existing bypass installation procedures have been conservatively reviewed for technical adequacy and for administrative controls.

c. Radiation Protection Procedures

Assure that procedures for access control and personnel accountability in areas subject to accidents are current.

d. Shift Transition Procedure (Turnover)

Assure that complete and detailed procedures are in effect that provide instructions for a proper and conservative turnover of shift responsibilities. Such procedures must include requirements for communicating the status of all safety related equipment and conditions.

2. Management Controls

Assure that your management controls that are in effect provide for qualified technical and administrative reviews and approvals of temporary circuitry changes and temporary off-normal plant conditions. This review should assure that the responsibilities and requirements associated with the review and approval, installation, verification, removal, and subsequent testing of temporary circuitry changes and temporary off-normal plant conditions are clearly delineated in station procedures, are understood by the station staff, and are being properly implemented.

3. Licensed Operator Performance

Assure that management provides the necessary opportunities and time so that operators are adequately trained to carry out their assigned responsibilities. In particular, confirm that shift crew members are provided special training for safety related activities that are infrequent, complex, or have unusual safety significance.

If you have any questions concerning this request, please contact this office.

Attachment:

Vermont Yankee AO No. 73-31 - Letter dated November 14, 1973 to the Directorate of Licensing, USAEC, Washington, D.C.

# VERMONT YANKEE NUCLEAR POWER CORPORATION

SEVENTY SEVEN GROVE STREET

RUTLAND, VERMONT 05701

VYV-3071

REPLY TO:

P. O. BOX 157

VERNON, VERMONT 05554

November 14, 1973

Director  
Directorate of Licensing  
United States Atomic Energy Commission  
Washington, D.C. 20545

REFERENCE: Operating License DPR-28  
Docket No. 50-271  
Abnormal Occurrence No. AO-73-31

Gentlemen:

As defined in Section 6.7.B.1 of the Technical Specifications for the Vermont Yankee Nuclear Power Station, we are reporting the following Abnormal Occurrence as AO-73-31.

On November 7, 1973, at 2101, while the plant was in a shutdown condition and while the required Control Rod Friction testing was being performed on control rod 26-23, a reactor scram occurred initiated by a high-high flux signal from the Intermediate Range Neutron Monitoring System.

An immediate investigation revealed that rod 30-23 was in the fully withdrawn position while rod 26-23 was being withdrawn for its friction test. This situation was a result of inadequate implementation of administrative or procedural controls and constituted a violation of Section 1.A.8 of the Technical Specifications.

Section 14.5.3.2 of the Vermont Yankee FSAR deals with control rod withdrawal errors when the reactor is at power levels below the power range. The most severe case occurs when the reactor is just critical at room temperature and an out-of-sequence rod is continuously withdrawn. The results of these analyses indicate that no fuel damage will occur due to the rod withdrawal.



Directorate of Licensing  
November 14, 1973  
Page 2

The station had been in a planned shutdown condition since September 28, 1973, in order to perform core reconstitution and interconnection of the Advanced Off-Gas System. On November 7, 1973, work had progressed to the point where final core loading had been completed. At that point, it became desirable to perform final core verification concurrent with control rod timing and friction tests. In order to accommodate both requirements, it was necessary to install jumpers to the refuel interlock portion of the Reactor Manual Control System in order to allow traversing of the television camera mounted on the fuel grapple while performing control rod friction and timing tests. Although the intent of installing the jumpers was reasonable and proper, the ensuing implementation of this program went beyond the scope of original intent. The reasons for this were the inadequacy of interdepartmental communications; in addition, certain procedures demonstrated inadequacies, specifically AP 504, Lifted Leads Log, OP 408, Control Rod Drive System. Further, the control rod friction testing was being performed in accordance with a Startup Test Procedure; an approved operating procedure did not exist. The result of the jumper installation was a condition of interlocks which did not prevent withdrawal of more than one control rod at a time. The operating personnel were not adequately informed of the jumpered interlock status; control rod testing was resumed concurrent with core verification. As control rod testing progressed, rod 30-23 was inadvertently left in the fully withdrawn position. After core verification was completed, and since the reactor operator was not cognizant that control rod 30-23 was still withdrawn, an adjacent lateral control rod 26-23 was selected and its continuous withdrawal begun in preparation for the friction test. Between notch position 20 and 26, the operator noticed rapid source range monitor response. He immediately initiated control rod insertion. At this time a full rod scram was initiated by the intermediate range monitor high-high flux signals. It was later demonstrated that control rod 30-23 digital position display was functioning properly. The reactor operator could not explain his failure to observe the indication of control rod 30-23 being fully withdrawn.

The immediate action of the Shift Supervisor on duty was to notify higher plant management and to determine if personnel were on the refueling floor during the incident and to request dosimeter readings of all personnel at that location on the conservative assumption that a criticality may have occurred. Five personnel were on the refueling floor at the time in areas not adjacent to the open vessel. The maximum dosimeter reading of the personnel involved was 25 mR; however, this total was accumulated over a five hour work period and not attributable to this incident alone. It was also verified that the local area monitors, the continuous air monitor on the refueling floor, as well as the Reactor Building Ventilation Exhaust monitors showed no increased level of radiation.

Directorate of Licensing  
November 14, 1973  
Page 3

Following the arrival on site of the Assistant Plant Superintendent and the Reactor Engineer, further evaluation determined that the scope of installed jumpers was beyond the original intent. The jumpers were removed and it was decided to perform a subcriticality test on each of the two involved control rods which verified their proper effectiveness. Based upon the above evaluations, it was determined that no fuel failure had occurred and no radiation problem existed. The installed interlock jumpers were removed and a verification test conducted to determine that the rod block interlock was restored.

On November 8, 1973, consultation with off-site higher management and engineering personnel resulted in the removal of the involved fuel assemblies from the core for sipping and visual inspection. No evidence of leakage or visual degradation was observed. The following is a listing of the assemblies examined and their location:

<u>Assembly Number</u>	<u>Core Location</u>
VT 164*	27-22
VT 171*	29-22
VT 167	27-24
VT 175	29-24
VT 049	31-32

In addition, a two rod critical test was conducted utilizing control rods 30-23 and 26-23. As a result of this test, it was determined that with control rod 30-23 in the fully withdrawn position, criticality was achieved when control rod 26-23 was withdrawn to notch 16.

The film badges assigned to personnel on the refueling floor at the time of the incident were sent out for processing. The results of the badge bearing neutron sensing indicated a total of 50 mr beta-gamma and zero neutron exposure. This total badge exposure was accumulated over a two day work period. The results of the remaining four badges indicated that two badges measured 20 mr beta-gamma and two badges measured 0 mr beta-gamma.

Subsequent calculations by General Electric Co. verified criticality at notch 16 on rod 26-23 with rod 30-23 fully withdrawn. Further calculation by General Electric Co. determined that with rod 30-23 fully withdrawn and rod 26-23 at notch 26, the excess reactivity was 0.67%  $\Delta K$ , and had rod 26-23 been fully withdrawn, the excess reactivity would have been 0.97%  $\Delta K$ .

\* These assemblies were visually inspected.



Directorate of Licensing

November 14, 1973

Page 4

General Electric personnel with recognized competency in the area of core kinetics, and in particular control rod drop accidents, uncontrolled withdrawal incidents, etc., did a qualitative evaluation of what transpired based on the above statistical information. An estimate based upon many previous calculations of a similar nature, was that the bounding results were as follows. The peak fuel center line temperature would have increased no more than 500°F and the peak clad temperature would have increased no more than 50°F from the starting conditions. Therefore, the fuel center line temperature was no higher than 585°F and the peak clad temperature was no higher than 135°F.

Plant management has discussed at length with all involved personnel the significance of this incident and stressed the areas of inadequate personnel performance. Further, a review has been made of the past and present performance of the employees directly involved in this incident. This assessment has determined that these employees are capable, sincere, and conscientious and that every reasonable assurance exists that they are adequately qualified in all respects to continue in their present assigned job responsibilities.

Upon completion of an indepth evaluation of the total incident and the various now apparent inadequacies, it is concluded that no singular outstanding area was predominant.

The Plant Operations Review Committee (PORC), met to review the incident and made the following recommendations and/or conclusions:

1. The original intent of the jumpers was reasonable; however, the final condition obtained was improper and the applied jumpers should have been removed immediately following the completion of core verification.
2. The results obtained from the fuel assemblies sipped and inspected on November 8, 1973, showed no observed indications which would preclude plant startup.

The Plant Operations Review Committee questioned whether adequate sensitivity to sipping still existed considering the elapsed shutdown time and recommended taking two known leakers previously removed during this shutdown and sipping to determine if adequate sensitivity still existed. On November 14, 1973, two fuel assemblies were sipped in an attempt to prove 1131 and 1132 sensitivity. The positive results obtained verify the adequacy of sipping sensitivities observed on November 8, 1973.



Directorate of Licensing  
November 14, 1973  
Page 5

3. Subcritical testing results of the two involved control rods and the management evaluation of the plant condition on November 7, 1973, were deemed sufficient to permit further control rod friction testing following the incident.
4. Administrative Procedure AP 504 "Lifted Lead Log" was not adhered to. Jumper installation was not recorded in the general plant log.
5. All plant procedures relating to control rod movement shall be modified to reflect interlock requirements imposed by the reactor mode switch position.
6. Specific operating procedures addressing control rod friction and settling tests shall be developed.
7. The present AP 504, Lifted Leads Log procedure, is inadequate and a PORC sub-committee has been appointed to review and/or revise the current procedure.
8. Until the above appointed PORC sub-committee performs its task, no installation of jumpers or lifted leads shall be performed on the circuitry associated with the Reactor Protection System, the Primary Containment Isolation System, any ECC System, the Reactor Manual Control System and any refuel interlock until approved by PORC.
9. No further two (2) rod critical testing shall be performed on side by side rods.
10. The following items contributed to the incident:
  - a. A lack of definition on the interfacing of responsibilities on an interdepartmental level.
  - b. Failure by plant supervision to exercise rigorous skepticism relative to abnormal or inadequate plant conditions that are encountered.
  - c. Operator error.


Directorate of Licensing  
November 14, 1973  
Page 6

At the request of the Manager of Operations, the Nuclear Safety Audit and Review Committee met in a special meeting on November 14, 1973, to review the incident. The NSAR returned the following conclusions:

1. No unreviewed safety question was involved.
2. The health and safety of the public and plant personnel was not impaired.
3. There is no undue risk to the health and safety of the public if the plant is started up and operated in accord with the proposed schedule.

Sincerely;

VERMONT YANKEE NUCLEAR POWER CORPORATION



B.W. Riley  
Plant Superintendent

BWR/WFC/kbd