

**North  
Atlantic**

North Atlantic Energy Service Corporation  
P.O. Box 300  
Seabrook, NH 03874  
(603) 474-9521

The Northeast Utilities System

June 27, 1997

Docket No. 50-443  
NYN-97068

United States Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, D.C. 20555

Seabrook Station  
Emergency Diesel Generator Exhaust Inspection

North Atlantic Energy Service Corporation (North Atlantic) has enclosed the inspection data and conclusions for the Emergency Diesel Generator (EDG) Exhaust Inspection conducted during first ten year inspection interval at Seabrook Station. This inspection was conducted on June 24, 1996, followed by Engineering review of the inspection results.

North Atlantic committed, as documented in the Seabrook Station Safety Evaluation Report (SER)<sup>1</sup> Section 9.5.8 to an inspection program for the EDG exhaust system piping and to submit the results of the first inspection to the NRC. The inspections are to ensure that unacceptable wall thinning will not occur during the 40-year design lifetime of the system. The inspection program includes one EDG exhaust system and is initially limited to the area of highest potential corrosion and erosion, the exhaust silencer outlet elbow. Enclosed are the results of the first inspection conducted on the "A" EDG. North Atlantic has concluded that the EDG exhaust elbow is acceptable for continued operation. North Atlantic will perform a second inspection on the EDG by the end of the sixth refueling outage. That outage is scheduled to begin in the first quarter of 1999.

7001  
11

<sup>1</sup> NUREG-0896, "Safety Evaluation Report Related to the Operation of Seabrook Station, Units 1 and 2," March 1983.

9707080192 970627  
PDR ADOCK 05000443  
G PDR


070103



Should you have any questions regarding this response, please contact Mr. Terry L. Harpster, Director of Licensing Services, at (603) 773-7765.

Very truly yours,

NORTH ATLANTIC ENERGY SERVICE CORP.



Ted C. Feigenbaum  
Executive Vice President  
and Chief Nuclear Officer

cc: H. J. Miller, Region I Administrator  
A. W. De Agazio, Sr. Project Manager  
W. T. Olsen, NRC Senior Resident Inspector

ENCLOSURE TO NYN-97068



# ULTRASONIC THICKNESS EXAMINATION REPORT


LOCATION DF-4355 Elbow SYSTEM DF WORK REQUEST 96W 000 966

## EXAMINATION AREA/RESULTS

### DESCRIPTION OF EXAMINATION AREA AND RESULTS

UT exam of outside of elbow from support upper weld to 3 (2") grids above.

### SKETCH (Include obstructions, components, extensions, etc.)



EXAMINED [Signature] LEVEL III DATE 6/24/96

EXAMINED \_\_\_\_\_ LEVEL \_\_\_\_\_ DATE \_\_\_\_\_

### EXAMINATION RESULTS

☐ ACCEPTABLE ☒ EVALUATION REQ'D

REVIEWED \_\_\_\_\_ LEVEL \_\_\_\_\_ DATE \_\_\_\_\_

REVIEWED [Signature] DATE 6/24/96  
Responsible Engineer

## INSTRUMENT DATA

INSTRUMENT: MFG/MODEL KB DM2 GTE/SN 2531

☐ CRT ☒ CRT/DIGITAL ☐ DIGITAL ☐ HORIZONTAL LINEARITY PERFORMED

COMP SURFACE TEMP > 125° ☒ NO ☐ YES FLS No. \_\_\_\_\_ CAL DUE DATE \_\_\_\_\_

### TRANSDUCER

☐ PITCH/CATCH

☒ PULSE/ECHO

MFG. KB  
SER# KBA560/GTE2531  
SIZE .5 FREQ. 5 MHz

CAL BLOCK MATEL	THICKNESS	.300	.500	.800	1.0006	TIME CHECKED
	FLS NO.	6330	6330	6330	6330	
CALIBRATION CHECK	CAL DUE DATE	9/20/98	9/20/98	9/20/98	9/20/98	
	INITIAL	.298	.500	.804	1.008	14:08
	INTERPM	.298	.500	.805	1.008	14:30
	INTERPM					
	FINAL					

### COUPLANT

MFG. UTRage/IL  
BATCH # 092121

## ENGINEERING EVALUATION

☐ N/A ☐ ATTACHED ☐ SEE BELOW

### EVALUATION/COMMENTS

☐ ACCEPT ☐ REPAIR/REPLACE

Responsible Engineer \_\_\_\_\_ Date \_\_\_\_\_

## ULTRASONIC THICKNESS EXAMINATION SKETCH

LOCATION DG-4355 ElbowSYSTEM DGWORK REQUEST 96W000966

N	M	L	K	J	I	H	G	F	
590	603	599	598	799	615	614	623	628	1
588	590	588	590	752	614	609	615	610	2
607	588	600	X	X	X	622	615	612	3
580							604	607	4

Support

N	M	L	K	J	I	H	G	F	
X	40	43	57	42	35	40	23	21	1
X	51	53	55	93	41	46	30	36	2
34	51	41	X	X	X	27	33	33	3
60							42	40	4
PORT									

In N4 at the support weld, the reading was .565 which is a difference of 75 mils from the baseline.  
 Remainder of inspection (rows 5-21) unable to be performed due to welded support interference.  
 Original exam performed on the ID of elbow.



**CONCLUSION:**

The "A" Train DG exhaust elbow is acceptable for continued operation. This conclusion is based on the following rationale:

- The maximum wall loss at location J2 is 0.093" (0.845" to 0.752"). The existing pipe stress analysis, which is documented in Calculation MCD 600.10 considers the elbow at 0.375" thick. Maximum stress levels in the elbow based on 0.375" thickness are 713 psi (Deadweight), 712 psi (OBE) and 1080 psi (SSE). The allowable stress for the elbow material is 17500 psi. Minimum safety factor for ASME Equation (9) based on the elbow being 0.375" is  $(1.2 \cdot 17500) / (713 + 712) = 14.7$ .

To monitor any further wall loss, a second inspection shall be performed by the end of ORO 6 for evaluation.