

# PRECURSOR DESCRIPTION AND DATA

NSIC Accession Number: 90421

Date: April 17, 1974

Title: Auxiliary Feed Pump Suction Strainers Clogged at Point Beach 1

The failure sequence was:

1. With Unit 1 in a cooldown, the "A" motor-driven AFW pump did not provide adequate flow.
2. An in-line suction strainer, of which the operators were unaware, was found to be 95% plugged.
3. A similar strainer, similarly plugged, was found in the suction line of the "B" motor-driven AFW pump.
4. A partially plugged strainer was found in the suction lines of both units turbine-driven pumps.

Corrective action;

1. All the strainers were removed.
2. Other piping systems were examined to determine if other unidentified strainers existed.

Design purpose of failed system or component:

1. The auxiliary feedwater pumps provide water to the steam generators for reactor cooling in the event the main feedwater system is not operable.


Unavailability of system per WASH 1400:\* auxiliary feedwater:  $2.5 \times 10^{-4}$   
(start + 8 hours)

Unavailability of component per WASH 1400:\* strainers, not included  
pumps, failure to run:  $3 \times 10^{-5}/\text{hr.}$

---


\* Unavailabilities are in units of per demand  $D^{-1}$ . Failure rates are in units of per hour  $HR^{-1}$ .

|  |   |  |   |                                       |
|--|---|--|---|---------------------------------------|
| Unit 1 in cooldown<br>Unit 2 status<br>unknown | Motor-driven AFW<br>pump A fails to<br>deliver adequate<br>flow to Unit 1<br>due to clogged<br>suction strainer | Motor-driven AFW<br>pump B suction<br>strainer clogged | Turbine-driven AFW<br>pump suction<br>strainer partially<br>clogged (applicable<br>to both unit turbine-<br>driven pumps) | Potential<br>Severe<br>Core<br>Damage |
|--|---|--|---|---------------------------------------|



NSIC 90421 - Actual Occurrence for Auxiliary Feed Pump Suction Strainers Clogged at Point Beach 1 & 2

| Loss of Main Feedwater | Reactor Trip | Auxiliary Feedwater and Secondary Heat Removal | PORV Demanded | PORV or PORV Isolation Valve Closure | High Pressure Injection | Long Term Core Cooling | Potential Severe Core Damage | Sequence No. |
|------------------------|--------------|--|---------------|--------------------------------------|-------------------------|------------------------|------------------------------|--------------|
|------------------------|--------------|--|---------------|--------------------------------------|-------------------------|------------------------|------------------------------|--------------|



NSIC 90421 - Sequence of Interest for Auxiliary Feed Pump Suction Strainers Clogged at Point Beach 1 & 2

\*Use of HPI following AFW failure not included in mitigation procedures.

CATEGORIZATION OF ACCIDENT SEQUENCE PRECURSORS

NSIC ACCESSION NUMBER: 90421

DATE OF LER: April 17, 1974

DATE OF EVENT: April 7, 1974

SYSTEM INVOLVED: Auxiliary feedwater

COMPONENT INVOLVED: AFW pump strainers

CAUSE: Strainers plugged

SEQUENCE OF INTEREST: Loss of feedwater

ACTUAL OCCURRENCE: Inoperable AFW pumps during plant cooldown.

REACTOR NAME: Point Beach 1

DOCKET NUMBER: 50-266

REACTOR TYPE: PWR

DESIGN ELECTRICAL RATING: 497 MWe

REACTOR AGE: 3.5 yr

VENDOR: Westinghouse

ARCHITECT-ENGINEERS: Bechtel

OPERATORS: Wisconsin Electric Power Co.

LOCATION: 15 miles north of Manitowoc, Wisc.

DURATION: 360(a) hours

PLANT OPERATING CONDITION: Unit 1 in cooldown

SAFETY FEATURE TYPE OF FAILURE: (a) inadequate performance; (b) failed to start;  
(c) made inoperable; (d) \_\_\_\_\_

DISCOVERY METHOD: during operation

COMMENT: The affected AFW pumps provide auxiliary feedwater for both units. Monthly tests failed to reveal strainers because test was run at shutoff head - the only flow was through a 1" ID bypass line & this low flow masked the plugged strainer.