

Sequoyah Nuclear Plant

1B Emergency Diesel Generator Regulatory Conference May 02, 2024

TVA Introductions and Meeting Agenda – Tom Marshall

• Purpose	Tom Marshall, Site Vice President
Background Information	James Hodge, Director of Engineering
 Event and Immediate Actions Timeline 	John Tuite, Director of Maintenance
Timeline Continued	Beth Jenkins, Plant Manager
 Causal Product Results 	Brad Basham, Root Cause Lead
 Root Cause Review and Considerations 	Gary Thompson, Diesel Technical Expert, MPR
Compliance Summary for Performance Deficiency	Rick Medina, Site Licensing Manager
 Probabilistic Risk Evaluation 	Frank Hope, J-H Risk-Informed Engineering Mgr
Closing	Matt Rasmussen, TVA Senior Vice President



- Provide an overview of the event, timeline associated with the event, corrective actions, the root cause analysis and the safety significance of the event.
- Provide Sequoyah's conclusion based on material analysis findings along with third party technical input.
- Provide a detailed summary of the risk factors and inputs for the significance determination of the identified performance deficiency.



Background Information – James Hodge

- Valve lash is controlled through a combination of:
 - Rocker Arm Adjusting Screw
 - Hydraulic lash adjuster
- The hydraulic lash adjusters are incorporated into the tip of the valve bridge assembly that spans across two exhaust valves that interacts with a single rocker arm.





Background Information

• Fig. 1 Global lash - Involves both inboard and outboard exhaust valves, their respective hydraulic lash adjuster assemblies, and is ultimately impacting the whole valve bridge assembly. • Fig. 2 Local lash - Is concentrated on either the inboard or outboard exhaust valves and the respective hydraulic lash adjuster.





Background Information

- Exhaust valve bridge translates the action of a single rocker arm to a pair of exhaust valves.
- Valve bridge spring seat rest in a corresponding semi-spherical seat in the cylinder head.





- Each valve bridge contains two hydraulic lash adjuster assemblies.
- During engine operation the hydraulic lash adjusters receive oil through oil gallies in the bridge assembly.



Event and Immediate Actions Timeline – John Tuite



Timeline Continued – Beth Jenkins



Root Cause Analysis Team Charter – Brad Basham

Root Cause Team Composition

- Team Leader Root Cause SME
- Analyst Corporate Root Cause analyst / SME
- Two Experienced Diesel Generator Engineers
- Experienced Licensing Engineer
- Mechanical Maintenance Supervisor
- Consultant from MPR, Gary Thompson

<u>Approach</u>

- Validate the as found conditions
- Conduct interviews
- Reviewed the previous level 2 evaluation
- Examine the ESI failure analysis
- Perform review of maintenance work practices, maintenance work history and training
- Document all potential equipment failure modes and build failure sequencing
- Conduct extensive OE search
- Then cross examine using metallurgical examination



Root Cause Investigation – Brad Basham

Maintenance Video Walk-through





Root Cause Investigation – Brad Basham

- Failure Scenarios examined as correlated to similar industry Operating Experience:
 - Exhaust valve spring retaining ring failure
 - ANO cracked retaining rings
 - Turkey Point cracked retaining rings
 - Rocker arm set screw loose locknut
 - Davis Besse loose locknut
 - Hydraulic lash adjuster failure
 - Turkey Point lash adjuster failure
- We specifically mapped the loose locknut failure scenario using Industry precedent root cause findings based on the similarity of the ESI conclusion.





Davis Besse OE #219503 vs Sequoyah

• Based on comparison to the Davis Besse OE, the Sequoyah initiating event did not cause excessive global lash.



Fig. 3 Davis Besse Damaged Bridge Stem Spherical Brass Seat



Fig. 4 Sequoyah Event (No Damage to Bridge Stem Spherical Brass Seat)

Event Comparison

Davis Besse Event:

- Tapping noise was heard
- Damage to bridge stem brass seat
- Dislodging of the bridge stem
- Damaged cylinder head socket

Sequoyah Event:

- No noise heard in multiple opportunities
- No Bridge Stem brass seat damage
- Bridge stem not dislodged
- No damage to cylinder head socket



Davis Besse OE #219503 vs Sequoyah



Figure 5 Davis Besse Damaged Bridge Stem Cylinder Head Socket with Brass Shavings from Bridge Stem Seat



Figure 6 Sequoyah Bridge Stem Cylinder Head Socket (No Elongation Damage)



Central Labs Metallurgic Analysis

Valve Bridge



Figure 7 Exhaust Valve Bridge Internals

Metallurgic analysis found a pre-existing
fatigue crack on the plunger spring.

• The exhaust valve spring seats had a highly undesirable microstructure that would have made it more susceptible to fracture.



Material Flaw



Figure 8 Rear Outboard Lash Adjuster Spring

Figure 8

The rear outboard lash adjuster spring was examined in a scanning electron microscope for fractographic analysis.

The fracture has a helicoidal shape that is indicative of fatigue in springs.

A fatigue crack initiation site w as found at the indicated location on the opposite, inside surface of the spring.

Figure 9

A small thumbnail region oriented 45° from the main spring axis w as found on the inside surface of the rear outboard lash adjuster spring.

Fig 9 is a backscattered electron (BSE) image of the fracture.

The contrast mechanism in BSE images is that of atomic number contrast where lighter areas contain elements with higher atomic numbers and vice versa. In effect, the light areas on fracture are the spring material and the dark areas are typically carbonaceous deposits and/or oxides. This fracture surface was sonicated in alcohol to remove any loose deposits on the surface. How ever, oily deposits persisted around the fatigue

initiation site.

This indicates that this fracture has been present for a long period of time, i.e., there is a good likelihood that this fatigue crack predated the fracture event.



Figure 9 Inside Surface of Adjuster Spring



Root Cause Investigation – Brad Basham

LASH ADJUSTER FAILURE SCENARIO

- 1. Lash Adjuster spring cracks
- 2. Lash Adjuster spring fails
- 3. Lash Adjuster Plunger collapses
- 4. Local Lash (gap) forms between exhaust valve stem and lash adjuster
- 5. Hammering effect on valve stem and valve bridge assembly
- 6. The magnitude of the vibrations and impact forces increases as the local lash increases. Excess vibrations and impact forces on the following:
 - i. Exhaustvalve
 - ii. Rocker arm adjusting screw
 - iii. Lash adjuster
 - iv. Rocking force on valve bridge stem
- 7. Global Lash (gap) forms between bridge assembly and rocker arm adjusting screw (after the locknut loosens sufficiently)
- 8. Retaining Ring failure, dropped exhaust valve, exhaust valve bridge stem fracture, inboard lash adjuster fails, etc





Diesel Failure Expert Perspective – Gary Thompson (MPR)

TVA engaged MPR Associates to provide technical support for the SQN RCA effort. Support was provided by Dr. Gary Thompson and other MPR engineers.

Scope of MPR Support

- Provide direct support to SQN RCA team (e.g., perform visual inspections, discuss key observations)
- Perform a separate, comprehensive review of relevant information identify root and contributing cause based on support-refute matrix (11 potential causes considered)

<u>Conclusions</u>

- · Most probable cause is lash adjuster failure due to fatigue fracture of internal spring
- Lash adjustment screw locknut loosening was a consequence
- Based on ...
 - Central Labs evidence of spring fatigue fracture
 - Dissimilarity between SQN and Davis-Besse failures
 - Asymmetry of SQN failure damage
 - Same TVA team used for all lash adjustments; all other locknuts > 80 ft-lbf after failure
 - Number of starts and operating hours between lash adjustment and failure
 - Lack of audible noise prior to failure event (was prominent during Davis-Besse event)
 - · Potential for locknut loosening following valvetrain component failure



Valvetrain Operating Loads Assessment

Conclusions

- · Lash adjuster failure results in significant vibrational loading of valvetrain components
 - · Lash adjustment screw and locknut subjected to increased axial loading and additional lateral loading
 - Loads are significant in magnitude and occur at relatively high frequency (900 rpm or 15 Hz)
- Threaded fasteners are susceptible to self-loosening due to vibration, in particular from lateral loading
- Locknut @ 80 ft-lbf adequate adjustment screw preload (normal conditions); marginal preload (w/ failed lash adjuster)
- · Locknut loosening as a consequence of a lash adjuster failure is plausible and should be expected



Self-Loosening from Vibration

Vibrational self-loosening of threaded fasteners is well-documented in technical literature

- G. Junker performed pioneering research in late 1960s*; subject of numerous subsequent studies
- · Junker vibration test developed machine for studying phenomenon and testing effectiveness of solutions

	880065
	New Criteria for Self-Lourseine
	of Easteness Hade to a
	or Pasteners Under Vibration
	Serbert K. Junter
	Review Rear and Departure
	A 198228 TBT solided out appendix over solide 1 parties: compare all consening of Bander Selecters. No Sen- te appendixes conditions of effective Bar are set any output, affect at replanation for participants and participants.
	to be and be and the state of t
	er breite is nacht is stellte of breite ite bertig sel site inter affere if is corpel of dealing
New Criteria for Self-Loosenin	Be within it forge follow, will recently it for more . It into four of an and part thread of all and the second se
there enterna for Self E00Selfill	This say to fit much fu do unbertown thereas in for antice unit to portion and ad instanting for 5. No This say to fit much fu do unbertown the same and the sam
of Fasteners Under Vibratio	appert is prove all country of devoted balance with incide operated in price her order
	manifest server himsen to control of the impaction distance. No pass, "Antipactor of the Westmann of the services provide the impact of the im
	that there have been new approach. To be sen, much the pi-th, present the from the been been been provided to be the probability in respirate the probability of the
	then have these district a summaries descences. counting have an end of the summary in section with the summaries descences with the barriers and the summary of the summar
Gerhard H Junke	indicated by a first september is denote of only and the set over a set of a set over a set of a set over a se
Gernard II. Julike	Souther and Accesses (1)," as well as house, to make a first a south of the souther of a first and the souther of the souther
	and type (b), but the prin of the biller to down 1 and to be to be a part down to a final to be a set of the s
	Be includes of all dealers. He wanted of the second
SAE Transaction	Number & Josephere Sergers and August a
Vol 70 Continue de D	M**
Vol. 78, Section 1: Papers 690001_60012	AND DOLLARS AND ADDRESS AND ADDRESS ADDRES
apers 050001-05015	The design of well constants & document. The Appli- in an in the state of the out of some of some of species in the
(1969) nn 314.32	tion the statements are used at the part for parts which we have
Dublished (1909), pp. 314-33	and about processing of the state of the sta

Junker, G.H. Video Click Here



* Junker, G.H., New Criteria for Self-Loosening of Fasteners Under Vibration, SAE Trans 78, 314-355 (1969).

Compliance Summary – Rick Medina

No LER Submitted

- When the event occurred, Sequoyah entered our Past Operability Evaluation process.
 - In accordance with NRC NUREG-1022

"For the purpose of evaluating the reportability of a discrepancy found during surveillance testing that is required by the TS, licensees should do the following:

For testing that is conducted within the required time, **it should be assumed that the discrepancy occurred at the time of its discovery unless there is firm evidence**, based on a review of relevant information such as the equipment history and the cause of failure, to indicate that the discrepancy existed previously."

•Time of Discovery was September 19, 2023. It is not conclusive, and no firm evidence exists that the failure was attributed to Preventive Maintenance activities completed in January 2023 which performed checks and inspections on diesel generator 1B.

•The station remained in process and had no condition prohibited by Tech Spec or met any other conditions to report under §50.73, therefore, was not required to submit a Licensee Event Report (LER).



Compliance Summary

Performance Deficiency Summary

- It is Sequoyah's conclusion that the 1B diesel generator failure occurred on September 19th and the engine was operable until that date.
- Based on the contrast in thoroughness and technical justification, it is more reasonable to conclude the cause of the 1B diesel cylinder failure was due to an equipment failure and therefore not a performance deficiency.
- A Self-Revealed AV of TS 5.4.1, "Procedures," was identified. The licensee's procedures for maintenance on the 1B diesel generator were not adequately prescribed and/or accomplished in accordance with documented instructions and procedures of a type appropriate to the circumstances.
- Sequoyah Procedure MMTP-104 requires that in part "If no torque value can be determined for the specific application, Engineering is to provide specific written guidance or design output for tightening requirements".
- The significance of the procedure violation is consistent with NRC Inspection Manual Chapter 0612 App E Example 4.m.
 - Example 4.m states: The PD did not adversely affect the mitigating systems cornerstone objective because the inadequate procedure would not have resulted in equipment damage. Specifically, although not required by the procedure, maintenance worker training would have the worker set the torque switch to the prior setting.
- Sequoyah's RCE was completed and delivered one week after the NRC's SERP. We respectfully request that you consider our conclusion and results of the causal analysis, restoring compliance, and ensuring our continued safe operations.



PRA Analysis

- SQN uses RG 1.200 PRA Model for FPIE, Flood, Fire & Seismic Hazards
- Includes Level 2 Model Based on NUREG/CR-6595
- Approved for 10 CFR 50.69 (ML22334A073)
- Approved for RMTS (ML22210A118 & ML15236A351)
- No Open Peer Review Findings
- RASP Handbook Methodology Used to Evaluate Risk Associated with DG 1B Failure



PRA Analysis

- SQN PRA Model Uses Static Event Trees to Evaluate Event Progression which Assume Run Failures During Mission Time Occur at t = 0 hour
- NRC RASP Methodology Assumes Variable 1B-B Diesel Run Capability During Exposure Time that Does Not Easily Fit into t = 0 hour Run Failure Assumption





PRA - Model Adjustments

Model Updates were Performed Consistent with ASME/ANS RA-Sa-2009 to Accommodate Variable Diesel Run Failure Timing and Increase Realism:

- High Pressure Fire Protection Credit for Steam Generator Feed
- Full Circuit Analysis for Permanently Installed 3MW FLEX Diesel Generators to Allow Credit in Additional Fire Areas
- RCP Seal LOCA Adjustment for Time Dependent Late EDG Failures
- Main Control Room Abandonment Adjustment for Late EDG Failures
- LERF Adjustment to Classify Late SBO Sequences As Non-Early Release
- Turbine Building Fire Modeling Refinement to Split Turbine-Generator Fire Scenarios into Catastrophic vs. Non-Catastrophic
- Model Updates Supported by Operations Interviews and MAAP Analysis



PRA – Model Conservatisms

- No Credit for FLEX High, Intermediate and Low Pressure Pumps
- FLEX 6.9kV and High Pressure Fire Protection Not Credited for Sequences with Assumed Immediate SBO Conditions
- These Conservatisms Significantly Affect the Results if RASP Handbook CCF Adjustment for Failure to Run During 24 hour Mission Time is Conservatively Applied at Time Zero (i.e., increased probability of all diesels start but failing to run applied at t = 0 hr due to same cause)
- Qualitative/Quantitative Consideration for FLEX/Fire Water Strategies Can Be Applied to Show Significance Determination Not Affected by CCF Adjustments Even if Conservative Diesel Failure Timing Assumptions are Applied



BDB Strategy Considerations

SQN Beyond Design Basis Strategies More Robust than Industry Norms

- Two Installed 3MW 6.9kV FLEX DGs
- Either DG Can Support PRA Loads
- NEI 12-06 Timeline ~3 hr 30 min to Energize 6.9kV Shutdown Board
- Accelerated "Non-ELAP" Deployment if TDAFW fails; ~2 hr 20 min in Tabletop Exercise from SBO initiation
- SQN Uses INL DG Failure Data for FLEX Generators (FTS/FTL/FTR)
- Data Treatment Accepted by NRC for RICT (ML22118A496, ML22210A118)





BDB Strategy Considerations

- High Pressure Fire Protection Has
 Permanent Connection to AFW
- Strategy Applicable to ECA-0.0 and FR-H.1
- Quick Deployment ~1 hr 50 min Following LOOP Initiator





BDB Strategy Considerations

	AFW	RCP Seal Leakage	RCS	Core Damage	3MW FLEX	Fire Water
MAAP Run*	Available	(per RCP)	Cooldown	Time	Deployment Time	Deployment Time
SBO-02	Yes	21 gpm	No	> Mission Time	N/A	N/A
SBO-07	Yes	182 gpm	No	6.43 hr	3.50 hr	N/A
SBO-12	Yes	480 gpm	No	2.52 hr	3.50 hr	N/A
SBO-11	Yes	480 gpm	Yes	5.05 hr	3.50 hr	N/A
SBO-05	Fails at 4 Hrs	21 gpm	No	6.51 hr	3.50 hr	5.83 hr
SBO-09	Fails at 4 Hrs	182 gpm	No	5.65 hr	3.50 hr	N/A
SBO-05	No	21 gpm	No	2.66 hr	2.33 hr	1.83 hr
SBO-10	No	182 gpm	No	2.43 hr	2.33 hr	N/A

*SQN Calculation MDN-000-999-2010-0221

- 3MW FLEX DG 3.5 hr Deployment Supports RCP Seal LOCA Mitigation
- Accelerated FLEX DG Deployment for Non-ELAP Procedure Path Results in Power Available Prior to Core Damage for Early TDAFW Failure Sequences
- Fire Water Credit for SG Feed Also Feasible to Mitigate AFW/FLEX Failures
- Insights Also Apply to Hydrogen Igniters for Level 2 Application



Conditional CCF Adjustment

TVA Risk Results Based on No CCF Adjustment Because Section 5.0 of RASP Handbook is Not Appropriate for Fatigue Related Material Failures

Sensitivity Performed Using Alpha Factor Method from RASP Handbook

- Timing of Maintenance Related Run Failures Can't Be Predicted
- Maintenance Related Run Failures Occurring at Same Time is Not Realistic
- Run Failures with Maintenance Related Proximate Cause Can Be Assumed to Occur with Uniform Distribution Throughout Surveillance Frequency
- Run Failures with Maintenance Related Proximate Cause Can Be Assumed to Occur with Uniform Distribution Throughout PRA Mission Time
- INL SPAR Data Framework DG Run CCF Failure (EPS-EDG-FR) Requires At Minimum Successful Start, Load and One Hour Run of the DGs



Sensitivity Analysis for Conditional CCF Adjustment

Sensitivity #1 NUREG/CR-6268 Timing Factors for Multiple Failures High (1.0) Failures Separated by No More Than the PRA Mission Time Medium (0.5) Failures Separated by 1-2 PRA Mission Times Low (0.1) Failures Separated by 2-3 PRA Mission Times Not CCF (0.0) Failures Separated by >3 times the PRA Mission Time

Sensitivity #2 PM Frequency Weighting Factor for Multiple Failures CCF Multiplier Using Ratio of Exposure Time to PM Interval (4 year assumed) Applied to All Common Cause Failure Groups

Sensitivities Do Not Include Quantitative Credit for FLEX/Fire Water to Mitigate Time Zero Common Cause Failure of All Diesels to Run 24 Hours.

Early/Late Model Refinements Can Also Be Applied if CCF Events are Broken Up into Different Timing Bins Over the Mission Time.

Sensitivity Analysis for Conditional CCF Adjustment





PRA Results and Conclusion

- Combined internal events, internal flood, seismic PRA risk, and fire risk analysis results including the supplemental information for the identified deficiency and calculated exposure time:
 - ΔCDF calculated to be 5.14E-06/yr (Unit 1) and 9.31E-07/yr (Unit 2)
 - ΔLERF calculated to be 4.08E-07/yr (Unit 1) and 9.53E-08/yr (Unit 2)
- Results are well below the Yellow risk threshold of 1E-5/yr (ΔCDF) and 1E-6/yr (ΔLERF) for Unit 1.
- Results are below the White risk threshold of 1E-6/yr (ΔCDF) and 1E-7/yr (ΔLERF) for Unit 2.





Closing – Matt Rasmussen

- Impactful Event for the Sequoyah Nuclear Station and the TVA Fleet
 - Lessons Learned
 - Corrective Actions
- Summary of TVA's position
 - An independent failure analysis provided technical justification for a most likely cause of the Diesel Generator failure.
 - It is Sequoyah's conclusion that the 1B diesel generator failure was due to a material flaw, and we did not have reasonable ability to foresee and prevent this event.
 - Based on our PRA insights and review of conservatisms, the significance of the event would be White on Unit 1 and Green on Unit 2.



