NRC FORM 366 (12-81)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011 EXPIRES 4-30-82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | N C M G S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)

LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 6 9 (7) | 0 8 1 3 8 2 (8) | 0 9 1 0 8 2 (9)

DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in mode 1, during performance of the "Aux. Feedwater Low Suction Function-
03 al Test" two Aux. Feedwater Pump Turbine (AFPT)low suction pressure switches
04 failed to perform properly and were declared inoperable. This violates T.S.3.3.2
05 which is reportable per T.S.6.9.1.13(c). A review of work requests on 8/26/82
06 discovered that the switches had been incorrectly calibrated when corrective
07 action was performed for the 8/13/82 failure, and the switches were again de-
08 clared inoperable. Since at no time did a loss of the assured water supply to the
AFPT occurred health and safety of the public were unaffected.

09 | SYSTEM CODE I B (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE I N S T R U (14) | COMP. SUBCODE S (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 8 2 — SEQUENTIAL REPORT NO. 0 6 7 / OCCURRENCE CODE 0 3 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN E (18) | FUTURE ACTION H (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0 0 0 0 (22) | ATTACHMENT SUBMITTED Y (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER L (25) | COMPONENT MANUFACTURER U 0 7 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The switches (United Electric Type J302) were found out of calibration (on 8/13/
11 82), possibly due to instrument drift or misadjustment. The incorrect adjustment
12 during corrective action on the 8/13/82 failure was due to personnel error attri-
13 butable to a lack of training in the use of setpoints obtained from the Mechani-
14 cal Instrument List. The switches were recalibrated and declared operable. Appro-
priate training will be given, and methods of obtaining setpoints reviewed.

15 | FACILITY STATUS B (28) | % POWER 0 5 0 (29) | OTHER STATUS (30) N/A | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Periodic Testing

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) N/A | LOCATION OF RELEASE (36) N/A

17 | PERSONNEL EXPOSURES NUMBER 0 0 0 (37) | TYPE Z (38) | DESCRIPTION (39) N/A

18 | PERSONNEL INJURIES NUMBER 0 0 0 (40) | DESCRIPTION (41) N/A

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) N/A

8209210147

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) N/A | NRC USE ONLY

NAME OF PREPARER Phillip B. Nardoci PHONE: (704) 373-7432