NRC FORM 366 (12-81) 10 CFR 50

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

APPROVED BY OMB 3150-0011

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | P A S E S 1 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | (5)
LICENSEE CODE (7–14) LICENSE NUMBER (15–25) LICENSE TYPE (26–30) CAT (57–58)

CON'T

01 | REPORT SOURCE L (6) | 0 5 0 0 0 3 8 7 (7) | 0 2 1 9 8 3 (8) | 0 3 1 0 8 3 (9)
(8) (60) DOCKET NUMBER (61–68) EVENT DATE (69–74) REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Condition 4, during a ten-day outage, an I&C Technician performing a
03 quarterly calibration surveillance (SI-83-320) on PSH-B21-N056 B and C (Low
04 Condenser Vacuum pressure switches - channel B and C) found the devices to not
05 meet the Technical Specification allowable value. The pressure switches are
06 part of the MSIV isolation circuitry. There were no consequential effects on
07 the public health and safety. The redundant switches were operable and isola-
08 tion capability on this trip function was maintained.

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
09	S D (11)	E (12)	E (13)	I N S T R U (14)	S (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 3	—	0 2 7	/	0 3	L	—	0
	(21–22)	(23)	(24–26)	(27)	(28–29)	(30)	(31)	(32)

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER (26)
E (18)	X (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	B 0 6 9
(33)	(34)	(35)	(36)	(37–40)	(41)	(42)	(43)	(44–47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The switches failed to meet acceptance criteria due to setpoint drift. The
11 switches were recalibrated. This event is considered an isolated incident.
12 This type of instrument (Barksdale Model DLT-H18SS) has not shown setpoint
13 drift problems in the past. At the next quarterly calibration, the instruments
14 will be checked for drift.

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15	G (28)	0 0 0 (29)	n/a	B (31)	surveillance testing

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
16	Z (33)	Z (34)	n/a	n/a

	PERSONNEL EXPOSURES NUMBER	TYPE	DESCRIPTION (39)
17	0 0 0 (37)	Z (38)	n/a

	PERSONNEL INJURIES NUMBER	DESCRIPTION (41)
18	0 0 0 (40)	n/a

	LOSS OF OR DAMAGE TO FACILITY TYPE	DESCRIPTION (43)
19	Z (42)	n/a

	PUBLICITY ISSUED	DESCRIPTION (45)	NRC USE ONLY
20	N (44)	n/a	

8303240523 830310
PDR ADOCK 05000387
S PDR

Jon T. Todd

PHONE: (717)542-2181 X3524