

2/18/00

Tabern of IP2 (Cameron) ^(?)

Water found for MSL on night of event.
Will file a "condition report"

Open & inspected MSIV to investigate.

More leakage during hydro than during the event.

Calculated P-S loss for event.

John Ventura is looking at this for IP2

2/22

John McLean

John Ventura 914-734-5224

SG 24 hydro


24 MSIV majority (disk was inch off seat)
bypass valve (double disk) - non-preferred
direction

Event - water in headers

Loss than 10mils average around seat & between
7-8 mgs was measured at front
circumference in

Pressure above 200 psi stopped leakage.

MS-1-24 DISC TO SEAT CLEARANCES IN INCHES



~ 14 in² opening



DATE: 4/19/00 NO. OF PAGES: 3

(INCLUDING THIS PAGE)

TO: Steve Long FAX: 301-415-3577

FROM: Matt Walther FAX: (914) 739-8098

SUBJECT: _____

