

OC 211

June 4, 1979

M. Plesset Chairman
Oyster Creek Subcommittee

OYSTER CREEK ECCS ANALYSIS

In a May 29, 1979 memo to you, I reported that the Exxon Oyster Creek ECCS analysis had not considered plant operation with less than 5 recirculation pumps in service. However, I erroneously stated that this event was reported as an abnormal occurrence. The event was reported as an licensee event report.

Paul Boehnert
Reactor Engineer

cc: ACRS Members
M. W. Libarkin
T. G. McCreless

C/14
Oyster Creek

OFFICE	du:PB					
SURNAME						
DATE						