

PSL Summary/Status					
LAR Number	Unit	Submittal Date	Exp Issue Date/Outage	Description	Next Action
2001-017	2	T 2/19/03	SL2-14	UNIT 2 ISI R/R 34 NON-CODE REPAIR OF THE 2A AND 2B ICW PUMP DISCHARGE HEADERS ASME CLASS 3 ICW SYSTEM PIPING LINES. NRC COMMITMENT TO RPR/REPL AFFECTED PIPING DURING SL2-14. RAI	ENG-MECH
2003-002	1/2	T 2/28/03	SL2-14 SL1-19	U1/2 ISI R/R 24/36 ALTERNATE TO UT QUALIFICATION INSPECTION, FOR DISSIMILAR METAL PIPING WELDS. INDUSTRY ISSUE.	ENG-CSI
2002-006	2	T 3/3/03	SL2-14	REDUCE TECH SPEC MINIMUM RCS FLOW TO ACCOMMODATE 15% S/G TUBE PLUGGING - RAI.	ENG-FUELS
2001-020 SUPP	1/2	T 4/1/03	SL2-14	ISI PLAN - CONTINGENCY R/R 20, 21, 30, 31 OUTAGE RX HEAD RPR SUPP W/WELD PROC QUALS - RAI.	ENG-CSI

*** LICENSING ***

(cont'd)

LICENSEE EVENT REPORT STATUS:

UNIT 1:

LER Number	Rev	Due Date	Description
03-001	0	4/4/03	U1 CREACS IN-LEAKAGE

CR
Number
03-0319

UNIT 2:

NONE

*** PROTECTION SERVICES ***

NAME: NWhiting

DATE/TIME: 02/12/2003

ENVIRONMENTAL COMPLIANCE STATUS:SITE

A diseased loggerhead turtle removed from the intake canal was sent to rehab 2/12. Not causal to plant operation. All notifications made as necessary.

Less than 25 gallons of diesel fuel was spilled on the pavement in the back yard during a pump down of the Unit 1 Diesel Sump on peak shift 2/12.. Not reportable. Spill cleaned up by MM.

*** SECURITY ***

NAME: B. Boskey

DATE/TIME: 02/13/2003

B/62