

June 25, 2003

From: Mahesh Chawla
To: Joseph.bauer@exeloncorp.com
Date: 6/20/03 4:39PM
Subject: 2002 SG Inspection Report for Braidwood Unit 2

In reference to the above report, the staff would like to discuss with the following questions. Please review these and let me know your availability to have a telephone conversation. Please call me if you have any questions/comments at (301) 415-8371.

1) A visual inspection of the secondary side tubesheet region was conducted in each of the four steam generators during the 2002 outage. Please discuss the results of this inspection. This discussion should address whether any loose parts were identified, the source of any loose parts, the effect the parts had on any tubes, and a discussion of whether the loose parts were removed from the steam generator.

2) If the parts were not removed, please discuss any tube integrity implications.

CC: Gregory Makar; Louise Lund

Mail Envelope Properties

(3EF37105.12A : 15 : 21352)

Subject: 2002 SG Inspection Report for Braidwood Unit 2
Creation Date: 6/20/03 4:39PM
From: Mahesh Chawla
Created By: MLC@nrc.gov

Recipients	Action	Date & Time
exeloncorp.com	Transferred	06/20/03 04:39PM
Joseph.bauer (Joseph.bauer@exeloncorp.com)		
nrc.gov		
owf2_po.OWFN_DO	Delivered	06/20/03 04:39PM
GLM CC (Gregory Makar)	Opened	06/23/03 07:08AM
LXL CC (Louise Lund)	Opened	06/20/03 04:39PM
Post Office	Delivered	Route
owf2_po.OWFN_DO	06/20/03 04:39PM	exeloncorp.com nrc.gov
Files	Size	Date & Time
MESSAGE	1371	06/20/03 04:39PM

Options

Auto Delete:	No
Expiration Date:	None
Notify Recipients:	Yes
Priority:	Standard
Reply Requested:	No
Return Notification:	None
Concealed Subject:	No
Security:	Standard
To Be Delivered:	Immediate
Status Tracking:	Delivered & Opened