



TXU Energy
Comanche Peak Steam
Electric Station
P.O. Box 1002 (E01)
Glen Rose, TX 76043
Tel: 254 897 8920
Fax: 254 897 6652
lance.terry@txu.com

C. Lance Terry
Senior Vice President &
Principal Nuclear Officer

Ref: TDLR Boiler

CPSES-200302012
Log # TXX-03172
File # 10010.1

September 26, 2003

Mr. Terry Parks
Chief Inspector
Texas Department of Licensing and Regulation
Boiler Division
E. O. Thompson State Office Building
P. O. Box 12157, Capitol Station
Austin, Texas 78701

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-446 AND 50-445
TRANSMITTAL OF INSPECTION REPORT AND FEE FOR
BOILER NO. 150536

Enclosed is the Inspection Report (Form R-1) for CPSES Boiler No. 150536 and the corresponding fee to renew the certificate for operations.

Additionally a memo from the Site ANI is being enclosed, which describes the extent of repairs made to the subject boiler prior to the inspection. A copy of this letter is also being forwarded to the U. S. Nuclear Regulatory Commission, Attention: Document Control Desk.

IE01

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

TXX-03172
Page 2 of 2


Should you need additional copies or require additional information, please contact
Obaid Bhatti at (254) 897-5839.

Sincerely,

TXU Generation Company LP

By: TXU Generation Management Company LLC
Its General Partner

C. L. Terry
Senior Vice President and Principal Nuclear Officer

By: 
Fred W. Madden
Nuclear Licensing Manager

OAB/jch

Enclosures

cc: NRC, Attn: Document Control Desk
B. S. Mallett, Region IV
W. D. Johnson, Region IV
M. C. Thadani, NRR
Resident Inspectors, CPSES
J. C. Hair, ANII (CPSES)

September 8, 2003


Mr. Terry Parks
Chief Inspector
TDLR
P. O. Box 12157
Austin, TX. 78711

SUBJECT: Boiler # 150536

Dear Mr. Parks:

This letter is to accompany Inspection Report for the subject boiler. The boiler was last inspected on 25 February 2002. Boiler was then being prepared for an external inspection under operating conditions when TXU Electric personnel discovered external corrosion in the outer casing of the boiler. Smart Form 2002 - 00725 was generated to address the condition. Repairs have since been made to subject boiler and a Form R-1 completed for a routine repair by Fluor Corporation. No welding on the boiler pressure boundary was required. Boiler is in proper condition and has been inspected in accordance with the Texas Boiler law.

Sincerely,

A handwritten signature in cursive script that reads "Joe C. Hair".

Joe C. Hair
Inspection Specialist
HSBCT

INSP ORDER CD