

SAFETY LIGHT CORPORATION

4150-A OLD BERWICK ROAD, BLOOMSBURG, PA 17815
717-784-4344 TWX 510-655-2634

17 October 1983

U.S. Nuclear Regulatory Commission
Region I
631 Park Ave.
King of Prussia, PA 19406

ATTN: Mr. Thomas T. Martin, Director
Division of Engineering and Technical Programing.

RE: Docket Nos. 30-5980 License Nos. 37-00030-02
 30-5982 37-00030-08

Dear Sir:

With respect to your letter of 22 September 1983, please be advised as follows:

1. Notice Of Violation (Page 1, 3rd Paragraph):

- a. Corrective steps taken and results achieved - Subsequent to the 9 March 1983 Exit Interview, prompt action was taken by Health and Safety personnel to review and reallocate certain job priorities. As a result, a steady improvement in the situation was noted thereafter.
- b. Corrective steps which will be taken to avoid further violations - A chart type record system has been established to show, at a glance, the smear test survey situation in any one of the areas involved. Examination of the charts shows a steady improvement in the situation since March 1983.
- c. Full compliance in all areas was achieved by 31 August 1983.

2. Soil Stabilization (Page 1, 4th Paragraph):

During the latter part of March 1983, the exposed surfaces of the contaminated soil mound were seeded heavily with 'shade type' grass seed. Because of the subsequent growth of grass, plus weeds and brush, stabilization of the soil against wash-off by heavy rains, etc., appears to have been achieved.

/ . . . continued

SAFETY LIGHT CORPORATION

U.S. Nuclear Regulatory Commission
Mr. Thomas T. Martin
17 October 1983
Page 2

3. Change of Ownership, etc. (Page 1, 5th Paragraph):

A separate letter, covering the various items listed, will be forwarded to the U.S. NRC in Washington, D.C. within 30 days of the date of this letter.

Yours very truly,
SAFETY LIGHT CORPORATION


Jack Miller
President

JTM:cwl