



NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Jacobi Geotechnical Engineering 798 Hoff Rd 01 Fallon, Mo 63366 REPORT 2005001		2. NRC/REGIONAL OFFICE US NRC Reg III 2443 Warnerville Rd Suite 210 Lisle, IL 60532	
3. DOCKET NUMBER(S) 03035293	4. LICENSEE NUMBER(S) 24-32231-01	5. DATE(S) OF INSPECTION Sep 28, 2005	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<div style="display: flex; flex-direction: column;"> <div style="margin-bottom: 10px;"> <input checked="" type="checkbox"/> 1. Based on the inspection findings, no violations were identified. </div> <div style="margin-bottom: 10px;"> <input type="checkbox"/> 2. Previous violation(s) closed. </div> <div style="margin-bottom: 10px;"> <input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. </div> <div style="margin-bottom: 10px;"> _____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): </div> <div style="margin-bottom: 10px;"> <input type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. </div> <div> (Violations and Corrective Actions) </div> </div>			
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title LICENSEE'S REPRESENTATIVE	Printed Name G. Parker	Signature 	Date Sep 28, 2005
NRC INSPECTOR			Sep 28, 2005

NRC FORM 591M PART 1 (10-2003)

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Jacobi Geotechnical Engr REPORT NUMBER(S) 2005-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35293	4. LICENSE NUMBER(S) 24-32231-01	5. DATE(S) OF INSPECTION Sept 28, 2005	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT James Pyatt	4. TELEPHONE NUMBER 636/978-7112
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 9/10	
<input type="checkbox"/> Field Office			
<input checked="" type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee is an engineering firm located in O'Fallon, Missouri. They perform soil density and compaction testing throughout the greater St. Louis area. The licensee has 10 Troxler 3440 series gauges. The gauges are normally stored at licensee's facility or locked in construction trailers at temporary job sites. The licensee does not performed any service or maintenance activities on the gauges. The licensee employees 20 gauge users who have completed the manufacturers training.

Performance Observations

Licensee demonstrated how the gauge is used for the inspector. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

Independent surveys of the gauge storage area indicated minimal results. Although licensee personnel are badged, readings for the past year were nominally at the minimum level. Licensee has implemented the new gauge security policy. Adequate security is provided for in the storage location and in the truck used to transport the gauge. Surveys of the storage area by the inspector revealed only minimal results. No violations of requirements were noted.