

Initiated Date: 8/26/2005 11:22**Owner Group :**Eng Project Mgmt**Current Contact:****Current Significance:** C - REVIEW & CORRECT**Closed by:** Schmidt,George P

9/15/2005 12:13

Summary Description:

During excavation of Unit 2 Fuel Storage Building loading bay area in support of the dry cask storage project, a hole opened up in the soil beneath the east loading bay cinder-block wall. This does NOT effect the integrity of the spent fuel pool, which is a separate structure. The cinder-block wall remains structurally sound because it is supported by coulumn-to-column beams.

Remarks Description:**Closure Description:**

Per CA&A review noted the CR owner recommended closure of this CR.

Per CA&A review, concur with the CR owner's recommendation to close the CR. The issue was resolved, therefore this CR closed.