

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Precision Custom Components, LLC
P.O.Box 15101, 500 Lincoln Street
York, Pennsylvania 17405-7101

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region I, 475 Allendale Road
King of Prussia, Pennsylvania 19406-1415

REPORT Nos 2006-001

3. DOCKET NUMBER(S)
03010722

4. LICENSE NUMBER(S)
37-16280-01

5. DATE(S) OF INSPECTION
February 9, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 34.33 REQUIRES THAT ENTRANCES TO PERMANENT RADIOGRAPHIC INSTALLATION HIGH RADIATION AREA ENTRANCES, NOT INTERLOCKED TO REDUCE THE RADIATION LEVEL, BE INTERLOCKED TO PROVIDE VISIBLE AND AUDIBLE WARNING SIGNALS. DURING THE INSPECTION IT WAS IDENTIFIED THAT THE ACCESS GATE TO THE HIGH RADIATION AREA OF A FENCED ROOF AREA WAS NOT INTERLOCKED. THIS ARRANGEMENT HAS BEEN IN PLACE FOR OVER 10 YEARS AND WAS DESCRIBED IN THE LICENSEE'S RENEWAL DATED 12/2003. A SECOND LOCKED ACCESS TO THE ROOF IS ALSO PROVIDED TO THIS ROOF AREA TO MINIMIZE THE POTENTIAL FOR ACCESS TO THIS AREA. THE LICENSEE HAS AGREED TO REMOVE THE ACCESS PATHWAY INTO THE HIGH RADIATION AREA BEFORE ANY FURTHER RADIOGRAPHY IS PERFORMED IN THE 400KV CELL.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|-------------------|--|--------|
| LICENSEE'S REPRESENTATIVE | James A. Rowlands |  | 2/9/06 |
| NRC INSPECTOR | James Schmidt |  | 2/9/06 |