



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
SAM NUNN ATLANTA FEDERAL CENTER  
61 FORSYTH STREET, SW, SUITE 23T85  
ATLANTA, GEORGIA 30303-8931

March 13, 2006

Florida Power and Light Company  
ATTN: Mr. J. A. Stall, Senior Vice President  
Nuclear and Chief Nuclear Officer  
P. O. Box 14000  
Juno Beach, Florida 33408-0420

SUBJECT: TURKEY POINT NUCLEAR PLANT - INTEGRATED INSPECTION REPORT  
05000250/2005005 AND 05000251/2005005; PRELIMINARY WHITE FINDING  
ERRATA LETTER

On January 27, 2006, the U. S. Nuclear Regulatory Commission (NRC) issued the subject inspection report for the Turkey Point Nuclear Plant. In reviewing this report, it was noted that the date was incorrect on the cover letter. Accordingly, we are providing a revised first page of the cover letter. Please replace the first page of the cover letter with the enclosed revision.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) components of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

I apologize for any inconvenience this error may have caused. If you have any questions, please contact me at (404) 562-4560.

Sincerely,

/RA/

Joel T. Munday, Chief  
Reactor Projects Branch 3  
Division of Reactor Projects

Docket Nos: 50-250, 50-251  
License Nos. DPR-31, DPR-41

Enclosure: As stated

cc w/encl:  
T. O. Jones  
Site Vice President  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW 344<sup>th</sup> Street  
Florida City, FL 33035

Walter Parker  
Licensing Manager  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW 344<sup>th</sup> Street  
Florida City, FL 33035

Michael O. Pearce  
Plant General Manager  
Turkey Point Nuclear Plant  
Florida Power and Light Company  
9760 SW 344<sup>th</sup> Street  
Florida City, FL 33035

Mark Warner, Vice President  
Nuclear Operations Support  
Florida Power & Light Company  
P. O. Box 14000  
Juno Beach, FL 33408-0420

Rajiv S. Kundalkar  
Vice President - Nuclear Engineering  
Florida Power & Light Company  
P. O. Box 14000  
Juno Beach, FL 33408-0420

M. S. Ross, Managing Attorney  
Florida Power & Light Company  
P. O. Box 14000  
Juno Beach, FL 33408-0420

FP&L

3

Distribution w/encl:

E. Brown, NRR

B. Westreich, NSIR

B Moroney, NRR

S. Sparks, RII, EICS

L. Trocine, OE

L.. Slack, RII EICS

J. Ortega-Luciano, NRR

RIDSNNRRDIPMLIPB

PUBLIC

☐ PUBLICLY AVAILABLE

☐ NON-PUBLICLY AVAILABLE

☐ SENSITIVE

☐ NON-SENSITIVE

ADAMS: ☐ Yes      ACCESSION NUMBER: \_\_\_\_\_

OFFICE	RII:DRP						
SIGNATURE	JTM						
NAME	JMunday						
DATE	03/13/06	3/ /2006	3/ /2006	3/ /2006	3/ /2006	3/ /2006	3/ /2006
E-MAIL COPY?	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO	YES NO

OFFICIAL RECORD COPY

DOCUMENT NAME: E:\Filenet\ML060720341.wpd



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
SAM NUNN ATLANTA FEDERAL CENTER  
61 FORSYTH STREET, SW, SUITE 23T85  
ATLANTA, GEORGIA 30303-8931

**ATTACHMENTS 2 AND 3 CONTAIN PROPRIETARY INFORMATION**

January 27, 2005

EA 06-027

Florida Power and Light Company  
ATTN: Mr. J. A. Stall, Senior Vice President  
Nuclear and Chief Nuclear Officer  
P. O. Box 14000  
Juno Beach, FL 33408-0420

SUBJECT: TURKEY POINT NUCLEAR PLANT - INTEGRATED INSPECTION REPORT  
05000250/2005005 AND 05000251/2005005; PRELIMINARY WHITE FINDING

Dear Mr. Stall:

On December 31, 2005, the US Nuclear Regulatory Commission (NRC) completed an inspection at your Turkey Point Units 3 and 4. The enclosed integrated inspection report documents the inspection findings which were discussed on January 12, 2006, with Mr. W. Webster and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

This letter and the enclosed supporting documentation discuss a finding that appears to have low to moderate safety significance (White). This finding was assessed based on the best available information, including influential assumptions, using the applicable Significance Determination Process (SDP) and was preliminarily determined to be a White finding (i.e., a finding with some increased importance to safety, which may require additional NRC inspection).

This finding is characterized as an Apparent Violation (AV) of NRC requirements and is being considered for escalated enforcement action in accordance with the NRC Enforcement Policy. The current Enforcement Policy is included on the NRC's Web site at <http://www.nrc.gov/what-we-do/regulatory/enforcement/enforce-pol.html>.

**DOCUMENT TRANSMITTED HERewith CONTAINS SENSITIVE UNCLASSIFIED  
INFORMATION WHEN SEPARATED FROM ATTACHMENTS 2 AND 3, THIS DOCUMENT IS  
DECONTROLLED**



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
SAM NUNN ATLANTA FEDERAL CENTER  
61 FORSYTH STREET, SW, SUITE 23T85  
ATLANTA, GEORGIA 30303-8931

**ATTACHMENTS 2 AND 3 CONTAIN PROPRIETARY INFORMATION**

January 27, 2006

EA 06-027

Florida Power and Light Company  
ATTN: Mr. J. A. Stall, Senior Vice President  
Nuclear and Chief Nuclear Officer  
P. O. Box 14000  
Juno Beach, FL 33408-0420

SUBJECT: TURKEY POINT NUCLEAR PLANT - INTEGRATED INSPECTION REPORT  
05000250/2005005 AND 05000251/2005005; PRELIMINARY WHITE FINDING

Dear Mr. Stall:

On December 31, 2005, the US Nuclear Regulatory Commission (NRC) completed an inspection at your Turkey Point Units 3 and 4. The enclosed integrated inspection report documents the inspection findings which were discussed on January 12, 2006, with Mr. W. Webster and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.

This letter and the enclosed supporting documentation discuss a finding that appears to have low to moderate safety significance (White). This finding was assessed based on the best available information, including influential assumptions, using the applicable Significance Determination Process (SDP) and was preliminarily determined to be a White finding (i.e., a finding with some increased importance to safety, which may require additional NRC inspection).

This finding is characterized as an Apparent Violation (AV) of NRC requirements and is being considered for escalated enforcement action in accordance with the NRC Enforcement Policy. The current Enforcement Policy is included on the NRC's Web site at <http://www.nrc.gov/what-we-do/regulatory/enforcement/enforce-pol.html>.

**DOCUMENT TRANSMITTED HERewith CONTAINS SENSITIVE UNCLASSIFIED INFORMATION  
WHEN SEPARATED FROM ATTACHMENTS 2 AND 3, THIS DOCUMENT IS DECONTROLLED**