

From: Dan Hoang
To: Jad;pxw
Date: Mon, May 8, 2006 8:57 AM
Subject: AMR's questionnaire for Pilgrim

Gentlemen,

As promised, I have been finished my AMR for Pilgrim.

Attached is a list of my seven (7) questions to them (before I am going to Vermont Yankee for my "Vacation" next week).

With that, I am NOT be able to attend the next week meeting in Germantown.

Regards,

Dan

Mail Envelope Properties (445F4032.C28 : 17 : 35826)

Subject: AMR's questionnaire for Pilgrim
Creation Date Mon, May 8, 2006 8:57 AM
From: Dan Hoang

Created By: DVH@nrc.gov

Recipients

nrc.gov

OWGWPO01.HQGWDO01

JAD (Jad;pxw)

Post Office

OWGWPO01.HQGWDO01

Route

nrc.gov

Files

MESSAGE

Size

988

Pilgrim AMRs questionaries Rev1.wpd
8:45 AM

Date & Time

Monday, May 8, 2006 8:57 AM

8020

Monday, May 8, 2006

Options

Expiration Date: None
Priority: Standard
ReplyRequested: No
Return Notification: None

Concealed Subject: No
Security: Standard

Junk Mail Handling Evaluation Results

Message is not eligible for Junk Mail handling

Message is from an internal sender

Junk Mail settings when this message was delivered

Junk Mail handling disabled by User

Junk Mail handling disabled by Administrator

Junk List is not enabled

Junk Mail using personal address books is not enabled

Block List is not enabled

AMR's for Pilgrim (Total 7 questions from Dan Hoang)**Sect. 3.5.1-13 (GALL sect. II.B4-3 SS bellows)**

The applicant is requested to identify the "Other" aging management to detect of aging effect. Since, your VT-3 may not be able to detect the fine crack. Please provide a procedure, guideline, and/or any documents to support your answer.

Sect. 3.5.1-34 (GALL sect. III.A6-1)

Do you (PNPS) has any experience with aggressive ground water/soil, and/or where the concrete structural elements have experienced degradation? If yes, When? And what was your corrective and preventive actions?

Sect. 3.5.1-37 (GALL sect. III.A6-6)

- A- In Table 2 of section 3.5.1-37 please fill in the column for:
 - 1- Structure and/or Component
 - 2- Material
 - 3- Environment
 - 4- Aging Management Program (AMP)
- B- Does this sect. Met GALL X1.S7?
- C- Relationship to NUREG-1557?

Sect. 3.5.1-39 (GALL sect. III.B.2-10)

For structural bolting, describe the AMR. How is "loss of preload" managed?

Sect. 3.5.1-5 (GALL sect. II.B1.1-2)

Was the containment concrete in contact with the embedded containment shell or liner met the ACI 318 or 349 and the guidance of ACI 201.2R? Please, tell us how are you going to detect concrete's penetrating cracks?

Sect. 3.5.1-53 (GALL sect. III.B1.1-13)

- 1- More information is needed about bolting materials used in structural applications at PNPS including Group B1.1 applications. What are the bolting materials used? What are the nominal yield strengths and upper-bound as-received yield strengths? Describe the PNPS resolution of the bolting integrity generic issue, as it relates to structural bolting. Was any structural bolting identified as potentially susceptible to cracking due to SCC? Was any structural bolting replaced as part of the resolution?
- 2- Describe the scope and AMR for Class MC Pressure Retaining Bolting. How is loss of preload managed?