

September 8, 2006

Mark B. Bezilla
Vice President
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
Mail Stop A-DB-3080
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: BULLETIN 2004-01, "INSPECTIONS OF ALLOY 82/182/600 MATERIALS USED IN THE FABRICATION OF PRESSURIZER PENETRATIONS AND STEAM SPACE PIPING CONNECTIONS AT PRESSURIZED-WATER REACTORS," RESPONSE FOR DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1 (TAC NO. MC3475)

Dear Mr. Bezilla:

On May 28, 2004, the U.S. Nuclear Regulatory Commission (NRC) issued Bulletin 2004-01, "Inspections of Alloy 82/182/600 Materials Used in the Fabrication of Pressurizer Penetrations and Steam Space Piping Connections at Pressurized-Water Reactors," to the industry. This bulletin informed addressees that current methods of inspecting the pressurizer penetrations and steam space piping connections fabricated from Alloy 82/182/600 materials may need to be supplemented with additional measures (e.g., bare-metal visual inspections) to detect pressurizer penetration and steam space piping connection flaws or leakage. The bulletin requested that addressees provide the NRC with information related to the materials of construction, the inspections that have been performed, and the inspections which will be performed to verify the integrity of the pressurizer penetrations and steam space piping connections.

The following requested information documented in Bulletin 2004-01, item (1), pertaining to your plant was required within 60 days of the May 28, 2004, date of the bulletin:

- (a) a description of the pressurizer penetrations and steam space piping connections,
- (b) a description of the inspection program for Alloy 82/182/600 pressurizer penetrations and steam space piping connections that has been implemented,
- (c) a description of the Alloy 82/182/600 pressurizer penetration and steam space piping connection inspection program that will be implemented during the next and subsequent refueling outages, and

- (d) in light of the information discussed in the bulletin and your understanding of the relevance of recent industry operating experience to your facility, an explanation why the inspection program identified in your response to item (1)(c) above is adequate for the purpose of maintaining the integrity of your facility's reactor coolant pressure boundary (RCPB) and for meeting all applicable regulatory requirements.

Furthermore, documented in Bulletin 2004-01, item (2), was a request that within 60 days of plant restart following the next inspection of the Alloy 82/182/600 pressurizer penetrations and steam space piping connections, you should either:

- (a) submit to the NRC a statement indicating that the inspections described in your response to item (1)(c) of this bulletin were completed and a description of the as-found condition of the pressurizer shell, any findings of relevant indications of through-wall leakage, followup non-destructive examination (NDE) performed to characterize flaws in leaking penetrations or steam space piping connections, a summary of all relevant indications found by NDE, a summary of the disposition of any findings of boric acid, and any corrective actions taken and/or repairs made as a result of the indications found

or

- (b) if you were unable to complete the inspections described in response to item (1)(c) of this bulletin, submit to the NRC a summary of the inspections performed, the extent of the inspections, the methods used, a description of the as-found condition of the pressurizer shell, any findings of relevant indications of through-wall leakage, followup NDE performed to characterize flaws in leaking penetrations or steam space piping connections, a summary of all relevant indications found by NDE, a summary of the disposition of any findings of boric acid, and any corrective actions taken and/or repairs made as a result of the indications found. In addition, supplement the answer which you provided to item (1)(d) above to explain why the inspections that you completed were adequate for the purpose of maintaining the integrity of your facility's RCPB and for meeting all applicable regulatory requirements which pertain to your facility.

By letter dated July 26, 2004, as supplemented by letter dated August 22, 2005, you provided your responses to items (1)(a), (1)(b), (1)(c), and (1)(d) of Bulletin 2004-01 for Davis-Besse Nuclear Power Station, Unit 1 (Davis-Besse). Your responses described its materials of fabrication and past, current and future pressurizer penetrations and steam space piping inspection programs at Davis-Besse.

Your response to item (1)(a) reported that some of the materials used in the fabrication of the pressurizer penetrations and steam space piping connections were Alloy 82/182/600 materials. This reply required you to provide further responses to the remaining items in the bulletin.

In response to item (1)(b), you described prior inspections and inspection results of pressurizer penetrations and steam space piping connections which had been performed at Davis-Besse. Your response included the basis for concluding that Davis-Besse satisfies the applicable regulatory requirements related to the integrity of pressurizer penetrations and steam space

piping connections.

In response to item (1)(c), you provided a description of the Alloy 82/182/600 pressurizer penetration and steam space piping connection inspection program that will be implemented at your plant during the next and subsequent refueling outages. The description included the items to be inspected; the percent coverage that would be performed at each location; the inspection methods to be used; the qualification standards for the inspection methods and personnel; the process used to resolve any inspection indications; the inspection documentation to be generated; and the basis for concluding that your plant will satisfy the applicable regulatory requirements related to the structural and leakage integrity of pressurizer penetrations and steam space piping connections. If leaking pressurizer penetrations or steam space piping connections are found, you indicated that follow-up NDE will be performed to characterize flaws in the leaking penetrations. You provided plans for expansion of the scope of NDE to be performed if circumferential flaws are found in any portion of the leaking pressurizer penetrations or steam space piping connections.

In response to item (1)(d), you explained why the inspection program identified in your response to item (1)(c) is adequate for the purpose of maintaining the integrity of the Davis-Besse RCPB and for meeting all applicable regulatory requirements.

By letter dated August 22, 2005, you provided a response to item (2)(a) in Bulletin 2004-01. This letter provided a statement to the NRC indicating that the inspections described in your response to item (1)(c) were completed during the Davis-Besse Cycle 14 Mid-cycle outage and a description of the as-found condition of the locations inspected was provided. You also described any findings of relevant indications of through-wall leakage and follow-up NDE performed to characterize flaws in leaking penetrations or steam space piping connections. A summary of all relevant indications found by NDE, a summary of the disposition of any findings of boric acid, and a description of any corrective actions taken and/or repairs made as a result of the indications found was also provided in this letter.

The NRC staff has completed its activities associated with the review of your responses to Bulletin 2004-01 and finds your response to be acceptable. It should be noted that industry commitments or NRC staff regulatory actions may result in the need for you to modify your plans for the inspection and repair of items discussed in Bulletin 2004-01. It is the NRC staff's expectation that you will revise your plan for the inspection and repair of items discussed in Bulletin 2004-01 consistent with other industry commitments or NRC staff regulatory actions.

M. Bezilla

- 4 -

This closes the NRC staff's efforts with regard to the review of the Bulletin 2004-01 response for Davis-Besse. Please contact me at (301) 415-1486 if you have any questions on this issue.

Sincerely,

/RA/

Stephen J. Campbell, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

M. Bezilla

- 4 -

This closes the NRC staff's efforts with regard to the review of the Bulletin 2004-01 response for Davis-Besse. Please contact me at (301) 415-1486 if you have any questions on this issue.

Sincerely,

/RA/

Stephen J. Campbell, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-346

cc: See next page

DISTRIBUTION:

PUBLIC	EAndruskiewicz, NRR	MMitchell, NRR	RidsNrrPMTColburn
RidsNrrPMSCampbell	RidsNrrLADClarke	LPL3-2 R/F	RidsNrrDorIDpr
RidsNrrDorlLpl3-2	RidsOgcRp	RidsAcrsAcnwMailCenter	EW hitt, NRR

ADAMS ACCESSION NUMBER: ML062150557

OFFICE	LPL3-2/PM	LPL3-2/LA	LPL3-2/BC
NAME	SCampbell:mw	DClarke	DCollins
DATE	9/8/2006	9/8/2006	9/8/2006

OFFICIAL RECORD COPY

Davis-Besse Nuclear Power Station, Unit 1

cc:

Manager - Regulatory Affairs
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State - Route 2
Oak Harbor, OH 43449-9760

Director, Ohio Department of Commerce
Division of Industrial Compliance
Bureau of Operations & Maintenance
6606 Tussing Road
P.O. Box 4009
Reynoldsburg, OH 43068-9009

Regional Administrator
U.S. Nuclear Regulatory Commission
801 Warrenville Road
Lisle, IL 60523-4351

Resident Inspector
U.S. Nuclear Regulatory Commission
5503 North State Route 2
Oak Harbor, OH 43449-9760

Barry Allen, Plant Manager
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
5501 North State - Route 2
Oak Harbor, OH 43449-9760

Dennis Clum
Radiological Assistance Section Supervisor
Bureau of Radiation Protection
Ohio Department of Health
P.O. Box 118
Columbus, OH 43266-0118

Carol O'Claire, Chief, Radiological Branch
Ohio Emergency Management Agency
2855 West Dublin Granville Road
Columbus, OH 43235-2206

Zack A. Clayton
DERR
Ohio Environmental Protection Agency
P.O. Box 1049
Columbus, OH 43266-0149

State of Ohio
Public Utilities Commission
180 East Broad Street
Columbus, OH 43266-0573

Attorney General
Office of Attorney General
30 East Broad Street
Columbus, OH 43216

President, Board of County
Commissioners of Ottawa County
Port Clinton, OH 43252

President, Board of County
Commissioners of Lucas County
One Government Center, Suite 800
Toledo, OH 43604-6506

The Honorable Dennis J. Kucinich
United States House of Representatives
Washington, D.C. 20515

The Honorable Dennis J. Kucinich
United States House of Representatives
14400 Detroit Avenue
Lakewood, OH 44107

Gary R. Leidich
President and Chief Nuclear Officer
FirstEnergy Nuclear Operating Company
Mail Stop A-GO-19
76 South Main Street
Akron, OH 44308

Joseph J. Hagan
Senior Vice President of Operations and
Chief Operating Officer
FirstEnergy Nuclear Operating Company
Mail Stop A-GO-14
76 South Main Street
Akron, OH 44308

David W. Jenkins, Attorney
FirstEnergy Corporation
Mail Stop A-GO-18
76 South Main Street
Akron, OH 44308

Davis-Besse Nuclear Power Station, Unit 1

cc:

Danny L. Pace
Senior Vice President, Fleet Engineering
FirstEnergy Nuclear Operating Company
Mail Stop A-GO-14
76 South Main Street
Akron, OH 44308

Manager, Fleet Licensing
FirstEnergy Nuclear Operating Company
Mail Stop A-GHE-107
395 Ghent Road
Akron, OH 44333

Manager, Site Regulatory Compliance
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
Mail Stop A-DB-3065
5501 North State Route 2
Oak Harbor, OH 43449-9760

Jeannie M. Rinckel
Vice President, Fleet Oversight
FirstEnergy Nuclear Operating Company
Mail Stop A-GO-14
76 South Main Street
Akron, OH 44308