

(11-2003)
10 CFR 2.201

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Advanced Service Providers
3014 White sands Terrace
Green Bay, WI 54313

2. NRC/REGIONAL OFFICE

REPORT NUMBER(S) 2006-001

3. DOCKET NUMBER(S)

030-36444

4. LICENSE NUMBER(S)

48-32464-01

5. DATE(S) OF INSPECTION

August 4, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	E. L. Kulzer	<i>E. L. Kulzer</i>	08/04/2006

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Advanced Service Providers REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE	
3. DOCKET NUMBER(S) 030-36444	4. LICENSE NUMBER(S) 48-32464-01	5. DATE(S) OF INSPECTION August 4, 2006	
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3225	2. PRIORITY K5	3. LICENSEE CONTACT Steve Conour	4. TELEPHONE NUMBER 515-418-3679
----------------------------	-------------------	-------------------------------------	-------------------------------------

☒ Main Office Inspection Next Inspection Date: 08/04/2011

☐ Field Office Inspection _____

☐ Temporary Job Site Inspection _____

PROGRAM SCOPE

This was an initial inspection of this fixed gauge service provider with a corporate location in Green Bay, WI.

The licensee performs service, maintenance, leak testing and installation of fixed gauges for approximately 26 clients in 12 states. About 20 authorized technicians are employed and service the devices at the various locations. Currently the licensee does not possess licensed material as authorized on the current NRC license.

Since gauge work was not being performed in the Green Bay, WI. office, the inspection included interviews with the president. This was the president's home.

The RSO's phone number listed on the previous inspection report has changed. The correct phone number is listed above. The RSO's address is 302 S. 4th Street, Milo, IA. 50166-1030.

The only records that the president maintains at his home office are the original dosimetry reports which did not indicate exposures in excess of the 10 CFR 20 limits. Most work on these gauges involves the electrical portion of the gauge.

NOTE: Since the licensee does not currently possess or plan to possess any byproduct material, the next inspection should be conducted in five years.

[Handwritten signature]