

August 9, 2007

Mr. David A. Christian
Senior Vice President and
Chief Nuclear Officer
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: KEWAUNEE POWER STATION - REQUEST FOR ADDITIONAL
INFORMATION STEAM GENERATOR TUBE INSPECTION (TAC NO. MD5226)

Dear Mr. Christian:

By letter dated January 8, 2007, Dominion Energy Kewaunee, Inc. (DEK), submitted a summary report of the various inservice inspection examinations that were performed during the 2006 refueling outage at the Kewaunee Power Station (KPS). This report included the results of the eddy current testing of the steam generator tubes.

On March 29, 2007, DEK submitted the steam generator tube inservice inspection report, pursuant to KPS Technical Specification (TS) 6.9.b.4, which required submittal of the report 180 days after the initial entry into intermediate shutdown following completion of an inspection performed in accordance with the TS 6.22, "Steam Generator Program." KPS entered into the intermediate shutdown mode on October 20, 2006.

The Nuclear Regulatory Commission (NRC) staff is reviewing the information provided in these reports, and has determined that additional information is required to complete the review. The specific information requested is addressed in the enclosure to this letter. During a discussion with your staff on August 7, 2007, it was agreed that DEK would provide a response within 45 days of the date of this letter.

The NRC staff considers that timely responses to requests for additional information help ensure sufficient time is available for staff review and contribute toward the NRC's goal of efficient and effective use of staff resources. If circumstances result in the need to revise the requested response date, please contact me at (301) 415-1457.

Sincerely,

/RA/

Patrick D. Milano, Senior Project Manager
Plant Licensing Branch III-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-305

Enclosure:
Request for Additional Information

cc w/encl: See next page

Mr. David A. Christian
Senior Vice President and
Chief Nuclear Officer
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: KEWAUNEE POWER STATION - REQUEST FOR ADDITIONAL
INFORMATION STEAM GENERATOR TUBE INSPECTION (TAC NO. MD5226)

Dear Mr. Christian:

By letter dated January 8, 2007, Dominion Energy Kewaunee, Inc. (DEK), submitted a summary report of the various inservice inspection examinations that were performed during the 2006 refueling outage at the Kewaunee Power Station (KPS). This report included the results of the eddy current testing of the steam generator tubes.

On March 29, 2007, DEK submitted the steam generator tube inservice inspection report, pursuant to KPS Technical Specification (TS) 6.9.b.4, which required submittal of the report 180 days after the initial entry into intermediate shutdown following completion of an inspection performed in accordance with the TS 6.22, "Steam Generator Program." KPS entered into the intermediate shutdown mode on October 20, 2006.

The Nuclear Regulatory Commission (NRC) staff is reviewing the information provided in these reports, and has determined that additional information is required to complete the review. The specific information requested is addressed in the enclosure to this letter. During a discussion with your staff on August 7, 2007, it was agreed that DEK would provide a response within 45 days of the date of this letter.

The NRC staff considers that timely responses to requests for additional information help ensure sufficient time is available for staff review and contribute toward the NRC's goal of efficient and effective use of staff resources. If circumstances result in the need to revise the requested response date, please contact me at (301) 415-1457.

Sincerely,

/RA/

Patrick D. Milano, Senior Project Manager
Plant Licensing Branch III-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-305

Enclosure:
Request for Additional Information

cc w/encl: See next page

DISTRIBUTION:

PUBLIC

RidsNrrDciCsgb

A. Johnson, CSGB

RidsAcrcAcnwMailCenter

LPL3-1 R/F

RidsNrrPMPMilano

RidsOgcRp

RidsNrrDoriDpr

RidsNrrDoriLpl3-1

RidsNrrLATHarris

RidsRgn3MailCenter

ADAMS Accession No.: **ML072190202**

OFFICE	LPL3-1/PM	LPL3-1/LA	CSGB/BC	LPL3-1/BC(A)
NAME	PMilano	THarris	AHiser	TTate
DATE	08/08/07	08/7/07	08/02/07	08/9/07

OFFICIAL RECORD COPY

Kewaunee Power Station

cc:

Resident Inspectors Office
U.S. Nuclear Regulatory Commission
N490 Hwy 42
Kewaunee, WI 54216-9510

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
Suite 210
2443 Warrenville Road
Lisle, IL 60532-4351

Ms. Leslie N. Hartz
Dominion Energy Kewaunee, Inc.
Kewaunee Power Station
N 490 Highway 42
Kewaunee, WI 54216

Mr. Chris L. Funderburk
Director, Nuclear Licensing and
Operations Support
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

Mr. Thomas L. Breene
Dominion Energy Kewaunee, Inc.
Kewaunee Power Station
N490 Highway 42
Kewaunee, WI 54216

Ms. Lillian M. Cuoco, Esq.
Senior Counsel
Dominion Resources Services, Inc.
Millstone Power Station
Building 475, 5th Floor
Rope Ferry Road
Waterford, CT 06385

REQUEST FOR ADDITIONAL INFORMATION
REGARDING STEAM GENERATOR TUBE INSERVICE INSPECTION REPORTS
FOR THE 2006 REFUELING OUTAGE
KEWAUNEE POWER STATION
DOCKET NO. 50-305

By letters dated January 10 and March 29, 2007 ((Agencywide Documents Access and Management System (ADAMS) Accession No. ML070100524 and ML071020161, respectively), Dominion Energy Kewaunee, Inc (the licensee) submitted information regarding the steam generator tube inspection results from the 2006 refueling outage inspection at Kewaunee Power Station. In reviewing the information, the Nuclear Regulatory Commission staff has determined that the following information is needed in order to complete its review:

1. Regarding the inspections performed on each steam generator, discuss the scope and results of any secondary side inspections performed during the 2006 outage. In addition, discuss whether the two loose parts, which were assessed and not removed from the steam generator during the 2003 outage, were observed in the 2006 eddy current data. Discuss whether these loose parts were removed during the 2006 outage (e.g., during a foreign object search and retrieval inspection).
2. In Paragraph d. on page 2 of Attachment 1 to the March 29, 2007, letter, several indications in steam generator 1A were identified as "not called during the pre-service inspection." Clarify whether these indications were present in the pre-service inspection but were not identified (i.e., reported) or whether the indications were not present in the pre-service inspection data. If the indications were present in the pre-service data, discuss whether the indications have changed since the pre-service inspection. If the indications have changed or the indications are new (i.e., not present in the pre-service inspection), discuss any insights on the nature of these indications.

ENCLOSURE