

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

American Tower Scanning, Inc.
Port Huron, Michigan

2. NRC/REGIONAL OFFICE

REGION III
US NUCLEAR REGULATORY COMMISSION
2443 WARRENVILLE ROAD, SUITE 210
LISLE, ILLINOIS 60532

REPORT 2007-001

3. DOCKET NUMBER(S)

030-35936

4. LICENSEE NUMBER(S)

21-32347-01

5. DATE(S) OF INSPECTION

8/21/07

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Michael M LaFrance	Michael M LaFrance	8/21/07

**Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE American Tower Scanning REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35936	4. LICENSE NUMBER(S) 21-32347-01	5. DATE(S) OF INSPECTION 8/21/2007	
6. INSPECTION PROCEDURES USED 87113	7. INSPECTION FOCUS AREAS 3.1-3.7		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 3111	2. PRIORITY 5	3. LICENSEE CONTACT Mark Gledhill	4. TELEPHONE NUMBER 519-331-9684
<input type="checkbox"/> Main Office Inspection <input checked="" type="checkbox"/> Field Office <u>3560 Pine Grove Avenue</u> <input type="checkbox"/> Temporary Job Site _____			
Next Inspection Date: 08/2012			

PROGRAM SCOPE

The licensee's main office is located in Sarnia, Ontario; Canada. However, the licensee's US mailing address is located at an office complex in Port Huron, Michigan. The licensee is a tower scanning company that performed real time scanning on above ground reaction tanks for the purpose of inner structural analysis. The licensee's clients were mainly refineries and industrial chemical companies. The licensee possesses a number of sources but has only entered the United States three times on 2003 to conduct licensed operations. The licensee's main storage area is located in Canada with a staging area in Port Huron, Michigan. The licensee's staff consists of the RSO/President and one other technician.

Performance Observations

As of the inspection date, the licensee transported and performed licensed operations with a number of sources on three separate occasions in 2003. The inspector interviewed the RSO/President of the company and found that he was knowledgeable regarding NRC regulations. The inspector reviewed a representative sample of paperwork provided by the licensee which was stored in Canada; no abnormal issues were identified. Since the licensee does not stored licensed material within the United States, the inspector was unable to physical confirm issues concerning security. However, interviews with the RSO/President with the inspector indicated that a sufficient amount of knowledge and equipment is available to ensure the security of licensed material while within US jurisdiction.