


INADVERTANT OPENING OF RRMV LINE
 RESULTING IN FLOW OF COOLANT




NOTES

- (1) THE FLOW OF COOLANT TO THE PRT IS NOT SERIOUS BECAUSE REDUNDANT INSTRUMENTATION WILL INFORM THE OPERATOR IN SUFFICIENT TIME TO PREVENT COOLANT FLOW FROM THE PRT THROUGH THE PRT'S RUPTURE DISC
- (2) DETERMINATION OF A VOID OR BUBBLE REQUIRES MULTIPLE CHECKS OF SYSTEM PARAMETERS TO BE ADDRESSED IN PROCEDURES

PRC
 APERTURE
 CARD

8206080318-01


INABILITY TO REMOTELY CLOSE MOTOR OPERATED VALVE AFTER VENTING



PRC
APERTURE
CARD

8206080318-02

INABILITY TO CLOSE -- FAILURE OF CONTROL CIRCUIT



PRC
APERTURE
CARD

8206080318-03