

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO: J.G. KEPPLER

FROM: IOWA ELEC. LIGHT & PWR CO.
CEDAR RAPIDS, IOWA
E.L. HAMMONDDATE OF DOCUMENT
2/11/77DATE RECEIVED
2/24/77☒ LETTER
☒ ORIGINAL
☐ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM,...

NUMBER OF COPIES RECEIVED

40

DESCRIPTION

LTR. TRANS THE FOLLOWING.....

(1P)

PLANT NAME: DUANE ARNOLD

ENCLOSURE

LICENSEE EVENT REPORT FOR RO 77-8, ON 1/31/77
CONCERNING THE MOUNTING BRACKET FOR HYDRAULIC
SHOCK SUPPRESSOR HBB-25-SS-178 ON THE FUEL POOL
TO RHR LINE WAS FOUND TO BE LOOSE FROM THE
WALL.....

(1P)

(1 SIGNED CY. RECEIVED)

Do Not Remove **ACKNOWLEDGED**NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION

SAB 2/25/77

BRANCH CHIEF:	LEAR		
W/3 CYS FOR ACTION			
LIC. ASST.:	PARRISH		
W/ CYS			
ACRS 16 CYS HOLDING/SENT	CAT " B"		

INTERNAL DISTRIBUTION

REG FILE				
NRC PDR				
I & E (2)				
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON				
NOVAK/CHECK				
GRIMES				
CASE				
BUTLER				
HANAUER				
TEDESCO/MACCARY				
EISENHUT				
BAER				
SHAO				
VOLLMER/BUNGH				
KREGER/J. COLLINS				

EXTERNAL DISTRIBUTION

CONTROL NUMBER

LPDR: CEDAR RAPIDS, IOWA				
TIC:				
NSIC:				

1910

IOWA ELECTRIC LIGHT AND POWER COMPANY


DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
February 11, 1977
DAEC - 77 - 105



Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 77-8
(14 day)

File: A-118a



Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49
Technical Specifications and Bases for Duane Arnold Energy Center and
Regulatory Guide 10.1, please find attached a copy of the subject
Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

1910

LICENSEE EVENT REPORT

Regulatory Docket File

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 I A D A C 1
 LICENSE NUMBER: 00-000000-000
 LICENSE TYPE: 41111
 EVENT TYPE: 01
 CATEGORY: 01 CON'T
 REPORT TYPE: T
 REPORT SOURCE: L
 DOCKET NUMBER: 050-0331
 EVENT DATE: 013177
 REPORT DATE: 021177

EVENT DESCRIPTION

02 During inspection the mounting bracket for hydraulic shock suppressor
 03 HBB-25-SS-178 on the fuel pool to RHR line was found to be loose from t
 04 he wall. 1 concrete fastener was pulled loose from the wall and 3 mount
 05 ing bolts were backed out slightly. The fastener was replaced and the m
 06 ounting bolts tightened. (RO 77-8)

SYSTEM CODE: C F
 CAUSE CODE: E
 COMPONENT CODE: H A N G E R
 PRIME COMPONENT SUPPLIER: A
 COMPONENT MANUFACTURER: X 9 9 9
 VIOLATION: Y

CAUSE DESCRIPTION

08 Unknown. A nonconformance review has been initiated to investigate the
 09 cause of the occurrence.
 10

FACILITY STATUS: E
 % POWER: 083
 OTHER STATUS: NA
 METHOD OF DISCOVERY: C
 DISCOVERY DESCRIPTION: Special Inspection
 FORM OF ACTIVITY RELEASED: Z
 CONTENT OF RELEASE: Z
 AMOUNT OF ACTIVITY: NA
 LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

13 NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

14 NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

NAME: J. Van Sickel

PHONE: 319-851-5611