

MEMO ROUTE SLIP		See me about this.	For concurrence.	For action.
Form AEC-93 (Rev. May 14, 1947) AECM 0240		Note and return.	For signature.	For information.
TO (Name and unit) RO Chief, FS&EB RO:HQ (4) Licensing (4) <u>DR Central Files</u> Region I	INITIALS	REMARKS Iowa Electric Light & Power Company Duane Arnold 50-331		
	DATE			
TO (Name and unit) Region II PDR Local PDR NSIC TIC	INITIALS	REMARKS		
	DATE			
TO (Name and unit) OGC, Beth, P-506A F. Rizzo, RO:HQ A/D for Info Processing, OOE	INITIALS	REMARKS		
	DATE			
FROM (Name and unit) G. Fiorelli RO:III	REMARKS Attached is licensee's reply dated November 14, 1974 to RO Bulletin 74-12.			
PHONE NO.	DATE 11-19-74			

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO : 1971 O - 445-469

5

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office

CEDAR RAPIDS, IOWA

November 14, 1974

IE-74-2160

CHARLES W. SANDFORD
EXECUTIVE VICE PRESIDENT

Docket 50-331

Mr. J. G. Keppler
U.S. Atomic Energy Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Re: Duane Arnold Energy Center #1
Subject: RO Bulletin No. 74-12 "Incorrect
Coils in Westinghouse Type SG Relays"
File: Q-313, A-110

Dear Mr. Keppler:

This is in reply to your letter of October 25, 1974 regarding the possibility of incorrect coil in Westinghouse Type SG Relays associated with Class IE equipment.

A thorough investigation of all electrical equipment in DAEC identified one Westinghouse Type SG Relay. This relay is not associated with Class IE equipment. The coils' resistance was checked and found to be proper for its application.

Very truly yours,

Charles W. Sandford
Charles W. Sandford
Executive Vice President

CWS/ms

cc: J. A. Wallace
G. G. Hunt
L. D. Root
H. W. Rehrauer
J. N. Ward
G. A. Cook
J. R. Newman

NOV 18 1974