



**FPL.**

POWERING TODAY.  
EMPOWERING TOMORROW.®

AUG 05 2011

L-2011-254  
10 CFR 50.55a

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555-00001

Re: Turkey Point Unit 4  
Docket No. 50-251  
Inservice Inspection Program  
Fourth Interval-Second Period-Third Refueling Outage  
Owner's Activity Report (OAR-1)

Attached find the Owner's Activity Report (Form OAR-1), for Turkey Point Unit 4 Fourth Inservice Inspection Interval, Second Period, Third Refueling Outage (PTN 4-26). The Form OAR-1, Owner's Activity Report, implements Code Case N-532-4.

Should there be any questions concerning this report, please contact Robert J. Tomonto at 305-246-7327.

Very truly yours,

Michael Kiley  
Vice President  
Turkey Point Nuclear Plant

SM

Attachment

A047  
NRK

FORM OAR-1 OWNER'S ACTIVITY REPORT

Report Number: ISI-PTN-4-2011

Plant: Turkey Point Nuclear Power Plant Unit 4  
P.O. Box 4332  
Florida City, Florida 33032

Commercial Service Date: September 7, 1973 Refueling Outage No.: PTN 4-26

Current Inspection Interval: ISI-Fourth IWE-Second Current Inspection Period: ISI-Second IWE-First

Edition and Addenda of Section XI applicable to the inspection plans: ISI-1998 Edition with Addenda through 2000 and IWE-2001 with Addenda through 2003.


Date and Revision of inspection plans: ISI-July 23, 2010 Rev. 3 IWE-March 15, 2009, Rev. 0

Edition and Addenda of Section XI applicable to repairs and replacements, if different than the inspection plan: Same

Code Cases Used: N-460, N-532-4, N-533-1, N-566-1, N-624, N-686

**CERTIFICATE OF CONFORMANCE**

I certify that (a) the statements made in this report are correct; (b) the examinations and tests meet the Inspection plan as required by the ASME Code, Section XI; and (c) the repair/replacement activities and evaluations supporting the completion of PTN 4-26 conform to the requirements of Section XI.

Signed  CSZ HCN Date 7/18/11  
Owner or Owner's Designee, Title

**CERTIFICATE OF INSERVICE INSPECTION**

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Florida and employed by HSBCT of Hartford Connecticut have inspected the items described in this Owner's Activity Report, and state that, to the best of my knowledge and belief, the Owner has performed all activities represented by this report in accordance with the requirements of Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the repair/replacement activities and evaluation described in this report. Furthermore, neither the inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

 Commissions FL 477 (A, C, N, I)  
Inspector's Signature National Board, State, Province, and Endorsements

Date 8-4-11

FORM OAR-1 OWNER'S ACTIVITY REPORT

---

TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE		
Examination Category and Item Number	Item Description	Evaluation Description
D-B/D2.10	Valve 4-12-029	Thru-wall leakage on valve body

FORM OAR-1 OWNER'S ACTIVITY REPORT

<p><b>TABLE 2</b></p> <p><b>ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE</b></p>				
<b>Code Class</b>	<b>Item Description</b>	<b>Description Of Work</b>	<b>Date Completed</b>	<b>Repair/Replacement Plan Number</b>
2	Support	Replace corroded section of beam	4/17/2011	RR40006832-04
2	Snubber	Replace Snubber failed functional test	4/4/2011	RR40016909-01
2	Pump Block	Replace Pump Block	3/6/2011	RR39018415-02
2	Piping	Reduced Indications to acceptable limit found during scheduled ISI exam on a weld-o-let 4"-SI-1401-52	4/18/2011	RR40080713-01
2	Piping	Reduced Indications to acceptable limit found during scheduled ISI exam on a weld-o-let 4"-SI-1401-53	4/18/2011	RR40078181-01
2	Piping	Replace pipe due to min-wall violations	5/4/2011	RR39023458-01
3	Tank	Repair Corroded Vent Pipe	4/23/2011	RR40053145-05