

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 12377

FILE: INCIDENT REPORT FILE

FROM: Northern States Power Co. Minneapolis, Minn. Mr. R.S. Boyd		DATE OF DOC 10-24-75	DATE REC'D 10-28-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. R.S. Boyd		ORIG None	CC 40	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 40	DOCKET NO: 50-263		

DESCRIPTION:

Letter trans the following.....

ENCLOSURES:

Licensee Event Report # 75-21, on 10-15-75,
Concerning Failure of # 2 Starting System of # 11
Diesel Generator.....
(40 Copies Enclosure Recieved)

PLANT NAME: Monticello

FOR ACTION/INFORMATION

SAB 10-28-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	FEED W/ Copies

ACKNOWLEDGED

DO NOT REMOVE

INTERNAL DISTRIBUTION

<u>REG FILE</u> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE GIAMBUSSO BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<u>TECH REVIEW</u> SCHROEDER MACCARY KNIGHT PAWLICKI SHAO ** STELLO ** HOUSTON ** NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	<u>DENTON</u> GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHROCK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<u>A/T IND.</u> BRAITMAN SALTZMAN MELTZ <u>PLANS</u> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
---	---	--	--	--

EXTERNAL DISTRIBUTION

1 - LOCAL PDR Minneapolis, Minn.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST R. Diggs		
** SEND ONLY TEN DAY REPORTS		



NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

October 24, 1975

Regulatory

File Cy.

Mr R S Boyd, Acting Director
Division of Reactor Licensing
U S Nuclear Regulatory Commission
Washington, DC 20555

Dear Mr Boyd:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Failure of #2 Starting System of #11 Diesel Generator



The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/ak

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman



-over-

12377

LICENSEE EVENT REPORT

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 6

LICENSEE NAME 01 M N M N P 1	LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0	LICENSE TYPE 4 1 1 1 1	EVENT TYPE 0 1
7 8 9 14	15 25	26 30	31 32

CATEGORY 01 CON'T	REPORT TYPE P O	REPORT SOURCE T L	DOCKET NUMBER 0 5 0 - 0 2 6 3	EVENT DATE 1 0 1 5 7 5	REPORT DATE 1 0 2 3 7 5
7 8	57 58	59 60	61 68	69 74	75 80

EVENT DESCRIPTION

02 During test, #2 start system on #11 Diesel Generator Failed due to a loose fitting

03 on a control air line to the air start motors. The redundant start system and re-

04 dundant diesel generator were operable. The fitting was tightened and

05 operability was demonstrated.

06 (AO 263/75-21)

SYSTEM CODE E H	CAUSE CODE A	COMPONENT CODE E N G I N E	PRIME COMPONENT SUPPLIER A	COMPONENT MANUFACTURER E 1 4 7	VIOLATION N
7 8 9 10	11	12 17	43	44 47	48

CAUSE DESCRIPTION

08 Fitting was apparently not tightened sufficiently when preventive maintenance

09 was performed in August, 1975. Electro-Motive Division Model 999-20. Fitting

10 tightened.

FACILITY STATUS H	% POWER 0 0 0	OTHER STATUS NA	METHOD OF DISCOVERY B	DISCOVERY DESCRIPTION NA
7 8 9	10 12 13	44	45 46	80

FORM OF ACTIVITY RELEASED Z	CONTENT OF RELEASE Z	AMOUNT OF ACTIVITY NA	LOCATION OF RELEASE NA
7 8 9	10 11	44	45 80

PERSONNEL EXPOSURES

NUMBER 0 0 0	TYPE Z	DESCRIPTION NA
7 8 9 11	12	13 80

PERSONNEL INJURIES

NUMBER 0 0 0	DESCRIPTION NA
7 8 9 11	12 80

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE Z	DESCRIPTION NA
7 8 9 10	80

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 Operability of the diesel generators not required at time of discovery.

19

NAME: Richard A Goranson

PHONE: 612/295-5151