

50-263

## NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:

Northern States Power Co.  
Minneapolis, Minnesota  
L. O. Mayer

DATE OF DOCUMENT

7/15/77

DATE RECEIVED

7/21/77

☒ LETTER☐ ORIGINAL☐ COPY☐ NOTORIZED☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 CC

DESCRIPTION

DO NOT REMOVE

PLANT NAME:

Monticello

RJL

ACKNOWLEDGED (1-P)

ENCLOSURE

Licensee Event Report (RO 50-263/77-11) on  
6/17/77 concerning moisture separator drain  
line leak.....

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED  
SEND DIRECTLY TO KREGER/J. COLLINS

## FOR ACTION INFORMATION

BRANCH CHIEF:

W/ 3 CYS FOR ACTION

LIC ASST.:

Davis (4)

## INTERNAL DISTRIBUTION

REG FILE

NRC PDR

I &amp; E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

KNIGHT

BUTLER

HANAUER

TEDESCO

EISENHUT

BAER

SHAO

VOLLMER/RUNCH

KREGER/ J. COLLINS

ROSA

## EXTERNAL DISTRIBUTION

LPDR:

Minneapolis, Min

TIC:

NSIC:

ACRS (16) SENT AS CAT, B

CONTROL NUMBER

772020247




NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 15, 1977

Mr. J G Keppler, Director, Region III  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137



**Regulatory Docket File**

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Moisture Separator Drain Line Leak

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

*David Musolf* FOR  
L O Mayer, PE

Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)  
Director, MIPC, USNRC (3)  
G Charnoff  
MPCA  
Attn: J W Ferman

1977 JUL 21 AM 11 31

RECEIVED DOCUMENT  
PROCESSING UNIT

772020247

# LICENSEE EVENT REPORT

**CONTROL BLOCK:**

1					B

**(PLEASE PRINT ALL REQUIRED INFORMATION)**

LICENSEE NAME					LICENSE NUMBER								LICENSE TYPE					EVENT TYPE						
01	M	N	M	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	3	
7	8	9				14	15									25	26					30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE												
01				L	L	0	5	0	-	0	2	6	3	0	6	1	7	7	7	0	7	1	5	7	7					
7	8			57	56	59	60							61						68	69				74	75				80

### EVENT DESCRIPTION

02 | During plant startup, routine inspection of hotwell area revealed leak in welded  
7 8 9 80

03 | joint in 1" drain line connected to the "C" moisture separator drain line. Leak  
7 8 9 60

04 | temporarily patched until joint could be re-welded on 6/26/77. No previous  
7 8 9 80

05 | similar occurrences.  
7 8 9 80

06 | (M-RO-77-11)  
7 8 9 80

PRIME

SYSTEM CODE      CAUSE CODE      COMPONENT CODE      PRIME COMPONENT SUPPLIER      COMPONENT MANUFACTURER      VIOLATION  
 07    H    H    B    P    I    P    E    X    X    A    B    3    4    5    N  
 7    8-9    10    11    12    13    14    15    16    17    43    44    45    46    47    48

## CAUSE DESCRIPTION

08	Inspection revealed poor quality of welded joint original weld joint ground off	80
09	and re-welded.	80
10		80

FACILITY STATUS		% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	C	087	NA	B	NA

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
1	2	Z		NA		NA	
7	8	9	10	11		44	45
							80

## PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
1	3	000	Z	NA

## PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	00	NA

## OFFSITE CONSEQUENCES

[illegible]

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
1	8	Z	NA

## PUBLICITY

17	NA
----	----

### ADDITIONAL FACTORS

18

19 \_\_\_\_\_ 80

NAME: Byron D Day PHONE: 612/295-5151