

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO: Mr. J. G. Keppler	FROM: NSP Minneapolis, Minnesota 55401 L. O. Mayer	DATE OF DOCUMENT 10/27/77
<input checked="" type="checkbox"/> LETTER <input checked="" type="checkbox"/> ORIGINAL <input type="checkbox"/> COPY	<input type="checkbox"/> NOTORIZED <input checked="" type="checkbox"/> UNCLASSIFIED	DATE RECEIVED 11/11/77
PROP		NUMBER OF COPIES RECEIVED 1 signed
INPUT FORM		

DESCRIPTION	ENCLOSURE Licensee Event Report (RO 50-263/77-31) on 10/13/77 concerning during inspection, it was noted that torus internal catwalk sections were not attached in same manner....
1p	1p
PLANT NAME: MONTICELLO jcm 11/14/77	NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS 1 CY ENCL Rec'd *

FOR ACTION/INFORMATION

BRANCH CHIEF:	DAVIS
W/ 4 CYS FOR ACTION	
REG ASST:	

INTERNAL DISTRIBUTION

REG FILES			
NRC PDR			
I & E (2)			
MIPC			
SCHROEDER/ IPPOLITO			
HOUSTON			
NOVAK/ CHECK			
GRIMES			
KNIGHT			
BUTLER			
HANAUER			
TEDESCO			
EISENHUT			
BAER			
SHAO			
VOLLMER/ BUNCH			
KREGER/ J. COLLINS			
ROSA			

EXTERNAL DISTRIBUTION


LPDR: MINNEAPOLIS, MN.		CONTROL NUMBER
TIC		
NSIC		773180094
ACRS (16) CYS SENT AS CAT. B		

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

D. Lantham
REGULATORY DOCKET FILE COPY



October 27, 1977

Mr J G Keppler, Director, Region III
Office of Inspection and Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 263 License No. DPR-22

Torus Internal Catwalk Construction Deficiencies

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are 3 copies.

Yours very truly,

L O Mayer for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/LLT/ak

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
G Charnoff
MPCA - Attn: J W Ferman

OCT 31 1977

773180094

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 M N M N P 1 14 15 0 0 - 0 0 0 0 - 0 0 25 26 4 1 1 1 1 1 30 31 0 1 32

CON'T: 01 7 8 9 CATEGORY: 57 58 REPORT TYPE: T 59 REPORT SOURCE: L 60 DOCKET NUMBER: 0 5 0 - 0 2 6 3 68 EVENT DATE: 1 0 1 3 7 7 74 REPORT DATE: 1 0 2 7 7 7 80

EVENT DESCRIPTION

02 7 8 9 During inspection, noted torus internal catwalk sections not attached in same manner. Review of drawings revealed requirement for weld and bolt at attachment locations. Of 64 locations, 2 neither bolted nor welded, 2 welded only, 2 bolted and welded, and remaining bolted only. All locations will be upgraded to design requirement prior to end of current outage. Not repetitive occurrence. (M-R0-77-31)

SYSTEM CODE: S A 7 8 9 10 CAUSE CODE: B 11 COMPONENT CODE: V E S S E L 17 PRIME COMPONENT SUPPLIER: N 43 COMPONENT MANUFACTURER: C 3 1 0 44 47 VIOLATION: N 48

CAUSE DESCRIPTION

08 7 8 9 Welds and bolts were omitted during original construction of torus. GE Mark I Containment. All locations will be upgraded to design requirements prior to end of current outage.

FACILITY STATUS: H 9 POWER: 0 0 0 10 12 13 OTHER STATUS: NA 44 METHOD OF DISCOVERY: B 45 DISCOVERY DESCRIPTION: NA 46 60

FORM OF ACTIVITY RELEASED: Z 9 CONTENT OF RELEASE: Z 10 AMOUNT OF ACTIVITY: NA 11 44 LOCATION OF RELEASE: NA 45 80

PERSONNEL EXPOSURES

13 7 8 9 NUMBER: 0 0 0 11 TYPE: Z 12 DESCRIPTION: NA 13 80

PERSONNEL INJURIES

14 7 8 9 NUMBER: 0 0 0 11 12 DESCRIPTION: NA 80

OFFSITE CONSEQUENCES

15 7 8 9 NA 80

LOSS OR DAMAGE TO FACILITY

16 7 8 9 TYPE: Z 10 DESCRIPTION: NA 80

PUBLICITY

17 7 8 9 NA 80

ADDITIONAL FACTORS

18 7 8 9 NA 80

19 7 8 9 80

NAME: Richard Goranson

PHONE: 612/295/5151

GPO 881-887

RECEIVED DOCUMENT PROCESSING UNIT
1977 NOV 11 PM 1 57