

D. Lanham

NSP

REGULATORY DOCKET FILE COPY

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 19, 1977

Mr J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Licensee Update Report M-R0-77-33

The Licensee Event Update Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

M O Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman

DEC 22 1977

over

780040181

UPDATE REPORT - PREVIOUS
REPORT DATE 11/30/77

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 M N M N P 1 14 15 0 d - 0 0 0 0 0 0 - 0 0 25 26 4 1 1 1 1 30 31 0 3 32

CATEGORY: 01 CON'T 57 58 REPORT TYPE: L 59 REPORT SOURCE: L 60 DOCKET NUMBER: 0 5 0 - 0 2 6 3 68 EVENT DATE: 1 0 3 1 7 7 69 74 REPORT DATE: 1 1 2 1 9 7 7 75 80

EVENT DESCRIPTION

02 7 8 9 ADDITIONAL INFORMATION #15 BUS AUTO TRANSFER MALFUNCTION: PROBLEM WITH LOAD CENTER 80
03 7 8 9 ADDITION WIRING TERMINATIONS WAS DISCOVERED DURING INSTALLATION PRIOR TO DG SURVEIL- 80
04 7 8 9 LANCE TEST. INVESTIGATION OF TERMINATION PROBLEM IN PROGRESS AT TIME DG SURVEIL- 80
05 7 8 9 LANCE TEST REVEALED AUTO TRANSFER CIRCUIT MALFUNCTION. OCCURRENCE DID NOT AFFECT 80
06 7 8 9 DG OPERABILITY, ONLY AFFECTED AUTOMATIC SEQUENCING OF POWER SUPPLIES TO BUS #15. 80

SYSTEM CODE: 07 E B 9 10 CAUSE CODE: B 11 COMPONENT CODE: C K T E R K 12 17 PRIME COMPONENT SUPPLIER: A 43 COMPONENT MANUFACTURER: Z 9 9 9 44 47 VIOLATION: N 48

CAUSE DESCRIPTION

08 7 8 9 LOAD CENTER WIRES WERE LANDED AS SHOWN ON CONSTRUCTION PRINTS HOWEVER PRINTS WERE 80
09 7 8 9 INCORRECT. DESIGNER REVIEWED ONLY EXTERNAL PANEL PRINTS TO DETERMINE SPARE 80
10 7 8 9 TERMINAL LOCATIONS. 80

FACILITY STATUS: 11 G 9 % POWER: 0 0 0 10 12 13 OTHER STATUS: NA 44 METHOD OF DISCOVERY: B 45 46 DISCOVERY DESCRIPTION: NA 80

FORM OF ACTIVITY RELEASED: 12 Z 9 CONTENT OF RELEASE: Z 10 11 AMOUNT OF ACTIVITY: NA 44 45 LOCATION OF RELEASE: NA 80

PERSONNEL EXPOSURES

13 7 8 9 NUMBER: 0 0 0 11 TYPE: Z 12 DESCRIPTION: NA 13 80

PERSONNEL INJURIES

14 7 8 9 NUMBER: 0 0 0 11 12 DESCRIPTION: NA 80

OFFSITE CONSEQUENCES

15 7 8 9 NA 80

LOSS OR DAMAGE TO FACILITY

16 7 8 9 TYPE: Z 10 DESCRIPTION: NA 80

PUBLICITY

17 7 8 9 NA 80

ADDITIONAL FACTORS

18 7 8 9 (Event Description continued) M-RO-77-33 80

19 7 8 9 80

NAME: D. D. Tilly

PHONE: 6 295-5151

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

DATE OF DOCUMENT
12/19/77DATE RECEIVED
1/4/78TO:

Mr. J. G. KeppelerFROM:
Northern States Power Company
Minneapolis, Minnesota
L. O. Mayer☒ LETTER
☐ ORIGINAL
☒ COPY☐ NOTORIZED
☒ UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 CC

DESCRIPTION

PLANT NAME: Monticello
RJL 1/4/78

(1-P)

ENCLOSURE

Licensee Event Report (RO 50-263/77-33) on
10/31/77 (Update Rept.) concerning Auto
Transfer Circuit Malfunction.....NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS
1 ENCL

FOR ACTION/INFORMATION

BRANCH CHIEF: (4)
W/ 3 CYS FOR ACTION
L.R. ASST.:

DAVIS

INTERNAL DISTRIBUTION

REG FILE
NRC PDR
T & E (2)
MTC
SCHROEDER/IPPOLITO
HOUSTON
NOVAK/CHECK
CRIMES
KNIGHT
BUTLER
HANAUER
TEDESCO
EISENHUT
BAER
SHAO
VOLLMER/BUNCH
KREGER/J. COLLINS
BOSA
4 CRACKER

EXTERNAL DISTRIBUTION

LEDR: MINNEAPOLIS MN
TIC:
NSIC:
ACRS (16) SENT AS CAT. B

CONTROL NUMBER

A04
780040181