

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3316

FILE: _____

FROM: Northern States Power Company Monticello, Minnesota 55362 C. E. Larson			DATE OF DOC 4-15-74	DATE REC'D 4-15-74	LTR Y	MEMO	RPT	OTHER Facsimile
TO: Mr. Keppler			ORIG	CC	OTHER	SENT AEC PDR X SENT LOCAL PDR X		
CLASS	UNCLASS XXXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-263		

DESCRIPTION:
Facsimile, reporting an Abnormal Occurrence on 4-12-74, in which two cracks were found in the stainless steel tee associated with the flow switch.....

ENCLOSURES:

Do Not Remove

PLANT NAME: Monticello

FOR ACTION/INFORMATION

4-16-74

AB

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	✓ ZIEMANN(L) W/ 7 Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
PARR(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u>	<u>TECH REVIEW</u>	DENTON	<u>LIC ASST</u>	<u>A/T IND</u>
✓ AEC PDR	✓ HENDRIE	GRIMES		BRAITMAN
✓ OGC, ROOM P-506A	SCHROEDER	GAMMILL	✓ DIGGS (L)	SALTZMAN
✓ MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	R. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	<u>PLANS</u>
GIAMBUSSO	✓ PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓ SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L) (BWR)	✓ STELLO	<u>ENVIRO</u>	REED (E)	<u>INFO</u>
DEYOUNG(L) (PWR)	✓ HOUSTON	MULLER	SERVICE (L)	C. MILES
SKOVHOLT (L)	✓ NOVAK	DICKER	SHEPPARD (L)	✓ B. KING (E/W-358)
✓ GOLLER(L)	✓ ROSS	KNIGHTON	SLATER (E)	✓ KLECKER
P. COLLINS	✓ IPPOLITO	YOUNGBLOOD	SMITH (L)	✓ EISENHUT
DENISE	✓ TEDESCO	REGAN	TEETS (L)	
REG OPR	✓ LONG	PROJECT LDR	WADE (E)	
✓ FILE & REGION(3)	✓ LAINAS		WILLIAMS (E)	
✓ MORRIS	✓ BENAROYA	HARLESS	WILSON (L)	
✓ STEELE	✓ VOLMER			

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR Minneapolis, Minn.	(1) (2X10) NATIONAL LAB'S	1-PDR-SAN/LA/NY
✓ 1 - TIC (ABERNATHY)	1-ASLBP(E/W Bldg, Rm 529)	1-GERALD LELLOUCHE
✓ 1 - NSIC(BUCHANAN)	1-W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
1 - ASLB	1-CONSULTANT'S	1-AGMED(Ruth Gussman)
1 - P. R. DAVIS (AEROJET NUCLEAR)	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
✓ 16 - CYS ACRS holding SENT TO LIC ASST.	1-GERALD ULRIKSON...ORNL	1-RD..MULLER..F-309 GT
R. DIGGS ON 4-16-74	1-B & M SWINEBROAD, Rm E-201 GT	

NSP


NORTHERN STATES POWER COMPANY

Monticello, Minnesota 55362

Rec'd 4/15
10:53 BETH

April 15, 1974

Mr. J. G. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
United States Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 61073



Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Cracked Tee in Standby Liquid Control System

On April 12, 1974, while performing a non-destructive examination of a seal weld on a FEBCO flow switch (following removal of the flow switch actuator paddle) two cracks were found in the stainless steel tee associated with the flow switch.

Investigation into the cause of the cracks is being conducted.

Yours very truly,

C. E. Larson
C. E. Larson
Plant Manager

CEL/mm

cc: J F O'Leary, Directorate of Licensing
G Charnoff
Minnesota Pollution Control Agency
Attn: E A Pryzina

Copies sent by telecopier to Keppler and O'Leary

