

**Recent Licensee Event Report (LER) Search Results - for “Seismic” related LERs**  
**(Jan-26-2009 and Jan-26-2011) – 18 LERs**

NOTE: This document is referenced from and supports Information Notice 2012-01 “SEISMIC CONSIDERATIONS—PRINCIPALLY ISSUES INVOLVING TANKS” issued under Agencywide Documents and Management System (ADAMS) Accession Number: [ML1129A175](#)

<b>LER Active Hyper-link</b>	<b>Event Date</b>	<b>Plant /Unit #</b>	<b>Title/ Brief Description</b>
<a href="#">2372009008</a>	11/03/2009	Dresden 2	Unit 2 Core Spray Break Detection Instrument Line Not Seismically Supported
<a href="#">2702010001</a>	07/02/2010	Oconee 2	Operation Prohibited by TS due to Removal of West Penetration Room Brick Wall Support Girts
<a href="#">2772010002</a>	09/18/2010	Peach Bottom 2, Peach Bottom 3	Improperly Fastened Rod Hanger Results in Inoperable Subsystem of Emergency Service Water
<a href="#">2932010001</a>	01/10/2010	Pilgrim	Single Train of Reactor Building Closed Cooling Water System Inoperable for Time Period Exceeding Technical Specification Limits
<a href="#">3312010006</a>	11/10/2010	Duane Arnold	Standby Liquid Control Test Tank Seismic Analysis
<a href="#">3382010005</a>	12/12/2010	North Anna 1	Unanalyzed Scaffolding Renders Charging Pump Inoperable due to Human Error
<a href="#">3612009002</a>	03/28/2009	San Onofre 2, San Onofre 3	Inoperable 1E Breaker Causes Containment Chiller to be Inoperable
<a href="#">3612009003</a>	09/29/2009	San Onofre 2	Pressurizer Auxiliary Spray Failed Inservice Test
<a href="#">3612010001</a>	01/26/2010	San Onofre 2	Broken Manual Valve Prevents Timely Condensate Storage Tank Isolation
<a href="#">3612010002</a>	05/12/2010	San Onofre 2	Non-qualified Part in Turbine Driven Auxiliary Feedwater Pump
<a href="#">3612010005</a>	10/13/2010	San Onofre 2, San Onofre 3	Refueling Water Storage Tank Alignment to Non-Seismic Piping Results in Potential Loss of Safety Function
<a href="#">3612010006</a>	10/13/2010	San Onofre 2, San Onofre 3	Breakers Left in Non-Seismically Qualified Condition Result in Condition Prohibited by Technical Specifications
<a href="#">3642009001</a>	10/06/2009	Farley 2	Service Water Pump Seismic Supports Degraded
<a href="#">3732010003</a>	10/28/2010	LaSalle 1, LaSalle 2	Standby Liquid Control Test Tank Seismic Analysis
<a href="#">4002010003</a>	09/16/2010	Harris	Condition Prohibited by Technical Specifications When Non-seismic System Was Aligned to Refueling Water Storage Tank
<a href="#">4552010002</a>	06/04/2010	Byron 2	Essential Service Water System Inoperable Due to Inadequate Seismic Restraint from Original Construction Error
<a href="#">4822010010</a>	09/22/2010	Wolf Creek	Inadequate Analysis Results in a Component Cooling Water Train to be Declared Inoperable
<a href="#">4832010008</a>	09/23/2010	Callaway	Inadequate Analysis Results in a Component Cooling Water Train Declared Inoperable

**LER Search Restrictions:**

Status: Active

Event Dates: between Jan-26-2009 and Jan-26-2011

Keyword(s): seismic

Keyword Scope: Title and Abstract

NRC ADAMS Accession # ML11292A197