



Progress Energy Florida

**Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report**

Primary and Orthogonal Fracture Pattern
Local Avon Park Formation Outcrops
FIGURE 2.5.4.1-202

Rev 1