



PSEG Power, LLC

PSEG Site ESPA
Part 2, Site Safety Analysis Report

Synthetic Modulus and Damping
Degradation Curves for Soil
Layers 2 through 5

FIGURE 2.5.2-38

Rev 0