



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 EAST LAMAR BLVD
ARLINGTON, TEXAS 76011-4511

March 5, 2013

Matthew Sunseri, President and
Chief Executive Officer
Wolf Creek Nuclear Operating Corporation
P.O. Box 411
Burlington, KS 66839

Subject: ERRATA FOR WOLF CREEK GENERATING STATION – NRC INTEGRATED
INSPECTION REPORT 05000482/2012003

Dear Mr. Sunseri:

Please remove page 18 from the Wolf Creek Generating Station - NRC Integrated Inspection Report 05000482/2012003 and replace it with pages 18 and 18A, which are enclosed with this letter. The purpose of this change is to add documentation for an inspection sample completed during the report period.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response, if you choose to provide one for cases where a response is not required, will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html>. To the extent possible, your response should not include any personal, privacy or proprietary information so that it can be made available to the Public without redaction.

Sincerely,

/RA/

Neil O'Keefe, Chief
Project Branch B
Division of Reactor Projects

Docket No. 50-482
License No. NPF-42

Enclosure:
NRC Inspection Report 05000482/2012003 ERRATA, Pages 18-18A

Electronic Distribution by RIV:

Regional Administrator (Elmo.Collins@nrc.gov)
 Acting Deputy Regional Administrator (Steven.Reynolds@nrc.gov)
 DRP Director (Kriss.Kennedy@nrc.gov)
 Acting DRP Deputy Director (Michael.Scott@nrc.gov)
 Acting DRS Director (Thomas.Blount@nrc.gov)
 Acting DRS Deputy Director (Jeff.Clark@nrc.gov)
 Senior Resident Inspector (Charles.Peabody@nrc.gov)
 Branch Chief / B (Neil.OKeefe@nrc.gov)
 Senior Project Engineer (Michael.Bloodgood@nrc.gov)
 Project Engineer (David.You@nrc.gov)
 Public Affairs Officer (Victor.Dricks@nrc.gov)
 Public Affairs Officer (Lara.Uselding@nrc.gov)
 Regional State Liaison Officer (Bill.Maier@nrc.gov)
 Congressional Affairs Officer (Jenny.Weil@nrc.gov)
 NRR Project Manager (Fred.Lyon@nrc.gov)
 RITS Coordinator (Marisa.Herrera@nrc.gov)
 TSB Technical Assistant (Loretta.Williams@nrc.gov)
 ROPreports@nrc.gov
 RIV/ETA: OEDO (John.Cassidy@nrc.gov)

File located: S:\DRP\DRPDIR_WC Errata WC2012-003 rpt MRB.docx

SUNSI Rev Compl.	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	ADAMS	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Reviewer Initials	MRB
Publicly Available	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Sensitive	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sens. Type Initials	MRB
SPE:DRP/B	RI:DRP/B	C:DRP/B			
MBloodgood	CPeabody	NOKeefe			
/E-Okeefe for/	/E-Okeefe for/	/RA/			
3/5/2013	3/5/2013	3/5/2013			

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

- Reference setting data
- Annunciators and alarms setpoints

The inspectors also verified that licensee personnel identified and implemented any needed corrective actions associated with the surveillance testing.

- June 10, 2012, Spent fuel pool pump B inservice testing
- March 19, 2012, Main steam isolation valve inservice testing
- June 20, 2012, STS BB-006, reactor coolant system leak rate calculation
- June 21, 2012, Containment spray pump B inservice testing
- June 27, 2012, Residual heat removal pump A inservice testing
- June 28, 2012, TMP 11-013, Reactor coolant system to emergency core cooling system check valve leak test

Specific documents reviewed during this inspection are listed in the attachment.

These activities constitute completion of six surveillance testing inspection samples as defined in Inspection Procedure 71111.22-05.

b. Findings

No findings were identified.

Cornerstone: Emergency Preparedness

1EP6 Drill Evaluation (71114.06)

.1 Emergency Preparedness Drill Observation

a. Inspection Scope

The inspectors evaluated the conduct of a force-on-force emergency drill on April 3, 2012, to identify any weaknesses and deficiencies in classification, notification, and protective action recommendation development activities. The inspectors observed emergency response operations in the exercise control room to determine whether the event classification, notifications, and protective action recommendations were performed in accordance with procedures. The inspectors also attended the licensee drill critique to compare any inspector-observed weakness with those identified by the licensee staff in order to evaluate the critique and to verify whether the licensee staff was properly identifying weaknesses and entering them into the corrective action program. As part of the inspection, the inspectors reviewed the drill package and other documents listed in the attachment.

These activities constitute completion of one sample as defined in Inspection Procedure 71114.06-05.

b. Findings

No findings were identified.

2. RADIATION SAFETY

Cornerstone: Occupational and Public Radiation Safety

2RS05 Radiation Monitoring Instrumentation (71124.05)

a. Inspection Scope

This area was inspected to verify the licensee is assuring the accuracy and operability of radiation monitoring instruments that are used to: (1) monitor areas, materials, and workers to ensure a radiologically safe work environment and (2) detect and quantify radioactive process streams and effluent releases. The inspectors used the requirements in 10 CFR Part 20, the technical specifications, and the licensee's procedures required by technical specifications as criteria for determining compliance. During the inspection, the inspectors interviewed licensee personnel, performed walkdowns of various portions of the plant, and reviewed the following items: