

SUBJECT: Forwards monthly outage rept for 850716-0815 describing occurrences resulting in degradation of auxiliary feedwater sys. Unit 2 had 9% component unavailability. Unit 3 had 1% unavailability.

NOTES:ELD Chandler 1cy.	05000361
OL:02/16/82	
ELD Chandler 1cy.	05000362
OL:11/15/82	

INTERNAL:							
ACRS	09	6	6	ADM/LFMB		1	0
ELD/HDS2		1	0	NRR/DE/MTEB		1	1
NRR/DL DIR		1	1	NRR/DL/ORAB		1	0
NRR/DL/TSRG		1	1	NRR/DSI/METB		1	1
NRR/DSI/RAB		1	1	REG FILE	04	1	1
RGNS		1	1				
EXTERNAL:							
24X		1	1	EG&G BRUSKE,S		1	1
LPDR	03	1	1	NRC PDR	02	1	1
NSIC	05	1	1				

NOTES: 1 1

Southern California Edison Company



P. O. BOX 800
2244 WALNUT GROVE AVENUE
ROSEMEAD, CALIFORNIA 91770

M. O. MEDFORD
MANAGER, NUCLEAR LICENSING

September 10, 1985

TELEPHONE
(818) 302-1749

Director, Office of Nuclear Reactor Regulation
Attention: Mr. George W. Knighton, Branch Chief
Licensing Branch No. 3
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Auxiliary Feedwater System Monthly Outage Report
San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to License Condition 2.C(26) of Facility Operating License NPF-15 for San Onofre Unit 3, this submittal provides the required monthly report describing any occurrence resulting in the degradation of the Units 2 and 3 Auxiliary Feedwater Systems (AFWS). This report covers the period from July 16, 1985 to August 15, 1985. The component involved, cause of outage, outage duration, and corrective actions taken to return the equipment to operable status are listed.

Units 2 and 3 operated in Mode 3 and above during the entire reporting period, with 100% AFWS availability. Unit 2 had a 9% component unavailability and Unit 3 had a 1% component unavailability.

In accordance with License Condition 2.C(26), our next report will cover the period from August 16, 1985 to September 15, 1985.


If there are any questions regarding this report, please contact me.

Sincerely,

Enclosure

cc: J. B. Martin (Regional Administrator,
U.S. Nuclear Regulatory Commission, Region V)
H. Rood (Project Manager, SONGS 2/3,
U.S. Nuclear Regulatory Commission, NRC)

F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)



A001

San Onofre Nuclear Generating Station, Units 2 and 3
Monthly AFWS Outage Report
July 16, 1985 to August 15, 1985

Date	Unit	Outage	Duration (hours)	Outage Cause	Corrective Action
7/26	2	Corrective Maintenance	30	Auxiliary Feedwater to Steam Generator E088 Isolation Valve HV4714 was removed from service due to the hydraulic pump cycling too often and the motor being too hot.	Changed oil and filter. Investi- gation of the ac- tuator identified minor leak in solenoid valve. Repair is waiting parts. In the interim valve (HV4714) was returned to service and continues to operate satisfac- torily.
8/12	2	Preventa- tive Maintenance	40	Auxiliary Feedwater Pump P141 was removed from service to change motor oil.	Changed oil and returned to service.
8/10	3	Preventa- tive Maintenance	0.5	Auxiliary Feedwater Pump P141 was removed from service for Subgroup Relay Testing.	Test satisfact- ory. Returned to service.
8/15	3	Corrective Maintenance	5.75	Auxiliary Feedwater Pump P140 was removed from service due to oil deflector ring on the inboard pump bearing working out.	Replace defective setscrew on bearing and returned to service.