

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7906270239 DOC. DATE: 79/06/22 NOTARIZED: NO
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California
 50-362 San Onofre Nuclear Station, Unit 3, Southern California
 AUTH. NAME: MOORE, J.B. AUTHOR AFFILIATION: Southern California Edison Co.
 RECIP. NAME: ENGELKEN, R.H. RECIPIENT AFFILIATION: Region 5, San Francisco, Office of the Director

DOCKET #
 05000361
05000362

SUBJECT: Forwards final deficiency rept re surface defects in Taylor
 Forge carbon steel pipe.

DISTRIBUTION CODE: 8019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+8
 TITLE: CONSTRUCTION DEFICIENCY REPORT (10CFR50.55E).

NOTES: SEND ALL FSAR & ER AMENDS TO L. CHANDLER.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM <u>ROOD</u>	1 1	15 BC <u>LWR #2</u>	1 1
	20 LA <u>LWR #2</u>	1 1	21 AD <u>VASSALLO</u>	1 1
INTERNAL:	01 <u>REG FILE</u>	1 1	02 NRC POR	1 1
	05 ISE	2 2	07 EDC & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	12 JORDAN, E/IE	1 1	13 FIELD COOR/IE	1 1
	16 AD FOR ENGR	1 1	17 AD PLANT SYS	1 1
	17 AD REAC SFTY	1 1	19 AD SYS/PROJ	1 1
	22 DIR DPM	1 1	23 OELD	1 1
	AD/SITE TECH	1 1	DIRECTOR DSE	1 1
	GEOSCIENCES BR	1 1	STRUCT ANALYS BR	1 1
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

JUN 28 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 43 ENCL 43

MA 1

60

Southern California Edison Company

P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

JACK B. MOORE
VICE PRESIDENT

TELEPHONE
213-572-2292

June 22, 1979

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

REGULATORY DOCKET FILE COPY

Dear Mr. Engelken:


Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

By letter dated January 23, 1979, we confirmed notification concerning a reportable condition in construction of San Onofre Units 2 and 3 related to surface defects in carbon steel pipe manufactured by Taylor Forge. An interim report on this condition was forwarded by our letter dated February 22, 1979.

Enclosed in accordance with 10CFR50.55(e) are twenty-five (25) copies of a final report entitled "Final Report on Taylor Forge Pipe Defects, San Onofre Nuclear Generating Station, Units 2 and 3."

If you have any questions regarding this report, we would be pleased to discuss this matter with you at your convenience.

Very truly yours,



Enclosure

cc: John G. Davis (NRC, Acting Director I&E)
R. J. Pate (NRC, San Onofre)

*Boia
5/1*

7906270 239: