

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8001090463 DOC. DATE: 80/01/02 NOTARIZED: NO DOCKET #
 FACIL: 50-361 San Onofre Nuclear Station, Unit 2, Southern California 05000361
 50-362 San Onofre Nuclear Station, Unit 3, Southern California 05000362

AUTH. NAME: ARENAL, A. AUTHOR AFFILIATION: Southern California Edison Co.
 RECIP. NAME: ENGELKEN, R.H. RECIPIENT AFFILIATION: Region 5, San Francisco, Office of the Director

SUBJECT: Supplement to final deficiency rept re deficiencies in
 SA-312 Type 304 pipe mfg by Youngstown Welding & Engineering
 Co. One addl pipe spool & one addl pipe support identified as
 product of company. Parts will be returned.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Send ALL FSARTER Amendments TO

L. CHANDLER

ACTION:	ID CODE/NAME	COPIES		RECIPIENT	ID CODE/NAME	COPIES	
		LTR	ENCL			LTR	ENCL
	14 PMROOD	1			15 BC LWR#2	1	
	20 LALWR#2	1			21 ADAD/LWR	1	
INTERNAL:	01 REG FILE	1			02 NRC PDR	1	
	05 I&E	2			07 EDU & STAFF	1	
	08 MPA	1			09 DEPY DIR DPM	1	
	10 QAB	1			11 STANDRDS DEV	1	
	12 JORDAN, E/IE	1			13 FIELD COUR/IE	1	
	16 AD FOR ENGR	1			17 AD PLANT SYS	1	
	17 AD REAC SFTY	1			22 DIR DPM	1	
	23 OELD	1			AD/SITE TECH	1	
	DIRECTOR OSE	1			GEOSCIENCES BR	1	
	I&C SYS BR	1			MATL ENG BR	1	
	MECH ENG BR	1			POWER SYS BR	1	
	S HANAUER	1			STRUCT ENG BR	1	
EXTERNAL:	03 LPDR	1			04 NSIC	1	
	24 ACRS	16	16				

Ltr

MOORE
 EPB#2
 D. SCALETT
 EPB#2

JAN 11 1980

MA

60

TOTAL NUMBER OF COPIES REQUIRED: LTR

48

ENCL

0

Southern California Edison Company



P. O. BOX 800

2244 WALNUT GROVE AVENUE

ROSEMEAD, CALIFORNIA 91770

A. ARENAL
VICE PRESIDENT

TELEPHONE
213-572-1476

January 2, 1980

Mr. R. H. Engelken, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1990 North California Boulevard
Walnut Creek, California 94596

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362
San Onofre Nuclear Generating Station, Units 2 and 3

In a letter to your office dated December 1, 1978, we transmitted a report pursuant to 10CFR50.55(e)(3) entitled "Final Report Concerning Deficiencies in SA-312 Type 304 Pipe Manufactured by Youngstown Welding and Engineering Company, San Onofre Nuclear Generating Station, Units 2 and 3." The report discussed four pipe spools and five pipe supports which were identified for inspection of potentially defective longitudinal seam welds and corrective action taken with regard to these pipe spools and supports.

Subsequent to submittal of the above report, one additional pipe spool and one additional pipe support attachment have been identified as containing material supplied by Youngstown Welding and Engineering Company. The additional spool and support attachment will be returned to Pullman Power Products for testing and/or replacement.

The above information supplements our original report on this matter. All other aspects of the report remain the same. If you have any questions or wish additional information, please let us know.

Very truly yours,

A. Arenal

BO19
SE
1/0

cc: Victor Stello (NRC, Director I&E)
R. J. Pate (NRC, San Onofre Units 2 and 3)

8001090463